BGC BGC ENGINEERING INC.

200, 1121 Centre Street NW, Calgary, Alberta, Canada. T2E 7K6 Phone (403) 250-5185 Fax (403) 250-5330

MEMORANDUM

То:	Deloitte & Touche	Fax No.:	Via e-mail
Attention:	Doug Sedgwick	CC:	Dana Haggar
From:	Ashton Friesen, Gerry Ferris	Date:	May 15, 2008
Subject:	Intermediate Dam Trigger Levels		
No. of Pages	(including this page): 15	Project No:	0257-044-04

The Intermediate Dam at the Faro Mine retains both tailings and a small pond. This dam was constructed in stages between 1981 and 1991 and is a zoned earthfill dam with gravel shells and a silty till core. As part of on going monitoring and as part of updating the Operations, Surveillance and Maintenance Manual (OMS), a trigger level slope stability analysis has been performed. The scope of work for this study was detailed in a proposal dated May 2nd, 2007. The purpose of the study is to define piezometric readings that would trigger different incident levels for the dam or slope instability in the dam.

Four different incident levels, in terms of factors of safety, were defined as part of the EPP (BGC 2003) and are shown in Table 1. Actions are defined and reporting requirements detailed in the OMS and Emergency Preparedness Plan (EPP) for each of the incident levels.

This memo defines piezometric elevations that would trigger changes to the incident levels. Other trigger mechanisms exist for this dam and are related to other failure modes. The reader should refer to the OMS and EPP for further guidance on triggers for the incident levels due to other failure modes. Of note the EPP and OMS are scheduled for revision in 2008 and the results of this study should be used to update the OMS and EPP documents.

Incident Level	Factor of Safety
Normal	1.5 or greater,
Normai	Piezometric levels below historic maximum
Alort	1.3 or greater,
Alen	Piezometric levels above historic maximum
Emergency	1.1 to 1.3
Failure	1.0 to 1.1

Table 1 Piezometric Incident Levels

1.0 INTERMEDIATE DAM DESIGN

The Intermediate Dam is located in the Rose Creek valley, immediately downhill from the mine and milling operations (see Figure 1). It was built as part of the Down Valley development in 1981 with three subsequent dam raises in 1988, 1989 and 1991, to a final crest elevation of 1049.4 m amsl. The Intermediate Dam was built downstream of the original and second tailings impoundments, and provided storage for tailings prior to ceasing operations at the mine.

A list of general characteristics of the Intermediate Dam is provided in Table 2. Figure 2 provides a plan view and a typical cross section of the Intermediate Dam along with the piezometer locations.

Туре	Zoned Earthfill Dam			
Fill Details	Gravel shell with a silty till core.			
	Starter Dam with a central core, changing to upstream sloping			
	core at subsequent dam raises			
Foundation Cut-off	Partially cut-off			
Purpose	Retain tailings solids, supernatant water and run-off water.			
Year Constructed	Staged construction between 1981-1991.			
Location	See Figures 1 and 2.			
Access	Access to south end of dam via dike crest of Rose Creek			
	Diversion Canal. Access to north end via access road to Down			
	Valley area from the Main Mine access road and across the			
	spillway.			
Failure Consequence*	High.			
Reason for Consequence	Release of non-compliant water and tailings.			
	Qualitative Risk Assessment damages include repair, fines and			
	clean-up with costs estimated between US \$10-100 Million.			
Reference(s) for	Klohn Crippen Consultants Ltd. 2002.			
Consequence Information	Gartner Lee Ltd. 2002.			
	Klohn Crippen Berger 2008			
Emergency Spillway (Y/N)	Υ.			
	Rip rap lined earthen channel. Un-gated free overflow into			
	channel.			
Operation Spillway	Removable 36 inch diameter PVC siphon			
Appurtenances	None.			
*ODA 0007 alagaitiantian 1/C				

Table 2 General Characteristics of the Intermediate Dam

*CDA 2007 classification, KCB 2008

The overall design criteria and key elevations for the Intermediate Dam are provided in Table 3.

Table 3 Intermediate Dam Design Criteria and Key Elevations

Crest Of Dam 1		am 1	18.83 m amsl (2003 survey)			
Top of Core 104		e 1	8.5 m amsl (2003 / 2004 survey)			
Full Supply Level, FSI 104		Level. FSL	047.7 m amsl (2005 survey)			
Spillv	vay In	let 1	047.7m amsl (2005 survey)	7.7m amsl (2005 survey)		
Desi	gn Fre	eboard (0.5 m (Golder 1980)	m (Golder 1980)		
Actua	al Free	eboard (0.68 m (2005 survey)	3 m (2005 survey)		
Desig	gn See	epage (0.22 m ³ /s Golder (1980)			
Rese	ervoir A	Area 1	,957,000 m ² Gartner Lee (2002)			
Total	Stora	ge Capacity 2	28,600,000 m ³ Gartner Lee (2002)			
	ope oility	Upstream / Downstre	am, steady state	FS = 1.5		
	Slo Stał	Upstream, rapid drav	/down	FS = 1.2		
nents	ke	Closure Requirement	: – 1:10,000 year	0.3g (Atkinson 2004)		
quiren	irthqua	CDA Requirement –	1:2,500 year	0.21g (Atkinson 2004)		
gn Re	Ea	Water Licence Requi	rement – 1:500 year	0.08g (Atkinson 2004)		
esi		Closure Requirement	: - PMF	692 m ³ /s (WMC 2006)		
ŏ	Flood	CDA Requirement –	1/3 between 1:1,000 year and PMF	342 m ³ /s (nhc 2004) (WMC 2006)		
		Water Licence Requi	rement – 1:500 year	11.2 m ³ /s (nhc 2006)		
ay		Туре	Earthen Spillway	·		
illv		Rating Curve	Yes (nhc 2006)			
Sp		Capacity	32 m ³ /s (nhc 2006)			
Earthdrake Earthdrake Earthdrake Earthdrake Earthdrake Earthdrake		Comments	Recent work indicates that this dam 1:10,000 year earthquake (0.3 g). T both the 500 and 2,500 return perio	h can withstand the Thus the dam is stable for ds (KCB 2004)		
Downstream		Downstream	FS = 1.6			
Upstrea		Upstream	FS = 1.6			
Upst draw		Upstream, rapid drawdown	Varies with initial water level, see T	able 10 of this report.		

The Intermediate Dam is bordered by the tailings pond on the upstream side and the polishing pond (contained by the Cross Valley Dam) on the downstream side of the Dam. Typical pond levels for both the tailings pond and polishing pond are provided in Table 4.

Water Elevations	Tailings Pond (m amsl)	Polishing Pond (m amsl)
2007 Average	1046.49	1028.67
Historic Maximum	1047.94	1026.25
Historic Minimum	1045.53	1031.70
Spillway Invert	1047.70	1031.20

Table 4 Intermediate Dam Pond Levels (Tailings and Polishing Ponds)

Since 2003 the operating level of the tailings pond has been consistently lower (as low as 1045.53 m amsl) than historically observed. This is due to the rerouting of discharge water from Faro Pit. Prior to 2003 the Faro Pit discharge water was treated at the tailings pond and is now being treated at the Faro Mine treatment plant. This water is then directly or indirectly discharged through the Cross Valley Dam and then into Rose Creek.

2.0 STABILITY ANALYSIS

The purpose of the stability analysis was to define piezometric trigger levels for the Intermediate Dam based on a Factor of Safety criteria (Table 1). The analysis considered a downstream critical failure plane which would, upon failure, release tailings and supernatant from the tailings pond. Similarly on the upstream side the largest possible failure surface, which consisted of a failure plane exiting the dam body above the tailings surface, was analyzed. Shallow surface instabilities of the downstream face were not analyzed in this study. If shallow failures occur they indicate that the dam should be considered within the Alert incident level and treated the same as other Alert level incidences.

The analyses were completed using the Morgenstern – Price method for circular failure surfaces within the slope stability program Slope/W (GEO-SLOPE, 2004). The analysis was conducted under static loading conditions only.

2.1 Material Properties

The material properties used in the analysis are provided in Table 5. These material properties were chosen based on a review of information contained in previous reports on the Intermediate dam and based on typical strength properties for the various material types. The two main references, which included site investigation results and stability analysis were Golder (1980) and Klohn (2004). The friction angles selected are thought to be conservative.

Material	Effective Friction Angle (⁰)	Cohesion (kPa)	Unit Weight (kN/m ³)
Shell and Core	34	0	20
Foundation	32	0	20

Table 5 Material Properties

2.2 Piezometric Readings

The piezometric readings indicate that all the piezometers (except BH91-ID3) can either be classified as a crest or a toe piezometer (BGC 2007), as shown in Table 6. The piezometric elevation measured at all of the crest piezometers were similar, the same situation is encountered at the toe. Thus for the purpose of the slope stability analysis only one cross section was analyzed using a generic crest and toe piezometer. Thus if any of the crest (or toe) piezometers read above the defined elevation, then the appropriate incident level is triggered.

The Intermediate Dam has a total of 14 pneumatic piezometers and standpipes which are located on both the crest and downstream (DS) toe of the Dam, as shown in Figure 2. The historic data associated to these piezometers are provided in Table 6.

Name or	or		Historic Water Levels		
ID	Instrument Type	Location	(m amsl)		
			Max	Min	Average
P01-03	Standpipe Piezometer	Тое	1030.63	1027.75	1029.31
P01-04	Standpipe Piezometer	Toe	1031.98	1029.31	1030.69
96-4	Standpipe Piezometer	Toe	1031.93	1027.87	1029.73
96-3	Standpipe Piezometer	Тое	1031.42	1027.43	1029.29
96-2	Standpipe Piezometer	Crest	1031.94	1029.40	1030.41
96-1	Standpipe Piezometer	Crest	1031.65	1027.85	1029.75
94-IDC-1	Standpipe Piezometer	Crest	1035.47	1035.31	1035.42
91-ID7	Pneumatic Piezometer	Тое	1035.20	1029.17	1031.34
91-ID5	Pneumatic Piezometer	Toe	1040.08	1020.69	1022.81
91-ID6	Pneumatic Piezometer	Toe	1033.35	1027.50	1029.86
91-ID4	Pneumatic Piezometer	Toe	1033.22	1027.76	1030.13
91-ID3	Pneumatic Piezometer	Crest	1038.64	1033.88	1035.55
		(affected by RCDC)			
BKSO4-06	Pneumatic Piezometer	Crest	dry	dry	dry
BKSO4-07	Standpipe Piezometer	Crest	1037.72	1037.68	1037.70

Table 6 Intermediate Dam Piezometers

The south abutment piezometer (BH91-ID3) has higher piezometric levels due to seepage from the Rose Creek Diversion Canal (RCDC). The RCDC is located just south of the Intermediate Dam, at a higher elevation than the dam crest (Figure 2).

In addition to the piezometers the pond water elevations define the piezometric conditions within the Intermediate Dam. For the analysis, it was assumed that the pond water elevations remained constant. It was assumed that the water elevations in the ponds were at their full supply levels, or at the elevation of the emergency spillways as shown in Table 7. The water levels have been significantly lower over the past five years, but are appropriate for this analysis. The "baseline" piezometric conditions were assumed for the crest and toe piezometers, as the average of the last few years readings, these are shown in Table 7 and graphically on Figure 3.

	Water Elevations (m amsl)
Tailings Pond	1047.7
Polishing Pond	1031.2
Toe Piezometer	1029.7
Crest Piezometer	1030.0

Table 7 Intermediate Dam Typical Conditions

2.3 Stability Analysis Results

A sensitivity analysis was performed by varying the piezometer water elevations (with the ponds at typical levels – Table 7) to determine piezometric trigger levels. Based on the typical ranges of pond water and piezometric elevations the dam is typically operating with a Factor of Safety between 1.5 and 1.6. Table 8 provides factor of safety data corresponding to the various piezometric elevations considered. Table 9 outlines the trigger levels for the piezometers located on the crest and downstream toe, in accordance with the incident levels indicated in Table 1.

	Toe Piezometric Elevations (m amsl)					
Crest	1029.7	1031.0	1032.0	1034.0	1035.0	1036.0
Piezometric			(flowing	(flowing	(flowing	(flowing
Elevations			artesian)	artesian)	artesian)	artesian)
(m amsl)						
1030.0	1.6	1.5	1.5	1.4	1.4	1.3
1030.5	1.6	1.5	1.5	1.4	1.4	1.3
1031.0	1.6	1.5	1.5	1.4	1.4	1.3
1033.0	1.5	1.5	1.5	1.4	1.3	1.3
1035.0	1.5	1.5	1.4	1.3	1.3	1.3
1037.0	1.5	1.4	1.4	1.3	1.3	1.2
1039.0	1.4	1.4	1.3	1.2	1.2	1.2
1041.0	1.4	1.3	1.3	1.2	1.1	1.1
1042.0	1.3	1.3	1.2	1.1	1.1	1.0
1043.0	1.3	1.2	1.2	1.1	1.0	1.0

 Table 8 Intermediate Dam Stability Analysis Results

	Toe Piezometric Elevations (m amsl)					
Crest	1029.7	1031.0	1032.0	1034.0	1035.0	1036.0
Piezometric			(flowing	(flowing	(flowing	(flowing
Elevations			artesian)	artesian)	artesian)	artesian)
(m amsl)						
1030.0	normal	normal	normal	Alert	alert	alert
1030.5	normal	normal	normal	Alert	alert	alert
1031.0	normal	normal	normal	Alert	alert	alert
1033.0	normal	normal	normal	Alert	alert	alert
1035.0	normal	normal	alert	Alert	alert	alert
1037.0	normal	alert	alert	Alert	alert	emergency
1039.0	alert	alert	alert	Emergency	emergency	emergency
1041.0	alert	alert	alert	Emergency	FAILURE	FAILURE
1042.0	alert	alert	emergency	FAILURE	FAILURE	FAILURE
1043.0	alert	emergency	emergency	FAILURE	FAILURE	FAILURE

Table 9 Piezometric Incident Levels

3.0 RAPID DRAWDOWN

Another potential slope stability failure mode for this dam is a rapid drawdown of the water within the tailings pond. In this case the slope instability would occur into the tailings impoundment. Similar to the downstream analysis, only critical failure surfaces (defined in this study as a failure surface that would remove more than half of the crest of the dam) were included in this analysis. Smaller, shallower failure surfaces may occur prior to these larger scale failures and should trigger alert or emergency incident levels. The reader is referred to the OMS and EPP for further information on these smaller failures.

The piezometers in the Intermediate Dam are not installed within the core of the dam, and thus no monitoring can be undertaken to help the understanding of the dam's performance during a rapid drawdown event.

In order to assess the potential for rapid drawdown to affect the dam sensitivity analysis was completed. Some of the key information used in the analysis included:

- Strength parameters for the dam as per Table 5.
- Piezometric conditions within the dam's core as per Table 6.
- Water in the pond removed immediately.
- The upstream filter and shell drains just as rapidly as the water in the tailings pond. The piezometric elevation in the core remains unchanged as compared to typical conditions, see Figure 4.

Slope stability analyses were conducted using the Morgenstern – Price method. In this analysis the tailings pond water level was manipulated to simulate different rapid drawdown scenarios. Figure 4 provides the cross section of this analysis.

The results of the analysis are strongly dependent on the average pond elevation prior to the start of rapid drawdown. Two different analysis results are shown in Table 10, when drawdown starts with the pond full, 1047.7 m amsl and a second case when drawdown starts from the 2007 typical pond elevation, 1046.5 m amsl. The incident levels corresponding to normal, alert, emergency and failure stages for the rapid drawdown failure mode at the Intermediate Dam are shown in Table 10.

Incident Level	Pond elevation range for different incident levels (m amsl) [drawdown from initial elevation m]			
Starting Tailings pond Elevation (m amsl)	d 1047.7 1046.			
Normal	1047.7 to 1047.4 [0 to 0.3]	1046.5 to 1046 [0 to 0.5]		
Alert	1047.4 to 1046.8 [0.3 to 0.9]	1046 to 1044.3 [0.5 to 2.2]		
Emergency	1046.8 to 1045.8 [0.9 to 1.9]	1044.3 to 1043.5 [2.2 to 3] ²		
Failure ¹	1045.8 to 1044.9 [1.9 to 2.8]			

Table 10 Rapid Drawdown Incident Levels

1. Below this elevation the Factor of Safety is less than unity.

2. Entire pond is drained at elevation 1043.5 m amsl.

4.0 CONCLUSIONS

Stability analyses were conducted in order to evaluate the piezometric trigger levels for the Intermediate Dam at the Faro Mine site. The analysis was conducted for a failure plane that would discharge supernatant and/or tailings upon failure. Historically the piezometric levels measured have been indicated that the dam is operating in the normal level (factor of safety of 1.5 to 1.6). This analysis outlines the piezometric levels that would constitute alert, emergency, and failure incident levels. Rapid drawdown of the tailings pond was also considered in this analysis and an alert level breakdown is provided based on tailings pond water levels. The actions to be taken at each of these trigger levels is defined in the EPP. This information along with the previously outlined alert levels based on visual monitoring and other factors are used to understand the performance of the Intermediate Dam. This information is in the process of being included in the updated OMS and EPP manuals for 2008.

5.0 CLOSURE

This report summarizes the physical conditions as observed by BGC and the instrumentation results as collected by site staff on various mine waste facilities and structures at Faro Mine. Thank you for the opportunity to be of service to Deloitte & Touche and Faro Mine. Should you have any questions on this report, please contact BGC at your convenience.

Respectfully submitted, BGC ENGINEERING INC. Per:

Ashton Friesen, EIT (AB) Mining Engineer Gerry Ferris, M.Sc., P.Eng. Geotechnical Engineer

Holger Hartmaier, M.Eng., P.Eng. (AB) Senior Geotechnical Engineer

REFERENCES

- Atkinson 2004. Seismic Hazard Assessment for Faro, YK. Report submitted to Deloitte & Touche.
- BGC Engineering Inc. 2003. Emergency Preparedness Plan for Selected Dams and Water Diversion Structures. Report submitted to Deloitte & Touche.
- BGC Engineering Inc. 2007. 2006 Annual Geotechnical Evaluation and Instrument Review. Report submitted to Deloitte & Touche.
- BGC Engineering Inc. 2007. Operations, Maintenance and Surveillance Manual for Selected Dams. Report submitted to Deloitte & Touche.
- Canadian Dam Association, 2007. Dam Safety Guidelines, January, 2007.
- Gartner Lee Limited 2003. 2004-2008 Water Licence Renewal Application Report, Anvil Range Mining Corporation (Interim Receivership), Prepared May 2003.
- Golder Associates Ltd. 1980. Final Design Recommendations for the Down Valley Tailings Disposal Project. Report submitted to Cyprus Anvil Mining.
- Klohn Crippen Consultants Ltd. 2002. Anvil Range Property, 2002 Dam Safety Reviews. Report submitted to Deloitte and Touche Inc., Project No. 3003.01.510, December 5, 2002.
- Klohn Crippen. 2004. Rose Creek Tailings Impoundment Seismic Stability Assessment. Report submitted to Deloitte & Touche.
- Klohn Crippen Berger. 2008. Anvil Range Mining Complex 2007 Dam Safety Review for Cross Valley, Intermediate and Little Creek Dams. Report submitted to Deloitte & Touche.
- northwest hydraulic consultants. 2006. Faro Mine Hydraulic Capacity Analysis. Report submitted to Deloitte & Touche.
- northwest hydraulic consultants. 2004 Hydrotechnical Study for Closure Planning Faro Mine Site Area, Yukon Final Report. Report submitted to Deloitte & Touche.
- Water Management Consultants. 2006. Rose Creek Probable Maximum Flood, Faro Mine. Report submitted to Deloitte & Touche.

FIGURES





DAM INTER For SECTIONS Å 2

	BGC ENC	GINEERING INC.
	AN APPLIED EART	TH SCIENCES COMPANY
BGC	Calgary, AB	Phone: (403) 250 5185

PROJECT No. 0257-044-04 FIGURE No.

2

REV. 0

TITLE PLAN AND SECTION VIEW OF INTERMEDIATE DAM

INTERMEDIATE DAM TRIGGER LEVELS

SCALE:	N/A	and the second se
DATE:	MAY 2008	
DRAWN:	JL	
DESIGNED:	ALF	
CHECKED:	GWF	
APPROVED:	GWF	a second and

REV.	DATE	REVISION NOTES	DRAWN	CHECKED	APPROVED

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

CLIENT:

Screened Intervals of Standipe Piezometers Bottom of Standpipe Piezometers

Pneumatic Piezometer Tips

Crest Piezometers

Downstream Toe Piezometers

C'

PROJECT

A'





AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE	AN APPLIED EARTH SCIENCES COMPANY	INTERMEDIATE DAM TRIGGER LEVELS						
CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.	Client: Deloitte & Touche	Title: STABILITY ANALYSIS CROSS SECTION (RAPID DRAW DOWN)						
		Project #: 0257-044-04	Date: MAY 2008	Scale: NA	Drawn: ALF	Approved: GWF	Figure: 4	