



Klohn Crippen Berger

Yukon Government

Faro Mine Complex

2016 Annual Geotechnical Review



M09770A06.730

ISO 9001
ISO 14001
OHSAS 18001

March 2017



March 27, 2017

Yukon Government
Faro Mine Remediation Project
Suite 2C-4114-4th Ave
PO Box 2703 (K-149)
Whitehorse, Yukon Territory
Y1A 2C6

Carrie Gillis
A/Project Manager - Faro Mine Remediation Project

Dear Ms. Gillis:

Faro Mine Complex
2016 Annual Geotechnical Review

We are pleased to submit the report on Faro Mine Complex - 2016 Annual Geotechnical Review. The review covers the geotechnical and hydrotechnical aspects of the water management and tailings storage facilities at the Faro Mine Complex. The review is based on site observations by Mr. David Willms and Ms. Kate Patterson on May 15 to May 16, 2016 (emergency site visit by D. Willms in response to Intermediate Dam sloughing), July 27 to July 1, 2016 (spring site visit by K. Patterson) and September 2 to September 7, 2016 (fall site visit by D. Willms) and ongoing review of monitoring data.

Yours truly,

KLOHN CRIPPEN BERGER LTD.

A handwritten signature in black ink, appearing to be 'D. Willms', is written over a horizontal line.

David Willms, P.Eng. (YT)
Project Manager

DW/KP/DH:dl/jcp

170327R-2016 Annual Review.docx
M09770A06.730

Yukon Government

Faro Mine Complex

2016 Annual Geotechnical Review

TABLE OF CONTENTS

1	INTRODUCTION.....	1
1.1	Project Background.....	1
1.2	Project Scope	3
2	NOTABLE OCCURENCES IN 2016	4
2.1	Intermediate Dam Emergency Site Visit.....	4
2.2	Little Creek Dam Repairs	4
2.3	Earthquake.....	4
3	FARO SITE FACILITIES.....	5
3.1	Faro Pit and Faro Creek Diversion Channel	5
3.1.1	Observations.....	5
3.1.2	Instrumentation.....	6
3.1.3	Recommendations.....	7
3.2	North Wall Interceptor Ditch.....	8
3.2.1	Observations.....	8
3.2.2	Instrumentation.....	8
3.2.3	Recommendations.....	9
3.3	Rose Creek Diversion Channel and Canal Dyke	9
3.3.1	Observations.....	9
3.3.2	Instrumentation.....	10
3.3.3	Recommendations.....	12
3.4	North Fork Rock Drain	12
3.4.1	Observations.....	13
3.4.2	Instrumentation.....	13
3.4.3	Recommendations.....	13
3.5	K8 Creek Rock Drain.....	13
3.5.1	Observations.....	14
3.5.2	Recommendations.....	14
3.6	Secondary Dam.....	14
3.6.1	Observations.....	14
3.6.2	Instrumentation.....	15
3.6.3	Recommendations.....	15
3.7	Intermediate Dam.....	15
3.7.1	Observations.....	16
3.7.2	Instrumentation.....	16
3.7.3	Recommendations.....	17

TABLE OF CONTENTS

(continued)

3.8	Cross Valley Dam	17
3.8.1	Observations	18
3.8.2	Instrumentation	18
3.8.3	Recommendations	19
4	VANGORDA PLATEAU SITE FACILITIES	21
4.1	Grum Pit	21
4.1.1	Observations	21
4.1.2	Instrumentation	21
4.1.3	Recommendations	21
4.2	Vangorda Pit	22
4.2.1	Observations	22
4.2.2	Instrumentation	22
4.2.3	Recommendations	22
4.3	Vangorda Waste Rock Dump	22
4.3.1	Observations	22
4.3.2	Instrumentation	23
4.3.3	Recommendations	24
4.4	Grum Pit Interceptor Ditch	24
4.4.1	Observations	24
4.4.2	Recommendations	24
4.5	Vangorda North East Interceptor Ditch	25
4.5.1	Observations	25
4.5.2	Recommendations	25
4.6	Vangorda Creek Diversion Flume	25
4.6.1	Observations	26
4.6.2	Recommendations	26
4.7	Little Creek Dam	26
4.7.1	Observations	27
4.7.2	Instrumentation	27
4.7.3	Recommendations	28
4.8	Sheep Pad Sediment Ponds	28
4.8.1	Observations	29
4.8.2	Recommendations	29
4.9	Fresh Water Pond for Vangorda Water Treatment Plant	29

TABLE OF CONTENTS

(continued)

4.9.1	Observations.....	30
4.9.2	Recommendations.....	30
4.10	V-15 Seep Ditch and Moose Pond	30
4.10.1	Observations.....	30
4.10.2	Recommendations.....	30
4.11	Vangorda Water Treatment Plant Clarifier Pond Dyke	30
4.11.1	Observations.....	31
4.11.2	Recommendations.....	31
5	MONTHLY MONITORING REPORTS	32
6	SUMMARY OF RECOMMENDATIONS	33
7	CLOSING.....	37
	REFERENCES.....	38

List of Tables

Table 3.1	Faro Pit Lake Level and Faro Creek Diversion Channel Flow.....	7
Table 3.2	North Valley Wall Interceptor Ditch - Flow	9
Table 3.3	Flow in North Fork Rose Creek and Rose Creek Diversion Channel.....	10
Table 3.4	Instrumentation for RCDC Canal Dyke, Spoil Piles and Back Slope.....	11
Table 3.5	North Fork Rock Drain - Water Level.....	13
Table 3.6	Secondary Tailings Impoundment – Pond and Piezometer Levels.....	15
Table 3.7	Intermediate Dam - Pond and Piezometer Levels.....	17
Table 3.8	Cross Valley Dam – Pond and Piezometer Levels.....	19
Table 3.9	Cross Valley Dam - Weir Flows	19
Table 4.1	Vangorda Waste Dump - 2016 Drain Flow	23
Table 4.2	Vangorda Waste Dump - 2016 Piezometer Levels	23
Table 4.3	Little Creek Dam - Pond and Piezometer Levels.....	28
Table 5.1	Monthly Observations	32
Table 6.1	Summary of Recommendations	34

List of Figures (within Text)

Figure 1.1	Site Location Plan.....	2
Figure 3.1	FCDC Flow Station Locations	5

TABLE OF CONTENTS

(continued)

List of Figures (end of Text)

Figure 1	Faro Site – General Layout
Figure 2	Faro Site – Air Photo
Figure 3	Vangorda Plateau Mine – Site Overview
Figure 4	Vangorda Annual Inspection – General Arrangement Plan
Figure 5	Vangorda Plateau Site – Air Photo
Figure 6	Faro Pit Brim – Reference Bars and Survey Prisms
Figure 7	Down Valley Tailings Containment Instrument Location – 1 of 2
Figure 8	Down Valley Tailings Containment Instrument Location – 2 of 2
Figure 9	Section View of Intermediate Dam
Figure 10	Section View of Cross Valley Dam
Figure 11	Grum Pit Brim – Reference Rods and Survey Prisms
Figure 12	General Arrangement Plan – Vangorda Waste Rock Dump
Figure 13	Little Creek Dam – General Arrangement Plan
Figure 14	Little Creek Dam – Section B-B

List of Appendices

Appendix I	Select Site Photographs
Appendix II	Instrumentation Plots and Data
Appendix III	Instrumentation Summary and Monitoring Frequency

1 INTRODUCTION

1.1 Project Background

The Faro Mine Complex is located about 200 km north-northeast of Whitehorse, Yukon, as shown on Figure 1.1. This site consists of two mines: The Faro Mine and the Vangorda Plateau Mine. Faro Mine was in operation from 1969 to 1992. Vangorda Plateau Mine was in production between 1986 and 1998. The Faro Mine Complex was managed by court-appointed interim receiver Deloitte & Touche from 1998 to 2008. Since 2009 the site has been managed by the Yukon Government (YG). Ongoing care, maintenance and environmental protection activities are conducted by the care and maintenance contractor. These activities are focussed on a seasonal pumping and water treatment program for the Faro and Vangorda open pits, and inspection and maintenance of the water management and tailings storage structures. The role of care and maintenance contractor was filled by Denison Environmental Services (DES) from 2009 to 2011, by Tlicho Engineering and Environmental Services (TEES) from 2012 to 2016 and then Parsons since April 2016.

The Operations, Maintenance and Surveillance (OMS) Manual for the Secondary, Intermediate, Cross Valley, and Little Creek dams is currently being updated and will be issued in 2017. The Emergency Response Plan (ERP) for the four dams and the Rose Creek and Faro Creek diversion channels and the Vangorda Creek Diversion Flume is also being updated and will be issued in 2017.


The Intermediate Dam and Cross Valley Dams are located in the Rose Creek Valley and were constructed between 1981 and 1991 to form the Down Valley tailings area (Golder 1980, 1981, 1982, 1983, 1990a, 1990b and 1992). The Little Creek Dam, constructed in 1991 with a spillway added in 1998, is located adjacent to Vangorda Creek to capture water discharging from the Vangorda Waste Rock Dump (SRK 1990 and 1998).

The annual geotechnical review reports for the mine contain a summary of the site observations, provide the instrumentation monitoring data, and note recommendations for operation and maintenance for the coming year. These reports have been prepared by Golder Associates Ltd. (Golder 1996 to 1999, 2010, 2011), BGC Engineering (BGC 2000 to 2009), and SRK Consulting Engineers (SRK 1996 to 2011). Geo-Engineering (MST 1999) conducted an independent review for government agencies. The annual reviews for 2011 to 2015 were completed by Klohn Crippen Berger (KCB 2012 to 2013, 2014d, 2015c and 2016a).

In September 2014 Worley Parsons conducted a dam safety review (DSR) for the Intermediate Dam, Cross Valley Dam and Little Creek Dam with a site visit on September 25 and 26, 2014 (Worley Parsons 2015). Worley Parsons concluded that all three dams should be classified as “high” consequence.

A list of design references for the dams and a summary of the designs are given in the OMS Manual.

Figure 1.1 Site Location Plan



1.2 Project Scope

The review is based on our site observations in 2016 and ongoing review of monitoring data collected by KCB and Parsons. This report documents the 2016 annual review of the geotechnical performance of the following waste and water management facilities at the Faro Mine Complex:

Faro Site (see Figures 1 and 2):

- Faro Pit and Faro Creek Diversion Channel;
- North Valley Wall Interceptor Ditch;
- Rose Creek Diversion Channel;
- North Fork Rock Drain;
- K8 Creek Rock Drain;
- Secondary Dam;
- Intermediate Dam; and
- Cross Valley Dam.

Vangorda Plateau Site (see Figures 3 to 5):

- Grum Pit;
- Vangorda Pit;
- Grum Overburden Dump;
- Vangorda Waste Rock Dump;
- Grum Interceptor Ditch;
- Vangorda Northeast Interceptor Ditch;
- Vangorda Creek Diversion Flume;
- Little Creek Dam;
- Sheep Pad Sediment Ponds;
- Grum Settling Pond;
- V-15 Seepage Ditch and Moose Pond; and
- Sludge Pond Embankment at Vangorda Water Treatment Plant.

Representative photos are provided in Appendix I.

Monitoring data are summarized in Appendix II.

KCB was on site from June 27 to July 1 reviewing the condition of geotechnical instruments associated with the tailings dams, Little Creek Dam and Rose Creek Diversion. The results of this review are presented in KCB 2016c. Recommendations were made for repair and replacement of instruments which are summarized in Section 6. The operating status of instruments and the monitoring program recommended for 2017 is provided in Appendix III.

2 NOTABLE OCCURENCES IN 2016

2.1 Intermediate Dam Emergency Site Visit

The Intermediate Dam experienced some sloughing and erosion on the downstream slope in 2016. The response for this is documented in KCB 2016b and KCB 2016d. This was determined to have resulted from a combination of continuing rill erosion and placing wet, poorly compacted material during the last repair. Preliminary repairs were completed.

2.2 Little Creek Dam Repairs

The erosion on the downstream slope of Little Creek Dam was repaired and the trees removed but erosion quickly started again. A second round of repairs was done which involve improving drainage at the crest and on the small benches on the downstream dam face. Plans are underway to vegetate the slope to control erosion. This is expected to take significant effort given the difficult growing conditions.

2.3 Earthquake

On August 23, 2016 at about 4:30 PM an earthquake with a magnitude of 4.3 occurred 16 km west of Faro. The earthquake was felt in the town of Faro, at the Faro site, and at the Vangorda site. Parsons notified YG and KCB promptly and carried out instrument readings over several days as well as visual inspections of the structures. No evidence of damage to the dams or other structures was noted.

3 FARO SITE FACILITIES

3.1 Faro Pit and Faro Creek Diversion Channel

The Faro Pit (Figure 2) is an inactive, inundated open pit, roughly elliptical in shape with the major axis oriented to the northwest/southeast. The east wall is roughly 375 m high and has two main instability zones (North and South) which are separated by a more stable calc-silica rich rock slope.

The Faro Creek Diversion Channel (FCDC) diverts flow from the headwaters north of the Faro Pit around the east side of the Faro mine site and discharges into the North Fork of Rose Creek. The minimum distance between the Faro Pit east wall and the diversion channel are 18.5 m and 93 m, respectively, in the North and South instability zones. Flow station locations are shown on Figure 3.1.

Figure 3.1 FCDC Flow Station Locations



3.1.1 Observations

Faro Pit

- Pit wall condition is similar to that observed in 2015.

- Faro pit is currently used to store water pumped back from Intermediate Pond and seepage interception systems.
- As treatment of water stored in the Faro Pit was suspended in 2013 and most of 2014, the pit-lake level has risen above the maximum recommended level to within the range of the fractured/competent bedrock contact elevation. Treatment has since resumed and the water level is slowly being drawn down.
- Golder was onsite setting up photogrammetry stations to improve monitoring in terms of accessibility, safety, and being able to visualize the pit wall from different angles.

Faro Creek Diversion Channel

- Some cracking, likely related to annual freeze-thaw condition, was noticed near the top of the channel hillside slope occurring sporadically between FCD 1 and FCD 3 during spring 2014, 2015 and 2016 visit. This cracking was not evident in fall of 2015 or 2016. The cracking appears to be localized and not a concern for the safety of the FCDC.
- Minor vegetation growth along channel.
- Overhead wires for the Streamflo flow measurement device are in good condition. Parsons report that these flow stations are often destroyed during the winter and new stations and rating curves need to be established in the spring.
- Minor slumps on the channel hillside slope have not been repaired in recent years due to safety concerns and access limitations.
- There is a waste rock pile that acts as a dam containing the Faro Creek Overflow (FCO) Sump that collects the seepage from the upper reaches of the FCDC and would possibly overtop during a flood event that breached the FCDC. We understand that the Faro Creek Overflow Sump captures flow from the diversion in the event of a breach and provides a sump that can be pumped out. YG reports that the risk from potential overtopping of the dam of this impounded water has been considered by Golder and the Technical Review Committee.
- Minor sloughing of side slopes.

3.1.2 Instrumentation

Faro Pit

Instrumentation at the Faro Pit includes one pond level indicator at the Faro Pit, nine reference bars to monitor pit wall regression and nine prisms to monitor pit wall movements (Golder 2009b and 2014). Pit wall movement measurements are currently taken via a photogrammetry system which was installed in 2016. Survey of the reference bars has been discontinued since 2014 due to unsafe access to the other instruments (reference bars and prisms). Monitoring data for the pit water level is presented in Appendix II-A.

In December 2016 Faro Pit lake level was about El. 1149.1 m, 4.8 m above the maximum recommended level of approximately El. 1144.3 m, established by Others. A key concern is that this

reduces the available storage in the pit and subsequently the time the mine has to respond if the FCDC flows into the pit due to a pit wall failure of Faro Pit or an overtopping or failure of the FCDC. If the pit were to overflow, there would be environmental impacts from the contaminated water. There could also be dam safety or water management consequences depending on the flow rate, since the overflow would eventually report to the Intermediate Pond. YG is working to draw down the pit lake but is limited by the requirement to treat the water and the achievable treatment rate. The pit lake elevation has been reduced from a 2015 high of about El. 1153.2 m near the end of April to a 2016 high of about El. 1152.6 m at the beginning of May. Current efforts appear to be effective at drawing down the pit lake level. The effects of the current efforts should become more apparent as a trend in pit lake elevation develops over subsequent years.

Faro Creek Diversion Channel

Instrumentation at the Faro Creek Diversion Channel includes four staff gauges (FCD-1 to FCD-4) used for flow measurements.

Discharge rating curves for the staff gauges are shown in Section II-B1 of Appendix II. Two rating curves are shown for FCD-3 and FCD-4, one for the period 2008 to 2010; and the other for the period 2011 onwards. Different staff gauge calibration equipment was used during these two periods, and it is believed that the equipment used after 2010 (StreamPro) is more accurate.

Plots of channel discharges estimated from the rating curves shown in Section II-B1 are presented in Section II-B2 (Appendix II). High flows shown in the plots are based on the extrapolation of the rating curves beyond their calibrated range therefore not as reliable. These flows should be recalculated when the rating curves are re-calibrated with high flow measured with the StreamPro.

Recorded historical and 2016 flows in the Faro Creek Diversion Channel are shown in Table 3.1.

Table 3.1 Faro Pit Lake Level and Faro Creek Diversion Channel Flow

Structure	Monitor Location	Historical		2016 (Note 1)	
		Max	Min	Max	Min
Faro Pit – Pond El. (m)	FP	1153.2	1140.7	1152.6	1148.9
Faro Creek Diversion Channel Flow (L/s)	FCD-1	2,213	44.5	1188	99
	FCD-2	6,178	7	372	121
	FCD-3	1,366	47	457	209
	FCD-4	6,018	30	458	201

Notes:

1. Values are based on periodic spot measurements and may not provide an accurate indication of the range of flows experienced during the reporting period.

3.1.3 Recommendations

- The pit lake level exceeds maximum recommended elevation (≈El. 1144.3 m, established by Others). Continue procedures described in our technical memo dated February 10, 2015 titled “Faro Pit East Rim Slope Stability Monitoring during Elevated Lake Level”. Draw down pit lake as soon as practical. The current efforts to draw down the pit lake appear to be effective and the pit lake should be below the maximum recommended elevation within several years.

- Develop a contingency plan for potential blockage.
- Develop staff gauges that aren't destroyed every winter. This could occur after the FCDC is realigned. Once more permanent staff gauges are developed, take flow readings to re-establish calibration curves.

3.2 North Wall Interceptor Ditch

The North Wall Interceptor Ditch (NWID) (sometimes referred to as the North Valley Wall Interceptor Ditch) (Figures 1 and 2) diverts creek flow from the north valley wall around the tailings impoundment area. It is approximately 3 km long and includes constructed and natural stream channel reaches. The ditch has relatively flat channel gradients along the constructed reaches and steep gradients along the natural stream reaches. The constructed channel reaches include:

- 920 m long upper reach;
- 430 m long middle reach; and
- 500 m long lower reach.

3.2.1 Observations

- Partial vegetation removal for access and along channel side slopes has been completed, but portions of the mid- and lower channel have not been cleared. Heavy vegetation growth remains in the mid-channel reach.
- Vegetation that was previously cleared in the upper channel was removed using an excavator which also removed the roots. The areas that were cleared are subject to erosion.
- Culverts were reinstalled in 2015 and are performing satisfactorily.
- There is evidence of overtopping of the weir in the upper channel reach.
- Flow from the Faro Interim Water Treatment System and siphons from the Polishing Pond are discharging into the lower channel reach.
- The channel and side slopes appeared to be stable.

3.2.2 Instrumentation

Instrumentation at the North Wall Interceptor Ditch includes one flow monitoring location, NWID, within the diversion channel. A weir was installed at this station in July 2015. Flow data for the NWID is shown in Section II-C1 of Appendix II and Table 3.2. Readings prior to July 2015 were made either by visual estimation or Global Water Flow Meter. Readings after July 2015 used the newly installed weir to measure the flow. No flow data was reported for 2016.

Table 3.2 North Valley Wall Interceptor Ditch - Flow

Structure	Monitoring Location	Historical ¹ Flow (L/s)		2016 Flow (L/s)	
		Maximum	Minimum	Maximum	Minimum
North Wall Interceptor Ditch	NWID	554	0.1	22.9	1.9

Notes:

1. Historical data was taken from the 2015 Annual Geotechnical Review (KCB 2016a).
2. Values are based on periodic spot measurements and may not provide an accurate indication of the range of flows experienced during the reporting period.

3.2.3 Recommendations

- Continue clearing vegetation along the upper and middle channel reaches as per guidelines in KCB brushing letter dated August 5, 2016. Clearing should also include the access road and Canal Dyke to facilitate future inspection.
- Implement erosion control measures on slopes where vegetation has been removed. May require experimenting with reseeding, straw mats, and riprap to determine the most appropriate measures.
- Extend the weir such that it does not overtop during the spring freshet i.e. the freshet flow is contained within the v-notch and does not overtop the sides.

3.3 Rose Creek Diversion Channel and Canal Dyke

The Rose Creek Diversion Channel (RCDC) (Figures 1 and 2) diverts Rose Creek flow around the south side of the tailings impoundment. It is approximately 3.8 km long with, typically flat to moderate channel gradients along the upper reaches and steep gradients along the lower reaches. The upper reach of the diversion channel has three areas that are of geotechnical significance:

- Canal Dyke (CD): The dyke flanks the north side of the channel along the upper reach of the diversion channel and separates the channel from the tailings deposit, the Intermediate Pond, Intermediate Dam, Polishing Pond and Cross Valley Dam, see Figures 1 and 2.
- Spoil Piles (SP): The spoil piles are wastes generated by the construction of the Canal Dyke. They are downslope of the Canal Dyke and located at various spots along the southern periphery of the tailings impoundment.
- Back Slope (BS): The Back Slope is the hillside slope of the Diversion Channel excavation.

3.3.1 Observations

- Moderate flow in channel at time of inspections.
- The channel and side slopes are generally stable; rock armour conditions appear satisfactory.
- Trees impede access to the Back Slope.
- Trees are growing in the diversion channel.
- Several instruments appear to be abandoned or overgrown (limited access).

- Three to four areas of the deformed back slope were flagged (with stakes or flagging tape) or noted. These areas are shown on Figure 7. Slope slump activity has progressed since 2015 and a new area has been identified.
- Overhead wires were installed across the channel by TEES in 2014 at existing staff gauges for measurement of high flows for calibration of the gauges. Only one remains standing. Not all overhead wire locations have a staff gauge for daily measurement.
- Minor seepage was observed from the RCDC onto the tailings beach above the Intermediate Pond.
- Flow stations are in poorly suited location for flow measurement and result in inconsistent readings for NFRD-2B.

3.3.2 Instrumentation

Rose Creek Diversion Channel

There is one in-stream flow monitoring location in the RCDC: RCDC-4. There are two flow monitoring locations along the North Fork of Rose Creek, upstream of the RCDC: NFRD-2B, and X2. There are two monitoring locations in Rose Creek downstream of the RCDC: X10 and X14.

- Historical and 2016 maximum and minimum flows for the stream flow stations are shown in Table 3.3.
- Discharge rating curves for the staff gauges NFRD-2B, RCDC-4 and X14 are shown in Section II-D1 of Appendix II-D. Discharge curves have not been developed for X2 and X10 as flow data is unavailable for X2 while staff gauge readings are unavailable for X10.
- Plots of channel discharges estimated from the rating curves shown in Appendix II-D2.

Table 3.3 Flow in North Fork Rose Creek and Rose Creek Diversion Channel

Location	Name	Historical ¹ Flow (L/s)		2016 Flow (L/s)	
		Maximum	Minimum	Maximum	Minimum
North Fork Rose Creek	NFRD-2B	8,000	0	1,660	1,370
	X2 ³	1,538	207	-	-
Rose Creek Diversion Channel	RCSG4/RCDC-4 ²	38,000	<500 ⁵	5,410	1,440
Rose Creek	X10 ⁴	-	-	5,290	1,630 ⁷
	X14	99,000 ⁵	210	10,200	1,150

Notes:

1. Historical data from the 2015 Annual Geotechnical Review (KCB 2016a).
2. RCDC-4 is a replacement of RCSG4 in 2012.
3. No calibration curve or flow data available for X2.
4. No staff gauge readings available for X10.
5. Flow value is unreliable as it is outside of the calibrated range of staff gauge readings.
6. Values are based on periodic spot measurements and may not provide an accurate indication of the range of flows experienced during the reporting period.
7. Minimum value is higher than the minimum value for X14 due to different sampling dates. If measured at the same time, X14 will have a larger flow than X10 since X10 plus other stations report to X14.

Canal Dyke, Spoil Piles, and Back Slope

A summary of existing instrumentation on the Canal Dyke, Spoil Piles and Back Slope of the diversion channel is shown in Table 3.4. Plots and recorded data for these instruments are given in Appendix II-E: (Piezometers in Section II-E1, Thermistors in Section II-E2 and Inclinometers in Section II-E3).

- Some thermistor beads are not functioning:
 - ♦ CD-10: 10 of 12 beads functioning;
 - ♦ CD-15: 4 of 12 beads functioning;
 - ♦ CD-26: Not functioning;
 - ♦ BGC-05-04: Not functioning;
 - ♦ SP-2: 7 of 12 beads functioning;
 - ♦ SP-3: 4 of 10 beads functioning;
 - ♦ BS-5: 6 of 10 beads functioning;
 - ♦ BS-9: 2 of 10 beads functioning;
 - ♦ BS-10: 9 of 10 beads functioning; and
 - ♦ BS-12: 9 of 10 beads functioning.
- In 2015 we reviewed the Back Slope instrumentation and could not determine conclusively the cause of the slumping; however, we believe the slumping is due to the melting of the underlying permafrost as shown in the general warming trend of BS-5 and BS-10 which correspond to the areas of slumping. Other possible causes include infiltration of surface water from upslope, and/or freeze-thaw action on the loose sand and gravel cover. We believe that this can be managed through a program of monitoring and maintenance.
- No instability of the Canal Dyke or Spoil Piles was observed in 2016.

Table 3.4 Instrumentation for RCDC Canal Dyke, Spoil Piles and Back Slope

Structure	Instrumentation
Canal Dyke	5 Paired pneumatic piezometers (BGC05-02 & BGC05-03, BGC05-06, CD-13, CD-15, and CD-26) and one single pneumatic piezometer (CD-21-S)
	4 Thermistors (BGC05-07, CD-10, CD-15, CD-21 and CD-26)
	6 Inclinometers (BGC05-05, BGC05-08, CD-10, CD-15, CD-21 and BH91-CD-1)
Spoil Piles	3 Thermistors (SP-2, SP-3 and SP-5)
	1 Inclinometer (SP-2)
Back Slope	2 Single pneumatic piezometers (BS-5 and BS-9)
	4 Thermistors ² (BS-5, BS-9, BS-10 and BS-12)
	3 Inclinometers (BS-5, BS-9 and BS-10)

Notes:

1. Non-functioning instrumentation is not shown in this table. See Appendix III for a status summary of instrumentation.
2. Some of the thermistor beads are not functioning.

3.3.3 Recommendations

- Take calibration flow measurements at the staff gauges in 2017 during high flows, using the overhead StreamPro guidance wires. Extend staff gauges, if required, such that they can be read during high flows.
- Rehabilitate or replace malfunctioning thermistors installed along the Back Slope. We suggest that a thermistor supplier such as RST be engaged to carry out the assessment.
- Monitor condition of slope slump scarps from the four new standard photograph locations supplied by KCB at the Back Slope, and continue instrumentation monitoring along the Back Slope. This has now been included in the ongoing monitoring.
- Explore permit requirements regarding investigation and repair of the above slope slumps. RCDC is the main diversion channel at the Faro site; prevention of a major slump and blockage is a high priority.
- Establish a means to access the Back Slope area with equipment for maintenance and potential repair activities, which may be required during periods of medium to high flow. May involve an improved crossing location or constructing a bridge.
- Develop an emergency response plan for failure of the Back Slope and blockage of the Rose Creek Diversion.
- Clear vegetation from the diversion and access path along the Back Slope as per guidelines in KCB brushing letter dated August 5, 2016. YG reports that Minnow Environmental Inc. are developing environmental considerations and measures for this work.
- Take flow measurements to develop a rating curve for staff gauge X2.
- Locate the missing annual review reports by Golder (1983 to 1999) and BGC (2000, 2001, and 2003), when repair works in the Back Slope area were conducted. Past successful repair experiences could provide guidance for current and future care and maintenance activities in the Back Slope area.
- Identify and install a new monitoring point on the North Fork of Rose Creek that allows use of a flow station and staff gauge that will provide consistent readings and not be easily destroyed in winter. KCB suggests placing the station in the culvert if access can be maintained.

3.4 North Fork Rock Drain

The North Fork Rock Drain (NFRD) (Figure 1) is a mine haul road stream crossing constructed of coarse waste rock fill. It functions as a conduit for the North Fork of Rose Creek flow to cross the haul road, see Figures 1 and 2. The haul road at stream crossing is approximately 55 m high with a 25 m crest width. Downstream of the haul road, the North Fork of Rose Creek crosses the Main Access Road to the mine via a culvert which is supplemented by an auxiliary culvert at a slightly higher elevation.

Construction of a new seepage interception system downstream of the NFRD was carried out from October 8, 2014 to January 30, 2015 (BGC 2015). The system pumps some of the seepage (approximately 5 L/s) from the NFRD to the Faro Pit during the winter months.

3.4.1 Observations

- Water level in the upstream pond is similar to previous years.
- The mine haul road crest and side slope are generally stable.
- Downstream drainage condition is acceptable with three braided channels combined to one channel at water-level monitor and sample location.
- Erosion washouts of upstream and downstream road shoulder and embankment slope appear to be filled in and a new low point is cut in the crest for road drainage. Remediation areas are performing well.

3.4.2 Instrumentation

Instrumentation at the North Fork Rock Drain consists of water level readings surveyed periodically throughout the year to record the upstream pond elevation (NF1) and downstream discharge (NF2). Before 2016, water elevation was recorded at NF2, however this was discontinued as it was not very meaningful due to turbulence of the flow at this location. Historical and 2016 maximum and minimum values are shown in Table 3.5. Plots of water level and flow are presented in Appendix II-F.

Table 3.5 North Fork Rock Drain - Water Level

Name	Historical ¹		2016		Comments
	Maximum	Minimum	Maximum	Minimum	
NF-1 (Elevation, m)	1094.35	1088.83	1091.5	1089.3	Upstream of haul road
NF-2 (Flow, L/s)	–	–	542	3598	Downstream of haul road

Notes:

1. Historical data is from the 2015 Annual Geotechnical Review (KCB, 2016a). No historical data was available for flows at NF2 available.
2. Values are based on periodic spot measurements and may not provide an accurate indication of the range of flows experienced during the reporting period.

3.4.3 Recommendations

None.

3.5 K8 Creek Rock Drain

The K8 Creek Rock Drain (K8CRD) (Figure 1.1) is a mine haul road stream crossing constructed of coarse waste rock fill. It functions as a conduit for the K8 Creek to cross the main mine haul road. The haul road at the creek crossing is approximately 40 m high on the downstream side with a 25 m crest width. There is currently no instrumentation or monitoring program at this creek crossing.

3.5.1 Observations

- The crest and side slope of the mine haul road are generally stable.
- Drainage condition is acceptable downstream of the rock drain.
- Road surface runoff drains through a cut in the haul road berm. There appears to be recent placement of riprap to control erosion. It appears to be performing well.

3.5.2 Recommendations

- None.

3.6 Secondary Dam

The Secondary Dam contains the Secondary Impoundment, which is located on the north side of Rose Creek Valley. The dam crest is approximately 2300 m long, 6 m wide, with the crest level varying from El. 1060.2 m to El. 1063.3 m. The West Limb of the Secondary Dam is defined as that curved portion which crosses the valley roughly north to south. The East Limb is the portion of the Secondary Dam aligned parallel to the south valley wall. The West Limb of the Secondary Dam is approximately 27 m above original ground; however, the downstream slope of the dam is partially inundated by tailings deposited in the Intermediate Pond. The dam crest is approximately 14 m above the tailings surface in the Intermediate Pond. The East Limb is a low retention dyke (typically 4 m high).

The Secondary Impoundment does not have capacity to store water; the tailings surface is sloped such that surface water from the impoundment flows to a ditch in the tailings along the upstream side of the dam and routed to the spillway. Since the tailings stored behind the Secondary Dam is partially saturated, a portion of the tailings could flow out if the dam were breached, resulting in environmental impacts if failure occurred into Rose Creek.

The Secondary Dam was not reviewed as part of the 2014 DSR by Worley Parsons since it was not included in the scope of work. This dam should be included with the next DSR.

3.6.1 Observations

- Stable crest, upstream and downstream slopes.
- Minor amount of water ponding on lower downstream-berm road.
- The annual appearance of longitudinal cracks along the downstream berm road surface in the spring and their subsequent disappearance appear to be related to seasonal freezing and thawing. A crack was evident in the spring 2016, approximately paced out to be 180 m long.
- Some small trees on downstream slope.
- A ditch was constructed upstream of the dam crest. The ditch drains into the lower impoundment via a spillway cut on the north side of the impoundment. The ditch and spillway cut appear to be field fit and have no armouring. Erosion would likely occur under an extreme flood condition; however, any materials eroded would end up in the Intermediate Impoundment. Overtopping of the Secondary Dam is also a concern if the ditch capacity were to be exceeded.

- No seepage was observed from the Secondary Dam toe to the Intermediate Pond. However, there is seepage from the RCDC into the Intermediate Pond just downstream of the Fuse Plug.
- There is evidence of seepage out of the toe of the east limb of the Secondary Dam near the Rose Creek Diversion water level along the upper approximately 800 m of the RCDC, and into the Fuse Plug. This is evidenced by iron-rich precipitates. The amount of the orange precipitates suggest that this seepage has been occurring for several years or more.

3.6.2 Instrumentation

Instrumentation at the Secondary Dam (see Figure 8) consists of 3 standpipe piezometers installed in 1981 on the dam crest and 4 standpipe piezometers installed in 2003 in the tailings pond. Historical and 2016 maximum and minimum values are shown in Table 3.6. Plots of piezometric levels are included in Appendix II-G. Piezometers P81-6 to P81-8 are dry, while P03-1 to P03-3 are typically 5 m to 6 m below ground surface and show a variation less than 1 m to 2 m when not dry.

Table 3.6 Secondary Tailings Impoundment – Pond and Piezometer Levels

Location	Piezometer	Historical ¹ El. (m)		2016 El. (m)	
		Maximum	Minimum	Maximum	Minimum
Dam Crest	P81-06	Dry	Dry	Dry	Dry
	P81-07	Dry	Dry	Dry	Dry
	P81-08	Dry	Dry	Dry	Dry
Tailings Pond	P03-01	1055.60	1054.29	1054.75 ³	1054.75 ³
	P03-02	1056.41 ²	1053.72	1054.35 ³	1054.35 ³
	P03-03	1057.48 ²	1052.28	1055.32	1055.17

Notes:

1. Historical data is from the 2015 Annual Geotechnical Review (KCB, 2016a).
2. Maximum historical reading is near ground level and is likely due to blockage.
3. Only one valid reading taken.

3.6.3 Recommendations

- Clear trees from downstream slope of secondary tailings dam as per guidelines in KCB brushing letter dated August 5, 2016.
- Monitor the longitudinal cracks in a quantitative way, using pins and measuring tape. Visually monitor the condition of the road as part of routine inspections.
- Grade lower downstream berm road.
- Include the Secondary Tailings Dam in the next DSR.

3.7 Intermediate Dam

The Intermediate Dam (ID) (Figures 1, 2, and 9) is located at the west end of the Intermediate Pond. It retains tailings, supernatant, and run-off water. The toe of the ID is inundated by the Polishing Pond. The dam is approximately 650 m long, 7 m wide at the crest and 32 m high. The dam crest is at El. 1048.8 m, and the spillway invert elevation is at El. 1047.7 m. There is a 7 m wide berm on the downstream face above the Polishing Pond at approximately El. 1031.7 m. The Starter Dam has a

vertical core, which was modified to an upstream sloping core during subsequent dam raises. The remainder of the dam consists of gravel shells and filter zones.

3.7.1 Observations

- Stable crest, upstream slope and spillway channel, in general.
- Downstream rill erosion was repaired in some areas. Some repaired areas have sloughed and continue to erode.
- There is vegetation along crest, spillway and abutments.
- Spillway has a pipeline in the lower reaches for mixing lime into the Polishing Pond.
- A pipeline crosses the upper reach of the spillway and is supported by metal stands which appear to be designed to allow flow under the pipeline.
- A small excavation for a sea container was completed on the berm.

3.7.2 Instrumentation

Instrumentation at the Intermediate Dam (see Figures 7 and 9) consists of recording pond level; 15 standpipe piezometers at 10 locations; and 7 pneumatic piezometers at 4 locations. The piezometers are installed in the embankment zones downstream of the core above, in and below the horizontal drain at the downstream berm elevation as well as in the dam foundation. They are distributed from the northeast dam segment to the southwest abutment (see Figure 9). There is also one standpipe piezometer within the intermediate impoundment.

Historical and 2016 maximum and minimum values are shown in Table 3.7. Plots of pond and piezometric levels are included in Appendix II-H. The pond and piezometric levels in 2016 were consistent with previous years.

Table 3.7 Intermediate Dam - Pond and Piezometer Levels

Location	Name	Historical ¹ El. (m)		2016 El. (m)		Comments
		Maximum	Minimum	Maximum	Minimum	
Water Elevation Readings						
Intermediate Pond		1048.1	1042.2	1046.7	1044.6	
Standpipe Piezometers (Nested piezometers at P01-4, BH96-3 and BH96-4)						
Dam Crest	BH96-1	1031.65	1027.37	1030.36	1029.81	
	BH96-2	1031.94	1028.87	1030.84	1030.34	Only 1 reading.
	BH94-IDC-1	Dry	Dry	Dry	Dry	
	BKS04-06	Dry	Dry	Dry	Dry	
	BKS04-07	Dry	Dry	Dry	Dry	
Dam Toe	P01-3	1030.63	1027.48	1030.36	1029.12	
	P01-4A	1032.59	1029.27	1032.59	1031.37	Shallow
	P01-4B	1032.17	1029.06	1031.96	1031.05	Deep
	BH96-3A	1031.38	1026.62	1030.98	1029.70	Shallow
	BH96-3B	1031.45	1027.48	1030.29	1029.77	Deep
	BH96-4A	1032.04	1027.61	1030.34	1029.79	Shallowest
	BH96-4B	1032.28	1028.39	1030.35	1029.08	
	BH96-4C	1031.64	1026.9	1030.38	1029.85	
BH96-4D	1031.75	1027.62	1030.64	1029.34	Deepest	
Pneumatic Piezometers (BH91-ID3 to ID6 are nested piezometers with one tip deep and one shallow)						
South Abutment	BH91-ID3	1039.23	1036.33	1038.16	1036.87	Shallow
		1038.04	1029.95	1034.74	1032.06	Deep
Dam Toe	BH91-ID4	1035.91	1028.28	1031.64	1031.64	Shallow, only 1 reading
		1031.85	1026.74	1030.02	1029.52	Deep
	BH91-ID6	1030.95	1026.62	-	-	Reported Damaged in 2015
		1034.96	1020.82	-	-	
	BH91-ID7	1035.2	1028.82	-	-	Destroyed in winter of 2011/2012

Notes:

1. Historical data is from the 2015 Annual Geotechnical Review (KCB, 2016a).

3.7.3 Recommendations

- Repair the ruts on the downstream slope and the toe area.
- Upgrade spillway to meet CDA 2013/2014 dam safety criteria for Inflow Design Flood (IDF) for the high consequence classification dam. This is a key risk to the facility and should be addressed as a priority.
- Remove pipelines and equipment that may impede flow from the spillway.
- Remove vegetation from crest, slope, spillway and abutments as per guidelines in KCB brushing letter dated August 5, 2016.

3.8 Cross Valley Dam

The Cross Valley Dam (CVD) (Figures 1, 2, 7, and 10) impounds the Polishing Pond (also known as the Cross Valley Pond) at the downstream limit of the Rose Creek Tailings Facility. The Polishing Pond receives seepage from the Intermediate Impoundment and Rose Creek Diversion Channel, and

discharge from the Faro Water Treatment Plant. The Cross Valley Dam is 500 m long, 7 m wide at the crest and 17 m high. The dam crest elevation is at 1032.7 m, while the spillway channel invert is at El. 1030.8 m. The dam has a central silty till core with gravel shells and filters, an upstream impervious blanket and a downstream drainage blanket.

3.8.1 Observations

- A depression on the crest, close to the left abutment and upstream side was evident in spring of 2016 (coordinates: 580037E, 6914287N). This does not appear to be an indication of instability and may be related to dam construction or settlement.
- The annual appearance of longitudinal cracks along the dam crest in the spring and their subsequent disappearance seem to be related to freezing and spring thawing. This phenomenon was repeated in 2016 with only barely visible signs of spring cracks in the fall. The crack was visible in the spring of 2016 and was evident along the entire length of the dam. The crack was most prominent close to the left abutment. KCB installed five twin-pin locations to monitor the crack width.
- Upward seepage (with bubbles) on the low spot of the Down Valley Road was not evident in the fall. It was observed in spring 2016 and site staff indicate that this seepage is evident every spring/summer. This was determined to be an old well that Parsons exposed and subsequently covered in spring 2016.
- Downstream Weir No. 3 has been repaired and the culvert replaced; however, water is reportedly still bypassing the weir.
- X12 weir staff gauge is crooked, readings will be inaccurate. X13 weir staff gauge is unreadable and rocks downstream of the weir will affect the measurements.
- There is tree growth on the upstream and downstream slopes of the dam as well as within the spillway channel and on the dam abutments.
- Some erosion of downstream dam face.

3.8.2 Instrumentation

Instrumentation at the Cross Valley Dam (see Figures 7 and 10) consists of recording pond level, 12 standpipe piezometers, four pneumatic piezometers and two thermistors. Except for one piezometer installed in the embankment zone downstream of the core, piezometers are installed in the dam foundation at and beyond the downstream toe and beneath the dam crest. In addition, four weirs are installed downstream of the dam, Weir X11, X12, X13, and Weir 3.

One functional shallow thermistor string (BH88-4) is installed in the dam fill zone upstream of the dam core, and one deep thermistor string is installed in the dam foundation underneath the upstream dam crest shoulder (CVDC-6). Permafrost condition no longer exists at these locations and thermistor data is not required.

Plots of Polishing Pond and piezometric levels, ground temperature profiles, and downstream weir flows are included, respectively, in Sections II-I1 to II-I4 of Appendix II. Historical and 2016 maximum

and minimum piezometric and pond levels are shown in Table 3.8. Historical and 2016 maximum and minimum weir flows are shown in Table 3.9.

Table 3.8 Cross Valley Dam – Pond and Piezometer Levels

Structure	Name	Historical ¹ El. (m)		2016 El. (m)		Comments
		Maximum	Minimum	Maximum	Minimum	
Water Elevation Readings						
Polishing Pond		1031.20	1025.88	1030.36	1027.99	Target El. 1027 m
Standpipe Piezometers						
Dam Toe	CVDT-1	1018.57	1017.13	1017.96	1017.73	
	CVDT-2	1019.50	1015.40	1016.68	1016.18	
	P01-02 ²	1018.30	1017.42	Not reported	Not reported	Shallow
		1019.73	1017.86	Not reported	Not reported	Deep
P01-11	1017.83	1016.17	1016.81	1016.77		
Dam Crest	CVDC-4	1019.05	1016.72	1019.10	1018.92	Deep
	CVDC-7	1017.74	1015.14	1015.87	1015.75	Shallow
		1019.21	1015.27	1018.14	1018.00	Deep
	94CVDC-1	1024.58	1022.71	1024.00	1023.83	
	CVDC-9	1024.74	1019.91	1021.43	1021.21	Shallow
1025.61		1021.18	1024.74	1024.40	Deep	
Pneumatic Piezometers						
Dam Toe	CVDP-1	1019.83	1016.82	1018.59	1018.47	
	CVDP-3	1017.65	1016.11	Not reported	Not reported	
	CVDP-5	1022.05	Dry	1020.91	1020.75	
	CVDP-6	1019.55	1014.86	1017.61	1017.53	

Notes:

1. Historical data is from the 2015 Annual Geotechnical Review (KCB 2016a).
2. No readings for Piezometers P01-02 were given. (The piezometer is cracked at the base and flowing. It should be repaired.)

Table 3.9 Cross Valley Dam - Weir Flows

Weir Number	Historical ¹ Flow (L/s)		2016 Flow (L/s)	
	Maximum	Minimum	Maximum	Minimum
X11 (North)	24.38	2.56	24.38	7.38
Weir 3 (Central)	7.1	0.03	3.40	0.53
X12 (South)	2.03	0.02	0.72	0.08
X13 (Combined)	123	7.45	51.55	18.79

Notes:

1. Historical data is from the 2015 Annual Geotechnical Review (KCB 2016a).
2. Values are based on periodic spot measurements and may not provide an accurate indication of the range of flows experienced during the reporting period.

3.8.3 Recommendations

- Repair erosion on the downstream dam face.
- Remove vegetation from crest, slope, spillway and abutments as per guidelines in KCB brushing letter dated August 5, 2016.
- Remove siphon pipeline from the spillway.

- Upgrade spillway to meet CDA 2013/2014 dam safety criteria for the Inflow Design Flood (IDF) for the high consequence classification dam. This is a key risk to the facility and should be addressed as a priority.
- Monitor longitudinal tension cracks on dam crest and grade these cracks to minimize water ingress to the embankment dam.
- Repair Weir No. 3 such that water no longer bypasses the weir.

4 VANGORDA PLATEAU SITE FACILITIES

4.1 Grum Pit

The Grum Pit (GP) (Figures 3 to 5) is the northernmost major structure at the Vangorda Plateau Site, which is approximately 12 km southeast of the Faro Pit. Grum Pit is an inundated, inactive open pit with a roughly elliptical shape, extending 850 m in the north/south direction and 600 m in the east/west direction. The highwall of the pit is the east pit wall which is 160 m high. Instability of the east wall appears to be still evolving (Golder 2009a, 2013, and 2014), and ongoing monitoring of potential pit-wall rim movement started in the summer of 2010. Since August 2013, a pump barge has been used in the summer and fall to transfer water from Grum Pit to Vangorda Pit for treatment.

4.1.1 Observations

- East wall instability appears to be similar to spring 2015.
- The Survey Rods are no longer inspected due to safety concerns. Vegetation has grown around the Survey Rods. We understand that monitoring of these pins has been discontinued. Photogrammetry will be performed instead.
- Several nearby power poles tilt towards the pit.
- Water was ponding in the elevated portion of the pit (the Slot Cut).
- Ponding of surface water above the north pit rim across the road from Wes' Pond has been observed in the spring of 2014 and 2015 and the fall of 2016. This area is marshy and difficult/unsafe to access.
- Pumping and treatment rates since 2014 are drawing down the water level. Pit lake level remains above the maximum recommended level of El. 1144.34 m (established by others). At the current rate of drawdown, the pit lake will fall below the maximum recommended level in two to three years.
- Golder was onsite setting up photogrammetry stations to improve monitoring.

4.1.2 Instrumentation

Instrumentation at Grum Pit (see Figure 11) includes reference rods which are no longer read due to safety concerns, a pit lake-level measurement point, and two piezometers installed in the Grum Pit slot cut.

Plots showing pond elevation and piezometric levels in the slot cut piezometers (SRK09-GSA and SRK09-GSB) are included in Appendix II-J. The recurring seasonal fluctuation of the piezometers may be due to freezing or seasonally fluctuating ground water levels.

4.1.3 Recommendations

- Prepare a contingency plan for providing power in the area in case progressive failure of the pit wall disrupts the remaining two rows of power poles carrying live wires. We understand that this will be looked at as part of the upcoming electrical risk assessment.

- Dig a sump in the marsh on the opposite site of the road from Wes' Pond and experiment with pumping water out of the marsh to reduce the water near the pit rim.
- Continue drawing down the pit lake until it is less than the maximum recommended level.

4.2 Vangorda Pit

Vangorda Pit (VP) (Figures 3 to 5) is approximately 1.8 km southeast of Grum Pit, just to the north of Vangorda Waste Rock Dump. It is an inactive, inundated open pit with an approximate elliptical shape, with the long axis oriented in the northwest to southeast direction. Water pumped from Grum Pit flows into Vangorda Pit via a pipeline located on the northwest pit wall. Water in Vangorda pit is pumped to the Vangorda Water Treatment Plant.

4.2.1 Observations

- The pit lake level is consistent with historic trends.
- A sinkhole in fill material on the pit rim was observed on the south side of the pit in 2015. The hole was repaired in 2015, although signs of settlement were observed in 2016.
- Golder was onsite setting up photogrammetry stations to improve monitoring.

4.2.2 Instrumentation

- There is one pit lake level measurement point at the Vangorda Pit. A plot of pit lake level is included in Section II-K1 of Appendix II. The pit lake level fluctuated between El. 1083 m and El. 1089 m, which is consistent with historic patterns.

4.2.3 Recommendations

- Ask Golder to inspect the sinkhole. YG reports that this was completed in September 2016.

4.3 Vangorda Waste Rock Dump

Vangorda Waste Rock Dump (VWRD), located to the south of Vangorda Pit and Little Creek Dam, has six transverse basal drains installed beneath a glacial till starter dyke to direct dump seepage into a collection ditch. The collection ditch drains into Little Creek Pond, which is retained by Little Creek Dam, see Figures 3 to 5 (SRK-Robinson 1994).

4.3.1 Observations

- There was vegetation along the collection ditch.
- Some repairs have been completed on the drain weirs. Conditions of weirs are noted below.
- Drain 1 (V28) – No weir and no sign of seepage.
- Drain 2 (V29) – Weir is in satisfactory condition, minor flow. There is a sump downstream of weir.
- Drain 3 (V30) – Weir is in satisfactory condition, minor flow.

- Drain 4 (V31) – Weir is in satisfactory condition, minor flow.
- Drain 5 (V32) – Ponding downstream of weir, minor flow.
- Drain 6 (V33) – Weir is in satisfactory condition, minor flow.

4.3.2 Instrumentation

Instrumentation at the Vangorda Waste Dump (see Figures 4, 5, and 12) consists of five V-notch weirs, V29 to V33, for flow measurement from base drains, 14 piezometers and 4 groundwater monitoring wells in the dump area. Plots of base drain flows and piezometric levels are included in Section II-L of Appendix II. The weir flow data in 2016 are summarized in Table 4.1. The minimum and maximum piezometric levels in 2016 for the piezometers as well as alert levels as provided by SRK (2011b) are shown in Table 4.2.

Table 4.1 Vangorda Waste Dump - 2016 Drain Flow

Drain/Weir No.	2016	
	Flow (L/s)	Date Read
Drain No. 1 (V28)	-	-
Drain No. 2 (V29)	-	-
Drain No. 3 (V30)	0.335	2016-06-08
Drain No. 4 (V31)	0.195	2016-06-08
Drain No. 5 (V32)	0.017	2016-06-08
Drain No. 6 (V33)	0.163	2016-06-08

Note:

1. Values are based on periodic spot measurements and may not provide an accurate indication of the range of flows experienced during the reporting period.
2. Only one reading is available for 2016. V28 and V29 do not have data available for 2016.

Table 4.2 Vangorda Waste Dump - 2016 Piezometer Levels

Groundwater Monitoring Well/Piezometer		2016 El. (m)		Alert Level ¹ (m)	Above Alert Level?
		Maximum	Minimum		
V34	GW-94-01	Not reported	Not reported	1115	No
V35	GW-94-02	Not reported	Not reported	1115	No
V36	GW-94-03	Not reported	Not reported	1113	No
V37	GW-94-04	Not reported	Not reported	1109	No
V39	P-94-01A	1126.37	1126.25	1131	No
V40	P-94-01B	1131.56	1131.47	1133	No
V41	P-94-02A	1130.92	1130.84	1133	No
V42	P-94-02B	1132.51	1132.44	1134	No
V43	P-94-02C	1121.64	1121.60	1125	No
V44	P-94-03A	1121.17	1120.82	1126	No
V45	P-94-03B	1124.68	1124.62	1126	No
V47	P-94-04B	1125.50	1125.46	1126	No
DH1	PW-10-01	1127.50	1127.31	1135	No
DH2	PW-10-02	1128.16	1128.07	1131	No
DH3	PW-10-03	1123.49	1123.47	1130	No
DH4	PW-10-04	1132.78	1132.59	1133 ³	No

Groundwater Monitoring Well/Piezometer		2016 El. (m)		Alert Level ¹ (m)	Above Alert Level?
		Maximum	Minimum		
DH5	PW-10-05	1138.53	1138.29	1139	No
-	P2001-02A	Not reported	Not reported	-	-
-	P2001-02B	Not reported	Not reported	-	-
-	P2001-03	Not reported	Not reported	-	-

Notes:

- Alert levels are from SRK (2011b)

4.3.3 Recommendations

- remove trees from along the road running along the collection ditch and on the banks of the collection ditch; and
- improve drainage downstream of V32 by widening the outlet of the small pool downstream of the weir so that the water does not back up to the v-notch.

4.4 Grum Pit Interceptor Ditch

The Grum Interceptor Ditch diverts water around Grum Pit and the Grum Overburden Dump. It consists of three reaches:

- 900 m long ditch upslope of Grum Pit to divert clean water away from the pit;
- 900 m long ditch along the northeast toe of the Grum Overburden Dump; and
- 650 m long ditch to convey flow downhill to Tributary B of Vangorda Creek.

4.4.1 Observations

- Minimal flow in the upper ditch; Low to moderate flow in the middle ditch, most flow is coming from Vangorda Water Treatment Plant Sludge Pond.
- Stable channel side slopes, minor erosion in areas.
- Vegetation has been cleared using an excavator. This method disturbed the riprap and cleared all vegetation roots which will leave the slope susceptible to erosion.
- Rill erosion on the Till Overburden Dump slope. Silt fences for surface runoff sediment control on the Till Overburden Dump slope, have fallen over in sections.
- One culvert was removed (close to Fresh Water Pond).
- Culvert under road to Fresh Water Pond is dented in the center with rocks on the bottom.

4.4.2 Recommendations

- Use riprap, vegetation, straw mats, or other means to control erosion of the side slopes.
- Repair or replace:
 - The culvert under the road to the Fresh Water Pond.
 - The culvert at the road to the Vangorda Water Treatment Plant.

4.5 Vangorda North East Interceptor Ditch

The Vangorda North East Interceptor Ditch (Figures 4 and 5) diverts surface runoff away from the Vangorda Pit. There is currently no instrumentation in place to monitor the ditch flow.

4.5.1 Observations

- No flow in ditch along the upper (50%) reach of the ditch; increased flow along the reach downstream of the tributary confluence.
- Multiple side-slope slumps were observed along the lower reach: one at the road embankment slope was partially repaired in 2013 with large boulders, and remaining slumps are to be repaired as required before spring freshet including two on the back slope on the opposite side from the road. Additional slumping in multiple areas has been observed in 2015 and 2016.
- Cracking along the access road has progressed since fall 2015.
- Moderate vegetation growth in channel and along access road.
- At the main bend in road, slumping failures have occurred on both sides of the ditch, causing water to back-up. In ponded area upstream of the slumping, substantial algae growth has occurred.

4.5.2 Recommendations

- Repair slumps in side slopes with riprap. Sand and gravel should be placed between the riprap and the side slopes. If sand and gravel is not available, non-woven geotextile could be used but would likely not last as long. The maintenance should focus on ensuring access to ditch and adequate flow capacity of the Interceptor Ditch during the next spring freshet.
- Clear vegetation in channel and along access road.

4.6 Vangorda Creek Diversion Flume

The Vangorda Creek Diversion Flume diverts flow from Vangorda Creek around the Vangorda Pit via a Corrugated Steel Pipe (CSP) half-pipe, or flume. Headworks for the flume include: a main culvert under the road at the upstream end of the flume with a trash rack at the culvert inlet and two emergency spillway culverts under the road at a higher level, also with a trash rack. At the end of the diversion, the flume discharges to a plunge pool west of the Vangorda Pit and the flow is carried across the haul road via a CSP culvert and drop box to the Vangorda Creek. There is no instrumentation for the flume.

A flash flood occurred in June 2012 causing the flume to overflow. The flood flow was barely contained by the ditch bank slopes above the flume without spilling into the Vangorda Pit. During repair after the flood, the road surface adjacent to the flume ditch was raised in the area to help contain the flood flow. This flood and its impact were similar to an event in June 2004 (SRK 2004). Site staff indicate the flume overtops into the riprap channel every year.

4.6.1 Observations

- Moderate flow in the flume.
- Some sediments were observed at the bottom of the twin emergency culverts. Some of the sediment at the ends of the culverts has been cleaned out.
- Some galvanized flume braces have buckled under lateral pressure from riprap around the flume or been damaged during ice clearing operations. Flume has deformed in places as the result. Condition appears to be worsening.
- Several sections along the flume are being pinched/narrowed due to lateral earth pressure.
- CSP segments are not always connected, causing some water to flow under the CSP.
- Old truck beds are in place over the CSP in some places where the anchors are broken to anchor the flume.
- There appears to be a buildup of sediment in the flume plunge pool.
- Woody debris appears to have been removed from the trash rack at the outlet of the Flume Plunge Pool; however, there is minor build-up again. Debris should be removed monthly when water is flowing.
- At the upstream end of the flume main culvert, large boulders were added as riprap but no filter materials appeared to be present between the riprap and road embankment fill. A small steel trashrack, tied to a few boulders by ropes, has been installed to prevent unravelling of the boulders over the culvert entrance.

4.6.2 Recommendations

- Clear the twin emergency spillway culverts and lower the spillway channel invert at the discharge end of the culverts. The culverts should be cleared any time sediment buildup in the bottom of the culvert exceeds 150 mm.
- Develop a design criteria and design concept for the replacement or realignment of the flume. Meanwhile repair damaged sections of the flume and backfill any low areas along the adjoining road. Damaged sections of the flume should be repaired or replaced with an engineered open channel. The section of the flume that should be repaired first is located between Station 0+440 and Station 0+640, i.e. the section approximately 200 m upstream of the truck beds. YG reports that SRK has indicated that the lower section of the flume also requires repair.

4.7 Little Creek Dam

Little Creek Dam (LCD) (Figures 3 to 5, and 14) was completed in 1991 and impounds Little Creek Pond. The dam is located just northwest of the Vangorda Waste Rock Dump, and currently collects seepage and surface runoff contact water from the dump. Water collected in Little Creek Pond is pumped to Vangorda Pit for treatment at the Vangorda Water Treatment Plant, see Figures 3 to 5.

Little Creek Dam is a homogeneous embankment dam constructed of local glacial till. It has a cutoff trench and a granular base drains downstream under the downstream slope. The crest is about 10 m above natural ground, ranging in elevation from about 1114.3 m to 1120.0 m. The downstream slope is 2H:1V and the upstream slope is 2.5H:1V. A zone of permafrost encountered at the south abutment was excavated prior to till placement. A 900 mm diameter Corrugated Steel Pipe (CSP) emergency spillway located at the south abutment added in 1998 has capacity to route the 1 in 200-year flood. The emergency spillway appears to be undersized for the design flood (Worley Parsons 2015).

4.7.1 Observations

- Vegetation removal and repair of erosion was completed in the summer; however, there has been some erosion on the downstream slope since the summer repairs. This was repaired again in October 2016, with improvements to drainage on the crest and dam face.
- Culvert spillway is in good condition.
- Pond level is relatively low.
- The cracks in the ground at the downstream end of the spillway outfall channel appear to be similar to previous years.
- Some trees remain on upstream slope.
- Wet, soggy ground at the toe of the dam (possible seepage) was observed prior to 2016. No evidence of this during the spring 2016 site visit, fall site visit, or from Parsons.

4.7.2 Instrumentation

Instrumentation at Little Creek Dam (see Figures 13 and 14) consists of a pond level measuring point; three paired pneumatic piezometers (P94-LCD-1 to P94-LCD-3) with tips at both shallow and deep depths; and seven piezometers (P09-LCD-1 to P09-LCD-7) installed in 2010 along the downstream toe for monitoring groundwater quality (SRK 2011b). Pond and piezometric levels are included in Section II-M of Appendix II. Historical and 2016 maximum and minimum values are shown in Table 4.3. We have limited information on the installation details of the P09- series piezometers. This information would be useful in interpreting the readings.

Three thermistor strings were installed in 1994 on the dam crest (94LCD-4T to 94LCD-6T) to a depth ranging from 13 m to 17 m. As permafrost condition no longer exists at these locations, thermistor data is not required.

Table 4.3 Little Creek Dam - Pond and Piezometer Levels

Location	Name	Historical ¹ El. (m)		2016 El. (m)		Comments
		Maximum	Minimum	Maximum	Minimum	
Water Elevation Readings						
Little Creek Pond		1111.70	1106.48	1110.05	1108.40	Licence Limit = 1111.80
Standpipe Piezometers						
Downstream Toe	P09-LCD-1	1094.23	1093.45	1093.76	1093.75	
	P09-LCD-2	1095.40	1093.26	1093.37	1093.37	
	P09-LCD-3	1092.10	1091.83	1091.81	1091.80	
	P09-LCD-4	1091.98	1082.00	1092.51	1090.84	
	P09-LCD-6	1090.91	1087.47	1090.30	1090.29	
	P09-LCD-7	1097.50	1096.93	1097.28	1097.26	
Pneumatic Piezometers						
Dam Crest	BH94-LCD1	1105.77	1104.02	1105.08	1104.87	Shallow
		1105.82	1103.79	1105.08	1105.01	Deep
	BH94-LCD2	1101.76	1100.50	1101.27	1100.99	Shallow
		1102.39	1098.54	1099.33	1099.26	Deep
	BH94-LCD3	1106.77	Dry	1106.77	1105.93	Shallow
		1108.69	1102.89	1104.15	1103.92	Deep

Notes:

1. Historical data is from the 2015 Annual Geotechnical Review (KCB 2016a).

4.7.3 Recommendations

- Repair downstream slope erosion. See KCB guidance letter issued October 3, 2016. These repairs were completed in October 2016. YG reported that the material was not track packed so there are still some ruts from the machinery. The dam face should be assessed again in the spring.
- Confirm if the IDF can be stored or routed by conducting a hydrological assessment to confirm the design flood, and if it can be stored and/or whether the spillway should be resized.
- Complete clearing trees from dam crest and upstream slope as per guidelines in KCB brushing letter dated August 5, 2016.
- Check water quality of ponded water at toe to determine if water originates from Little Creek Pond. YG reported that the site was visited several times in 2016 but no water was present. It may be that the dam repairs have improved drainage and that water will no longer pond at the toe. This recommendation should be re-assessed in 2017.

4.8 Sheep Pad Sediment Ponds

The Sheep Pad Sediment Ponds (Figures 3 to 5) are located between the Grum and Vangorda pits along the main haul road. The facility consists of two ponds which collect surface runoff via the Grum Interceptor Ditch from upslope areas, including the Grum Overburden Dump and the Grum Water Treatment Plant. The upper pond discharges to the lower pond via a CSP half-round pipe. The lower pond discharges towards the plunge pool for the Vangorda Creek Diversion Flume via a riprap lined spillway channel. We have not reviewed construction documents for the Sheep Pad Sediment Ponds;

however, the ponds appear to be retained behind small man-made embankments rather than in natural depression and as such may be classified as dams as per the Canadian Dam Association guidelines (defined as capable of retaining 30,000 m³ of water and being at least 2.5 m high, CDA 2013). This is more likely to apply to the lower pond; but both ponds should be checked.

4.8.1 Observations

- Freeze-and-thaw longitudinal cracks were observed along dyke crest and upstream slope during the spring 2016 site visit, these were not evident in fall 2016.
- Upper and Lower ponds have high water levels with only about 0.3 m freeboard. There is potential for overtopping during a peak storm event.
- Large boulders weighing down the half-round CSP between the Upper and Lower ponds near the entrance are restricting flow. There are no stiffening braces across the top of the half-round CSP and the CSP sections are not tied together. The entrance CSP section appeared to have shifted.
- A silt fence has been added to the inlet of the upper pond.
- An old survey pin is located on the dyke crest of the Lower Pond.
- There is exposed geofabric at the Lower Pond Spillway.

4.8.2 Recommendations

- The spillway between the upper and lower ponds should be upgraded to improve flow and freeboard in the upper pond.
- Cover exposed geofabric, as required, with riprap materials, on the berm separating the Lower and Upper Pond spillway.
- Assess the flood routing capacity of the pond to ensure berms are high enough with adequate freeboard.
- Remove vegetation from crest and downstream slopes as per guidelines in KCB brushing letter dated August 5, 2016.
- Confirm storage capacity and height of impoundment to determine if the pond should be classified as a dam.

4.9 Fresh Water Pond for Vangorda Water Treatment Plant

The Fresh Water Pond (FWP) for Vangorda Water Treatment Plant, located just northwest of Grum Pit (Figure 4 and Figure 5), supplies fresh process water to the Vangorda Water Treatment Plant. Water from the pond discharges to the Grum Interceptor Ditch via a riprap lined spillway channel. There is no instrumentation for the FWP. We have not reviewed any construction documents for the FWP; however, the pond appears to be retained behind a small man-made embankment rather than a natural depression and as such, may be classified as a dam as per the Canadian Dam Association (defined as capable of retaining 30,000 m³ of water and being at least 2.5 m high, CDA 2013).

4.9.1 Observations

- Spillway channel appeared to be in good condition, with considerable vegetation growth.
- Vegetation growth on the dyke crest and downstream slope was overgrown in places.

4.9.2 Recommendations

- Clear trees from embankment slopes and spillway channel as per guidelines in KCB brushing letter dated August 5, 2016.
- Confirm the storage capacity and height of impoundment and embankment to determine if the embankment should be classified as a dam.

4.10 V-15 Seep Ditch and Moose Pond

The V-15 Seep Ditch and Moose Pond are located between the Grum Waste Rock Dump and the Vangorda Waste Dump (see Figures 3 to 5). The V-15 Seep Ditch is a bentomat lined ditch that collects Grum Waste Rock Dump seepage water from the V-15 Pond. Most of this seepage water is pumped to Vangorda Pit with a small amount of seepage flowing to Moose Pond. A small dyke of sandbags and bentonite is used to contain the flow in the V-15 Seep Ditch. Moose Pond is a natural pond that retains water in a geomorphic depression in coarse-grained glaciofluvial surficial deposits. The water is retained by a narrow natural landform. Water flows out of Moose Pond via seepage through the landform at Moose Seep. Moose pond was previously used as a natural exfiltration structure which is beneficial for the downstream water quality. The landform that contains the pond has a steep downstream slope and is eroding and raveling, therefore, flows from V15 and Grum Creek are redirected to Vangorda Pit except in the winter.

4.10.1 Observations

- Moose Pond was essentially dry during the spring and fall site visits. Slope erosion is progressing.

4.10.2 Recommendations

- None.

4.11 Vangorda Water Treatment Plant Clarifier Pond Dyke

The Vangorda Water Treatment Plant Clarifier Pond Dyke (also known as the Sludge Pond) (Figures 3 to 5), located just east of the Grum Pit, is a rectangular shaped pond retained by an embankment dyke. There appears to be no instrumentation at this pond or its periphery dyke. We have not reviewed construction documents for the pond; however, the pond is retained behind an embankment and as such, may be classified as a dam as per the Canadian Dam Association (defined as capable of retaining 30,000 m³ of water and being at least 2.5 m high, CDA 2013).

4.11.1 Observations

- Freeze-and-thaw longitudinal cracks (three cracks each about 6 m long) were observed on the dyke crest in the spring of 2016 but were not visible in the fall.
- Decommissioned lamp posts are sloping (progressed since the fall of 2015).
- Vegetation growth on the dyke crest and slopes.
- No engineered spillway.
- Minor erosion on upstream road.

4.11.2 Recommendations

- Clear trees from embankment crest and slopes as per guidelines in KCB brushing letter dated August 5, 2016.
- Confirm the storage capacity and height of impoundment and embankment to determine if the embankment should be classified as a dam.
- Assess the need for a spillway.
- Control erosion of the upstream road.

5 MONTHLY MONITORING REPORTS

KCB has reviewed monthly monitoring reports submitted by Parsons. Our monthly observations are noted in Table 5.1.

Table 5.1 Monthly Observations

Month	Observations
January	<ul style="list-style-type: none"> No new dam safety concerns identified.
February	<ul style="list-style-type: none"> No new dam safety concerns identified.
March	<ul style="list-style-type: none"> No new dam safety concerns identified.
April	<ul style="list-style-type: none"> No new dam safety concerns identified.
May	<ul style="list-style-type: none"> Vangorda Flume overflowing does not appear to be an immediate cause for concern since it overtops the half-round CSP but stays within the channel. However, it should be repaired to prevent further erosion. Sloughing observed May 4, 2016 and inspected during site visit by KCB was performing adequately (KCB 2016d). RCDC water levels above the creek banks in the North Fork of Rose Creek is not a dam safety concern as long as it is still contained within the terrain, however it may post a hazard to infrastructure in low lying areas in the vicinity. Slumping in North West Interceptor Ditch may reduce flow capacity.
June	<ul style="list-style-type: none"> No new dam safety concerns identified.
July	<ul style="list-style-type: none"> No new dam safety concerns identified.
August	<ul style="list-style-type: none"> No new dam safety concerns identified.
September	<ul style="list-style-type: none"> No new dam safety concerns identified.
October	<ul style="list-style-type: none"> Despite no longer being used as an exfiltration pond, Moose Pond still occasionally contains water which could accelerate slope failure downstream of Moose Pond and increase the consequence should the embankment breach.
November	<ul style="list-style-type: none"> No new dam safety concerns identified.
December	<ul style="list-style-type: none"> No new dam safety concerns identified.
January 2017	<ul style="list-style-type: none"> No new dam safety concerns identified. IP levels dropping more than normal. Parsons believe this to be due to the unusually small amount of snow cover and ice forcing some of the inflows to the IP to be shifting paths.
February 2017	<ul style="list-style-type: none"> No new dam safety concerns identified.

Our general observations are:

- To aid in interpreting site data, unusual instrument readings (i.e. inconsistent with previous readings, dry piezometers, no bubbles from return line for pneumatic piezometers, unstable readings, weirs with downstream water backed up to weir, etc.) should be accompanied by notes describing the abnormality. Any apparent potential causes for the unusual behavior should be noted.
- Beaver dams should be removed from weirs as they are encountered and before taking readings. It is not clear from the daily reports and reported readings if this is being done and the dams are being rebuilt by beavers after they are removed, or if the dams are not being removed and the weir levels are being reported with the dams in place.

6 SUMMARY OF RECOMMENDATIONS

Table 6.1 summarizes the recommendations in this report and relevant recommendations from our previous reports. The recommendations are prioritized into subjective categories of High, Medium, and Low which are described as follows:

- High – Should be completed as soon as possible. Critical infrastructure or instrumentation. Current environmental, H&S, or dam safety risk.
- Medium – Should be completed within a year. Important infrastructure or instrumentation. Could lead to environmental, H&S, or dam safety risk.
- Low – Should be completed within 2 years. Useful infrastructure or instrumentation. Affects quality of long term performance or monitoring.

The priorities and timelines for the recommendations should be developed further in consultation with YG in 2017.

Table 6.1 Summary of Recommendations

Structure/Item	Condition	Recommendation	Number	Priority	Action by	Timeline/Progress
				Priority Key: H - High Priority M - Medium Priority L - Low Priority In Progress		Timeline key: (I) - Immediate, can action now (S) - Short-term, before end of 2017 (L) - Long-term, before end of Fiscal Year 2018 (FY18) (ND) - Not determined, reliant on other parties' planning
General	Tool required for efficient vegetation removal.	Purchase brush cutter extension for vegetation removal.	KCB-2016-2	M	YG to authorize.	(S) - YG to provide cost estimate.
	OMS is out of date.	Update KCB Operations, Maintenance and Surveillance Manual (include Parsons contact information).	KCB-2016-3	In Progress	KCB preparing draft.	(I) - Actioned from site. In progress.
	ERP is out of date.	Update KCB Emergency Response Plan (include Parsons Emergency Response Plan and contact information).	KCB-2016-5	In Progress	KCB (issued in draft. Waiting on review board comments).	(L) - In progress.
	No site wide water management plan.	Complete a site wide water management assessment and plan, including: - Site wide hydrology monitoring program (assess locations and method for collecting flow data). - Flood management assessment for all structures (recommended design event, structure assessment). - Water balance (risk scenario assessments). - Develop a systematic approach for maintaining the rating curves at flow measurement stations.	KCB-2016-9	M	YG to assess timing.	(ND) - This should be performed in conjunction with the retention of an engineer of record. Some preliminary work can be prepared up-front.
Brush Cutting and Vegetation Removal	Vegetation growth impairing function, inspection and accessibility of site infrastructure.	North Wall Interceptor Ditch: Continue vegetation clearance along the upper and middle channel reaches. Clearing should include the access road and berm along the channel to facilitate future inspection. Some clearing has been complete, but portions of the mid and lower channel have not been cleared.	KCB-2014-2	L	Parsons. See KCB guidance letter issued August 5, 2016. YG to approve method for appropriate environmental protection.	(S) - To be completed when brush cutter is purchased.
		Rose Creek Diversion Channel: Clear vegetation along lower channel reaches and access path along Back Slope.	KCB-2014-4	M		
		Secondary Dam: Clear trees from the downstream dam slope.	KCB-2015-20	M		
		Intermediate Dam: Remove vegetation from the dam, dam abutments and spillway channel.	KCB-2015-33	M		
		Cross Valley Dam: Remove vegetation from the dam, dam abutments and spillway channel.	KCB-2014-8	M		
		Vangorda Waste Rock Dump: Clear trees along road and collection ditch.	KCB-2016-13	L		
		Vangorda Northeast Interceptor Ditch: Clear vegetation in channel and along access road.	KCB-2016-29	L		
		Little Creek Dam: Complete clearing of trees from dam crest and upstream slope.	KCB-2015-45	M		
		Sheep Pad Sediment Ponds: Remove vegetation from crest and downstream slopes of pond berms.	KCB-2016-30	M		
		Fresh Water Pond for Vangorda Water Treatment Plant: Clear trees from embankment slopes and spillway channel.	KCB-2015-53	M		
Vangorda Water Treatment Plant Clarification Pond Embankment: Clear trees from embankment crest and slopes.	KCB-2015-56	M				
Instrumentation (See KCB 2016c for further details)	Instruments missing cap	Rose Creek Diversion Channel: CD-10, CD-15, CD-19, BH91-CD-1, BS-9, BS-70 (add 70 mm inclinometer cap)	KCB-2016-31	L	Parsons	(I) - 2017
		Secondary Dam: P03-01, P03-02, P03-03 (add PVC cap with vent hole drilled on the side)				
		Intermediate Dam: BH91-ID3 (plastic cap is missing, can be replaced with tape)				
		Cross Valley Dam: CVDC-4-D, CVDT-2, 94-CVDC-1, CVDC-7-S (add PVC cap with vent hole drilled on the side)				
	Damaged instrument	Vangorda Waste Rock Dump: V39, V40, V41, V42, V43, V45 (add PVC cap with vent hole drilled on the side)	KCB-2016-32	L	Parsons	(I) - 2017
		Cross Valley Dam: P01-02 (repair casing and PVC pipe, sound hole)				
	Unprotected instrument	Secondary Dam: P81-6 (extend piezometer pipe to top of casing)	KCB-2016-33	L	Parsons	(I) - 2017
		Little Creek Dam: P09-LCD-1, P09-LCD-2, P09-LCD-3, P09-LCD-4, P09-LCD-6, P09-LCD-7 (seal around piezometer at surface with bentonite)				
	Missing labels or mislabeled	Cross Valley Dam: CVDP-1 & CVDP-3 (missing labels, at the same location), CVDP-5 & CVDP-6 (add tip label)	KCB-2016-34	L	Parsons	(I) - 2017
		Vangorda Waste Rock Dump: V39, V40, V44, V45 (confirm labels)				
		Intermediate Dam: BH91-ID7 (re-install protective casing)				
		Rose Creek Diversion Channel: BS-10 (re-label with correct A+ axis (south)), BGC05-05 (re-label with correct A+ axis (north)), BGC05-06 (labels are swapped with thermistor labels)				
	Instrument and ground surface survey elevation missing	Intermediate Dam: P01-04 (A and B labels appear to be swapped)	KCB-2016-35	L	YG to commission	(S) - 2017. May wish to combine with other survey activities.
Cross Valley Dam: CVDP-1 & CVDP-3 (missing labels, at the same location), CVDP-5 & CVDP-6 (add tip label)						
Pneumatic piezometer tips require replacement	Intermediate Dam: BH96-4 A/B/C/D, P01-04 A/B, BKS04-06, BKS04-07, BH91-ID5 (resurvey top of casing and ground surface elevation)	KCB-2016-36	L	Parsons	(S) - 2017	
	Rose Creek Diversion Channel: All inclinometers (CD, BGC-05, SP, and BS series) (resurvey top of casing and ground surface elevation)					
Thermistors inoperable	Rose Creek Diversion Channel: CD-13-S (replace tips)	KCB-2016-38	L	YG to commission	(S) - 2017	
	Intermediate Dam: BH91-ID6-S, BH91-ID6-D, BH91-ID7 (replace tips)					
Missing thermistor calibration and conversion data	Cross Valley Dam: CVDP-3 (replace tips)	KCB-2016-39	L	YG	(I) - 2017	
	Rose Creek Diversion Channel: SP-2, SP-3, BS-5, BS-9, BS-12, BGC05-04, CD-26, CD-10, CD-15, BGC05-07 (acquire RST Instruments Ltd. to assess thermistor operability and repair potential)					
	Rose Creek Diversion Channel: CD-10, BGC05-07, SP-2					
Inclinometer not functioning	Rose Creek Diversion Channel: SP-5 (replace inclinometer)	KCB-2016-40	M	YG to commission	(S) - 2017	
	Install one inclinometer in each of the Little Creek Dam, Cross Valley Dam and Intermediate Dam	KCB-2016-41	M	YG to commission		

Structure/Item	Condition	Recommendation	Number	Priority	Action by	Timeline/Progress
				Priority Key: H - High Priority M - Medium Priority L - Low Priority In Progress		Timeline key: (I) - Immediate, can action now (S) - Short-term, before end of 2017 (L) - Long-term, before end of Fiscal Year 2018 (FY18) (ND) - Not determined, reliant on other parties' planning
Faro Pit	Pit lake exceeds maximum recommended elevation established by Golder 2009.	Continue procedures described in KCB's technical memo dated February 10, 2015 titled "Faro Pit East Rim Slope Stability Monitoring During Elevated Lake Level". Draw down pit lake as soon as practical.	KCB-2014-11	In Progress	YG	(I) - Review of these procedures should take place between Parsons/YG, to ensure information is communicated clearly. Pit lake is falling but is still above the maximum recommended level.
Faro Creek Diversion Channel	Pit wall is regressing towards Faro Creek Diversion Channel and may eventually undercut channel resulting in flow into the pit.	Develop a contingency plan for potential blockage.	KCB-2015-4	M	INAC	(ND) - Follow-up to take place with Technical Review Committee, as to a timeline.
	Staff gauges are destroyed every winter and must be reinstalled each year.	Develop staff gauges that aren't destroyed every winter.	KCB-2016-24	L	Parsons	(L) - After realignment of the FCDC
North Wall Interceptor Ditch	Vegetation that was previously cleared in the upper channel was removed using an excavator which also removed the roots. The areas that were cleared are subject to erosion.	Grass, erosion control blankets (straw mats), or riprap should be placed to control erosion prior to snow fall and melt. May require some experimentation to determine the most appropriate means of controlling erosion.	KCB-2016-16	M	Parsons	(L) - Summer 2017.
	Evidence of weir overtopping during freshet.	Extend the weir such that it does not overtop during the spring freshet i.e. the freshet flow is contained within the v-notch and does not overtop the sides.	KCB-2015-9	L	Parsons	(L) - Spring 2017.
Rose Creek Diversion Channel	No calibration data has been collected for staff gauges at high flows.	Take calibration flow measurements at the staff gauges in 2017 during high flows, using the overhead StreamPro guidance wires. Extend staff gauges, if required, such that they can be read during high flows.	KCB-2015-10	In Progress	Parsons	(L) - In progress.
	Poor access conditions to Back Slope. May not be able to access with equipment during emergencies.	Develop an access plan for the back slope: - required permits regarding investigation and repair of the above slope slumps; and - general access (improved crossing and road, remove vegetation).	KCB-2014-3	M	YG to explore permits, Parsons to review access	(L) - YG to action.
	Slumping in areas of Back Slope.	Monitor condition of slope slump scarps from four new standard photograph locations supplied by KCB at the Back Slope, and continue instrumentation monitoring along the Back Slope.	KCB-2016-42	Complete	Parsons	Added to regular monitoring program.
	No calibration data has been collected at flow stations X2 and X10.	Take flow measurements and staff gauge readings to develop rating curves for X2 and X10.	KCB-2016-43	L	Parsons	(S) - 2017
	Reports potential describing previous Back Slope repairs are unavailable. Past successful repair experiences could provide guidance for current and future care and maintenance activities in the Back Slope area.	Locate annual review reports by Golder (1983 to 1999) and BGC (2000, 2001, and 2003), when repair works in the Back Slope area were conducted.	KCB-2014-6	L	YG	(I) - Some reports were located at the EMR map library; others to be further followed up on.
	No emergency response plan for failure of the Back Slope and blockage of Rose Creek Diversion.	Develop an emergency response plan for failure of the Back Slope and blockage of the Rose Creek Diversion.	KCB-2016-10	H	Parsons to develop incident plan to be reviewed and accepted by YG	(S) - YG to discuss with Parsons.
Flow stations routinely destroyed in winter; NFRD-2B and X2 have inconsistent readings.	Identify and install a new monitoring point that allows use of a flow station and staff gauge that will provide consistent readings and not be easily destroyed in winter. KCB suggests placing the station in the culvert if access can be maintained.	KCB-2016-19	L	Parsons	(L) - Spring 2017.	
North Fork Rock Drain	Acceptable.	None.	N/A	N/A	N/A	N/A
K8 Creek Rock Drain	Acceptable.	None.	N/A	N/A	N/A	N/A
Secondary Dam	Cracks along dam crest on Secondary Dam Downstream Berm road.	Monitor cracks using quantitative measures (pins for length and width).	KCB-2016-25	M	Parsons	(I) - To be actioned by site.
	Downstream berm road is rough and ponding water.	Grade lower downstream berm road.	KCB-2016-26	L	Parsons	(I) - To be actioned by site.
	Secondary Dam not included in DSR, OMS or ERP	Include the Secondary Dam in the next DSR, OMS and ERP.	KCB-2015-25	H	YG to include in scope	(ND) - YG to follow up with KCB.
Intermediate Dam	Erosion on dam face.	Repair latest erosion as per technical direction from KCB.	KCB-2016-20	In Progress	Parsons	(L) - Spring 2017 (Fall repairs are complete).
	Spillway inadequately sized for extreme flood events.	Upgrade spillway to meet CDA dam safety criteria for Inflow Design Flood (IDF) for the high consequence classification dam.	KCB-2015-27 WSR-2014	H	INAC	(ND) - Follow-up to take place with Technical Review Committee, as to a timeline, and comments as to short-term mitigation, if there are no plans to address this in the next year.
Cross Valley Dam	Pipelines and operational equipment in spillway, potentially impeding flow.	Remove pipelines and operational equipment that may impede spillway flow from the spillway	KCB-2016-27	M	Parsons	(I) - To be actioned by site.
	Rill erosion on downstream slope.	Repair rill erosions in local areas of the downstream slope near the dam crest.	KCB-2015-36	M	Parsons	(L) - YG to follow up with KCB for protocol, then actioned by site.
	Tension cracks longitudinally along dam crest.	Monitor using quantitative measures (pins for length and width), and seal to minimize water ingress to the embankment dam.	KCB-2015-37	In Progress	Parsons is monitoring the cracks. Parsons/KCB to discuss how to seal.	(S) - To be actioned by site.
	Siphon pipeline partially obstructing spillway.	Remove siphon pipeline from the spillway.	KCB-2015-38 WSR-2014	H	Parsons to discuss with YG/KCB	(S) - To be discussed between YG/Parsons/KCB.
	Water bypassing Weir No. 3.	Repair weir such that water no longer bypasses it.	KCB-2016-28	L	Parsons	(L) - Spring 2017.
	Spillway inadequately sized for extreme flood events.	Upgrade spillway to manage the design flood.	KCB 2015 WSR-2014	H	INAC	(ND) - Follow-up to take place with Technical Review Committee, as to a timeline, and comments as to short-term mitigation, if there are no plans to address this in the next year.


Structure/Item	Condition	Recommendation	Number	Priority	Action by	Timeline/Progress
				Priority Key: H - High Priority M - Medium Priority L - Low Priority In Progress		Timeline key: (I) - Immediate, can action now (S) - Short-term, before end of 2017 (L) - Long-term, before end of Fiscal Year 2018 (FY18) (ND) - Not determined, reliant on other parties' planning
Grum Pit	Power supply may be cut off by pit wall failure. We consider a loss of power to be related to water management as it would disrupt pumping.	Prepare a power supply contingency plan in case progressive failure of the pit wall endangers the remaining two rows of power poles carrying live wires.	KCB-2014-11	In Progress	YG	(L) - To be discussed between YG/Parsons/KCB.
	Area between the road near Wes' Pond and Grum Pit is flooded.	Dig a sump in the marsh on the opposite site of the road from Wes' Pond and experiment with pumping water out of the marsh to reduce the water near the pit rim.	KCB-2016-21	M	Parsons	(L) - To be discussed between YG/Parsons/KCB.
	Grum Pit Lake is above maximum recommended level.	Draw down the Grum Pit Lake as soon as practical such that it is below the maximum recommended level.	KCB-2014-13	In Progress	Parsons	(L) - To be actioned by site.
Vangorda Pit	Sinkhole repaired in 2015 appears to be settling.	Assess the depression at the sinkhole.	KCB-2016-22	Completed	YG to request	(S) - YG to ask Golder to look at the sinkhole.
Vangorda Waste Rock Dump	Water ponding downstream of seepage weir V32 potentially inhibiting function during high flows.	Improve drainage downstream of seepage weir V32.	KCB-2016-23	L	Parsons	(L) - To be actioned by site.
Grump Pit Interceptor Ditch	Erosion on side slopes.	Use riprap, vegetation, straw mats, or other means to control erosion of the side slopes.	KCB-2016-14	H	Parsons	(L) - To be actioned by site.
	Damaged culverts.	Repair or replace: - The culvert under the road to the Fresh Water Pond. - The culvert at the road to the Vangorda Water Treatment Plant.	KCB-2012-2	L	YG to commission	(L) - 2017. Culvert to be repaired/replaced.
Vangorda North East Interceptor Ditch	Multiple side-slope slumps were observed along the lower reach.	Repair slumps in side slopes with riprap and place filter materials between existing slope and newly added riprap materials. The maintenance activity should focus on maintaining adequate flow capacity of the Interceptor Ditch during the next spring freshet. Side slope repairs could use a simple design with coarse rock placed over filter cloth such that the side slopes and the channel capacity are maintained. Need to maintain access (clear vegetation and make sure the road doesn't slump away) and maintain positive drainage in the ditch.	KCB-2015-40	L	Parsons	(L) - To be actioned by site.
Vangorda Creek Diversion Flume	Bottom of twin emergency spillway culverts is filled with sediment.	Clear the twin emergency spillway culverts and lower the spillway channel invert at the discharge end of the culverts. The culverts should be cleared any time sediment buildup in the bottom of the culvert exceeds 150 mm.	KCB-2015-41	L	Parsons	(L) - To be discussed between YG/Parsons/KCB.
	Several damaged portions of flume render it less effective for containing flow.	Replace the flume with a new structure as early as practical. This is nearing high priority.	KCB-2014-14	M	INAC	(ND) - Follow-up to take place with Technical Review Committee, as to a timeline, and comments as to short-term mitigation, if there are no plans to address this in the next year.
Little Creek Dam	Erosion on downstream slope.	Repair erosion on the downstream dam slope. These repairs were completed in October. YG reported that the material was not track packed so there are still some ruts from the machinery. Dam face should be assessed again in the spring.	KCB-2015-42	Completed (to be assessed in Spring)	Parsons	(L) - To be completed in spring 2017. Fall repairs complete.
	Spillway is undersized.	Conduct a hydrological assessment to confirm the design flood, and if it can be stored and/or whether the spillway should be resized.	KCB-2015-44 (Worley 2014)	H	YG to commission	(ND) - Follow-up to take place with Technical Review Committee, as to a timeline, and comments as to short-term mitigation, if there are no plans to address this in the next year.
	Intermittent seepage at toe of dam.	If seeps return, check water quality of seeps to determine if they originate from Little Creek Pond. YG reported that the site was visited several times in 2016 but no water was present. It may be that the dam repairs have improved drainage and that water will no longer pond at the toe. This recommendation should be re-assessed in 2017.	KCB-2015-46	L	Parsons	(L) - To be actioned by site.
Sheep Pad Sediment Ponds	Spillway for Upper Pond is partially obstructed by boulders and is not effective for maintaining adequate freeboard under flood events.	Reduce the size of the large boulders weighing down the half-round CSP spillway between the Upper and Lower Ponds. Add stiffening braces to the top of the CSP to prevent further pipe deformation due to lateral pressure from riprap materials around the pipe.	KCB-2015-48	H	Parsons	(L) - To be actioned by site.
	Low freeboard in Upper Pond.	Review design of ponds and if existing ponds are adequate. Consider options for lowering the invert elevation of CSP half round between upper and lower Sheep Pond. This should help to maintain more freeboard in the upper pond.	KCB-2015-49	M	YG to commission	(L) - To be discussed between YG/KCB.
	Exposed geofabric.	Cover exposed geofabric, as required, with riprap materials, on the berm separating the Lower and Upper Pond spillway.	KCB-2015-50	L	Parsons	(L) - To be actioned by site.
	Containment berm may be large enough to be classified as a dam.	Confirm storage capacity and height of impoundment to determine if the pond should be classified as a dam.	KCB-2015-52	M	YG to commission	(S) - To be discussed between YG and KCB.
Fresh Water Pond for Vangorda Water Treatment Plant	Containment berm may be large enough to be classified as a dam.	Confirm storage capacity and height of impoundment to determine if the pond should be classified as a dam.	KCB-2015-54	M	YG to commission	(S) - To be discussed between YG and KCB.
V-15 Seep Ditch, GC Weir and Moose Pond	Acceptable.	None.	N/A	N/A	N/A	N/A
Vangorda Water Treatment Plant Clarification Pond	Containment berm may be large enough to be classified as a dam.	Confirm storage capacity and height of impoundment to determine if the pond should be classified as a dam.	KCB-2015-57	M	YG to commission	(S) - To be discussed between YG and KCB.
	No spillway.	Assess the need for a spillway on the pond (can be included in the assessment of the dam classification).	KCB-2015-58	M	YG to commission	(S) - To be discussed between YG and KCB.
	Minor erosion on upstream road	Control erosion of the upstream road.	KCB-2016-44	L	Parsons	(I) - 2017

7 CLOSING

This report is an instrument of service of Klohn Crippen Berger Ltd. (KCB) and has been prepared for the exclusive use of the Yukon government. The content of this report reflects Klohn Crippen Berger's best judgment in light of the information available to it at the time of preparation. Any use which a third party makes of this report, or any reliance on or decisions to be made based on it are the responsibility of such third parties. KCB accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report.

We appreciate the opportunity to work on this interesting and environmentally important project.

KLOHN CRIPPEN BERGER LTD.



David Willms, P.Eng. (YT)
Project Manager / Geotechnical Engineer

REFERENCES

- BGC. 2010. 2009 Annual Geotechnical Evaluation and Instrument Review, 2 Vols. Feb. 26.
- BGC. 2013. Annotated Repairs Map – GSC Cover, July 5.
- BGC. 2014. North Fork Rock Drain Seepage Collection - Preliminary Plan Next Steps, July 28.
- BGC. 2015. North Fork Rock Drain Seepage Interception System, Faro Mine – As-Built Report Downstream Elements, March 19.
- Brodie. 2010. Intermediate Dam Rip Rap Monitoring, October 19 Memorandum.
- Canadian Dam Association, 2007. “Dam Safety Guidelines”, January. (with Revised Section 6, issued in 2013)
- Canadian Dam Association, 2014. “Technical Bulletin: Application of Dam Safety Guidelines to Mining Dams”.
- CH2MHILL. 2013a. 2013 Grum Pit Slope Monitoring Locations, September 11
- CH2MHILL. 2013b. Review of Pit and Pond Water Elevations – Faro Mine Remediation Project, Draft Technical Memorandum, October 11.
- Golder. 1980. Final Design Recommendations for Down Valley Tailings Disposal Project, 3 Vols. Report 792-2025 to Cyprus Anvil, June.
- Golder. 1981. Recommendations for Performance Instrumentation of the Cyprus Anvil Down Valley Project near Faro, Oct. 5.
- Golder. 1982. Down Valley Tailings Containment Project - 1980-81 Construction, 3 Vols. Report 802-2038 to Cyprus Anvil, February.
- Golder. 1983. 1982 Performance Monitoring of Down Valley Tailings Project, 2 Vols. Report 822-2021 to Cyprus Anvil, February.
- Golder. 1990a. 1989 Performance Monitoring of Down Valley Tailings Project, Faro Mine, 2 Vols. Report 892-2406 (882-2410/882-2409 to Curragh Resources, March.
- Golder. 1990b. 1988 and 1989 Down Valley Tailings Construction Projects, Faro, Yukon, 2 Vols. Report 882-2413C (882-2406C) to Curragh Resources, April.
- Golder. 1992. 1991 Down Valley Tailings Construction Projects, Faro, Yukon, Report 912-2406 to Curragh Resources, May.
- Golder. 2009a. Geotechnical Slope Stability Assessment of the East Wall of the Grum Pit, Nov. 23.
- Golder. 2011a. 2010 Faro Pit Slope Stability - Monitoring Data Review, Feb. 23.
- Golder. 2011c. Geotechnical 2011 Data Review - Faro Mine Complex, Sept. 12.
- Golder. 2013. Faro Mine Complex Annual Pit Slope Stability Inspection, Feb. 7.


- Golder. 2014. Faro Mine Complex 2014 Annual Pit Slope Stability Inspection, Dec. 19.
- KCB. 2002. Dam Safety Review.
- KCB. 2008. 2007 Dam Safety Review - Cross Valley Dam, Intermediate Dam and Little Creek Dam, April 9.
- KCB. 2012-2013. Faro Mine Complex, 2011-2012 Annual Geotechnical Review.
- KCB. 2014a. Dam Breach and Inundation Study, Klohn Crippen Berger, February.
- KCB. 2014b. Operations, Maintenance and Surveillance Manual for: Intermediate Dam, Cross Valley Dam and Little Creek Dam, March.
- KCB. 2014c. Emergency Response Plan for: Intermediate Dam, Cross Valley Dam, Little Creek Dam, Faro Creek Diversion Channel, Rose Creek Diversion Channel and Vangorda Creek Diversion Flume, March.
- KCB. 2014d. Faro Mine Complex, 2013 Annual Geotechnical Review, August 24.
- KCB. 2014e. Memo on Grum Pit East Rim Surface Runoff Review – Draft, October 24.
- KCB. 2014f. Memo on Rose Creek Diversion Channel Backslope Review – Draft, November 7.
- KCB. 2015a. Memo on Faro Pit East Rim Slope Stability Monitoring During Elevated Lake Level, March 3.
- KCB. 2015b. Emergency Response Plan for: Intermediate Dam, Cross Valley Dam, Little Creek Dam, Faro Creek Diversion Channel, Rose Creek Diversion Channel and Vangorda Creek Diversion Flume - 2015 Update Draft, March 31.
- KCB. 2015c. Faro Mine Complex, 2014 Annual Geotechnical Review, September 18.
- KCB. 2016a. Faro Mine Complex, 2015 Annual Geotechnical Review, March 30.
- KCB. 2016b. Faro Mine Complex - Maintenance for Intermediate Dam and Little Creek Dam Erosion, October 3.
- KCB. 2016c. Faro Mine Complex – Instrumentation Condition Review, November 29.
- KCB. 2016d. Faro Mine Complex – Emergency Response to Intermediate Dam Sloughing, December 16.
- NHC. 2006. Faro Mine Hydraulic Capacity Analysis, June.
- SRK. 1990. Vangorda Plateau Development - Little Creek Collection Facility Geotechnical Investigation and Design, Report 160627 to Curragh Resources, September.
- SRK. 1991. Vangorda Plateau Development As-Built Construction Report for Little Creek Dam, Report 160636 to Curragh Resources, May.
- SRK-Robinson. 1994. Construction Report - Vangorda Rehabilitation, Nov.

- SRK. 1998. Little Creek Pond Emergency Spillway, Vangorda Mine, Yukon Territory. Report 1CD003.01 to Deloitte and Touche, December.
- SRK. 2004. Vangorda Creek Diversion – Inspection Report – Sudden Flood Event, June 8.
- SRK. 2011a. 2010 Annual Inspection - Waste and Water Management Facilities - Vangorda/Grum, Feb.
- SRK. 2011b. 2011 Geotechnical Inspection - Waste and Water Management Facilities - Vangorda/Grum, Aug.
- WorleyParsons. 2015. Faro Mine Dams – Dam Safety Review, March 12.
- YES. 2013a. Field Work and Results for Faro Pit Wall Surveys, Faro Mine Site Letter Report, November 4.
- YES. 2013b. Field Work and Results for Grum Monitoring Stations, Faro Mine Site Letter Report, December 6.
- YG. 2011a. Moose Pond and Associated Water Management Structures - Elevated TSS in Discharge to Vangorda Creek, Yukon Energy, Mines and Resources, May 18.
- YG. 2011b. Grum Sulphide Cell Surface Water Management: Elevated TSS and Zinc in Discharge to Vangorda Creek, Yukon Energy, Mines and Resources, May 27.
- YG. 2013. Faro Mine Complex: Elevated Total Suspended Solids and Zinc in Discharge to Vangorda Creek, May 17.
- YG. 2015. Faro Creek Diversion Channel - Failure Response Plan, March 16.

FIGURES

Figure 1	Faro Site – General Layout
Figure 2	Faro Site – Air Photo
Figure 3	Vangorda Plateau Mine – Site Overview
Figure 4	Vangorda Plateau Site – General Arrangement Plan
Figure 5	Vangorda Plateau Site – Air Photo
Figure 6	Faro Pit Brim – Reference Bars and Survey Prisms
Figure 7	Down Valley Tailings Containment Instrument Location – 1 of 2
Figure 8	Down Valley Tailings Containment Instrument Location – 2 of 2
Figure 9	Section View of Intermediate Dam
Figure 10	Section View of Cross Valley Dam
Figure 11	Grum Pit Brim – Reference Rods and Survey Prisms
Figure 12	General Arrangement Plan – Vangorda Waste Rock Dump
Figure 13	Little Creek Dam – General Arrangement Plan
Figure 14	Little Creek Dam – Section B-B

Date: 1/29/2013 Time: 13:25:10 Scale: 1:2,585
 Filename: \\NT-KLOHN.COM\PROJDATA\W\CR\M09770A02 - GOVT YUKON-FARO COMPLEX 400 DRAWINGS\CAD\2012 ANNUAL GEOTECHNICAL REVIEW\FIG 1-2.DWG
 Xref File(s): bn-faro-130221; for insert-by others-faro site plan-130221
 Image File(s):



LEGEND


- IMPACTED AREA BOUNDARY
- ACCESS ROADS
- STREAMS

NOT FOR CONSTRUCTION

To be read with Klohn Crippen Berger report dated

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

CLIENT
 YUKON GOVERNMENT



SCALE 0 1000m

PROJECT	FARO MINE COMPLEX 2012 ANNUAL GEOTECHNICAL REVIEW	
TITLE	FARO SITE GENERAL LAYOUT	
PROJECT No.	M09770A02 02	FIG. No. FIGURE 1

KCP-P-MLD



LEGEND

- Pit
- Tailings
- Pond
- - - Diversion

NOTE

Refer to Figures 3-1 and 3-2 for Down Valley Tailings Containment instrument location details.

REFERENCE

Ortho-image obtained from Google © 2007 Data SIO, NOAA, U.S. Navy, NGA, GEBCO Image © 2011 DigitalGlobe.
 Projection: UTM Zone 8 Datum: NAD 83



Fig. 2 Original Source: Figure 2-1 General Arrangement Plan
 Golder 2011, 2010 Annual Geotechnical Dam Inspection,
 Faro Mine Complex, Faro, Yukon

FIGURE 2

PROJECT DENISON ENVIRONMENTAL SERVICES
 FARO MINE COMPLEX
 YUKON

TITLE FARO SITE AIR PHOTO



PROJECT No. 10-1427-0032		PHASE No. 2000	
DESIGN	WJP	08FEB11	SCALE AS SHOWN
GIS	AL	08FEB11	REV. 0
CHECK	WJP	28FEB11	FIGURE 2-1
REVIEW	JAH	28FEB11	





Fig. 3 Original Source: Figure 3 Vangorda Plateau Mine Site - Overview BGC 2003. Report on Emergency Preparedness Plan for Selected Dams and Water Diversion Structures

CLIENT: **Deloitte & Touche**

NOTE: BASE MAP FIGURE PROVIDED BY GARTNER LEE LTD.

LEGEND:

	ROADS		WATER TREATMENT PIPELINE
	EXISTING SURFACE DRAINAGE		SURFACE WATER
	PRE-MINE DRAINAGE		
	EFFLUENT PIPELINE		
	PIPELINE		
	POWERLINE		

REV.	DATE	REVISION NOTES	DRAWN	CHECKED	APPROVED


SCALE:	AS SHOWN
DATE:	OCTOBER 2003
DRAWN:	GEJ
DESIGNED:	KM
CHECKED:	HHH/JWC
APPROVED:	JWC

FIGURE 3		
PROJECT ANVIL RANGE EPP FOR DAMS & WATER DIVERSION STRUCTURES		
TITLE VANGORDA PLATEAU MINE SITE OVERVIEW		
PROJECT No.	FIGURE No.	REV.
0257-018-02	3	0

BGC ENGINEERING INC.
AN APPLIED EARTH SCIENCES COMPANY

BGC Calgary, AB Phone: (403) 250 5185

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.



J:\01_SITES\FAR01\117_1CD009001_2010_Geot_insp\140_AutoCAD\site_plan.dwg

Map Scale: 1:2500
 Contour Interval: 2m
 Date of Photography: 03/07/20
 Scale of Photography: 1:20000
 Survey control derived from existing 1:20000 photography
 Survey control based on: UTM Projection, NAD27
 Compiled by The ORTHOSHOP, Calgary, September 2003
 WO 8856




Fig 4. Original Source: Figure 2 2011 Geotechnical Inspection, Waste and Water Management Facilities Vangorda/Grum

SRK Consulting
 Engineers and Scientists
 Vancouver

SRK JOB NO.: 1CD009.003
 FILE NAME: site_plan.dwg

Denison Environmental Services

FARO MINE COMPLEX

FIGURE 4		
2010 Vangorda Annual Inspection		
General Arrangement Plan		
DATE:	APPROVED:	FIGURE:
Feb. 2011		2





FIGURE 5

Map Scale: 1:2500
 Contour Interval: 2m
 Date of Photography: 18/09/09
 Survey control derived from existing 1:20000 photography
 Survey control based on: UTM Projection, NAD27




2011 Vangorda Geotechnical Inspection		
VANGORDA PLATEAU SITE AIR PHOTO		
DATE: July 2011	APPROVED: PMH	FIGURE: 3

Fig. 5 Original Source: Figure 3 Photo-Rectified Mosaic, with Contours, of Vangorda Plateau Area SRK 2011. 2010 Annual Inspection - Waste and Water Management Facilities - Vangorda/Grum

SRK JOB NO.: 1CD009.005
 FILE NAME: site_plan_photos.dwg

FARO MINE COMPLEX



NOTES:
 1) ALL DIMENSIONS AND ELEVATIONS ARE IN METRES UNLESS OTHERWISE NOTED.



LEGEND:
 13878 MONITORING SURVEY PRISMS
 13912 SLOPE MOVEMENT OBSERVATIONS - REFERENCE BARS
 274 OBSERVATION POINTS FIXED LOCATION

Date: 1/29/2013 Time: 13:25:10 Scale: 1:2,585
 Filename: \\INT.KLOHN.COM\PROJDATA\WCR\M09770A03-GOVYUKON-2013 FARO_400 DRAWINGS\ANNUALREVIEW\FIG_6_FAROPIT.DWG

NOTES:
 1. ORIGINAL FIGURE PROVIDED BY GOLDER ASSOCIATES.
 2. SLOPE MOVEMENT OBSERVATIONS 15717, 15737, 15742 AND 13908 APPROXIMATELY LOCATED.

To be read with Klohn Crippen Berger report dated

SCALE

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.	CLIENT 	PROJECT FARO MINE COMPLEX ANNUAL REVIEW
		TITLE FARO PIT BRIM REFERENCE BARS AND SURVEY PRISMS
PROJECT No. M09770A03 01		FIGURE 6


KS9-14-110

LEGEND

- ⊕ SITE INVESTIGATION BOREHOLES
- INSTRUMENTATION BOREHOLES
- △ SURVEY CONTROL STATION (UNDERHILL ENGINEERING LTD)
- CD CANAL DYKE
- BS BACK SLOPE
- SP SPOIL PIPE
- CVDC CROSS VALLEY DAM CREST
- CVDB CROSS VALLEY DAM U/S BLANKET
- CVDT CROSS VALLEY DAM TOE
- CVDP CROSS VALLEY DAM CONSTRUCTION PIEZOMETER
- CVDS CROSS VALLEY DAM CONSTRUCTION SETTLEMENT PLATE
- ID INTERMEDIATE DAM
- IDP INTERMEDIATE DAM CONSTRUCTION PIEZOMETER
- INSTRUMENTATION MONITORED IN 2009
- PBI TAILINGS DAM
- BKI KLOHN LEONOFF PIEZOMETER
- SI SLOPE INDICATOR
- S INCREMENTAL SETTLEMENT
- V VERTICAL SETTLEMENT
- H HORIZONTAL SETTLEMENT
- T THERMISTOR STRING
- PP PNEUMATIC PIEZOMETER
- HP HYDRAULIC PIEZOMETER
- P01 MONITORING WELL INSTALLED IN 2001 BY GARTNER LEE LTD. (LOCATION APPROXIMATE)

NOTE APPROXIMATE LOCATION OF BH95-1, BH95-2, BH95-3, BH95-4-1, BH95-4-2 BY ACCORDANCE WITH INFORMATION SUPPLIED BY ROBERTSON GEOCONSULTANTS INC.

NOTE PLAN BASED ON SURVEYS BY UNDERHILL ENGINEERING LTD. WHITEHORSE, DONE DURING CONSTRUCTION, 1991. GRID SYSTEM DERIVED FROM THE METRIC EQUIVALENT OF THE MINE GRID SYSTEM, ASSUMING MINE GRID CO-ORD SUPPLIED BY CYPRUS ANVIL FOR STATION 78-17 (320.09mN, 3220.50mE). ELEVATIONS ARE WITH RESPECT TO THE NORTHWEST CORNER OF THE FLOOR SLAB INSIDE THE CYPRUS ANVIL PUMPHOUSE (1089.515m AS PROVIDED BY CYPRUS ANVIL).



NOTE: FIGURE 1 FROM GOLDER ASSOCIATES REPORT 992-2416 USED AS REFERENCE




FIGURE 7

Fig. 7 Original Source: Figure 2 - 2009 Geotechnical Evaluation and Instrumentation Review, Volume 1

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT. AUTHORIZATION FOR ANY USE AND/OR PUBLICATION OF THIS REPORT OR ANY DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS, THROUGH ANY FORM OF PRINT OR ELECTRONIC MEDIA, INCLUDING WITHOUT LIMITATION, POSTING OR REPRODUCTION OF SAME ON ANY WEBSITE, IS RESERVED PENDING BGC'S WRITTEN APPROVAL. IF THIS REPORT IS ISSUED IN AN ELECTRONIC FORMAT, AN ORIGINAL PAPER COPY IS ON FILE AT BGC ENGINEERING INC. AND THAT COPY IS THE PRIMARY REFERENCE WITH PRECEDENCE OVER ANY ELECTRONIC COPY OF THE DOCUMENT, OR ANY EXTRACTS FROM OUR DOCUMENTS PUBLISHED BY OTHERS.						SCALE: N/A DATE: FEB 2010 DRAWN: TMW DESIGNED: TMW CHECKED: HHH APPROVED: GWF		PROFESSIONAL SEAL:				PROJECT: 2009 ANNUAL GEOTECHNICAL EVALUATION AND INSTRUMENTATION REVIEW TITLE: DOWN VALLEY TAILINGS CONTAINMENT INSTRUMENT LOCATION 1 OF 2		
REV. DATE REVISION NOTES DRAWN CHECK APPR.						CLIENT:		PROJECT No.: 0762-002-05	FIGURE No.: 2			REV.: 0		




FIGURE 8

Fig. 8 Original Source: Figure 3 - 2009 Annual Geotechnical Evaluation and Instrumentation Review, Volume 1

<small>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT. AUTHORIZATION FOR ANY USE AND/OR PUBLICATION OF THIS REPORT OR ANY DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS, THROUGH ANY FORM OF PRINT OR ELECTRONIC MEDIA, INCLUDING WITHOUT LIMITATION, POSTING OR REPRODUCTION OF SAME ON ANY WEBSITE, IS RESERVED PENDING BGC'S WRITTEN APPROVAL. IF THIS REPORT IS ISSUED IN AN ELECTRONIC FORMAT, AN ORIGINAL PAPER COPY IS ON FILE AT BGC ENGINEERING INC. AND THAT COPY IS THE PRIMARY REFERENCE WITH PRECEDENCE OVER ANY ELECTRONIC COPY OF THE DOCUMENT, OR ANY EXTRACTS FROM OUR DOCUMENTS PUBLISHED BY OTHERS.</small>					
REV.	DATE	REVISION NOTES	DRAWN	CHECK	APPR.

SCALE:	N/A
DATE:	FEB 2010
DRAWN:	TMW
DESIGNED:	TMW
CHECKED:	HHH
APPROVED:	GWG



PROFESSIONAL SEAL:

BGC ENGINEERING INC.
AN APPLIED EARTH SCIENCES COMPANY

CLIENT:

PROJECT: 2009 ANNUAL GEOTECHNICAL EVALUATION AND INSTRUMENTATION REVIEW		
TITLE: DOWN VALLEY TAILINGS CONTAINMENT INSTRUMENT LOCATION 2 OF 2		
PROJECT No.: 0762-002-05	FIGURE No.: 3	REV.: 0

K:\Projects\0762-002-005 Annual Inspection And Report\05 Reporting\Graphics\Workspaces\0762-002-005 Fig 18.dwg Layout: Plan And Sections Plot Date Feb 18 10 Time: 12:11 PM



- Screened Intervals of Standpipe Piezometers
- ▬ Bottom of Standpipe Piezometers
- Pneumatic Piezometer Tips
- Crest Piezometers
- Downstream Toe Piezometers






Fig. 9 Original Source: Figure 18 - 2009 Annual Geotechnical Evaluation and Instrumentation Review, Volume 1

FIGURE 9

REV.	DATE	REVISION NOTES	DRAWN	CHECK	APPR.

SCALE:	AS SHOWN
DATE:	FEB 2010
DRAWN:	JL
DESIGNED:	TMW
CHECKED:	HHH
APPROVED:	GWF

PROFESSIONAL SEAL:



BGC

ENGINEERING INC.

AN APPLIED EARTH SCIENCES COMPANY


CLIENT:

PROJECT: 2009 ANNUAL GEOTECHNICAL EVALUATION AND INSTRUMENTATION REVIEW		
TITLE: SECTION VIEW OF INTERMEDIATE DAM		
PROJECT No.: 0762-002-05	FIGURE No.: 18	REV.: 0



- [SP] Standpipe Piezometers
- [PP] Pneumatic Piezometers
- [T] Thermistor Cables
- [□] Screened Intervals of Standpipe Piezometers
- [⊥] Bottom of Standpipe Piezometers
- [▽] Pneumatic Piezometer Tips
- [△] Thermistor Nodes

Cross Valley Dam - Cross-Section D - D'



Cross Valley Dam - Cross-Section F - F'




FIGURE 10

Fig. 10 Original Source: Figure 24 - 2009 Geotechnical Evaluation and Instrumentation Review, Volume 1

<small>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT. AUTHORIZATION FOR ANY USE AND/OR PUBLICATION OF THIS REPORT OR ANY DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS, THROUGH ANY FORM OF PRINT OR ELECTRONIC MEDIA, INCLUDING WITHOUT LIMITATION, POSTING OR REPRODUCTION OF SAME ON ANY WEBSITE, IS RESERVED PENDING BGC'S WRITTEN APPROVAL. IF THIS REPORT IS ISSUED IN AN ELECTRONIC FORMAT, AN ORIGINAL PAPER COPY IS ON FILE AT BGC ENGINEERING INC. AND THAT COPY IS THE PRIMARY REFERENCE WITH PRECEDENCE OVER ANY ELECTRONIC COPY OF THE DOCUMENT, OR ANY EXTRACTS FROM OUR DOCUMENTS PUBLISHED BY OTHERS.</small>					
REV.	DATE	REVISION NOTES	DRAWN	CHECK	APPR.

SCALE:	N/A
DATE:	FEB 2010
DRAWN:	TMW
DESIGNED:	TMW
CHECKED:	HHH
APPROVED:	GWF


PROFESSIONAL SEAL:

BIGC **BGC ENGINEERING INC.**
AN APPLIED EARTH SCIENCES COMPANY







CLIENT:

PROJECT: 2009 ANNUAL GEOTECHNICAL EVALUATION AND INSTRUMENTATION REVIEW		
TITLE: SECTION VIEW OF CROSS VALLEY DAM		
PROJECT No.: 0762-002-05	FIGURE No.: 24	REV.: 0

Date: 1/29/2013 Time: 13:25:10 Scale: 1:2,585
 Filename: \\INT.KLOHN.COM\PROJECTS\M09770A03-GOV\YUKON-2013 FARO_400 DRAWINGS\ANNUALREVIEW\FIG_11.DWG





LEGEND

-  ACCESS ROADS
-  STREAMS
-  POWER POLE
-  MP014 2014 SURVEY PRISM
-  MP005 2013 SURVEY PRISM
-  GP-N1 REFERENCE ROD

To be read with Klohn Crippen Berger report dated







AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.	CLIENT		PROJECT	FARO MINE COMPLEX ANNUAL REVIEW
			TITLE	GRUM PIT BRIM REFERENCE RODS AND SURVEY PRISMS
			PROJECT No.	M09770A03 01

KCB-R-MLD



FIGURE 12

LEGEND

-  Piezometer Location
-  Monitoring Well Location (2009)
-  Monitoring Well Location (1994)
-  Monitoring Well Location (2010)

Contour Interval: 2m
 Survey control based on: UTM Projection, NAD83
 Based on The ORTHOSHOP, Calgary, September 2003




Fig. 12 Original Source: Figure 4 - 2011 Geotechnical Inspection Waste and Water Management Facilities Vangorda/Grum



SRK JOB NO.: 1CD009.005
 FILE NAME: site_plan nod 83.dwg



FARO MINE COMPLEX

2011 Vangorda Geotechnical Inspection		
General Arrangement Plan Vangorda Waste Rock Dump		
DATE: July 2011	APPROVED: JK	FIGURE: 4

I:\01_SITES\FARO\2210_1CD009.005_Vangorda_2011_Geotech_Inspection\40_AutoCad\site_plan nod 83.dwg




FIGURE 13

2011 Vangorda Geotechnical Inspection

LITTLE CREEK DAM
 GENERAL ARRANGEMENT PLAN

srk consulting

SRK JOB NO.: 1CD009.005
 FILE NAME: FIG-10.dwg

Denison
 Environmental
 Services

FARO MINE COMPLEX

DATE: July 2011	APPROVED: PMH	FIGURE: 10
--------------------	------------------	---------------

Fig. 13 Original Source: Figure 10 - 2011 Geotechnical Inspection Waste and Water Management Facilities Vangorda/Grum





FIGURE 14

2011 Vangorda Geotechnical Inspection

LITTLE CREEK DAM
SECTION B-B



SRK JOB NO.: 1CD009.005

FILE NAME: FIG-11.dwg

FARO MINE COMPLEX

DATE: July 2011

APPROVED: PMH

FIGURE: 11

Fig. 14 Original Source: Figure 11 - 2011 Geotechnical Inspection Waste and Water Management Facilities Vangorda/Grum

APPENDIX I

2016 Select Site Photographs

Faro Pit

Spring 2016



Fall 2016



Photograph 1 Faro Pit from “eye-in-the-sky” (Looking at the North and East Walls). Similar conditions in spring and fall.

Faro Pit

Spring 2016




Fall 2016



Photograph 2 Faro Pit Northwest Wall and West Wall (from the Faro Creek Diversion Channel). Similar conditions in spring and fall.

Faro Creek Diversion Channel



Photograph 3 Faro Creek Diversion Overflow (FCO) Sump (looking west)

Faro Creek Diversion Channel



Photograph 4 Upper Faro Creek Diversion. Satisfactory conditions.

Faro Creek Diversion Channel



Photograph 5 **Vegetation and Slumping on the Faro Creek Diversion Ditch (Upstream of the FCD-4 Stream Gauge Station)**

North Valley Wall Interceptor Ditch



Photograph 6 Interceptor Ditch upstream of upper man-made reach at new weir location. Evidence of overtopping on right abutment.

North Valley Wall Interceptor Ditch



Photograph 7 Interceptor Ditch upper man-made reach - vegetation roots were removed in fall 2016. Erosion control measures should be implemented in spring 2017. Approximately 565 m from the diversion inlet.

North Valley Wall Interceptor Ditch



Photograph 8 Interceptor Ditch (Faro Creek) upstream side of the well access road. Satisfactory conditions. Approximately 255 m from the diversion inlet.

North Valley Wall Interceptor Ditch

Spring 2016



Fall 2016



Photograph 9 Middle reach of ditch – vegetation along ditch and dyke, vegetation to be cleared for capacity and visibility. Fall photo looking east. Similar conditions in spring and fall. Approximately 2000 m from the diversion inlet.

North Valley Wall Interceptor Ditch

Spring 2016



Fall 2016



Photograph 10 Slumping at the End of the Middle Reach. Similar conditions in spring and fall. Approximately 2150 m from the diversion inlet.

North Valley Wall Interceptor Ditch

Spring 2016



Fall 2016



Photograph 11 Culvert between middle reach to lower reach of ditch – water treatment release pipeline. Direct discharge in fall. Approximately 2600 m from the diversion inlet.

Rose Creek Diversion Channel

Spring 2016



Fall 2016



Photograph 12 Rose Creek Diversion Channel near Secondary Tailings Dam, looking downstream. Similar conditions in spring and fall.

Rose Creek Diversion Channel

Spring 2016



Fall 2016



Photograph 13 Rose Creek Diversion Channel back-slope slumping. Similar conditions in spring and fall.

Rose Creek Diversion Channel

Spring 2016



Fall 2016



Photograph 14 Rose Creek Diversion Channel flow gauge station downstream of Tailings Facility. Satisfactory conditions.

Rose Creek Diversion Channel

Spring 2016



Fall 2016



Photograph 15 Rose Creek Diversion Channel Back Slope Observation Location A.

Rose Creek Diversion Channel

Spring 2016



Fall 2016



Photograph 16 Rose Creek Diversion Channel Back Slope Observation Location B. Conditions similar in spring and fall.

Rose Creek Diversion Channel

Spring 2016



Fall 2016



Photograph 17 Rose Creek Diversion Channel Proposed Back Slope Observation Location C. Conditions similar in spring and fall.

Rose Creek Diversion Channel

Spring 2016



Fall 2016



Photograph 18 Rose Creek Diversion Channel Proposed Back Slope Observation Location D. Conditions similar in spring and fall.

North Fork and K8 Rock Drains



Photograph 19 North Fork Rock Drain upstream pool at access road. Satisfactory condition.

North Fork and K8 Rock Drains



Photograph 20 North Fork Rock Drain outlet, looking downstream. Satisfactory conditions. Possible location of new flow station shown.

North Fork and K8 Rock Drains

Spring 2016



Fall 2016



Photograph 21 K8 Rock Drain upstream pool. Satisfactory conditions.

North Fork and K8 Rock Drains

Spring 2016



Fall 2016



Photograph 22 K8 Rock Drain downstream outlet, looking down. Satisfactory conditions.

Secondary Tailings Dam

Spring 2016



Fall 2016



Photograph 23 Secondary Tailings Dam upstream ditch looking south. Ditch appears deeper since spring.

Secondary Tailings Dam

Spring 2016



Fall 2016



Photograph 24 Fuse plug of Canal Dyke, looking upstream. Vegetation on downstream slope of Secondary Tailings Dam should be removed.

Intermediate Dam

Spring 2016



Fall 2016



Photograph 25 Intermediate Dam from access road, looking south. Satisfactory conditions.

Intermediate Dam

Spring 2016



Fall 2016



Photograph 26 Intermediate Dam crest and upstream slope, looking north. Satisfactory Conditions.

Intermediate Dam



Photograph 27 Repairs along downstream slope. Some surface erosion since spring.

Intermediate Dam



Photograph 28 Spillway, looking downstream. Pipeline in the spillway was removed in Fall 2016.

Cross Valley Dam

Spring 2016



Fall 2016



Photograph 29 Downstream slope of Cross Valley Dam looking south. Some minor rill erosion and vegetation on slope. Conditions are similar across the whole slope.

Cross Valley Dam



Photograph 30 Freeze-thaw longitudinal cracks closed along dam crest, looking south. Crack is closed (not visible in photo) in fall.

Cross Valley Dam

Spring 2016



Fall 2016



Photograph 31 Upstream slope (looking north), vegetation growth. Trees should be removed.

Cross Valley Dam

Spring 2016



Fall 2016



Photograph 32 Siphon pipelines in spillway, looking downstream

Grum Pit

Spring 2016




Fall 2016



Photograph 33 Grum Pit (looking south, southeast). Similar conditions in spring and fall.

Grum Pit



Photograph 34 East pit wall along instability zone. Similar conditions in spring and fall.

Vangorda Pit



Photograph 35 Northwest pit wall adjacent to Vangorda Diversion Flume

Vangorda Pit

Fall 2016



Photograph 36 Vangorda Diversion Sinkhole showing signs of settlement.

Vangorda Rock Dump

Spring 2016



Fall 2016



Photograph 37 Drain No. 3 (V30). Satisfactory conditions.

Vangorda Rock Dump

Spring 2016



Fall 2016




Photograph 38 Drain No. 4 (V31). Satisfactory conditions.

Vangorda Rock Dump



Photograph 39 Drain No. 5 (V32). Pooling downstream of weir. Pond should be cleaned out so it doesn't backwater the weir.

Vangorda Rock Dump



Photograph 40 Drain No. 6 (V33). Satisfactory conditions.

Grum Pit Interceptor Ditch

Spring 2016




Fall 2016



Photograph 41 Wes' Pond. Satisfactory conditions.

Grum Pit Interceptor Ditch



Photograph 42 Vegetation clearing in the upper reach of Interceptor Ditch (Fall 2016). Slopes are susceptible to erosion.

Grum Pit Interceptor Ditch



Photograph 43 **Vegetation in the diversion**

North East Interceptor Ditch

Spring 2016



Fall 2016



Photograph 44 Slumping on road slope. Progressed slightly since spring.

North East Interceptor Ditch

Spring 2016



Fall 2016



Photograph 45 Slumping of side slopes. Similar conditions in spring and fall.

Vangorda Creek Diversion Flume



Photograph 46 Flume emergency spillway culvert entrance area (only one culvert shown).
Sediment in culvert.

Vangorda Creek Diversion Flume

Spring 2016



Fall 2016



Photograph 47 Vangorda Flume intake culvert upstream trashrack. Satisfactory conditions.

Vangorda Creek Diversion Flume



Photograph 48 Damaged flume and bent bracing rods

Vangorda Creek Diversion Flume

Spring 2016



Fall 2016



Photograph 49 Weight added to flume for anchoring

Vangorda Creek Diversion Flume

Spring 2016



Fall 2016



Photograph 50 Damaged flume, flat slope, and constricted channel

Vangorda Creek Diversion Flume



Photograph 51 Flat slope section, overtops during high flow

Vangorda Creek Diversion Flume



Photograph 52 Outlet to Flume Plunge Pool - trash rack. Leaves and woody debris accumulate on the trash rack and need to be removed as part of regular maintenance.

Little Creek Dam

Spring 2016



Fall 2016




Photograph 53 Little Creek Dam from the access road (looking west). Satisfactory conditions.

Little Creek Dam

Spring 2016



Fall 2016



Photograph 54 Little Creek Dam downstream slope after vegetation removal (on left abutment, looking north).

Little Creek Dam

Spring 2016 – looking north



Fall 2016 – looking south



Photograph 55 Little Creek Dam downstream toe. Vegetation has been removed since spring. Slope is subject to erosion and should be repaired and stabilized.

Little Creek Dam

Spring 2016



Fall 2016



Photograph 56 Little Creek Dam upstream slope, repaired rill erosion. Minor vegetation.

Little Creek Dam

Spring 2016



Fall 2016



Photograph 57 Rill erosion on downstream berm slopes. To be graded in the fall and revegetated in the spring.

Little Creek Dam

Spring 2016



Fall 2016



Photograph 58 Ground slope crack across downstream spillway channel near discharge end. Similar conditions in spring and fall.

Sheep Pad Sediment Ponds

Spring 2016



Fall 2016



Photograph 59 Upper end of spillway from the Upper to Lower Sediment Pond. Boulders impeding flow.

Sheep Pad Sediment Ponds



Photograph 60 Outflow of Sediment Pond upstream of Plunge Pool. Satisfactory conditions.

Freshwater Pond

Spring 2016



Fall 2016



Photograph 61 Pond spillway channel, looking downstream towards Grum Interceptor Ditch. Trees on embankment and in spillway should be removed.

V-15 Seepage Collection Ditch and Moose Pond



Photograph 62 Sand bags and bentonite are blocking most of the seepage to Moose Pond.

V-15 Seepage Collection Ditch and Moose Pond



Photograph 63 V-15 ditch and pumps, water pumped out before reaching Moose Pond

V-15 Seepage Collection Ditch and Moose Pond



Photograph 64 Moose Pond Esker downstream slope. Similar conditions in spring and fall.

V-15 Seepage Collection Ditch and Moose Pond



Photograph 65 Moose Pond. Satisfactory conditions.

Vangorda Water Treatment Plant Clarification Pond

Spring 2016 – Looking west



Fall 2016 – looking east



Photograph 66 Clarification pond, dyke crest and downstream slope. Some trees to be removed.

Vangorda Water Treatment Plant Clarification Pond

Spring 2016



Fall 2016



Photograph 67 Clarification pond upstream slope (looking west)

Vangorda Water Treatment Plant Clarification Pond



Photograph 68 Clarification pond, longitudinal freeze-thaw cracks. Not as evident in the fall.

APPENDIX II

Instrumentation Plots and Data


Instrumentation Plots and Data

Site	Appendix: Structure	Data	Section	
Faro	II-A: Faro Pit	Pond Level	A1	
	II-B: Faro Creek Diversion Channel	Staff Gauge Calibrations	B1	
		Staff Gauge Flows	B2	
	II-C: North Wall Interceptor Ditch	Staff Gauge Flows	C1	
	II-D: Rose Creek Diversion Channel	Staff Gauge Calibrations	D1	
		Staff Gauge Flows	D2	
	II-E: Canal Dyke	Piezometers	E1	
		Thermistors	E2	
		Inclinometers	E3	
	II-F: North Fork Rock Drain	Water Level and Downstream Flow	F1	
	II-G: Secondary Dam	Piezometers	G1	
	II-H: Intermediate Dam	Pond Level	H1	
		Piezometers	H2	
	II-I: Cross Valley Dam	Pond Level	I1	
Piezometers		I2		
Thermistors		I3		
Downstream Weir Flows		I4		
Vangorda Plateau	II-J: Grum Pit	Pond Level	J1	
		Slot Cut Piezometers	J2	
	II-K: Vangorda Pit	Pond Level	K1	
		Weir Flows	L1	
	II-L: Vangorda Waste Rock Dump	Piezometers	L2	
		II-M: Little Creek Dam	Pond Level	M1
			Piezometers	M2
	Thermistors	M3		
II-N: Moose Pond	Pond Level	N1		
Faro Airport	II-O: Faro Airport Climate	Monthly Precipitation/Temperature	O1	



APPENDIX II-A

Faro Pit

A1 - Pond Level




Notes:
 1. Pit bottom is approximately El. 1050 m.



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.	CLIENT 	PROJECT FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW	
		TITLE FARO PIT WATER LEVEL	
		PROJECT No. M09770A06	FIG No. II-A1-1


APPENDIX II-B



Faro Creek Diversion Channel


B1 – Staff Gauge Calibrations
B2 – Staff Gauge Flows






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-1 RATING CURVE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B1-1</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-2 RATING CURVE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B1-2</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-3 RATING CURVE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B1-3</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-4 RATING CURVE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B1-4</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-1 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B2-1</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-1 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B2-2</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-2 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B2-3</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-2 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B2-4</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-3 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B2-5</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-3 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B2-6</p>



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-4 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B2-7</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO CREEK DIVERSION CHANNEL FCD-4 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-B2-8</p>

APPENDIX II-C

North Valley Wall Interceptor Ditch

C1 – Staff Gauge Flows






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>NORTH WALL INTERCEPTOR DITCH STAFF GAUGE FLOWS</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-C1-1</p>


APPENDIX II-D



Rose Creek Diversion Channel


D1 – Staff Gauge Calibrations
D2 – Staff Gauge Flows






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	CLIENT	PROJECT	
		FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW	
		TITLE	
		ROSE CREEK NFRD-2B RATING CURVE	
		PROJECT No.	FIG No.
		M09770A06	II-D1-1






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	CLIENT	PROJECT	
		FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW	
		TITLE	
		ROSE CREEK RCDC-4 RATING CURVE	
		PROJECT No.	FIG No.
		M09770A06	II-D1-2






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK X14 RATING CURVE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-D1-3</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK NFRD-2B CALCULATED DISCHARGE</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-D2-1</p>	





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK NFRD-2B CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-D2-2</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK RCDC-4 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-D2-3</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK RCDC-4 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-D2-4</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK X10 MEASURED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-D2-5</p>



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK X14 CALCULATED DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-D2-6</p>




No data available for 2014 and 2015



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK X14 CALCULATED DISCHARGE</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-D2-7</p>	


APPENDIX II-E



Canal Dyke


- E1 – Piezometers
- E2 – Thermistors (Thawed thermistors not included)
- E3 – Inclinerometers






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK DIVERSION CHANNEL CANAL DYKE PIEZOMETERS BGC05-02 & BGC05-03</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-E1-1</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK DIVERSION CHANNEL CANAL DYKE PIEZOMETERS BGC05-06</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-E1-2</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK DIVERSION CHANNEL CANAL DYKE PIEZOMETERS CD-13</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-E1-3</p>	






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK DIVERSION CHANNEL CANAL DYKE PIEZOMETERS CD-15</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-E1-4</p>	






Notes:
1. CD-21-D destroyed in 2005.


<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK DIVERSION CHANNEL CANAL DYKE PIEZOMETERS CD-21</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-E1-5</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK DIVERSION CHANNEL CANAL DYKE PIEZOMETERS CD-26</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-E1-6</p>




<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK DIVERSION CHANNEL BACK SLOPE PIEZOMETERS BS-5</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-E1-7</p>



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>ROSE CREEK DIVERSION CHANNEL BACK SLOPE PIEZOMETERS BS-9</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-E1-8</p>




Diversion Canal (Backslope) Thermistor BS-5






Diversion Canal (Backslope) Thermistor BS-9






Diversion Canal (Backslope) Thermistor BS-10






Diversion Canal (Backslope) Thermistor BS-12




Klohn Crippen Berger Ltd. - Vancouver BC



91CD-1, Inclinator 1+767


Sets marked * include zero shift and/or rotation corrections.

Klohn Crippen Berger Ltd. - Vancouver BC




Canal Dyke, Inclinometer BGC05-05

Klohn Crippen Berger Ltd. - Vancouver BC



Canal Dike, Inclinometer BGC05-08

Klohn Crippen Berger Ltd. - Vancouver BC




BS-10, Inclinator 1+900

Denison Environmental Service


Sets marked * include zero shift and/or rotation corrections.

Klohn Crippen Berger Ltd. - Vancouver BC



Backslope, Inclinator BS-5

Klohn Crippen Berger Ltd. - Vancouver BC




BS-9, Inclinator 1+530

Denison Environmental Service

Sets marked * include zero shift and/or rotation corrections.



Klohn Crippen Berger Ltd. - Vancouver BC



CD-10, Inclinator 0+990


Sets marked * include zero shift and/or rotation corrections.

Klohn Crippen Berger Ltd. - Vancouver BC





Canal Dyke, Inclinator CD-15

Klohn Crippen Berger Ltd. - Vancouver BC



Canal Dyke, Inclinator CD-21

Klohn Crippen Berger Ltd. - Vancouver BC






Spoil Pile, Inclinometer SP-2

APPENDIX II-F

North Fork Rock Drain

F1 – Water Level and Downstream Flow






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>NORTH FORK ROCK DRAIN WATER LEVEL AND DOWNSTREAM FLOW</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-F1-1</p>


APPENDIX II-G



Secondary Dam


G1 – Piezometers






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>SECONDARY DAM PIEZOMETERS P81-06</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-G1-1</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>SECONDARY DAM PIEZOMETERS P81-07</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-G1-2</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>SECONDARY DAM PIEZOMETERS P81-08</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-G1-3</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>SECONDARY DAM PIEZOMETERS P03-01</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-G1-4</p>



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>SECONDARY DAM PIEZOMETERS P03-02</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-G1-5</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>SECONDARY DAM PIEZOMETERS P03-03</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-G1-6</p>


APPENDIX II-H



Intermediate Dam


H1 – Pond Level (Intermediate Pond)
H2 – Piezometers






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM POND LEVEL</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H1-1</p>	





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS BH91-ID3</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-1</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	CLIENT	PROJECT	
		FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW	
		TITLE	INTERMEDIATE DAM PIEZOMETERS BH91-ID4
		PROJECT No.	FIG No.
		M09770A06	II-H2-2






Notes:
 1. Instruments not functioning. No valid readings have been reported.


<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS BH91-ID5</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-3</p>	






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS BH91-ID6</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-4</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS BH91-ID7</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-5</p>	






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS BH94-IDC-1</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-6</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS BH96-1</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-7</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	CLIENT	PROJECT	
		<p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		TITLE	
		<p>INTERMEDIATE DAM PIEZOMETERS BH96-2</p>	
		PROJECT No.	FIG No.
		M09770A06	II-H2-8






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS BH96-3</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-9</p>	






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS BH96-4</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-10</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS P01-03</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-11</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS P01-04</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-12</p>	



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	CLIENT	PROJECT	
	 	FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW	
		TITLE	
		INTERMEDIATE DAM PIEZOMETERS BKS04-06	
		PROJECT No.	FIG No.
		M09770A06	II-H2-13






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>INTERMEDIATE DAM PIEZOMETERS BKS04-07</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-H2-14</p>


APPENDIX II-I



Cross Valley Dam


- I1 – Pond Level
- I2 – Piezometers
- I3 – Thermistors (Not included)
- I4 – Downstream Weir Flows





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM POND LEVEL</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-11-1</p>	






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM PIEZOMETERS 94-CVDC-1</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-12-1</p>






Notes:
 1. CVDC-4-S Blocked. No valid readings have been reported.


AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.	CLIENT 	PROJECT FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW	
		TITLE CROSS VALLEY DAM PIEZOMETERS CVDC-4	
		PROJECT No. M09770A06	FIG No. II-12-2






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM PIEZOMETERS CVDC-7</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-12-3</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM PIEZOMETERS CVDC-9</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-12-4</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM PIEZOMETERS CVDT-1</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-I2-5</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM PIEZOMETERS CVDT-2</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-12-6</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM PIEZOMETERS CVDP-1</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-12-7</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM PIEZOMETERS CVDP-3</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-12-8</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM PIEZOMETERS CVDP-5</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-12-9</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM PIEZOMETERS CVDP-6</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-12-10</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM PIEZOMETERS P01-11</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-12-11</p>



Cross Valley Dam Thermistor BH 88-4









<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM X11 DISCHARGE</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-14-1</p>	






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM X11 DISCHARGE</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-14-2</p>	






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM X12 DISCHARGE</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-14-3</p>	






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM X12 DISCHARGE</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-14-4</p>	






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM X13 DISCHARGE</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-14-5</p>	





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM X13 DISCHARGE</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-14-6</p>	



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM WEIR 3 DISCHARGE</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-14-7</p>	




<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>CROSS VALLEY DAM WEIR 3 DISCHARGE</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-14-8</p>	



APPENDIX II-J


Grum Pit



J1 – Pond Level
J2 – Slot Cut Piezometers



Notes:
 1. Pit bottom is approximately El. 1135 m.

<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>GRUM PIT POND LEVEL</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-J1-1</p>	




<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>GRUM PIT SLOT CUT PIEZOMETERS SRK09-GS</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-J2-1</p>



APPENDIX II-K

Vangorda Pit

K1 – Pond Level




Notes:
 1. Pit bottom is approximately El. 1040 m.



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	CLIENT	PROJECT	
		FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW	
		TITLE	VANGORDA PIT POND LEVEL
		PROJECT No.	FIG No.
		M09770A06	II-K1-1


APPENDIX II-L



Vangorda Waste Rock Dump


L1 – Weir Flows
L2 – Piezometers






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP V29 DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L1-1</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP V30 DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L1-2</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP V31 DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L1-3</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP V32 DISCHARGE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L1-4</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	CLIENT	PROJECT	
		<p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		TITLE	
		<p>VANGORDA WASTE ROCK DUMP V33 DISCHARGE</p>	
		PROJECT No.	FIG No.
		M09770A06	II-L1-5






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP PIEZOMETERS GW-94-01 (V34)</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L2-1</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP PIEZOMETERS GW-94-02 (V35)</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L2-2</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP PIEZOMETERS GW-94-03 (V36)</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L2-3</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP PIEZOMETERS GW-94-04 (V37)</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L2-4</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP PIEZOMETERS P-94-01 (V39, V40)</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L2-5</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP PIEZOMETERS P94-02 (V41, V42, V43)</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L2-6</p>





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP PIEZOMETERS P-94-03 (V44, V45)</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L2-7</p>





Notes:
 1. P-94-04A (V46) broken. No records available.

<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP PIEZOMETERS P-94-04 (V47)</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L2-8</p>



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP PIEZOMETERS P2001-02, P2001-03</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L2-9</p>	






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>VANGORDA WASTE ROCK DUMP PIEZOMETERS PW-10-01 (DH1), PW-10-02 (DH2), PW-10-03 (DH3), PW-10-04 (DH4), PW-10-05 (DH5)</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-L2-10</p>


APPENDIX II-M



Little Creek Dam


M1 – Pond Level
M2 – Piezometers
M3 – Thermistors






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>LITTLE CREEK DAM POND LEVEL</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-M1-1</p>






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>LITTLE CREEK DAM PIEZOMETERS BH91-LCD1</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-M2-1</p>	





<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>LITTLE CREEK DAM PIEZOMETERS BH91-LCD2</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-M2-2</p>	




<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>LITTLE CREEK DAM PIEZOMETERS BH91-LCD3</p>	
	<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-M2-3</p>	




<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>LITTLE CREEK DAM PIEZOMETERS P09-LCD-1, P09-LCD-2, P09-LCD-3, P09-LCD-4, P09-LCD-6, P09-LCD-7</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-M2-3</p>


Little Creek Dam Thermistor BH94 LCD4



Little Creek Dam Thermistor BH94 LCD5




Little Creek Dam Thermistor BH94 LCD6





APPENDIX II-N

Moose Pond

N1 – Pond Level






<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>MOOSE POND POND LEVEL</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-N1-1</p>


APPENDIX II-O



Faro Airport Climate

O1 – Monthly Precipitation/Temperature



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO AIRPORT CLIMATE STATION MEAN MONTHLY TEMPERATURE</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-O1-1</p>



<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC, AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT, AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS, OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>	<p>CLIENT</p> 	<p>PROJECT</p> <p>FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p>	
		<p>TITLE</p> <p>FARO AIRPORT CLIMATE STATION MONTHLY PRECIPITATION</p>	
		<p>PROJECT No.</p> <p>M09770A06</p>	<p>FIG No.</p> <p>II-O1-2</p>

APPENDIX III

Instrumentation Summary and Monitoring Frequency

Appendix III Instrumentation Summary and Monitoring Frequency

This appendix summarizes the monitoring frequency for instruments at the Faro Mine Complex, as recommended in the 2016 Annual Review report. Also included are tables of known instruments and their status. Instrument locations for the Cross Valley Dam, Intermediate Dam, Secondary Dam, Rose Creek Diversion, Little Creek Dam and Vangorda Waste Rock Dump are shown in Figures III-1 to III-4.

III-1 INSTRUMENTATION MONITORING FREQUENCY

Table III-1 Instrumentation Monitoring Frequency

		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
Rose Creek Diversion Channel													
Thermistors	Canal Dyke: CD-10, CD-15, CD-21, CD-26, BGC05-04, BGC05-07						M						
	Spoil Pile: SP-2, SP-3, SP-5						M						
	Back Slope: BS-5, BS-9, BS-10, BS-12						M			M			
Inclinometers	Canal Dyke: CD-10, -15, -21. BH91-CD1, BGC05-05, -08.	One successful reading for all inclinometers											
	Spoil Pile: SP-2	One successful reading for all inclinometers											
	Back Slope: BS-5, BS-9, BS-10	Two successful readings for all inclinometers: one in spring/summer, the other in fall											
Piezometers	Canal Dyke: CD-13(D), -15, -21(S), -26. BGC05-02, -03, -06.					M	M			M			
	Back Slope: BS-5, BS-9					M	M			M			
Staff Gauges	RCDC-4				Daily	Daily	Daily	W	W	W			
Flows	RCDC-4 (Obtain one reading during high flow at freshet)				M	M	M	M	M	M	M		
Cross Valley Dam													
Piezometers	CVDC-4(D), -7(D), -9. CVDT-2. CVDP-1, -5, -6. 94 CVDC-1, P01-11					M	M			M			
Weir Flows	X11, X12, X13, Weir 3	W	W	W	W	W	W	W	W	W	W	W	W
Elevations	Polishing Pond	W	W	W	W	W	W	W	W	W	W	W	W
Visual Inspection	Visual Inspections of dam and spillway as required in the water license.	W	W	W	W	W	W	W	W	W	W	W	W
Intermediate Dam													
Piezometers	91ID-3, -4(D). 94-IDC-1, 96-1, -2, -3(A), -4(A, D). BKS04-06, -07.					M	M			M			
Observe	Seepage observations near south abutment					M	M		M	M			
Elevations	Intermediate Pond	W	W	W	W	W	W	W	W	W	W	W	W
Visual Inspection	Visual Inspections of the dam and spillway.	W	W	W	W	W	W	W	W	W	W	W	W
Secondary Dam													
Piezometers	P81-6, P81-7, P81-8, P03-01, P03-02, P03-03					M	M			M			
North Fork Rock Drain													
Data Loggers	NFRD2B (Relocate NFRD2B or establish new staff gauge downstream)				M	M	M	M	M	M	M		
Staff Gauges	NFRD2B, X2 (Relocate NFRD2B or establish new staff gauge downstream)				Daily	Daily	W	W	M	M	M		
Flows	NFRD2B, X2				M	M	M	M	M	M	M		
Water Elevation	NF1					W	W	W	TAM	TAM			
Observe	NF1, NF2	M	M	M	M	M	M	M	M	M	M	M	M
K8 Rock Drain													
Observe						M	M	M					
Faro Creek Diversion Channel													
Staff Gauges	FCD-1, FCD-2, FCD-3, FCD-4				TAM	TAM	M	M	M	M	M		
Flows	FCD-1, FCD-2, FCD-3, FCD-4				TAM	TAM	M	M	M	M	M		
Faro Pit													
Observe	Faro Pit	M	M	M	M	M	M	M	M	M	M	M	M
Grum Pit													
Observe	Grum Pit Wall	M	M	M	M	M	M	M	M	M	M	M	M
Vangorda Pit													
Observe	Vangorda Pit Wall	M	M	M	M	M	M	M	M	M	M	M	M
Vangorda Waste Rock Dump													
Observe	Weirs: V28, V29, V30, V31, V32, V33					M	M	M	M	M	M		
	Drainage Ditch						M						
	Northeast Dump Crest						M						
Flows	V29, V30, V31, V32, V33					M	M	M	M	M	M		
Piezometers	V39, 40, 41, 42, 43, 44, 45, 47. PW-10-01, -02, -03, -04, -05.					M				M			
Standpipe Data Loggers	PW-10-01, -02, -03, and -05 (DH1, DH2, DH3, DH5)					M				M			
Little Creek Dam													
Piezometers	BH94 LCD-2, -3, P09-LCD-1, -2, -3, -4, -6, -7					M				M			
Visual Inspection	Visual inspections of the dam and spillway.	W	W	W	W	W	W	W	W	W	W	W	W
Vangorda Creek Diversion													
Observe	Trash rack at headworks				M	M	M	M	M	M			
	Seepage collection pond				M	M	M						
	Side Slopes Above Flume					M	M						
Sludge Pond Embankment													
Observe	Downstream slopes and embankment				M	M				M			
Fresh Water Pond													
Observe	Spillway from Fresh Water Pond to Grum Interceptor Ditch					M				M			
Grum Interceptor Ditch and Sheep Pad Pond													
Observe	Outlets / Inlets to Ditch				M	M				M			
	Sheep Pad Pond Dyke				M	M				M			

Note:
M – Monthly
W – Weekly
TAM – Twice a month

III-2 KNOWN INSTRUMENTATION SUMMARY

Table III-2 Inclinerometer Summary

Area	Instrument Name	Easting (m) (NAD27 UTM)	Northing (m) (NAD27 UTM)	Bottom Depth (m)	Reading Start Depth (m)	Status	Comments
Cross Valley Dam	BH91-CD1	581,007	6,913,352	11.25	11	Functioning	
	BH94CD-1	580,533	6,913,591	2.5		Not functioning	
Rose Creek Diversion Channel	BGC05-05	580,859	6,913,424	11.75	11.5	Functioning	
	BGC05-08	580,701	6,913,521	12.75	13	Functioning	Keep reading with bottom depth of 12.5 m.
	BS-5	581,740	6,913,008	10.4	10	Functioning	
	BS-9	581,216	6,913,254	10.35	10	Functioning	
	BS-10	580,856	6,913,363	10.4	10	Functioning	
	CD-10	581,723	6,913,066	10.4	10	Functioning	
	CD-15	581,218	6,913,289	9.6	9.5	Functioning	
	CD-19	580,892	6,913,410	3.5	10	Not functioning	
	CD-21	580,703	6,913,504	10.05	10	Functioning	
	SP-2	581,263	6,913,326	7.25	7	Functioning	
	SP-5	580,236	6,913,773			Questionable	Pipe broken below ground surface.

Table III-3 Standpipe Piezometer Summary

Area	Instrument	Easting (m) (NAD27 UTM)	Northing (m) (NAD27 UTM)	Top of Casing Elevation (m)	Screen Top Depth (m)	Screen Bottom Depth (m)	Status	Comment
Cross Valley Dam	94-CVDC-1	580,253	6,914,336	1034.02		13.0	Functioning	
	CVDC-4-D	580,256	6,914,340	1033.60		33.9	Functioning	
	CVDC-4-S	580,256	6,914,340	1033.41		25.5	Not functioning	Blocked at 7.6 m
	CVDC-7-D	580,149	6,914,132	1033.47		30.6	Functioning	
	CVDC-7-S	580,149	6,914,132	1033.55		25.8	Questionable	Slow response to falling head test
	CVDC-9-D	580,097	6,914,028	1033.47		32.8	Functioning	
	CVDC-9-S	580,097	6,914,028	1033.55		25.8	Functioning	
	CVDT-1	580,208	6,914,362	1018.57		10.7	Not functioning	
	CVDT-2	580,091	6,914,157	1019.83		13.6	Functioning	
	P01-02	580,066	6,914,048				Questionable	Not measured recently
	P01-11	580,199	6,914,312	1017.87		10.6	Functioning	
P03-09	580,059	6,914,210	1018.53			Unknown	Not measured recently	
Grum Pit	SRK09-GSA	592,621	6,904,684				Functioning	
	SRK09-GSB	592,631	6,904,684				Functioning	
Intermediate Dam	BH94-IDC-1	580,595	6,913,975	1049.48		14.0	Functioning	
	BH96-1	580,552	6,913,924	1049.83	18.8	21.8	Functioning	
	BH96-2	580,686	6,914,105	1049.94	17.1	20.1	Functioning	
	BH96-3-A	580,520	6,913,947	1032.13	7.4	9.0	Functioning	
	BH96-3-B	580,520	6,913,947	1032.07	17.7	19.2	Questionable	Slow response to falling head test
	BH96-4-A	580,653	6,914,125	1033.11	5.7	6.5	Functioning	
	BH96-4-B	580,653	6,914,125	1033.03	9.8	11.3	Questionable	Blocked at El. 1029 m
	BH96-4-C	580,653	6,914,125	1033.07	15.0	16.5	Questionable	Blocked at El. 1020 m
	BH96-4-D	580,653	6,914,125	1033.04	26.8	28.3	Functioning	
	BKS04-06	580,457	6,913,803	1050.61	12.8	13.1	Functioning	
	BKS04-07	580,408	6,913,750	1050.71	11.5	11.8	Functioning	
	P01-03	580,627	6,914,077	1032.13	7.8	9.3	Questionable	Slow response to falling head test
	P01-04-A	580,484	6,913,899	1032.77	31.7	33.2	Not functioning	
P01-04-B	580,484	6,913,899	1032.77	51.0	52.5	Questionable	Slow response to falling head test	

Area	Instrument	Easting (m) (NAD27 UTM)	Northing (m) (NAD27 UTM)	Top of Casing Elevation (m)	Screen Top Depth (m)	Screen Bottom Depth (m)	Status	Comment
	P03-08	580,969	6,913,520	1048.42			Unknown	Not measured recently
Little Creek Dam	P09-LCD-1	593,483	6,903,144	1097.53			Functioning	
	P09-LCD-2	593,476	6,903,139	1097.69			Functioning	
	P09-LCD-3	593,456	6,903,114	1093.71			Functioning	
	P09-LCD-4	593,441	6,903,094	1093.68			Functioning	
	P09-LCD-6	593,426	6,903,064	1096.21			Functioning	
	P09-LCD-7	593,431	6,903,014	1101.68			Functioning	
Secondary Dam	P03-01	583,288	6,912,588	1061.11			Functioning	
	P03-02	583,121	6,912,578	1060.59			Functioning	
	P03-03	583,056	6,912,705	1061.49			Functioning	
	P03-04	582,066	6,913,189	1061.30			Unknown	Not measured recently
	P03-06	582,561	6,913,314	1062.90			Unknown	Not measured recently
	P81-06	582,790	6,912,686	1060.87		6.0	Questionable	Slow response to falling head test
	P81-07	583,221	6,912,421	1064.08		6.1	Functioning	
	P81-08	583,323	6,912,405	1064.00		7.5	Functioning	
Vangorda Waste Rock Dump	GW-94-01 (V34)	593,538	6,902,300	1117.45			Functioning	
	GW-94-02 (V35)	593,287	6,902,379	1117.41			Functioning	
	GW-94-03 (V36)	593,244	6,902,741	1118.43			Functioning	
	GW-94-04 (V37)	593,425	6,902,906	1116.17			Functioning	
	GW-94-05 (V38)			1101.67			Unknown	Not measured recently
	P2001-02A	593,241	6,902,689	1122.78			Unknown	
	P2001-02B	593,241	6,902,689	1122.77			Unknown	
	P2001-03	593,206	6,902,706	1120.00			Unknown	
	P-94-01A (V39)	593,356	6,902,429	1136.56			Functioning	
	P-94-01B (V40)	593,356	6,902,429	1136.49			Functioning	
	P-94-02A (V41)	593,278	6,902,572	1138.41			Functioning	
	P-94-02B (V42)	593,278	6,902,562	1138.33			Functioning	
	P-94-02C (V43)	593,255	6,902,528	1129.84			Functioning	
	P-94-03A (V44)	593,485	6,902,800	1134.37			Functioning	

Area	Instrument	Easting (m) (NAD27 UTM)	Northing (m) (NAD27 UTM)	Top of Casing Elevation (m)	Screen Top Depth (m)	Screen Bottom Depth (m)	Status	Comment
	P-94-03B (V45)	593,475	6,902,790	1134.46			Questionable	Slow response to falling head test
	P-94-04A (V46)	593,667	6,902,901				Not functioning	
	P-94-04B (V47)	593,657	6,902,891	1134.33			Functioning	
	PW-10-01 (DH1)	593,683	6,902,847	1149.08			Functioning	
	PW-10-02 (DH2)	593,318	6,902,638	1139.30			Functioning	
	PW-10-03 (DH3)	593,327	6,902,494	1137.72			Functioning	
	PW-10-04 (DH4)	593,849	6,902,319	1141.69			Questionable	Slow response to falling head test
	PW-10-05 (DH5)	593,631	6,902,510	1180.39			Functioning	

Table III-4 Pneumatic Piezometer Summary

Area	Instrument	Easting (m) (NAD27 UTM)	Northing (m) (NAD27 UTM)	Tip Elevation (m)	Status	Comment
Cross Valley Dam	CVDP-1	580,115	6,914,145	1014.51	Functioning	
	CVDP-3	580,115	6,914,145	1014.71	Not functioning	
	CVDP-5	580,221	6,914,362	1014.28	Functioning	
	CVDP-6	580,221	6,914,362	1014.37	Functioning	
Intermediate Dam	BH91-ID3-D	580,345	6,913,726	1028.62	Functioning	
	BH91-ID3-S	580,345	6,913,726	1036.82	Functioning	
	BH91-ID4-D	580,505	6,913,925	1017.08	Functioning	
	BH91-ID4-S	580,505	6,913,925	1024.22	Questionable	
	BH91-ID5-D	580,472	6,913,862	1017.08	Not functioning	
	BH91-ID5-S	580,472	6,913,862	1024.30	Not functioning	
	BH91-ID6-D	580,461	6,913,877	1016.90	Not functioning	
	BH91-ID6-S	580,461	6,913,877	1024.80	Not functioning	
Little Creek Dam	BH94-LCD1-D	593,453	6,902,995	1097.00	Functioning	
	BH94-LCD1-S	593,453	6,902,995	1103.60	Questionable	No bubbles returned.
	BH94-LCD2-D	593,476	6,903,064	1094.90	Functioning	
	BH94-LCD2-S	593,476	6,903,064	1100.50	Functioning	


Area	Instrument	Easting (m) (NAD27 UTM)	Northing (m) (NAD27 UTM)	Tip Elevation (m)	Status	Comment
	BH94-LCD3-D	593,524	6,903,122	1101.20	Functioning	
	BH94-LCD3-S	593,524	6,903,122	1105.50	Functioning	
Rose Creek Diversion Channel	BGC05-02	580,879	6,913,412	1044.65	Functioning	
	BGC05-03	580,866	6,913,418	1050.64	Functioning	
	BGC05-06-D	580,709	6,913,519	1041.50	Functioning	
	BGC05-06-S	580,709	6,913,519	1046.78	Functioning	
	BS-5	581,740	6,913,008	1053.00	Functioning	
	BS-9	581,216	6,913,254	1045.00	Functioning	
	CD-13-D	581,386	6,913,197	1044.70	Functioning	
	CD-13-S	581,386	6,913,197	1048.70	Questionable	
	CD-15-D	581,218	6,913,289	1043.30	Functioning	
	CD-15-S	581,218	6,913,289	1048.10	Functioning	
	CD-21-D	580,703	6,913,504	1042.00	Not functioning	
	CD-21-S	580,703	6,913,504	1047.50	Functioning	
	CD-26-D	580,267	6,913,733	1042.00	Functioning	
	CD-26-S	580,267	6,913,733	1048.20	Functioning	

Table III-5 Thermistor Summary

Area	Instrument	Easting (m) (NAD27 UTM)	Northing (m) (NAD27 UTM)	Status	Comments
Cross Valley Dam	BH88-4	580,117	6,914,061	Unknown	
	CVDC-6	580,197	6,914,225	Unknown	
Little Creek Dam	BH94-LCD4	593,456	6,903,014	Unknown	
	BH94-LCD5	593,497	6,903,095	Unknown	
	BH94-LCD6	593,535	6,903,126	Unknown	
Rose Creek Diversion Channel	BGC05-04	580,861	6,913,420	Not functioning	
	BGC05-07	580,714	6,913,518	Functioning	
	BS-5	581,740	6,913,008	Functioning	
	BS-9	581,216	6,913,254	Functioning	
	BS-10	580,856	6,913,363	Functioning	
	BS-12	580,539	6,913,512	Functioning	
	CD-10	581,723	6,913,066	Functioning	
	CD-15	581,218	6,913,289	Functioning	
	CD-21	580,703	6,913,504	Functioning	
	CD-26	580,267	6,913,733	Questionable	
	SP-2	581,263	6,913,326	Functioning	
	SP-3	581,006	6,913,375	Functioning	
SP-5	580,236	6,913,773	Functioning		

Table III-6 Weir and Staff Gauge Summary

Area	Type	Instrument	Easting (m, NAD27 UTM)	Northing (m, NAD27 UTM)
Cross Valley Dam	Weir	Weir 3	580,112	6,914,203
		X11	580,102	6,914,276
		X12	580,076	6,914,111
		X13	580,070	6,914,260
Faro Creek Diversion Channel	Staff Gauge	FCD-1	585,469	6,916,567
		FCD-2	585,026	6,915,674
		FCD-3	585,071	6,915,255
		FCD-4	585,346	6,914,854
North Fork Rock Drain	Staff Gauge	NF1	584,999	6,913,119
		NF2	584,811	6,912,864
		NFRD-2B	584,184	6,912,589
		X2	584,158	6,912,552
North Wall Interceptor Ditch	Weir	NWID		
Rose Creek Diversion Channel	Staff Gauge	RCDC-4	583,228	6,912,381
Vangorda Waste Rock Dump	Weir	V28	593,834	6,902,242
		V29	593,579	6,902,327
		V30	593,322	6,902,404
		V31	593,430	6,902,811
		V32	593,537	6,902,869
		V33	593,623	6,902,911
	Weir	GC Weir	592,886	6,903,216



PLAN
SCALE A

LEGEND

●	STANDPIPE PIEZOMETER	●	FUNCTIONING INSTRUMENT
▲	PNEUMATIC PIEZOMETER	●	QUESTIONABLE INSTRUMENT
■	INCLINOMETER	●	DEFUNCT INSTRUMENT
★	THERMISTERS	✕	RECOMMENDED INCLINOMETER

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.


CLIENT




PROJECT FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW	
TITLE CROSS VALLEY & INTERMEDIATE DAMS INSTRUMENTATION	
PROJECT No. M09770A06	FIG. No. III-1

Time: 13:52:46
 Date: 2/1/2017
 Scale: 1:25000
 Drawing File: Z:\M\CR\M09770A06 - COY-Far - 2016-17 Geotech\400 Drawings\CAD\2016 Annual Geotechnical Review\FIG_III-1_to_III-4.dwg (bolic)

KCB-R-MD



PLAN
SCALE A


LEGEND

- STANDPIPE PIEZOMETER
- ▲ PNEUMATIC PIEZOMETER
- INCLINOMETER
- ★ THERMISTERS
- FUNCTIONING INSTRUMENT
- QUESTIONABLE INSTRUMENT
- DEFUNCT INSTRUMENT

<p>AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.</p>		<p>PROJECT FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW</p> <p>TITLE ROSE CREEK DIVERSION & BACKSLOPE INSTRUMENTATION</p>
		<p>PROJECT No. M09770A06</p> <p>FIG. No. III-2</p>

Time: 13:52:46
 Date: 2/1/2017
 Scale: 1:25000
 Drawing File: Z:\WORK\M09770A06 - COY-Faro 2016-17 Geotech\400 Drawings\400 Drawings\CAD\2016 Annual Geotechnical Review\FIG_III-1_to_III-4.dwg (bolic)

KCB-R-MD



PLAN
SCALE A

- LEGEND**
- STANDPIPE PIEZOMETER
 - FUNCTIONING INSTRUMENT
 - QUESTIONABLE INSTRUMENT
 - DEFUNCT INSTRUMENT


AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.	Yukon Government

PROJECT FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW	
TITLE SECONDARY TAILINGS IMPOUNDMENT INSTRUMENTATION	
PROJECT No. M09770A06	FIG. No. III-3

Time: 13:52:46
 Date: 2/1/2017
 Scale: 1:25000
 Drawing File: Z:\M\CR\M09770A06 - COY-Faro 2016-17 Geotech\400 Drawings\400 Annual Geotechnical Review\FIG_III-1_to_III-4.dwg (bolic)

KCB-R-MD

Time: 13:52:46
 Date: 2/1/2017
 Scale: 1:25000
 Drawing File: Z:\WORK\M09770A06 - COY-Faro 2016-17 Geotech\400 Drawings\400 Annual Geotechnical Review\FIG III-1 to III-4.dwg (bolic)



PLAN
SCALE A

LEGEND	
●	STANDPIPE PIEZOMETER
▲	PNEUMATIC PIEZOMETER
●	FUNCTIONING INSTRUMENT
●	QUESTIONABLE INSTRUMENT
●	DEFUNCT INSTRUMENT
✕	RECOMMENDED INCLINOMETER

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA, STATEMENTS, CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

CLIENT

PROJECT	FARO MINE COMPLEX 2016 ANNUAL GEOTECHNICAL REVIEW
TITLE	LITTLE CREEK & VANGORDA WASTE ROCK DUMP INSTRUMENTATION
PROJECT No.	M09770A06
FIG. No.	III-4

KCB-R-MID