

**INDIAN AND NORTHERN AFFAIRS CANADA
ABANDONED CLINTON CREEK
ASBESTOS MINE
1998 SITE RECONNAISSANCE**

APRIL, 1999

PREPARED BY
UMA ENGINEERING LTD.
ENGINEERS AND PLANNERS
1479 BUFFALO PLACE
WINNIPEG, MANITOBA
R3T 1L7

UMA JOB NO. 41 01 8745 004 01 01

©UMA ENGINEERING LTD. ALL RIGHTS RESERVED.

This report has been prepared by UMA Engineering Ltd. ("UMA") for the benefit of the client to whom it is addressed. The information and data contained herein represent UMA's best professional judgement in light of the knowledge and information available to UMA at the time of preparation. Except as required by law, this report and the information and data contained herein are to be treated as confidential and may be used and relied upon only by the client, its officers and employees. UMA denies any liability whatsoever to other parties who may obtain access to this report for any injury, loss or damage suffered by such parties arising from their use of, or reliance upon, this report or any of its contents without the express written consent of UMA and the client.



UMA Engineering Ltd.
Engineers and Planners

1479 Buffalo Place, Winnipeg, Manitoba, Canada R3T 1L7
Telephone: (204) 284-0580 Fax: (204) 475-3646

Our File 4440 038 00 02

April 6, 1999

Indian and Northern Affairs Canada
345, 300 Main Street
Whitehorse, Yukon
Y1A 2B5

Attention: Brett Hartshorne

Dear Sir:

Reference: Abandoned Clinton Creek Asbestos Mine – 1998 Site Reconnaissance


Enclosed is our report summarizing site reconnaissance trips completed by UMA Engineering at the abandoned Clinton Creek Asbestos Mine in August and September, 1998. Site photographs are included in a separate binder referenced as Appendix A.

Based on our reconnaissance and a review of historical information, we are of the opinion that conditions are continuing to deteriorate at the waste rock dumps and tailings piles. Of particular concern is the potential for either Hudgeon Lake or the pond upstream of the Wolverine Creek tailings piles to drain suddenly, causing destructive flooding and debris flows downstream of these areas. The potential also exists for a sudden release of water upstream of the Porcupine Creek waste rock blockage, however, the watershed boundary is relatively small and the consequences of a failure are less significant by comparison.

Thank you for the opportunity to work on this most interesting assignment at this site. We would be pleased to discuss appropriate follow-up activities based on the observations and assessments developed from the 1998 site inspections. Please contact Mr. Ken Skafffeld or Mr. Tom Wingrove if you have any questions or require additional information.

Respectfully Submitted,

UMA ENGINEERING LTD.


J. A. Terris, P.Eng.
Vice President & Manager
Manitoba & Northwestern Ontario
KS/dh



T. Wingrove, P.Eng.
Director
Earth & Environmental Division

TABLE OF CONTENTS

	<u>PAGE</u>
SUMMARY	i
1.0 INTRODUCTION	1
2.0 CLINTON CREEK WASTE ROCK DUMP	2
3.0 CLINTON CREEK CHANNEL	5
4.0 PORCUPINE PIT	19
5.0 PORCUPINE CREEK WASTE ROCK DUMP	20
6.0 TAILINGS PILES	25
6.1 South Lobe	25
6.2 North Lobe	29
7.0 WOLVERINE CREEK CHANNEL	35
8.0 CLOSURE	38

DRAWING 01 LOCATION PLAN

DRAWING 02 CLINTON CREEK WASTE ROCK DUMP AND CREEK CHANNEL

DRAWING 03 PORCUPINE CREEK WASTE ROCK DUMP AND CREEK CHANNEL

DRAWING 04 WOLVERINE CREEK TAILINGS PILES AND CREEK CHANNEL

APPENDIX A SITE RECONNAISSANCE PHOTOS: COMPILED SEPARATELY IN BINDER

APPENDIX B SITE RECONNAISSANCE FIELD NOTES

Summary

Based on our 1998 reconnaissance of the abandoned Clinton Creek Asbestos Mine, we are of the opinion that conditions are continuing to deteriorate at the waste rock dumps and tailings piles. Of particular concern is the potential for either Hudgeon Lake or the pond upstream of the Wolverine Creek tailings piles to drain suddenly, causing destructive flooding and debris flows downstream of existing or potential channel blockages. The potential also exists for a sudden release of water upstream of the Porcupine Creek waste rock blockage, however, the upstream watershed boundary is relatively small and the consequences of a failure are less significant by comparison.

Significant erosion, undercutting, and downcutting of the Clinton Creek channel continues. The risk of a major breach increases with time as the channel deepens downstream of the lake outlet. Although the section of channel immediately downstream of the lake outlet has remained relatively intact, channel incising is likely to gradually advance upstream increasing the potential for a complete or partial breach at the lake outlet. The destructive nature of large creek flows is evident well downstream of the waste rock dump where flow debris can be seen over a large area. A breach of the plug at the lake outlet could result in flooding and debris flows more destructive than have been seen historically. Erosion and localized failures of the access road are also occurring, a process which will eventually result in the road becoming impassable.

The Clinton Creek Waste Rock Dump has historically advanced towards the valley and into Hudgeon Lake, as evidenced by ground surface movement monitoring during mine operation. Since the dump is considered at best to be marginally stable, continued movements (spreading) of the waste rock are likely as the channel is down-cut. An understanding of the performance of the rock dump since mine closure, in particular the amount of surficial movements, is essential to fully assess the impact of creek channel erosion, the risk of a catastrophic breach and the feasibility of remedial measures.

Significant instabilities of the southern section of the Porcupine Creek Waste Rock Dump are evident, although ground movement monitoring has never been undertaken to measure the magnitude of movements. Impounded water upstream of the waste rock dump continues

to flow either below or through the waste rock or along the east valley slope in subterranean channels. Both flow channels are at risk of blockage due to subsidence of either the waste rock or the overburden soils. Should this occur, it is possible that water levels upstream of the waste rock dump would increase and eventually overtop the toe of the waste rock along the east valley slope.

The north and south tailings lobes continue to advance toward the east valley slope. Tension cracks and slumping at and behind the crest indicate that the instabilities are retrogressive in nature i.e. as the toe advances and is eroded, the mid and upper sections of the tailings are destabilized resulting in increased rates of movement. Erosion and subsequent transport of tailings from the south and north lobe continues along Wolverine Creek. Given the remaining volume and height of tailings on the west valley slope, the potential for a significant channel blockage is real. Based on the events of 1974, this would likely result in a sudden breach and downstream flooding and debris (tailings) flows. An understanding of the current magnitude and movement rates would be valuable in assessing the present situation, the risk of a sudden breach and the feasibility of remedial measures.

Although the consequences of a sudden breach of the Clinton Creek and Wolverine Creek blockages would be most severe immediately downstream of the mine site, the potential exists for property damage as far downstream as the Forty Mile River. Of particular concern is the potential for loss of life from a sudden outburst flood and debris flow. The mine site is accessible to the public and was well travelled during our site reconnaissance. Camping downstream of the washed out bridge is not uncommon and placer mining was underway along Wolverine and Clinton Creeks in September, 1998 (claim stakes have recently been placed along the creeks).

1.0 INTRODUCTION

UMA Engineering Ltd. (UMA) is pleased to submit this summary report of our 1998 site reconnaissance of the abandoned Clinton Creek Asbestos Mine. The purpose of the two site visits was to: locate, map and inventory all pertinent site conditions relative to the extent of existing slope movements of the waste rock dumps and tailings piles; and assess any visual indicators of potential continued movement. We have also summarized site development activities and previous site inspections conducted since 1974, in particular photographic and observational records of the site over a 24-year period.

An initial one day fly-in visit was made to the site in August, 1998 by Ken Skafffeld, P.Eng. of UMA, Brett Hartshorne of DIAND and Matt Dodd of Royal Roads University (RRU). A more detailed three-day reconnaissance trip was carried out in September, 1998 by Ken Skafffeld, P.Eng. and Jeff Tutkaluk, P.Eng. of UMA in conjunction with an environmental sampling program by RRU. Based on these site reconnaissance trips, we have prepared this report which includes updated mine site drawings, a narrated videotape, and a detailed photographic record of areas of concern.

Similar to previous reports, separate discussions are presented for the Clinton Creek Waste Rock Dump, the Porcupine Creek Waste Rock Dump, the Tailings Piles (north and south lobes), and the Clinton Creek and Wolverine Creek channels including selected historical photographs. Selected photographs are included in the body of this report. A complete UMA photo record is separately bound as Appendix A. Reference numbers for photographs from previous inspections are as they appear in historical reports and as a result, are in no particular order.

The general mine layout is shown on Drawing 01 which is based on an air photo taken in August, 1988. Field notes from our 1998 site reconnaissance, previous reports, aerial photographs, and other relevant information have been used to generate drawings of the Clinton Creek Waste Rock Dump and creek channel (Drawing 02), the Porcupine Creek Waste Rock Dump and creek channel (Drawing 03) and the Wolverine Creek Tailings Pile and creek channel (Drawing 04). Photo numbers and locations are included on Drawings 02, 03 and 04. Copies of field notes are included in Appendix B.

2.0 CLINTON CREEK WASTE ROCK DUMP

The waste rock from Porcupine Pit was initially placed along the south valley slope west of the mine as shown on Photo CC-01, probably taken around 1970 (Geo-Engineering, December, 1986). It is apparent that the waste rock was unstable at this early stage as evidenced by visible slumping of the east section of waste rock. This early photograph, looking upstream, also illustrates Clinton Creek along its original alignment in the center of the valley (now Hudgeon Lake).



Photo CC-01: Clinton Creek Waste Rock Dump (Circa 1970)

Between 1970 and 1975, a considerable volume of waste rock was dumped across the valley as shown on Photo CC-03 taken in May, 1975. The resulting valley blockage impounded water from the Clinton Creek watershed creating Hudgeon Lake.



Photo CC-03: West end of Waste Rock Dump (May, 1975)

Significant lateral spreading of the rock fill, in particular at the west end of the dump towards Hudgeon Lake, occurred as a consequence of the continued placement of waste rock. Photo 1, taken in about May 1976 (Golder Associates, April 1977), shows tension cracks along the crest of waste rock adjacent to Hudgeon Lake. By 1985, the west end of the waste rock dump had slumped considerably towards, and into, Hudgeon Lake (Photo 2, Klohn Leonoff, September, 1986).



Photo 1: Tension Cracks at West End of Waste Rock Dump (1976)



Photo 2: View South at Waste Rock Dump (1985)

Based on observational records, active movement of the waste rock dump has continued since mine closure in 1978, although the magnitude of this movement has not been quantified since that time. Prior to mine closure, surveys of movement monitoring targets were conducted to assess the rate and magnitude (vertical and horizontal) of waste rock movement. With the exception of several targets along the south bank of the creek channel, most of the monitoring points are intact. Targets located during our reconnaissance are indicated on Drawing 02. Visible movements of the waste rock pile were reported in Geo-Engineering's July, 1998 report (Photo 17). Examination of the area near the center of Photo 17 (sparsely covered with young poplar trees) in September revealed that many of the tension cracks associated with slump blocks had been infilled, possibly suggesting reduced slope movement at this end of the dump (UMA Photo 9-3). More recent multiple tension cracks which further confirm on-going lateral movements of the waste rock were observed farther east along the access road during our September, 1998 site reconnaissance (UMA Photo 2-18, Appendix A).




Photo 17: Tension Cracks in Waste Rock Along Sparsely Treed Area (1998)

3.0 CLINTON CREEK CHANNEL

No photographic or written records are available from when the mine first opened until the waste rock dump forced the alignment of Clinton Creek against the north valley slope and ultimately impounded Hudgeon Lake. Photo CC-02 is the earliest available photograph of Hudgeon Lake, looking east at the waste rock dump, lake outlet, and the creek channel. Initially (1974), the creek channel flowed between the waste rock dump and the mill access road located on the north valley slope (Photo CC-03). However, as the water level in Hudgeon Lake increased, the unprotected channel eroded (down-cut) and migrated laterally to the north, eventually washing out the road (Photo CC-09).



Photo CC-02: Access Road and Hudgeon Lake Outlet at Clinton Creek (1974)



Photo CC-03: Access Road Along North Side of Clinton Creek (about 1974)



Photo CC-09: Erosion of Access Road on North Side of Creek (1975)

A new access road with a wide shoulder was subsequently constructed through the rock fill along the south side of the creek channel. However, the waste rock was undercut and began slumping soon after it was constructed as shown on Photo 5, (Golder Associates, April 1977). Slumping on the north side of the channel also began to undercut the natural valley slope can also be seen in Photo 5.




Photo 5: Erosion and Slumping of New Access Road on South Side of Creek (1976)

During the summer of 1979, an attempt was made to reduce channel erosion and undercutting by constructing rock weirs and armouring the banks of the channel immediately downstream of the lake outlet. Over the next few years, however, the creek flow bypassed the rock weirs on the north side causing significant erosion (Photo 3 Hardy Associates Ltd, July 1982). By 1983, channel flow had completely bypassed the weirs substantially increasing valley slope erosion as seen in Photo 3 (Klohn Leonoff, August 1983).



Photo 3: Creek Bypassing Weirs (1982)



Photo 3: Valley Erosion (1983)

Significant channel erosion and down-cutting is also evident downstream of the weir (Photo 4 Klohn Leonoff, August 1983).



Photo 4: Channel Erosion Downstream of Weirs (1983)

Remedial work was again undertaken in the fall of 1983 to reduce channel erosion. Flow was diverted along the south side of the rock weirs while the north side of the channel and the culvert outlets were armoured with rip rap as seen in Photos 7 and 10, respectively (Klohn Leonoff, November 1983). Woven geotextile was placed beneath the rip rap on the north side of the channel (Photo 6 Klohn Leonoff, November 1983).



Photo 7: Armouring of North Side of Channel (1983)



Photo 10: Channel Lining at Culvert Outlets (1983)



Photo 6: Channel Repairs (1983)

In June 1984, the channel was beginning to by-pass the last downstream rock weir (Photo 2 - Klohn Leonoff, August 1984). Photos 3 and 4, taken in June, 1985 illustrate the minor modifications made to the north side of the channel.



Photo 2: Channel Bypassing Rock Weirs (1984)



Photos 3 and 4: Channel repairs (1985)

Spring run-off in 1997 destroyed the rock weirs. Since that time, significant channel erosion and incising has occurred downstream of the washed out culverts, apparently down-cutting the channel by up to about 2m (UMA Photo 7-24). Down-cutting of the channel is also apparent farther downstream when Photo 4 (Page 9) is compared with UMA Photo 7-17. At present, numerous slumps and localized slope failures are occurring on either side of the channel as material is eroded (UMA Photos 7-6 and 7-18 and 7-25 in Appendix A). Once material has failed or slumped into the channel, flow is often forced to meander around the debris initiating erosion of the opposite bank.



UMA Photo 7-24: Channel Down-Cutting (1998)



UMA Photo 7-17: Channel Erosion (1998)



UMA Photo 7-6: Sloughed Till in Channel From Localized Bank Failure (1998)

This process has begun to impact the integrity of the access road along the waste rock dump as evidenced by tension cracks along the north shoulder of the access road (UMA Photo 7-14). Slumping has resulted in considerable narrowing of one section of the access road (UMA Photos 2-8 and 7-5 in Appendix A) and it is likely that the access road will become impassible in the near future as this process continues (Drawing 02).



UMA Photo 7-14: Tension Crack Along Access Road (1998)



UMA Photo 2-8: Failure Along Access Road Shoulder (1998)

Another contributing factor to erosion and slumping of the south bank is the presence of exposed bedrock along parts of the channel bottom and north valley toe. A substantial length of channel (approximately the downstream half) has been cut into the weathered Argillite bedrock as shown on Drawing 02. The bedrock generally consists of a weathered weaker bedrock unit overlying a stronger more competent bedrock unit with horizontal to slightly dipping bedding planes. The bedrock is less erodable than the waste rock that comprises the south bank and, as a result, the south bank appears to undergo preferential erosion and undercutting. In the upper reaches of the creek (downstream of the lake outlet), the channel is cut into highly erodable waste rock and till material on the north bank. Although portions of the channel contain large diameter boulders, the creek channel, in many cases, is beginning to meander around these more protected sections. Downcutting is evident just downstream of the lake outlet where the new creek bed is suspected to be at least 2 metres below its elevation following repair work in 1984 (Section A-A, Drawing 02).

The road crossing at the lake outlet is now washed out and only 2 of the original 4 CMP culverts remain (Drawing 02). Flow occurs through the culverts and between the second culvert and the north bank. The inlet for the first culvert is not visible and is blocked with debris, limiting flow. Water depths in the open channel are in the order of 0.5 metres (September, 1998) with velocities estimated to be 0.75 metres per second. The CMP section visible in the channel some distance downstream is believed to be either the end section of the second culvert or one of the missing culverts. The channel profile is estimated to drop about 3 metres between the outlet and Points A, B, and C, as shown on Drawing 02.

Two springs were observed exiting from the waste rock just downstream of the lake outlet. The first spring exits from what is believed to be the old creek bed, between the island and south bank (Drawing 02 and UMA Photo 8-16). The second spring exits about 2 metres above the creek water level on the south bank (UMA Photo 8-19 and Drawing 02). The water from both springs was clear with no evidence of fines. Brown slime was growing over the rocks at the downstream spring and the water had a noticeable hydrogen sulphide odour. A water sample was collected from the spring by RRU.



UMA Photo 8-16: Spring in Creek channel Remnant (1998)



UMA Photo 8-19: Spring on South Bank

Downstream of the washed out bridge at the east end of the waste rock dump, a single creek channel now meanders through a considerable area of flow debris consisting of gravel to 200mm diameter rock (UMA Photos 13-17 and 13-18, Drawing 02). There appears to be considerably more flow debris downstream of the bridge now (UMA Photo 2-7) as compared with Photo 7 taken in 1986 (Geo-Engineering, November 1986). Several channel remnants and evidence of significantly wider historic channel flow are visible. High water marks in trees in the area are about 600mm above the ground surface, or about 1.5 to 2 metres above the existing creek water elevation. At locations as far as 200 metres downstream of the bridge, trees and brush have trapped flow debris (UMA Photo 11-22 note leaning trees). Beaver dams several hundred metres downstream of the bridge have flooded a large area near the junction of Wolverine and Clinton Creek.



UMA Photo 13-17 and 13-18: Clinton Creek at washed out bridge



Photo 7: Clinton Creek Bridge Crossing (1986)



UMA Photo 11-22: Flow Debris in Treed Area

4.0 PORCUPINE PIT

Instabilities of the open pit (Porcupine Pit) sides-slopes have been on-going since closure of the open pit mine. Recent tension cracks were observed during our site reconnaissance, in particular at the crest along the entrance to the mine as shown on UMA Photos 9-10 to 9-12 and along the west edge of the crest where a significant slump block has developed (Drawing 03). Continued sloughing of the over-steepened pit walls is clearly evident and is expected to continue for an indefinite time period (UMA Photo 11-1). Debris could occasionally be heard falling into the water while completing our reconnaissance in the area.



UMA Photo 11-1: View Northeast at Porcupine Pit (1998)

5.0 PORCUPINE CREEK WASTE ROCK DUMP

Waste rock was placed across the Porcupine Creek valley slope as shown on Drawing 04 and in Photo 12, one of the earliest aerial photographs of the area taken in 1976 or 1977 (Hardy, 1977). The most northerly section of the dump was placed at least partially up the east valley wall. This area has remained relatively stable. Sections near the centre of the dump which were placed farther away from the east valley toe, however, have experienced slumping creating blockages at two locations, as indicated on Drawing 03.




Photo 12: East Edge of Porcupine Creek Waste Rock Dump (1977)

The first blockage (blockage 1) was photographed in 1987 by Geo-Engineering (Photo 8). Subsequent inspections and photos of this blockage and our 1998 site reconnaissance indicate there has been no significant change in the geometry of this is blockage (UMA Photos 10-3 & 10-6 in Appendix A).



Photo 8: View Downstream at Blockage 1 (1987)

Blockage 2, located upstream of blockage 1, is illustrated in Photo PC-01 taken in 1975. Since 1975, subsequent inspections suggest very little additional movement is occurring (UMA Photo 10-2 in Appendix A). Both blockages probably behave as permeable dams with some water seeping through the waste rock. During high water events however, it is possible the blockages might be overtopped.



Photo PC-01: View Downstream at Blockage 2 (1975)

The southern section of the waste rock dump has undergone extensive movement at the toe and crest due to both the volume of waste rock and the method of placement. Dumping probably would have begun at or near the crest of the original valley slope but was only advanced across a portion of the valley. Instabilities of the waste rock pile have heaved the valley floor several metres as shown in Photo PC-03 (May 1975). The heaving (up-thrusting) of the valley floor is the primary reason for the impoundment of water from Porcupine Creek.



Photo PC-03: Till Up-Thrust at Toe of Failed Waste Rock (1975)

Near the crest of the waste rock dump, movement has resulted in numerous tension cracks and backscarps as shown in Photo 11 (Geo-Engineering, November 1988) and UMA Photos 10-24 to 11-0 in Appendix A. At present, considerable downslope movements are continuing in the upper slope of this section of the waste rock dump as evidenced by recent tension cracks and backscarps. It is anticipated this movement will continue until the waste rock has become geometrically stabilized, a process that could greatly increase the size of the upstream impoundment.



Photo 11: Crest of Unstable Waste Rock (1988)

Drainage of the Porcupine Creek watershed through the waste rock dump occurs in two ways. The majority of the water drains through the waste rock pile, entering at a point along the southern limit of the stable waste rock pile (Drawing 03). Water drains from the pond to the waste rock via a drainage channel incised through the slide debris from the unstable southern portion of the waste rock. Evidence of this channel was observed by Geo-Engineering during their July 1987 inspection, although at that time, the channel was dry (Photo 9). During our site reconnaissance, water was entering the waste rock pile through an opening that was estimated to be about 0.3m^2 located at the toe of the waste rock (UMA Photo 10-9 in Appendix A).



Photo 9: Dry Inlet Channel From Pond to Waste Rock Pile (1987)

The discharge point is believed to be through the toe of the northern slope of the waste rock dump, or about 550 metres to the north of the inlet (Spring A). At the time of our reconnaissance, discharge at the outlet was estimated to be in the order of 6 to 9 l/s (100 - 150 gpm) approximately 5 m above ground surface. A second outlet point, about 2m above the ground surface, discharges about 1 to 2 l/s (15-20 gpm). Localized slumping is evident where water discharges the core rock slope as seen in Photo 13 (Geo-Engineering, November 1988) and UMA Photo 11-3 (Appendix A). Water is conveyed via a drainage course that has been incised along the south edge of the road (Photo 13).



Photo 13: Outlet and Drainage Ditch on North Waste Rock Slope (1988)

Discharge is also occurring via subterranean flow along the toe of the waste rock and east valley slope (Drawing 03). Flowing water could be heard below the organic mat at two locations and was exposed at one location (UMA Photo 9-24 in Appendix A). Flows at this location were estimated to be 3 to 5 gpm. Discharge from the subterranean flow system occurs as a spring (Spring B) near the northeast corner of the waste rock dump (UMA Photo 9-23 in Appendix A). Fine grained material deposited at the discharge point indicates some transport (erosion) of material is occurring.

6.0 TAILINGS PILES

Since the failure of the asbestos tailings pile, the tailings piles have historically been referred to as the south and north lobes (UMA Photo 3-5 and Drawing 04). Each tailings lobe is discussed separately as follows:



UMA Photo 3-5: View North at South and North Tailings Lobes (1998)

6.1 South Lobe

The southerly portion of the tailings pile (south lobe) failed suddenly in early 1974. The tailings moved down the west valley slope and completely blocked the existing creek channel. The blockage was subsequently breached releasing a significant amount of water borne tailings which were deposited downstream of the blockage as shown in Photo 7 (W.B. Bowie, June 1974). Remedial works, including removal of tailings from the channel, were implemented soon after the breach occurred (Photo WC-01, July 1974).




Photo 7: Tailings Deposition After Breach (1974)



Photo WC-01: Creek Channel Downstream of Breach (1974)

Following the 1974 failure, downslope movement of tailings continued resulting in occasional channel blockage as shown in Photos WC-06 (June 1976).



Photo WC-06: Channel Blockage (1976)

In 1978 a mid-slope portion of the south lobe was regraded (terraced) in an attempt to off-load this area and slow the advancement of the lobe (Drawing 04). The regraded area has since failed and evidence of the terraced slope is visible as inclined benches at the toe (Photo 18 Geo-Engineering, May 1993) and UMA Photos 3-6 and 5-11 in Appendix A.



Photo 18: Impoundment Upstream of South Lobe (1992)

As the tailings continue to move down-slope, they are eroded and transported downstream. A comparison of the position of the leading edge of the tailings in Photo 12 taken in June, 1988 by Geo-Engineering with UMA Photo 5-20 indicates the gradual advancement of tailings into the creek channel.




Photo 12: Toe of South Lobe in June (1998)



UMA Photo 5-20: Toe of South Lobe in September (1998)

It is clearly evident that the south lobe remains active as evidenced by numerous tension cracks and slump blocks between the crest and toe (UMA Photo 3-13). Although the magnitude of this movement has not been confirmed since mine closure, it is anticipated that sufficient up-slope material exists to continue the advancement of tailings for an indefinite period of time.



UMA Photo 3-13: Tension cracking of Upper Slope (1998)

6.2 North Lobe

Following the failure of the south tailings lobe, tailings were placed farther to the north. However, similar downslope movements occurred almost immediately forming the north lobe. Tailings were then placed farther to the northwest on flatter ground until mine closure.

One of first aerial photographs of the unstable north lobe was taken in 1977 (Photo 1, R.M. Hardy and Assoc.). Downslope movement of the north lobe was not as sudden as that which occurred on the south lobe. However, the tailings gradually moved down-slope and within 10 years reached the pond created by the south lobe blockage (Photo 7, Klohn Leonoff, 1984).




Photo 1: Aerial View of Advancing Toe of North Lobe (1977)



Photo 7: North Lobe at Edge of Pond (1984)

By July, 1986, the north lobe had nearly reached the east valley slope as shown on Photo 8 (Klohn Leonoff, September 1986). The lighter tailings areas in the upper portion of the tailings pile were relatively undisturbed in the photo. The darker areas in the mid and lower portion of the slope are indicative of heavily disturbed material as the north lobe advanced. These observations were verified with monitoring data in Hardy Associates (1978) Ltd.'s 1984 report that indicated upper-monitoring locations moved significantly less than mid and toe monitoring locations.



Photo 8: Failed North Lobe Near Valley Slope (1986)

Significant heaving (up-thrusting) of the valley floor also occurred along the north side of the lobe resulting in a narrowing of the upstream section of the channel and the formation of an upstream pond (Photo 8, Geo-Engineering, November 1986). Continued advancement of the north lobe heaved the valley floor directly in the path of the lobe resulting in additional channel constriction as seen in Photo 19 (Geo-Engineering, November 1988) and UMA Photos 1-3, 5-9 in Appendix A.



Photo 8: Toe of North Lobe Approaching Valley Slope (1986)



Photo 19: Erosion of Toe of North Lobe and Heaved Valley Floor (1988)

Recent photographs suggest the tailings are advancing faster than they are being eroded as evidenced by mounding near the toe. This can be seen in a comparison of Photo 17 (Geo-Engineering, 1988) with Photo 22 (Geo-Engineering, 1998) and UMA Photo 5-17 (Appendix A), taken 10 years later.



Photo 17: Toe of North Lobe (1988)




Photo 22: Toe of North Lobe (1998)

Continued erosion at the toe will undoubtedly trigger retrogressive failures and continued downslope movement. Recent tension cracks were observed in the mid and upper portions of the north lobe in 1998 confirming on-going movement (UMA Photos 1-6 and 1-5, 1-12 and 4-2 in Appendix A). Tension cracks and slumping are evident at and beyond the crest of the slope supporting the observations of continued movements (UMA Photo 1-15).



UMA Photo 1-6: Back Scarps at Crest of North Lobe (1998)



UMA Photo 1-15: Tension Cracks Upslope of North Lobe Crest

7.0 WOLVERINE CREEK CHANNEL

Between 1978 and 1981, channel improvements downstream of the south lobe were undertaken including a series of rock weirs as shown on Drawing 04 and Photos 22 (Geo-Engineering, November 1986) and 12 (Geo-Engineering, November 1988). These channel improvements have remained relatively intact since construction. The secondary channel between the downstream channel improvement and the east valley slope noted in Geo-Engineering's 1986 report was visible, but dry during our September 1998 reconnaissance.



Photo 22: Armoring of Wolverine Creek Channel Downstream of the South Lobe



Photo 12: Weirs Downstream of South Lobe (1988)

At the time of UMA's site reconnaissance, four beaver dams were present between the upstream side north lobe and the downstream end of the south lobe as shown on Drawing 04. Beaver dam 1 is located at the north end of the north lobe where the valley floor has been raised. This first beaver dam has raised the water level in the upstream pond about 1 metre higher than would occur from the overburden blockage at this location. High water marks on trees in the upstream pond suggest water levels have been about 0.5 metres higher than were observed in September, 1998. Surficial slumping of the east valley slope is also occurring opposite from beaver dam 1. Test Holes 1 and 2, drilled with a hand auger within and just above the slumped area, indicate that the surficial overburden soils consist of 0.3 metres of mossy organic cover overlying 1 metre of soft, wet silty clay containing bedrock fragments (holes were terminated at 1.3 metres). No ice or frozen soil was encountered in either hole.

The second beaver dam, located between the upstream end of a small channel island and the toe of the north tailings lobe does not impound a significant amount of water. The third beaver dam is located at the upstream end of the south lobe as shown in UMA Photo 5-18

and is responsible for raising the water in the pond between the two tailings lobes by at least a metre.



UMA Photo 5-18: Beaver Dam 3 (1998)

The four beaver dams have significantly reduced channel velocities and erosion of the channel where the tailings piles meet the valley slope. Downstream of beaver dam No. 4 however, velocities increase significantly as the channel narrows and the channel slope steepens. Between the beaver dam and the rock weirs, the channel has down-cut into the underlying weathered argillite bedrock resulting in surficial slumping of the overburden soils (UMA Photos 5-23 and 5-21, 6-1 and 6-2 in Appendix A). Downstream of the south lobe, flow appears to be contained within the original modified channel with no significant erosion or down-cutting observed.



UMA Photo 5-23:
View Upstream of South Lobe Toe and East Valley Slope


8.0 CLOSURE

Our site reconnaissance trips in 1998 have confirmed the observations made in several previous inspection reports since mine closure with respect to the overall condition of the waste rock dumps, creek channels and tailings piles. We trust this summary reconnaissance report will provide DIAND with additional information to more fully assess changes in site conditions. This report also completes an important initial step should a more comprehensive risk assessment program or remedial stabilization measures be considered.

Thank you for the opportunity to work with you on this most interesting project. Please contact either of the undersigned should you have any questions or require any additional information.

Yours Truly,

UMA ENGINEERING LTD.



Ken Skaffeld, P. Eng.
Senior Project Engineer
(Yukon Territory License Pending)



Jeff Tutkaluk
Geotechnical Engineer

DRAWINGS



APR 06, 1999
 Plot Scale: 1=2000
 MapInfo.dwg

Date of Photography: Aug. 17, 1988

REV.	DESCRIPTION	DWN.	APP.	DATE

SEAL

UMA UMA Engineering Ltd.
 Engineers and Planners
 1479 Balfour Place, Winnipeg, Manitoba, Canada R3T 1L7
 DATE: MARCH, 1999

APPROVED BY: _____
 DRAWN BY: JV DESIGNED BY: _____
 CHECKED BY: JMT/KMS CHECKED BY: _____
 SCALE: APPROX. 1:36,000 JOB No. 4440-038-0

INDIAN AND NORTHERN AFFAIRS CANADA

ABANDONED CLINTON CREEK ASBESTOS MINE
 SITE RECONNAISSANCE

LOCATION PLAN

DWG. No. **01** - REV.



APR 06, 1988
 Plot Scale: 1" = 2000'
 MesP1001.dwg

Date of Photography: Aug. 17, 1988

REV.	DESCRIPTION	DWN.	APP.	DATE

SEAL

SEAL

UMA Engineering Ltd.
 Engineers and Planners
 1479 Buffalo Place, Winnipeg, Manitoba, Canada R3T 1L7
 MARCH, 1999

APPROVED BY: _____ DATE: _____
 DRAWN BY: JV DESIGNED BY: _____
 CHECKED BY: JMT/KMS CHECKED BY: _____
 SCALE: APPROX. 1:36,000 JOB No. 4440-038-0

INDIAN AND NORTHERN AFFAIRS CANADA
 ABANDONED CLINTON CREEK ASBESTOS MINE
 SITE RECONNAISSANCE

LOCATION PLAN


01 -
 DWG. No. REV.

**APPENDIX A
SITE RECONNAISSANCE PHOTOS
COMPILED SEPARATELY IN BINDER**

APPENDIX B
SITE RECONNAISSANCE FIELD NOTES

pp 1-9 AUG 10/28 SITE RECONN.
 10-13 PLAN FOR SEPT. RECONN
 14-20 NURTAL LOBE
 21-22 WOLVERINE CREEK
 23 S. LOBE
 24-26 WOLVERINE CR. @ TICE
 OF S. LOBE
 27-30 WOLVERINE CR. @ S/CF TAILS.
 31-32 WOLV. CREEK @ ACCESS
 ROAD TO MINE.
 33-49 CLINTON CREEK @
 MON #68 ON WASTE
 ROCK (PP 49).
 50-60 CLINTON CREEK.
 61-62 WASTE ROCK DUMP.
 63-71 PORCUPINE CREEK.
 72-78 CLINTON CREEK @/S
 OF WASHED OUT BRIDGE.

①




FIELD

②

CLUSTON CR - AUG 10 1988

WEST SIDE OF N. LOBE
APPEARS REASONABLY STABLE



NUMEROUS (MENTIONED) TELEPHONE
CRACKS THROUGHOUT N. LOBE
AS FLOW BACK AS WEST
EDGE. CRACKS RUN N-S
≈ 4-6" WIDE.

1-11
View N OTC IN
MIDDLE OF RAMP
NEAR TOP OF N. LOBE

1-12
MULTIPLE T.C.'S ON
WEST SIDE OF RAMP NEAR
TOP OF N. LOBE.
- MOVEMENT TO WEST
BEGINNING TO OCCUR.

FIELD

②

(7)

1-13 (13) - VIEWS OF MATR WITH
VIEWS ON END OF
N. LOBE

- SIGNIFICANT SLUMPING,
MULTIPLE T.C.'S

1-14

(15) - BARE SCARP @
N. END OF N LOBE
NUMT TO CREST.


1-15

(16) VIEW N @ N/S CORNER
~~AT~~

LOCALIZED FAILURE ON
N SLOPE OF SLOPE.
(17) 1-16

(8)

CANTON CR. N. AUG 10/20



1-20 1-21
pile fly - over to waste pile from tailings

1-22 TUE SOUTH LOBE 1-23 SOUTH LOBE
1-24 V. NORTHERN LOBE 1-24 S. CORNER TUE
1-25 VIEW N

pile fly - over to waste pile from tailings


2-1 SOUTH LOBE 2-2 TUE W. S. LOBE 2-3
ABANDONED W. CR. 2-4 JUNCT OF W. CR. 2-5
CLUSTERS OF 2-5 V. NORTH CR. DISTANCE
FROM W. CR. 2-6 VIEW N W. CR. DISTANCE
2-7 CANTON CR. 2-8 2-2-3 CANTON CR. FIELD

(6)

PROPOSED ?
SHALE
2-10 HUDGEM LAKE CURVE
ROCK WEIR @ CUTLIFT FORD
HUDGEM LAKE IN FAIRLY
GOOD CONDITION ± 13-2' DROP
OVER 1-1/2" φ BOWDERS

2-11 (18) - VIEW NE / ST
STANDARDS ON CURVE

ROAD ON S SIDE OF
CLINTON CREEK



2-12 (19) - VIEW E
2-13 (16) VIEW N @ gate stile
2-14 (15) VIEW W


(7)

CLINTON CR. AUG 10 / 28

WASTE PILE SCRAPED NEARBY
WATER ON S SIDE OF
TRUCK WALKING D/S (16) 2-15
UP TO 25m HIGH

NUMEROUS INSTANTANEOUS
WTD CHANNELS AS CURVE
ROCK SCUMPS (17) 2-16

WASTE PILE REMOVED
W/TH SPAN SCUMPS OF
WOODS



2-17
(18) - VIEW NE @ BRIDGE

FIELD

8

2-18 MULTIPLE T.C.'S 4"
 WIDE ACROSS
 RAMP TO TOP OF WASTE PILE
 @ E. END OF ROCK
 DUMP.

NO - C.C.'S MINIMUMS
 Z.P.A.

2-19 to 2-25 half fly-over. →

21-23 Ingress level
 dump
 no want visible.

End well @ Heds on Lk.
 outlet

Field #3.

9

CLAYTON CR AUG 10 1988

2-19 VIEW W. @ MILL
 2-20 "
 2-21 PORCUPINE CR. OUTLET
 2-22 TOP OF WASTE ROCK
 2-23 "
 2-24 SANDPIT LK. OUTLET
 2-25 "
 2-26 "
 2-27 "
 2-28 3-1 PORCUPINE LK OUTLET
 3-2 MILL
 3-3 VIEW W OVER WASTE ROCK.
 3-4 VIEW N @ TAILS ABOVE WASTE CR.
 3-5 "
 3-6 VIEW W @ TAILS
 3-7 VIEW W @ N-LODE
 3-8 VIEW SW @ TAILS
 3-9 VIEW S @ TAILS
 3-10 VIEW S OVER TAILS
 3-11 VIEW SE OVER TAILS.
 3-12 VIEW NE "
 3-13 CREST OF S. LODE
 3-14 "

FIELD

SEPT 1978 CLINTON CREEK

TRAVELED FROM WHITE HORSE TO CLINTON CREEK TOWNSITE WITH JEFF TUTKALUK. MET UP WITH MATE & BILL @ CLINTON CREEK.

- SET UP CAMP @ TOWNSITE.

3-15 APPROX. SET. OF NEW CR.

3-16 VIEW E ALONG CLINTON CR.

3-17 " "

3-18 WASHED OUT BRIDGE @ MINE

3-19 " @ TOWNSITE

3-20 CLINTON CR. TOWNSITE

3-21 40 MILE R. BRIDGE

3-22 RD FROM HWY.

3-23 40 MILE R. DISCH. INTO YUKON R.

3-24 YUKON R.


3-25 DAWSON CITY.

SEPT 1978 - CLINTON CREEK

- PUNN IS TO INSPECT TAILINGS AREA TODAY.

GENERAL NOTES:
 GOLDEN V76003
 MAY, 1978 - LU MOVEMENT
 ANOMALIES INSTALLED ON TAILINGS PILES

- SOUTH ABEE PAVED (1974)
 - RADAR CRACKS IN SOUTH HOBE
 - NORTH HOBE D.K.



(12)

SEPT 12/28 CUSTON CR.

HARDY CG 100755 APRIL 84

- AREA & SOUTH LINES MONITORED SINCE 1978.

* 14 MONITORING POINTS WITHIN NORTH LOBE

• 7 MONITORING POINTS WITHIN SOUTH LOBE

- BEST PAW WITH MONITORING POINTS IS D-1004A FROM KLOHN'S 1984 REPORT. (AT WHICH TIME TOP OF N LOBE ALMOST REACHED CREEK)

- THERMISTOR SENSORS T5, T6, T7 INSTALLED BY GARDNER IN TAILINGS AREA.

(13)

SEPT 12/28 CUSTON CREEK

REVIEW OF TAILINGS DRAWINGS (CANNONDAQUINE)

KLOHN 1984 - TAILING GLOBE TOE HADN'T REACHED CREEK

GEDO - JUNE 1987 - TOE OF NORTH LOBE @ CREEK

ALOHAN D-4009 - TOE @ CREEK (CON-FIBERS GLOBE 1987 SKETCH)

4 GLOBES - JUNE '88 } SAME SKETCHES
 '91 }
 '93 } TAILINGS REMOVED

W. SIDE OF CREEK BEING ERODED VALLEY.


STATE INSPECTION OF TAILINGS AREA AT 9:30 - TAKE PYS'S CP WITH AMT & FILE.

- CREEKWAY 10-15%

FIELD

(19)

SEPT 12/98 CANTON CR.



Photos. 4-24-83

4-3-84 - Taken From 20m off

Point #4 4-44-85 From main 26

4-5-86 in N. Lobe.

4-6

From 80-2

with 26A

Back to dump.

4-7-8

S Lobe

4-8-8

Wolverine Creek Arroyo

4-9-80

Back Between Lobes.

4-10-81

N Lobe

From 80-2

(15)

SEPT 12/98 CANTON CR.

From Nov 80-2

ACTIVE MOVEMENTS OF BENTONITE SLIPS @ 80-2, LOOKING UP TO CREST.

- NO VISIBLE T.C. BEST NUMEROUS SMALL SLIPS / CRACKS UP SLOPE FROM 80-2

2 or 3 LARGE DUMP BLOCKS D/S OF 80-2.

CREST

30-35' ± 2.5m

10.4m 80-2

4.5-6.0m


WATER BENCH

FIELD


(16)

SEPT 12/98 CLINTON CR

BAND



RECENT T.C.'s
80-1




T.C.'s

PHOTO
TAKEN 130m →
NEAR 80-1

4-11
4-12 VIEW USE BOY
4-13 - VIEW OF BOTTOM
4-12
M. LOSE

C. THORNTON T7




EVIDENCE
SUBSEQUENT
MARK

(17)

SEPT 12/98 CLINTON CR

CREST



MARSHY
SEWER

STABLE
SCORE 20


6m

5m

TRAIL
MARKER

* POSSIBLY THE TOP
ALONG THE W. TH. EDGE
OF THE PILE WERE FOUND
HERE WHEN 1978 EXCAVATION
WAS DONE AT SOME TIME PLACE?
+ SOME AROUND NE CORNER.

FIELD




SEPT 12/98
CLUSTER CR.
T.C. ± 2m
4-5m


SEPT 12/98 CLUSTER CR.

4-16	VIEW NW FROM 650-1
4-17	VIEW SEE ACROSS TAILINGS
4-20	VIEW N @ END OF MID-BENCH
4-21	VIEW EAST ACROSS
4-22	LIMIT OF SLOPE TOE BENCH IN LEFT
	NO TREE TRUNKS
	TILL INCLUDED IN
	SLOPE FACE @
	END OF TOE BENCH @
	EDGE OF SLOPE
	SEE PHOTO (4-23) 4-22
4-23	
4-24	VIEW WEST FROM TOE BENCH


4-25 1-24 Sept 12/98 CLINTON CR.
 4-24 VIEW WEST FROM
 N.E. CORNER OF N. LOBBY
 4-25 VIEW N.E. CORNER
 FROM N.E. CORNER
 PAGE 5
 5-03 5-1 RESULTS OF 4-26.



SEPT 12/98
 CLINTON CR.
 WORKING DATE



(22)



SEPT 12/28 CLINTON CR.

W. VALLEY

ABOVE PROSPECT

HWL ON TREES

LAKE ± 1-2' ABOVE PROSPECT

LAKE #1

BEAVER DAM #1

BEAVER DAM #2

VALLEY

ISLAND

ACTIVATION

Trees

Cott's

15m

BEAVER DAM #1


BEAVER DAM #2

(23)

SEPT 12/28 CLINTON CR.

W. VALLEY

CAT TRACKS



PLUG (used) HOLE

5-12 ✓ W. VALLEY N.W. @ NEW 350-3A

4-5 ✓ TAKEN FROM

14 ✓ BEYOND SOUTH TO S OF


15 ✓ W. LINE T 30m

16 ✓ ABOVE Z. HOP. P. HOP.

FIELD


24

SEPT 18/83 CLINTON CR



25

SEPT 18/83 CLINTON CR



FIELD

(20)

SEPT 12/96 CUNYON CR

* SECONDARY FLOWS CHANGE
NOTED IN 1993 GEO SUR

NOTE RAN NOT EVIDENT
(NO FLOWS VISIBLE)


→ PRESENTLY ALSO TAILWAS??

6-8 (10) - US FROM 150m S
OF START OF
FLUCLINE

6-9 (10) D/S "

6-10 (10) VIEW D/S ALONG FILL
IN SECONDARY FLOW
CHANNEL.

WETTS.



FILL. T.C. GULL


SECONDARY CHANNEL DRY.

(21)

SEPT 12/96 CUNYON CR

6-11 (10) VIEW W. TOWER
FILL D/S E. SIDE OF
CLEARANCE
(T.C.)

6-12 (10) DIRECTION OF FLOW
AROUND VIEW W
END OF ANACONDA
(T.C. XING)



FIELD

SEPT 13/98 4:10 PM TO 5:00 PM
RAIN @ 7:00 PM.

CLINTON CREEK & WASTE REEF
DUMP.

CAREER LIST.

→ SEEPAGE THROUGH WASTE REEF
± 60m D/S FROM CREEK

→ EVIDENCE OF SEEPAGE
(POUDDER ABOVE CREEK)

SEPT 13/98


WALKING UP FROM BRIDGE TO
WATER HOUSE IN LAKE CREEK.

Ground Water

- PS MUSEUM AIR
- MONITOR #1 - (Rising slightly)
- Bit Monitor (2) - (Low visible)
- OLD WASTE REEFIC SLOPE

SECTION #1

MONITOR #1




SEPT 13 198 CLINTON CREEK

PHOTO (7-13) - VIEW UPstream
FROM EAST EDGE OF
HIGH GROUND ON N. SIDE
OF CHANNEL.
(Taken From S edge of Creek.)


PS - DAY - OBS. 08.30
TOP OF PIPE 1.3 m ABOVE
GRADE

VIEW N. stream
FROM SOUTH SIDE OF
PIPE
↑ 10m
↑ 10m
↑ 10m



SEPT 13 198 CLINTON CREEK

- BEDROCK UNDERLIES CHANNEL
FROM TO EAST EDGE OF
HIGH GROUND ON N. SIDE
OF CHANNEL.
- WHITE ROCK ALONG SOUTH
SIDE OF CHANNEL BEING UNDERCUT
AS CHANNEL WIDENS TO SOUTH.



SEPT 13/98 CUNTON CREEK

- DEBRIS SLIDE ON N BANK ± 5m WEST OF P3 P4

- Partially diked channel, work according to Seals

- Several 1-2m x beams opposite P3 (See photo # 7-9)

7-76 D₂ FROM AREA P4

7-67 N " "

7-78 U/S " "

7-89 - Boulder in channel

- Bank on N side about 25m HIGH

- OVER STEEPENED (??) BUT RELATIVELY STABLE - Boulders ALONG S SIDE OF CREEK

AGE KE MINIMUM UNDERSTUD

SEPT 13/98 CUNTON CREEK

MARKERS FOR X-SEC C-C

MON STA #4-69

- SOUTH BANK ± 10m HIGH

(X-SEC D-D GIVE SIN SURE AREA)

MURDER

T.C.'s 1-2''

WIRE 2-3m

FIRM CREST

WASTE ROCK

ROAD

P4

25m

10m

MON STA #4-69

C-C

1.30m WEST OF P5

40

SEPT 13/28 CLINTON CREEK

① UNKNOWN MONUMENT MARKER
45 m E of P3

7-18 19 DIS }
7-19 20 VIS }
7-20 21 N. }
AA

1/2 STAKE
REMOVED 20
X-500

OPPOSITE FROM P3

7-21 UNK DIS

- SIGNIFICANT UNMETASTAL
SLAB OF LAMINAR ROCK
SEVERAL M BACK FROM CREST

- LARGE TREE GROWING LARGE BECH
STUMP BEHIND DIS
(Photo 2-23)

- BEDROCK CONTACT NO
LARGER USABLE ON
NORTON BANK JUST W 5 FROM
HERE (± 25m?)

41

SEPT 13/28 CLINTON CREEK

P3

* @ 3-6.2m
- FURTHER SWEAP @ 3.55
- BOTTOM @ 5.17
50 ± 1.35m

- EXPOSED TILL ON
N. BANK VIS FROM
P2


- NEW MARKER 4m N
OF N. EDGE OF RD. OPPOSITE
FROM P3. (flagged)
(BEHIND EXPOSED MGN 69)



FIELD

42

SEPT 13/88 CLINTON CR.



7-24 7-25 USE REPAIR


7-25 7-26 NE TUN SUPE.

8-0 - Retake 7-26

270

43

SEPT 13/88 CLINTON CR.



FIELD

SEPT 13/78 CLINTON CR.

TC #1 (See pp 46)

1'-3" WIDE
← (2-20) T.C.

- OPEN MOUTH OF RAMP (NOT RECORDED) - See Geol Report.

WALKER CP ROAD FROM HUNTERD CARE DRIVE


- FOUND NEW #68 - Picked up E/W. WITH CORE ON E SIDE. MARCH 20, 1978

FOUND IN TRENCH ON BENCH OPPOSITE FROM RAMP (N SIDE) 1' ABOVE BENCH.

SEPT 15/78 CLINTON CR

1879 FROM BOTTOM OF RAMP. (See sketch)

SPRING ± 8m O/S FROM RAMP OF RAMP



± 2m ABOVE RAMP

EXTING SLOPE

± 2m ABOVE RAMP


- NO FINE SAND
- BROWN MOSS GROUND
- ROCKS IN AREA OF SPRING.

SEPT 13/98 CLINTON CR

X-SECTION OPPOSITE FROM
D/S SPRUZE

9-23
9-24
ST
cutting geostable

9-24
9-25
views
FROM
EXP. BEST.



9-20
9-21
9-22
9-23
9-24
9-25

SEPT 13/98 CLINTON CR

7-0 View U/S @ X SECTION
CREEK
- RETOP HAS DEPOSITED
SOME F. GRASS ON BANK S.
± 1-2' ABOVE BENCH
AGAINST RIP RAP

9-1
9-2
9-2
- REMOVE B-25.

JEFF COLLINS HANDBURGER
HELPER. MANN GOOD!

52

SEPT 14/98

CLINTON CREEK

CHAINAGE

ALONG CLINTON CR. RD

P5

STA

0+00

CLAIM MARKER

POST NO. 1 EVA 99 ✓

150' E 150' L

AUG 26/98


B. SAUER
SAUER

WEST POST 150' W / 150' R.

→ STA 20+00 W.

X-SEC ELS

STA 42+00 W.



53

SEPT 19/98

CLINTON CREEK

P4

1+25.7m W.

X-SEC C-C

1+50 SW.

T.C. 4' wide ± 4m long

FROM 1+96 TO 2+00


6m NORTH OF E.R.D.

2' x 2' aug

X-SEC BB - PP' aug.

2+06

2+15.5



54

SPT 14/98 CLINTON CREEK

3/4" STEEL BAR ON S. SIDE OF
RD (UNUSUAL) BUT FLAGGED
@ 3+02 W.

CONSTANT GRADE FROM PS
TO SECTION A-A (SHOULD BE
ABLE TO CORRECT FOR TOLP
MORSE DISTANCE)

X-SEC A-A. 3+08 W.


TOP OF ROAD @ 3+19 W.

P3 3+52 W.

MOU STA 69 3+55.5

55

SPT 14/98 CLINTON CREEK



FIELD

(57)

SEPT 19/92 CLINTON CREEK

TRANSU TIC. @ 4+84.5
ACROSS RD.

P2 4+96.2

— BELIEVED PIN TAPES @ 4+94

— LOW ACULT. RD FOR 15m
E-W OF P2 ± 0.5m
LOWER AREA.

1 X 2" STAKE SEE K-K

± 4" RE-CHK

± 5m N of E STA 5+22.4

FIELD

(56)

SEPT 14/92

CLINTON CREEK

X-SEC G.G. - 3/4" PIN ± 1 ft
above gr. N side
of road, 7m N of E


— 4+88.5
E-W. GROUND SURFACE

5m N of E

4+76.5


— 4+58.5

3+96.5



SEPT 14/96

CUNYON CREEK




4 TUNNUN T.C.S. 5+92.5

FROM 5+37 TO A

SEPT 14/96

CUNYON CREEK



PI 5+85.0 W

5+91.5 - SPRING IN CHANNEL

UP TO END OF TUNNUN 6+16.5

5

SEPT 14/98 CANTON CREEK

UNACKED UP WASTE ROCK DUMP

LOCATED MON 20-A

81-2

21-A

22-A

21-1 (AUG 1998)

HUGGESS LK

1.2 (NO SIGN)

UAC

0.22A

0.21A

76.58

STAMP PROPERTY

(See sketch '87)

Photo 9-3 VIEW N 2 way horizon

9-4

9-5

VIEW E

(21A IN BACKGROUND)

6

SEPT 14/98 CANTON CREEK

1XZ 1/4" REBAR

X-SECT 5-5


6+27.2

EDGE OF CURBET

6+58

Φ CURBET

6+56.8



6+52

6+60.5

± 6+65.5

STUCK OVER 10M.

51-04 = 13 seconds

RECURT.

27-41

14 sec.

SEPT 14/98 CUSTOM CREEK

9-5 VIEW S FROM ± 60m
 W OF MON 81-1

SUMMIT OF W DUNE
 TOWARDS LAKE.

9-6 (D) - J.T. in pic
 9-7 8 - PAN
 9-8 9
 9-9 (U) - 30m E of o/a crest
 ± 60m S of 81-1.

9-10 9-11 T.C.'s across MAIN
 RD INTO OPEN PIT.

9-11 9-12 ± open p.t.
 9-12 #3

9-13 9-14 FROM MINE BUDS
 LOOKING E DCT. OF
 MON. ± CUSTOM CR.

SEPT 14 CUSTOM CR.

9-14 9-15 VIEW OF PARKWAY & R
 9-15 16 FROM ROOM W OF
 9-16 17 MILC.
 9-17 HENRY
 VIEW OF SPRING
 ± POSSIBLE CHARACT.
 REMNANT.

WASHER DOWN ROAD FROM
 MILC ± UNIDENTIFIED
 HENRY SPRING (A) (See Gen
 Sheet 62).

SPRING LINES WE SLOPE
 OF WASTE ROCK ± SW
 ABOVE ROAD
 SLOPE EST C ± 100-150 ppm.

SMALL SPRING TO LEFT (T3m)
 ± 3m ABOVE GR.

9-18 9-19 SPRING (A)
 9-20 9-21 CRACK FROM SPRING
 (S.T. in pic)

CREEK WATER POUNDS ± FROM
D/S WHERE SANDY CREEK
(LESS FLOW?) CUES 1/3 WAY
THROUGH WIRE ROCK
TOWARDS WATERFALL.

9-20 ✓ NEW CHAIR
BEHIND C.S.T.

- * CULVERT @ ROAD
CROSSING (MUS APPROVED)

9-21 ✓ 2ND SPRING.

HEAVY FLOW AS
NOTED ON GEO DRUG.
+ 200 GRM
TO WATERFALL

- Saddle Creek denizens
had fishbones to north
of main spring.

SEPT 14 79 CANTON CR.


✓ 9-22 - VIEW MOUNTAIN
AT 17 AT JENNY
D.D. 1 AM. CHANGE
FROM SPRING A

SPRING B 15-20 GPM.

- FURS SAND/SILT DEPOSITED
D/S OF SPRING
REVERSE X DIPS.

✓ 9-23 - SPRING B CATCH
JEFF S ARM. SWALLOWED

- WAGON TRUCKLE DOWN
CROCK ABOVE SPRING B




(66)

HEAVY ~~USE~~ SUPERGRAVIAN
FROM NOTED 10m UPSIDE
FROM SPRING (LOW IN TRACKER
OF WHEELS VISIBLE)

- HEAVIER FLOW VISIBLE
- THROUGH LOW GROSS

LEVEL WITH
TOP OF MAN
APPROX ASSUME DEGR
BEHIND REAR ENGINE.



(67)

SEPT 14 CUSTON CR.

HEAVY SUPERGRAVIAN FLOW
FROM UP STAIRS FROM SPRING
D.

WATER IS RUNNING DOWN
SPRINGMAN MESS/ TRUCKS, ADJACENT
TOE OF REAR FLOW
-31

✓ 9-24 SET SPRING ON FLOOR
AS 30m. OPS TODAY
SPRING H
+ SW ABOVE ROAD
ENGINE (REAR ENGINE)

FLOW ENDS ± 7m ABOVE
GROUND @ MILL
MILL DECK.


✓ 9-25 (MILL)

✓ 10-0 Behind of 9-25 @
END OF ROLLING

W. N. 200m

FIELD

SEPTEMBER 2 (continued)



10-1-10-2
 2 CONF (Pond)
 (Photo 223)

Photo 10-3 higher up
 looking @ Pond 2.


10-4 10-5 Start Area Sign.
 10-5 6, 7, 8 South Lake
 10-6 7-8 (See Gen Plan)

10-8
 10-9 WATER FLOWING INTO
 CURVE ROCK

10-16 ✓ TILL LIFTED UP
± 100m W OF CREEK
(LINE W B.G.)

WINDING N. ALONG
TILL RIDGE
TOWARDS WASTE PILE
NOW ± 6m ABOVE

TREES, TILL BARRIERS
AND MERRILL
DISTURBED



BEACON & TILLS POINT

X-SECTION 100m D/S FROM
O.D. OUTLET.

(*) 17
18
19 - Run from lake shore

SEPT 14/98 CUSTON CR.

20
21
22 - Run from higher up
valley west

23
24
25 - Run from Tied Bldg.

1-0 JT SCENE AREA

11-2 OPEN PIT


12-3 - SPRING A FROM RD FROM
FARM DOGS.

✓ 6 - T.C.'s along road to 11-11

✓ 7
✓ 8
✓ 9 - Part of (11-11) in
FROM RAMP ± 50m D/S
AT P5

SEPT 14/78 CUNYAN CR

✓ 11-10	- VIEW UP E CROSSING
✓ 11-11	
✓ 11-12	- Same spot
✓ 11-13	
✓ 11-14	
✓ 11-15	- DIS. Feedback
✓ 11-16	WASHED OUT BRIDGE
✓ 11-17	VIEW DIS OF BRIDGE (NEW KING)
✓ 11-18	3-4" of GRAVEL & P.R.
✓ 11-19	± 150m N/S OF BRIDGE
✓ 11-20	ON N/S SIDE OF CHANNEL (420m)
✓ 11-21	UPTO 16" ASKED
✓ 11-22	(Channel 11-20) ± 17 (0/3)
✓ 11-23	11-20
✓ 11-24	TRASH (Washed)
✓ 11-25	TRASH (Washed)
✓ 11-26	TRASH (Washed)
✓ 11-27	TRASH (Washed)
✓ 11-28	TRASH (Washed)
✓ 11-29	TRASH (Washed)
✓ 11-30	TRASH (Washed)
✓ 12-1	TRASH (Washed)
✓ 12-2	TRASH (Washed)
✓ 12-3	TRASH (Washed)
✓ 12-4	TRASH (Washed)
✓ 12-5	TRASH (Washed)
✓ 12-6	TRASH (Washed)
✓ 12-7	TRASH (Washed)
✓ 12-8	TRASH (Washed)
✓ 12-9	TRASH (Washed)
✓ 12-10	TRASH (Washed)
✓ 12-11	TRASH (Washed)
✓ 12-12	TRASH (Washed)
✓ 12-13	TRASH (Washed)
✓ 12-14	TRASH (Washed)
✓ 12-15	TRASH (Washed)
✓ 12-16	TRASH (Washed)
✓ 12-17	TRASH (Washed)
✓ 12-18	TRASH (Washed)
✓ 12-19	TRASH (Washed)
✓ 12-20	TRASH (Washed)
✓ 12-21	TRASH (Washed)
✓ 12-22	TRASH (Washed)
✓ 12-23	TRASH (Washed)
✓ 12-24	TRASH (Washed)
✓ 12-25	TRASH (Washed)
✓ 12-26	TRASH (Washed)
✓ 12-27	TRASH (Washed)
✓ 12-28	TRASH (Washed)
✓ 12-29	TRASH (Washed)
✓ 12-30	TRASH (Washed)



79

11-23

Z0: Z1
D/S U/S

± 275m D/S 66
Z1+140
CR 5007
Flag on ROAD

lateral extent of debris
reduced to say 30m wide.

SHAWABE
BRIDGE
PACK TO

OTUD - EXTENSIVE BEAR
DAM FLOORING - NO
FLOW OBSTACLES U/S/BCE.

11-23

Z3? - END OF ROLL

- Check 190's.

70

11-23
SEPT 14/83

SON
U/S/BCE

- FLOW FROM DAMS
UNDER DAM
APPROX 200m

930m - CR 5007
RESUME BEAR DAM
DAM REPAIR

FLOW DEBRIS U/S/BCE
NO FLOW FROM 30 to 4 DAM

WATER BEHIND FISHBIE
98-1103

DEBRIS U/S/BCE BOTH DAMS
U/S OF 1483 TO 2+14
(road to road 02+14)

180 TO END OF CR E KING
± 452 TO E creek

FIELD

SEPT 14 76 CUSTON CREEK

- ON DRIVE OUT

- CORSE SPARK UPBICE

ON MOST OUTSIDE BENDS

SEVERAL KILOMETERS DOWN

STREAM - POSSIBLE THAT THIS

WATERFALL IS NATURAL &

NOT ASSOCIATED WITH

OTHER FLOW-

\$13000



	Richard Schlachten
	- Jimm Simmonds
	1975 at and 88
13-9	Helicopter from
	ALG 10 TRIP
13-10	5 FURTHER RAPIDS (MEASURE)
13-11	
13-12	
13	
14	CUSTOM CREEK
15	FROM TOP OF
16	WURSTEN BECK
17	FILE US DE
18	P.S.
19	
20	
21	

SEPT 15th / 95
 ARRIVED W. VA @ 11:30
 - MET DATA CENTER (MAYNARD) MATE & DIX
 - DINNER @ 6:00 @ 9:00
 - CAMPED @ MATE'S HOME

DEPART CLINTON CREEK CAMP
 SITE @ 4:15

ARRIVED WHITEHORSE @ 11:30 AM
 TUESDAY

REFERENCES

- Bowie, W.B. 1974. Inspections of Clinton Creek Mine Operations, ARMO Dawson City, June 10-11, 1974.
- Geo-Engineering Ltd., November 1983. Clinton Creek Asbestos Mine – Report on 1988 Site Inspection.
- Geo-Engineering Ltd., November 1986. Clinton Creek Asbestos Mine Abandonment Plan – Review Report.
- Geo-Engineering Ltd., July 1987. Clinton Creek Asbestos Mine – Report on 1987 Annual Inspection.
- Geo-Engineering Ltd., May 1993. Abandoned Clinton Creek Asbestos Mine – Report on Site Inspection.
- Geo-Engineering Ltd., July 1998. Abandoned Clinton Creek Asbestos Mine Report on 1997 and 1998 Site Inspections.
- Golder Associates, April 1977. Report to Cassiar Asbestos Corporation Ltd. on Stabilization Measures for Mine Closure.
- Hardy Associates Ltd., December 1977. Report on Requirements for Development of a Rehabilitation Plan – Clinton Creek Mine, Cassiar Asbestos Corporation.
- Hardy Associates Ltd., 1982. Cassiar Asbestos Mine, Waste Dump and Tailings Pile Inspection.
- Hardy Associates Ltd., April 1984. Rehabilitation Recommendations for Clinton Creek Asbestos Mine.
- Klohn Leonoff Consulting Engineers, August 1983. Report on Mine Waste Dumps.
- Klohn Leonoff Consulting Engineers, November 1983. Report on 1983 Remedial Works – Mine Waste Dumps Clinton Creek Asbestos Mines.
- Klohn Leonoff Consulting Engineers, August 1984. Clinton Creek Waste Dump and Tailings Piles - 1984 Site Visit.
- Klohn Leonoff Consulting Engineers, September 1986. Clinton Creek Asbestos Mine Abandonment Plan.