

## WOLVERINE MINE

# QUARTZ MINING LICENSE QML-0006

# 2010 ANNUAL REPORT

Prepared by: Yukon Zinc Corporation Vancouver, British Columbia

March 31, 2011

# **Table of Contents**

1	Introduction1
1.1	Quartz Mining License Requirements
2	2010 Mine Activities
2.1	Mine Development – Surface Infrastructure
2.2	Tailings Facility Activities
2.3	Underground Mine7
2.4	Updates to Estimates of Ore Reserves and Mine Life
2.5	Underground Stability Incidents 11
2.6	Paste Backfill11
2.7	Mill Operations
3	Annual Engineering Inspections 12
3.1	Mill and Associated Infrastructure Inspection
3.2	Tailings Storage Facility Inspection13
3.3	Underground Mine Inspection
4	Hydrogeology Studies
5	Environmental Monitoring and Surveillance15
<b>5</b> 5.1	Environmental Monitoring and Surveillance
5.1	Surface Water Quality Monitoring and Acute Lethality Testing15
5.1 5.2	Surface Water Quality Monitoring and Acute Lethality Testing
5.1 5.2 5.3	Surface Water Quality Monitoring and Acute Lethality Testing15Groundwater Quality Monitoring17Environmental Monitoring for Construction Activities17
5.1 5.2 5.3 <b>6</b>	Surface Water Quality Monitoring and Acute Lethality Testing15Groundwater Quality Monitoring17Environmental Monitoring for Construction Activities17Environmental Incidents19
5.1 5.2 5.3 <b>6</b> <b>7</b>	Surface Water Quality Monitoring and Acute Lethality Testing15Groundwater Quality Monitoring17Environmental Monitoring for Construction Activities17Environmental Incidents19Access Road Operation19
5.1 5.2 5.3 <b>6</b> <b>7</b> 7.1	Surface Water Quality Monitoring and Acute Lethality Testing15Groundwater Quality Monitoring17Environmental Monitoring for Construction Activities17Environmental Incidents19Access Road Operation192010 and Projected 2011 Use20
5.1 5.2 5.3 <b>6</b> 7.1 7.2	Surface Water Quality Monitoring and Acute Lethality Testing15Groundwater Quality Monitoring17Environmental Monitoring for Construction Activities17Environmental Incidents19Access Road Operation192010 and Projected 2011 Use202010 Work and Upgrades Conducted20
5.1 5.2 5.3 <b>6</b> 7.1 7.2 7.3	Surface Water Quality Monitoring and Acute Lethality Testing15Groundwater Quality Monitoring17Environmental Monitoring for Construction Activities17Environmental Incidents19Access Road Operation192010 and Projected 2011 Use202010 Work and Upgrades Conducted20Access Control Issues21
5.1 5.2 5.3 <b>6</b> <b>7</b> 7.1 7.2 7.3 7.4	Surface Water Quality Monitoring and Acute Lethality Testing15Groundwater Quality Monitoring17Environmental Monitoring for Construction Activities17Environmental Incidents19Access Road Operation192010 and Projected 2011 Use202010 Work and Upgrades Conducted20Access Control Issues21Projected Road Construction Activities21
5.1 5.2 5.3 <b>6</b> <b>7</b> 7.1 7.2 7.3 7.4 7.5	Surface Water Quality Monitoring and Acute Lethality Testing15Groundwater Quality Monitoring17Environmental Monitoring for Construction Activities17Environmental Incidents19Access Road Operation192010 and Projected 2011 Use202010 Work and Upgrades Conducted20Access Control Issues21Projected Road Construction Activities21Wildlife Incidents or Other Accidents21
5.1 5.2 6 7 7.1 7.2 7.3 7.4 7.5 <b>8</b>	Surface Water Quality Monitoring and Acute Lethality Testing15Groundwater Quality Monitoring17Environmental Monitoring for Construction Activities17Environmental Incidents19Access Road Operation192010 and Projected 2011 Use202010 Work and Upgrades Conducted20Access Control Issues21Projected Road Construction Activities21Reclamation Activities21Reclamation Activities21

# **List of Tables**

Table 1-1:	$QML\ Annual\ Report\ Information\ Requirements\ and\ Corresponding\ Report\ Section\ \ldots \ldots 1$
Table 1-2:	QML Submissions in 2010
Table 2-1:	Total Amount and Grade of Concentrate Produced, Stockpiled and Transported by End of 201011
Table 3-1:	2010 Mill Associated Infrastructure Inspection Recommendations and Actions Taken $\dots$ 13
Table 5-1:	Surface Water Monitoring Sites and Sampling Frequency16
Table 5-2:	Groundwater Monitoring Sites and Sampling Frequency17
Table 5-3:	2010 Summary of Completed Environmental Monitoring Reports by Area18
Table 6-1:	Environmental Incidents in 201019
Table 7-1:	2010 Access Road Vehicle Usage
Table 9-1:	Goods and Services Procured from Ross River, Watson Lake and the Yukon for 2010 24
Table 10-1:	Planned Total Ore to be Mined from Underground in 201124
Table 10-2:	Concentrate Production Estimated for 201125

# **List of Figures**

Figure 2-1:	Wolverine Mine Surface Infrastructure and Roads at End of 2010	. 6
Figure 2-2:	Overall 2010 Underground Development	. 8
Figure 2-3:	Underground Mine Refuge Station	. 9
Figure 2-4:	Plan View and Sections Through Typical Ventilation Overcasts	10
Figure 4-1:	2010 Daily Average Underground Recharge Rates	14

# **List of Pictures**

Picture 2-1: Overview of industrial complex area including camp, mill, concentrate load-out (CLO), crusher buildings, as well as power generator area and fuel storage areas	.4
Picture 2-2: Mill building, cement silo and conveyor.	
Picture 2-3: Power generation area and fuel storage	. 4
Picture 2-4: Tailings storage facility and mine access road.	. 5
Picture 2-5: Applying shotcrete during mine rehabilitation.	. 7
Picture 2-6: Fan raise for the ventilation of the underground mine	. 7
Picture 8-1: Road widening to improve sight lines at corner; subsequent work would entail preading of windrowed material on fill slope-slope stabilization.	
Picture 8-2: Slope stabilization long fill slope; organic material to be placed on slope after grading complete	22
Picture 8-3: Organic material and woody debris placed along downslope area to promote natural revegetation.	22
Picture 8-4: Woody debris and organics placed in previous borrow/staging area.	22
Picture 8-5: Coconut matting and seeding at erodible area draining to a newly installed culvert	22
Picture 8-6: Coconut matting, rip rap, and silt fence (temporary) at culvert inlet	22
Picture 8-7: Grading of borrow pit and placement of organic material along road corridor	23

# **List of Appendices**

#### (Content contained on enclosed CD)

Appendix A: Environmental Monitoring Reports

# 1 Introduction

This Annual Report has been prepared to satisfy requirements contained within Quartz Mining License QML-0006 (QML) Condition 10.5 for activities that occurred during the period of January  $1^{st}$  to December  $31^{st}$ , 2010 at the Wolverine Mine.

Table 1-1 outlines the QML Annual Report documentation requirements and the corresponding report section where the information is provided herein. A Socio-Economic Assessment summary is provided in Section 9 of this report, to satisfy requirements of the Environmental Assessment Screening Document (issued September 20, 2006 by the Development Assessment Branch, Government of Yukon).

 Table 1-1:
 QML Annual Report Information Requirements and Corresponding Report Section

QML Section	Requirement	Section
10.5 a)	A summary of mining activities at the mine.	2.3
10.5 b)	A map showing all structures, works and installations associated with the Undertaking.	2.1
10.5 c)	The total amount of ore and waste removed from the mine.	2.4
10.5 d)	The total amount and the average head grade of ore processed through the mill.	2.4
10.5 e)	The total amount and grade of all stockpiled ore.	2.4
10.5 f)	The total amount and grade of concentrate produced, stockpiled, and transported from the Undertaking.	2.4
10.5 g)	As-built drawings of the mine and of all structures, works and installations constructed or altered in the mine.	2.3
10.5 h)	Details respecting any action taken as a result of the recommendations made by the engineer in relation to the inspection referred to in paragraph 10.1.	3
10.5 i)	A summary of any updates to estimates of ore reserves and mine life, including reserve category, tonnage and grade.	2.4
10.5 j)	A summary of any underground stability incidents.	2.5
10.5 k)	A summary of paste backfill placement activities conducted and their locations in the mine.	2.6
10.5 l)	A summary of humidity cell tests undertaken for waste rock and paste backfill.	2.6
10.5 m)	A summary of quantity and related analysis of leachate collected from paste backfill.	2.6
10.5 n)	The total amount of tailings deposited in the tailings impoundment.	2.2
10.5 o)	An evaluation of the performance of the tailings facility, including an estimate of	2.2

QML Section	Requirement	Section
	remaining available storage capacity in the facility.	
10.5 p)	The data generated from the full depth sampling of the tailings.	2.2
10.5 q)	A summary of any hydrogeology studies undertaken and related analysis of these data, including groundwater flow pathways as influenced by underground workings.	4
10.5 r)	A summary and evaluation of data results from the field pilot test of the bio-pass system.	8.1
10.5 s)	A summary of surface water quality monitoring, including any acute lethality testing conducted.	5.1
10.5 t)	A summary of groundwater quality monitoring in wells downslope of the mine workings.	5.2
10.5 u)	A summary of the programs undertaken for environmental monitoring and surveillance as outlined in the Monitoring and Surveillance Plan and the Wildlife Protection Plan, including an analysis of these data and any action taken or adaptive management strategies implemented to monitor or address any changes in environmental performance.	5
10.5 v)	A summary of progressive and ongoing reclamation activities.	8
10.5 w)	A summary of proposed development and production for the coming year.	10
10.5 x)	A summary of activities related to care and maintenance of the Undertaking, including any temporary closure activities, if applicable.	8
10.5 y)	A summary of spills and accidents that occurred as a result of the Undertaking.	6
10.5 z)	A summary of the previous and projected use of the access road, including maintenance work conducted, a summary of the level of traffic, access control issues, wildlife incidents and other accidents, and upgrade or maintenance work planned for the upcoming year.	7

#### **1.1 Quartz Mining License Requirements**

All major and minor permits are in place for the Wolverine Mine, with all infrastructure located on YZC mineral claims. All QML requirements pertaining to monitoring and reporting were achieved in 2010, and the submissions to Yukon Energy, Mines and Resources (EMR) are summarized in Table 1-2. All plans and reports submitted to EMR are available on the EMR website: http://www.emr.gov.yk.ca/mining/wolverine.html.

#### Table 1-2:QML Submissions in 2010

Submission	Date Submitted
2009 Annual Report for QML-0006	19-Mar-10
Reclamation and Closure Plan V2009-03	15-Apr-10
Wildlife Protection Plan Annual Report	16-Apr-10
Notification of Milling	29-Apr-10
Mill Operating Plan V2010-02	25-May-10
Tailings Facility Starter Dam As-Constructed Report (Klohn Crippen Berger)	31-May-10
Monitoring and Surveillance Plan V2010-02	31-May-10
Mine Development and Operating Plan V 2010-02	8-Aug-10
EBA Engineering Consultants 2010 Annual Inspections of the On-Site Earth Structures	4-Aug-10
Klohn Crippen Berger Wolverine Tailings Facility Annual Tailings Facility Physical Inspection	4-Aug-10
Tailings Facility Operation, Maintenance +Surveillance Manual V2010-01	11-Aug-10
General Site Plan Addendum for Airstrip Emergency Stopway Extension	22-Aug-10
Mine Development Plan V2010-02 Section 5 Addendum	29-Dec-10
Rockland Ltd. Inspection Report For Quartz Mining License - Underground Geotechnical	04-Jan-11
Inspection	

### 2 2010 Mine Activities

Mine activities in 2010 focused on the completion of surface construction by mid 2010 for commissioning of the mill in late 2010, and continued underground development.

#### 2.1 Mine Development – Surface Infrastructure

Figure 2-1 provides the location of major surface infrastructure at the industrial complex area, airstrip and tailings facility in 2010. A report entitled *Wolverine Project Industrial Complex As-Constructed Report and Drawings* will be submitted under QML-0006 and Type A Water Use Licence QZ04-065 by Q2 2011. This report will include as-constructed details for the following:

- Mine support surface infrastructure (see Picture 2-1);
- Power generation and fuel storage (see Picture 2-3);
- Mill and associated infrastructure (see Picture 2-2);
- Camp and supporting infrastructure; and
- Airstrip.

The infrastructure constructed at the tailings storage facility (see Picture 2-4) was summarized in the *Starter Tailings Storage Facility -2009 Civil Works Construction Summary Report* (Klohn Crippen Berger) submitted to EMR on May 31, 2010.



Picture 2-1: Overview of industrial complex area including camp, mill, concentrate load-out (CLO), crusher buildings, as well as power generator area and fuel storage areas.



Picture 2-2: Mill building, cement silo and conveyor.


Picture 2-3: Power generation area and fuel storage.

#### 2.2 Tailings Facility Activities

The total amount of tailings deposited into the tailings impoundment in 2010 was 33,839 tonnes, comprised of 10,378 tonnes of waste and 23,461 tonnes of ore.

The tailings facility has performed as planned and as of December 10, 2010, was surveyed to contain 173,320 m<sup>3</sup>. As the starter impoundment has a capacity of 665,127 m<sup>3</sup>, the available volume remaining is 74%.

A full depth sampling of the tailings was not conducted for the purpose of determining tailings chemistry as the facility only contained tailings generated during the commissioning phase and stockpiled ore and waste rock is therefore not yet representative.



Picture 2-4: Tailings storage facility and mine access road.




Figure 2-1: Wolverine Mine Surface Infrastructure and Roads at End of 2010

#### 2.3 Underground Mine

The two primary objectives of underground development were to:

- 1. Excavate the main access ramp and develop a ventilation circuit through a series of fresh air raises (FAR). The ramp was developed to the 1213 stope access (SA) elevation and included an installation of an electrical substation (from 1230 SA to 1220 SA). The fresh air raise system in the Wolverine zone was completed to the 1210 SA. The Lynx zone fresh air raise / secondary egress system was developed to the 1240 SA, where a permanent 40 man mine refuge station was constructed.
- 2. Develop footwall drifts in both the Wolverine and Lynx ore zones. These drifts allowed geologist to analyze structures and correlate them to the current ore model as well as help anticipate situations which may be encountered during the mining cycle. Three stope footwall drifts (1270 SA, 1250 SA and 1220 SA) were completed almost to the ore extent, and two drifts (1260 SA and 1240 SA) were developed close to the beginning of the ore zone.





Picture 2-5: Applying shotcrete during mine rehabilitation.

Picture 2-6: Fan raise for the ventilation of the underground mine.

Road bed material for underground was sourced at km 19 of the access road via drilling, blasting and crushing.

The following drawings to illustrate the development completed in 2010 are provided below:

- Figure 2-2: Underground workings including stope accesses and fresh ventilation systems in the Lynx and Wolverine deposits;
- Figure 2-3: Mine refuge station at Lynx 1240 SA (another station will be established at 1160 SA once 69% of total planned development has been achieved).
- Figure 2-4: Ventilation raise system plan and section drawings.




Figure 2-2: Overall 2010 Underground Development




Figure 2-3: Underground Mine Refuge Station




Figure 2-4: Plan View and Sections Through Typical Ventilation Overcasts

#### 2.4 Updates to Estimates of Ore Reserves and Mine Life

An update was not determined for the ore reserve or mine life in 2010.

#### 2.5 Underground Stability Incidents

There were two stability incidents in 2010.

- 1. On March 12<sup>th</sup>, a ground failure occurred at the floor level on the footwall side of the stope at 1260 SA. It was determined that the ground was unravelling behind the shotcrete and remedial action was immediately undertaken.
- 2. On April 25<sup>th</sup>, two mechanics and an equipment operator were performing routine maintenance on a rock bolting machine, when the side wall gave way at the working face of the foot wall drift at 1220 SA. One of the mechanics was fatally injured while the other received minor injuries. The operator was not hurt. All underground development ceased and a geotechnical engineer was contracted to review the underground support requirements (see Section 3.3). All areas in the mine were inspected and by year-end, the mine was rehabilitated to requirements accepted by Yukon Workers Compensation, Health and Safety Board.

#### 2.6 Paste Backfill

Paste backfill was not placed in the mine in 2010, and hence paste backfill placement activities and their respective locations are not summarized herein, nor were leachate collection activities undertaken in 2010. Details of humidity cell tests conducted for paste backfill analysis are provided in the *Wolverine Mine Monitoring and Surveillance Plan 2010 Annual Report*.

#### 2.7 Mill Operations

The total amount of waste and ore removed from the mine in 2010 was 10,528 tonnes and 26, 826 tonnes, respectively. Ore removed from the mine was processed through the mill and the average head grade was:

• 6.57% Zn;

15.79% Fe; and
284 g/t Ag.

• 0.70% Cu;

0.90% Pb;

- The total amount and grade of concentrate produced, stockpiled, and transported from the Wolverine Mine is summarized in Table 2-1.

Table 2-1:Total Amount and Grade of Concentrate Produced, Stockpiled and Transported by Endof 2010

Concentrate	Cu (%)	Pb (%)	Zn (%)	Ag (g/t)	Dry Milled Tonnes				
concentrate	Cu (78)	PD (70)	211 (70)	AB (8/1)	Produced	Stockpiled	Transported		
Cu	16.30	3.39	5.64	3805	434	434	0		
Pb	5.03	16.40	11.43	3550	426	0	426		
Zn	1.64	2.71	38.03	690.1	2506	0	2506		

Details of humidity cell tests conducted for mine waste rock and ore analysis are provided in the *Wolverine Mine Monitoring and Surveillance Plan 2010 Annual Report*.

### **3** Annual Engineering Inspections

Three engineering inspections occurred in 2010 and subsequent reports were submitted to EMR within 45 days of the inspections being completed. The inspections and respective reports are as follows:

- EBA Engineering Consultants conducted an inspection of the structures at and around the industrial complex on June 19-21, 2010 and the report was submitted on August 4, 2010;
- Klohn Crippen Berger conducted an inspection of the tailings stoage facility on June 28, 2010 and the report and the report was submitted on August 4, 2010; and
- Rockland Ltd. conducted an inspection of the underground mine on December 13, 2010 and the report was submitted on January 4, 2011.

The results of these inspections are summarized below, as are the actions taken to date by YZC.

#### 3.1 Mill and Associated Infrastructure Inspection

The EBA inspection of structures associated with the mill (excluding the tailings storage facility) included a visual inspection of the following structures:

- 1. Industrial complex cut and fill slopes.
- 2. Industrial complex surface and underground water treatment sumps (1, 2, 3, 4 and 5) -liners and slopes.
- 3. Industrial complex diversion ditch 1 cut and fill slopes.
- 4. Industrial complex collection ditches (2, 3, 4 and 5) liners, cut and fill slopes.
- 5. Camp pad area including upper generator and water treatment pad, sewage treatment plant pad, and treated effluent pond liner, cut and fill slopes.
- 6. Temporary waste rock and ore storage facility including seepage collection sump and stockpiles, and cut and fill slopes.
- 7. Land treatment facility (contains hydrocarbon contaminated material) including runoff collection sump liners and fill slopes.
- 8. Vent raise and propane tank pad cut slopes.

Table 3-1 summarizes the recommendations in the report with the corresponding actions taken by YZC in 2010. EBA noted observations and concluded that the onsite earthen structures posed no significant risk to the environment or human health and safety.

Structure	Recommendation	YZC Completed Actions
Industrial complex Upper mill pad	Noticeable erosion channels along the south western side of the mill fill created during spring melt. Erosion channels should be filled in with coarse grained material until proper perimeter berms can be completed to divert surface runoff towards drainage ditches.	YZC completed installation of geotextile within eroded channels and placement of cobble to anchor in place. Monitored regularly and no further erosion observed.
Industrial complex surface and underground water treatment sumps (1, 2 & 3)	Sumps 1, 2 & 3: Noticeable settlement of the backfill along the perimeter lined key trenches and buried propane lines indicating that backfill material was not compacted during placement. Repairs should be carried out as soon as possible. Sump 1: Bubble in the liner caused by a high water table. This should be monitored for an increase in the size of the bubble.	Monitored regularly. No additional settlement observed. Poses no risk to the environment. No further lifting of the liner (due to high water table)
Collection Ditches 3 & 4	Ditch 3: A lot of sediment had collected in the bottom of the ditch. Also, tension cracks had appeared along the upper portion of the outer slope. The tension cracks should be filled to reduce water infiltration.	Tears in liner along both ditches identified. Monitored regularly, but water level below compromised liner.
	Ditch 4: Many small tears along both sides of the ditch cause by snow removal prior to spring run-off. The side slopes require repair. A large tension crack is visible on the western side of the ditch. Additional repair work should be conducted to fill in the depression. Other erosion channels and tension cracks should also be filled in.	Sediment to be removed before freshet in spring 2011. Roads running parallel to the ditches have been graded to minimize movement of fines into ditches with precipitation events.
Camp pad area including upper generator and water treatment pad, sewage treatment plant pad and treated effluent pond	Noticeable tension cracks along the perimeter of the fill slope of the camp, upper generator and water treatment pads. These areas should be monitored and repaired as required.	Monitored regularly. No changes since inspection date.

Table 3-1:	2010 Mill Associated Infrastructure Inspection Recommendations and Actions Taken
------------	--

#### 3.2 Tailings Storage Facility Inspection

A visual inspection of the tailings storage facility was conducted by Klohn Crippen Berger produced no significant observations that would suggest any concerns with the stability of the facility or its ability to store tailings as per the design. General recommendations summarized previously known to YZC are as follows:

1. Complete the 2010 construction works and installation of monitoring instrumentation.

- 2. Continue to operate the facility as described in the Operation, Maintenance and Surveillance Manual (OM&S Manual).
- 3. Observe the performance of Ditch B during high rainfall events and spring freshet to check if water reports to the impoundment or remains subsurface. If water emerges upslope above the impoundment liner, and flows into the impoundment, an estimate of the water flow rate should be made.
- 4. The settlement cracks along the perimeter road on the east side of the impoundment should be observed monthly to see if there are any changes.
- 5. Continue monitoring the spring near the toe of the dam on the south end to confirm that it is not significant.


Subsequent to receipt of the inspection report, YZC completed the 2010 construction works (emergency spillway and installation of instrumentation), is operating the facility as per the OM&S Manual and is monitoring the facility weekly and monthly. Ditch B will be monitored during high rainfall events and during freshet, as will the spring near the toe of the dam.

#### 3.3 Underground Mine Inspection

An inspection of the geotechnical aspects of the Wolverine underground mine was conducted by Rockland Ltd. Guidelines and recommendations contained within the report continue to be followed for underground mine development activities.

## 4 Hydrogeology Studies

Hydrological flow rates in the underground workings were monitored throughout 2010. Recharge rates were calculated using a flow meter on the discharge pipe and the average daily inflow was  $257 \text{ m}^3/\text{day}$  (monthly averages are shown in Figure 4-1). Recharge rates ranged from 162 m<sup>3</sup>/day (January 2010) to 346 m<sup>3</sup>/day (July 2010) and indicate seasonal variations consistent with previous years.





### 5 Environmental Monitoring and Surveillance

As per annual report requirements, summaries are provided below for:

- Surface water quality monitoring and acute lethality testing
- Groundwater quality monitoring in wells downslope of the mine workings

In addition, Section 5.3 provides information on construction monitoring. Specific information can be on wildlife monitoring in the *Wolverine Project Wildlife Protection Plan 2010 Annual Report*, and on environmental monitoring and surveillance in the *Monitoring and Surveillance Plan 2010 Annual Report*.

#### 5.1 Surface Water Quality Monitoring and Acute Lethality Testing

Surface water quality monitoring for the purposes of baseline monitoring (as per A Licence QZ04-065 (Yukon Water Board, 2007)) was taken at the locations and dates summarized in Table 5-1. A total of 197 sample sets were analyzed for physical parameters, TSS, dissolved and total metals (by ICP-MS) and mercury (by CVAS), as well as cyanide and dissolved organic carbon for select sampling sites (W16 & W31).

Because all underground water was sent, untreated, to the tailings storage facility in 2010, there were no discharges to the environment, and thus no acute lethality testing conducted in 2010.

Sampling Site	January	February	March	April	May	June	July	August	September	October	November	December
T1	n/a	n/a	n/a	n/a	n/a	n/a	19-Jul	30-Aug	6-Sep	30-Oct	20-Nov	22-Dec
L1	15-Jan	5-Feb	27-Mar	А	А	25-Jun	9-Jul	2-Aug	7-Sep	3-Oct	24-Nov	17-Dec
W1	18-Jan	5-Feb	27-Mar	А	А	Α	9-Jul	2-Aug	7-Sep	3-Oct	А	17-Dec
W8	15-Jan	5-Feb	D	А	23-May	25-Jun	3-Jul	26-Aug	7-Sep	10-Oct	21-Nov	18-Dec
W9	15-Jan	5-Feb	D	А	23-May	14-Jun	3-Jul	26-Aug	7-Sep	10-Oct	21-Nov	18-Dec
W12	21-Jan	21-Feb	А	17-Apr	18-May	6-Jun	14-Jul	22-Aug	11-Sep	2-Oct	9-Nov	А
W14	21-Jan	21-Feb	А	17-Apr	18-May	6-Jun	14-Jul	22-Aug	11-Sep	2-Oct	9-Nov	А
W15	29-Jan	19-Feb	19-Mar	А	15-May	7-Jun	28-Jul	21-Aug	11-Sep	22-Oct	23-Nov	29-Dec
W16	29-Jan	19-Feb	19-Mar	А	9-May	7-Jun	28-Jul	27-Aug	4-Sep	30-Oct	26-Nov	26-Dec
W21	31-Jan	7-Feb	20-Mar	16-Apr	15-May	5-Jun	9-Jul	9-Aug	8-Sep	1-Oct	5-Nov	9-Dec
W22	31-Jan	7-Feb	20-Mar	16-Apr	15-May	5-Jun	9-Jul	9-Aug	8-Sep	1-Oct	5-Nov	5-Dec
W31	D	D	D	22-Apr	17-May	15-Jun	28-Jul	20-Aug	9-Sep	20-Oct	20-Nov	D
W40	31-Jan	7-Feb	20-Mar	16-Apr	15-May	5-Jun	9-Jul	9-Aug	6-Sep	1-Oct	5-Nov	5-Dec
W71	28-Jan	7-Feb	20-Mar	18-Apr	8-May	5-Jun	9-Jul	24-Aug	6-Sep	1-Oct	6-Nov	5-Dec
W72	28-Jan	7-Feb	20-Mar	18-Apr	8-May	5-Jun	9-Jul	24-Aug	6-Sep	1-Oct	6-Nov	5-Dec
W73	28-Jan	7-Feb	20-Mar	18-Apr	8-May	5-Jun	9-Jul	24-Aug	6-Sep	1-Oct	6-Nov	24-Dec
W80	22-Jan	25-Feb	А	17-Apr	18-May	6-Jun	14-Jul	А	4-Sep	2-Oct	9-Nov	А
W81	22-Jan	25-Feb	19-Mar	А	15-May	6-Jun	28-Jul	21-Aug	4-Sep	22-Oct	23-Nov	29-Dec
W82	30-Jan	20-Feb	25-Mar	10-Apr	23-May	4-Jun	1-Jul	27-Aug	10-Sep	10-Oct	29-Nov	D

 Table 5-1:
 Surface Water Monitoring Sites and Sampling Frequency

n/a = the pump barge was not installed at site T1 in the tailings storage facility, hence it was not possible to safely sample at that site until the barge was installed in July, 2011

A = Site not sampled due to lack of safe access

D = Site dry (i.e., all water tied up in storage, and/or subsurface water table low) or frozen through

### 5.2 Groundwater Quality Monitoring

Groundwater wells downslope of the mine workings were sampled quarterly in 2011 as required by A Licence QZ04-065 and sampling is summarized in Table 5-3.

Monitoring Station	March	June	September	December
MW05-3A	F	20-Jun	29-Sep	F
MW05-3B	MW05-3B F		29-Sep	13-Dec
MW05-5A	11-Mar	20-Jun	29-Sep	14-Dec
MW05-5B	F	20-Jun	29-Sep	F
MW06-11S F		30-Jun	29-Sep	F

Table 5-2:Groundwater Monitoring Sites and Sampling Frequency

F = frozen well/no flow

#### 5.3 Environmental Monitoring for Construction Activities

Environmental monitoring reports for all construction activities were prepared by the YZC Environmental Department during the construction phase. Table 5-3 summarizes the Environmental Monitoring Reports prepared (detailed reports provided in Appendix A), including the area monitored, the monitoring period and the date of the monitoring report.

Monitoring Period			Monitoring Period				
Site	From	То	Report Date	Site	From	То	Report Date
	Access	Road	•		Industrial	Complex	•
		23-Feb-10	23-Feb-10	Ditch 3	13-Apr-10	26-Apr-10	26-Apr-10
	02-Mar-10	15-Mar-10	15-Mar-10			09-Jun-10	22-Jun-10
	16-Mar-10	27-Mar-10	29-Mar-10	Ditch 4	13-Apr-10	26-Apr-10	26-Apr-10
		03-Apr-10	03-Apr-10		11-May-10	25-May-10	25-May-10
	04-Apr-10	14-Apr-10	27-Apr-10		Lan	dfill	
	27-Apr-10	10-May-10	11-May-10		12-Jan-10	19-Jan-10	19-Jan-10
	11-May-10	24-May-10	25-May-10		20-Jan-10	27-Jan-10	27-Jan-10
	24-May-10	07-Jun-10	07-Jun-10		02-Feb-10	15-Feb-10	15-Feb-10
	23-Jun-10	04-Jul-10	05-Jul-10		16-Feb-10	01-Mar-10	01-Mar-10
	05-Jul-10	19-Jul-10	20-Jul-10		02-Mar-10	15-Mar-10	15-Mar-10
	20-Jul-10	02-Aug-10	02-Aug-10		16-Mar-10	29-Mar-10	29-Mar-10
	03-Aug-10	16-Aug-10	16-Aug-10		30-Mar-10	12-Apr-10	12-Apr-10
	24.6 40	09-Sep-10	13-Sep-10		13-Apr-10	26-Apr-10	26-Apr-10
	21-Sep-10	04-Oct-10	04-Oct-10		27-Apr-10	10-May-10	11-May-10
	05-Oct-10	19-Oct-10	19-Oct-10		11-May-10	24-May-10	25-May-10
Ac	cess Road - Cr		-		25-May-10	07-Jun-10	07-Jun-10
	01-Mar-10	08-Mar-10	15-Mar-10		08-Jun-10	21-Jun-10	22-Jun-10
		16-Mar-10	29-Mar-10		22-Jun-10	05-Jul-10	05-Jul-10
		03-Apr-10	03-Apr-10		06-Jul-10	19-Jul-10	20-Jul-10
		23-Apr-10	26-Apr-10		20-Jul-10	02-Aug-10	02-Aug-10
	08-May-10	10-May-10	11-May-10			28-Sep-10	28-Sep-10
		24-May-10	25-May-10		Tailings		
	26-May-10	07-Jun-10	07-Jun-10		13-Apr-10	26-Apr-10	26-Apr-10
		13-Jun-10	13-Jun-10		09-Jun-10	11-Jun-10	22-Jun-10
	Airstrip E				Tail	-	
	01-Sep-10	21-Sep-10	21-Sep-10		20-Jul-10	02-Aug-10	02-Aug-02
	Industrial				Temporary /		
Ind. Complex	19-Jan-10	27-Jan-10	27-Jan-10			26-Jan-10	28-Jan-10
	02-Feb-10	15-Feb-10	15-Feb-10		02-Feb-10	15-Feb-10	15-Feb-10
	15-Feb-10	01-Mar-10	01-Mar-10			30-Sep-10	30-Sep-10
	03-Mar-10	15-Mar-10	15-Mar-10		Temporar	-	
	16-Mar-10	29-Mar-10	29-Mar-10		11-Apr-10	17-Apr-10	17-Apr-10
	30-Mar-10	12-Apr-10	12-Apr-10		17-Apr-10	24-Apr-10	24-Apr-10
	13-Apr-10	26-Apr-10	27-Apr-10		05-May-10	09-May-10	09-May-10
	27-Apr-10	11-May-10	11-May-10		25-Jun-10	16-Jul-10	18-Jul-10
	25-May-10	07-Jun-10	07-Jun-10		Powe		
	08-Jun-10	21-Jun-10	21-Jun-10		25-Feb-10	02-Mar-10	02-Mar-10
	22-Jun-10	05-Jul-10	05-Jul-10		02-Mar-10	15-Mar-10	15-Mar-10
	06-Jul-10	19-Jul-10	20-Jul-10		16-Mar-10	27-Mar-10	29-Mar-10
	20-Jul-10	02-Aug-10	02-Aug-10		13-Apr-10	27-Apr-10	27-Apr-10
	03-Aug-10	16-Aug-10	16-Aug-10		Waste R		
	26-Sep-10	30-Sep-10	30-Sep-10			23-Apr-10	23-Apr-10
	05-Oct-10	19-Oct-10	19-Oct-10		27-Apr-11	11-May-10	11-May-10
					26-May-10	07-Jun-10	07-Jun-10

#### Table 5-3: 2010 Summary of Completed Environmental Monitoring Reports by Area

Yukon Zinc Corporation

## 6 Environmental Incidents

There were four reportable spills (defined by the *Yukon Spills Regulations* as "a release of a hazardous substance to the environment in quantities above the spill reporting thresholds, or any amount of spill onto a watercourse" and one unauthorized discharge in 2010, (Table 6-1). Spills were immediately reported and full spill reports were submitted to EMR within 10 days of their respective occurrences. Follow up reports were submitted upon receipt of laboratory results.

Date	Volume and Substance	Party Responsible	Cause	Reporting and Follow-up Actions
06-Jan-10	~600-800 L of diesel	Procon	Overfilling of a full tank via generator return line (which should have been connected to the adjacent tank)	Initial Report: 15-Jan-10 Follow-up Report: 19-Feb-10
11-Mar-10	~550 L of glycol	Gisborne	Fork-lift punctured glycol tote during transportation	Initial Report: 12-Mar-10 Follow-up Report: 16-Mar-10
23-Oct-10	~7.2 m <sup>3</sup> of ethylene glycol	Yukon Zinc	Overfill of vent drain catchment tote	Initial Report: 27-Oct-10 Follow-up Report: 02-Nov-10 Final Report: 12-Nov-10 Further soil samples to be collected in spring for confirmation testing.
20-Nov-10	100 L Underground mine effluent water	Yukon Zinc	Back pressure at the transfer elbow resulting when pumping water between sumps	Initial Report: 20-Nov-10 Follow-up Report: 30-Nov-10 The line is currently not in use and will be replaced in the spring 2011.
10-Dec-10	700 L of diesel fuel	Yukon Zinc	Broken weld in boiler house fuel supply line	Initial Report: 13-Dec-10 Follow-up Report: 4-Jan-11 Soil samples will be sampled during spring for testing.

 Table 6-1:
 Environmental Incidents in 2010

## 7 Access Road Operation

Access road activities outlined in the sections below include the 2010 use and projected 2011 use, maintenance work, access control, and road upgrade or maintenance activities.

#### 7.1 2010 and Projected 2011 Use

In 2010, all freight and service vehicles entering and exiting site were recorded by site security and are summarized by month in Table 7-1. The total annual access road usage for 2010 was 4100 vehicles and characterized as follows:

- 2593 freight truck deliveries to supply materials for construction purposes;
- 98 concentrate trucks;
- 1409 light vehicles; and

Table 7-1:2010 Access Road Vehicle Usage

Month	Vehicle Traffic
January	475
February	508
March	476
April	446
Мау	317
June	431
July	440
August	342
September	133
October	185
November	181
December	166
Total	4100

In 2011, the number of concentrate haul trucks and service vehicles on the road is anticipated daily to average a total of 30.

#### 7.2 2010 Work and Upgrades Conducted

Improvements to the access road included widening, raising and reducing grade, ditching and drainage control, decreasing side slopes, straightening of dangerous corners, installation of berms, improvements to existing and additional pull out bays, surfacing and defining shoulders. Culverts and culvert extensions were installed and rip rap was placed at culvert entrances. All these works were completed by the end of October.

Upgrading of the access road also occurred on the southeast side of the tailings facility from km 24+800 to km 24+300. This was to ensure that the seepage dam was constructed to elevation 1286.5 m.

Widening of a bottle neck portion of the road from km 27 to km 26+900 was done to allow safe access to the fresh water well pump-house. Heat trace insulated freshwater lines were later installed on this route to the mill.

Sediment and erosion control was conducted throughout construction and included silt fence installation, geotextile installation, and temporary sump construction with controlled pumping.

#### 7.3 Access Control Issues

There have been no issues with access control. There are two Wolverine Mine Access Control Gates at km 0.1 and km 0.49, to prevent public use of the access road. A radio-controlled automated gate opener was installed at the gate at km 0.1 in 2008 and is currently in use. The gate was manned 24 hours a day by site security until mid-2010; after which they conducted routine patrols along the access road during each shift. All vehicles entering and leaving the site are required to call security, via radio, to gain access/exit through the radio-controlled gate.

#### 7.4 Projected Road Construction Activities

YZC will continue with road improvements for concentrate haul trucks and service vehicle use as needed in 2011.

#### 7.5 Wildlife Incidents or Other Accidents

There were no wildlife incidents or other accidents on the access road in 2010.

### 8 Reclamation Activities

In 2010, the focus of activities was the completion of surface construction activities and improvements to the access road. All activities were completed within defined footprints and impacts minimized as necessary to lessen reclamation requirements. There were no activities related to care and maintenance or temporary closure in 2010. Progressive reclamation activities were completed during access road improvements, mainly including

- 1. Roadside slope stabilization and recontouring of slopes followed by placement of organic material and large wood debris.
- 2. In areas where permafrost was encountered, coconut mats were spread over the area for insulation and seeded.
- 3. Coconut matting was also used in roadside areas where there was minimal organics for seeding.
- 4. Old borrow pits were re-sloped in some areas and seeded.



Yukon Zinc Corporation

Picture 8-1: Road widening to improve sight lines at corner; subsequent work would entail preading of windrowed material on fill slope-slope stabilization.



Picture 8-3: Organic material and woody debris placed along downslope area to promote natural revegetation.

Picture 8-2: Slope stabilization long fill slope; organic material to be placed on slope after grading complete.



Picture 8-4: Woody debris and organics placed in previous borrow/staging area.



Picture 8-5: Coconut matting and seeding at erodible area draining to a newly installed culvert.



Picture 8-6: Coconut matting, rip rap, and silt fence (temporary) at culvert inlet.



Picture 8-7: Grading of borrow pit and placement of organic material along road corridor.

#### 8.1 Closure Trials

Bench scale test work for the bio-pass system was completed in 2010. The design of the field pilot test, will incorporate the results from this lab experiment. The design and installation of the field pilot test will occur during operations phase, as outlined in the *Wolverine Project Monitoring and Surveillance Plan V2010-02*.

### 9 Socio-Economic Assessment

The EA Screening Report requires that YZC report annually on the following:

- The number of Yukoners and non-Yukoners employed at the mine; and,
- The value of goods and services procured within Ross River, Watson Lake and the Yukon as a whole.

Over the course of the year, 240 Yukoners and 460 non-Yukoners were employed at the project site by YZC and numerous contracting companies. The main contractors included Procon Mining and Tunnelling Ltd.; ESS Compass Group Canada; and Arctic Construction Ltd.

The value of goods and services procured from Ross River, Watson Lake and the Yukon in 2010 is provided in Table 9-1. In addition to these Yukon Zinc expenditures, the Kaska First Nation communities (Ross River, Watson Lake and three in northern BC), who formed joint venture businesses with Arctic Construction Ltd., ESS Compass, Maple Leaf Loading, Procon Mining and Tunnelling, Tu Lidlini/Alberta Fuel Distributors, and Western Protection Alliance shared payments in 2010 estimated at \$3.35 million.

#### Table 9-1: Goods and Services Procured from Ross River, Watson Lake and the Yukon for 2010

Location	Amount
Ross River	\$65,000
Watson Lake	\$157,400
Yukon	\$16,150,700
Kaska Joint Venture Businesses	~\$3,350,000

### **10 Project Development and Production for 2011**

In 2011, stopes will continue to be developed for ore extraction. The projected amount of ore to be mined from underground workings is 358,800 tonnes (Table 10-1).

Stope Level	Total Ore for 2011 (tonnes)
1300	43000
1280	38800
1270	39000
1260	24000
1250	32000
1240	24000
1230	36000
1220	33000
1210	35000
1200	19000
1190	15000
1180	12000
1170	8000
Total	358800

 Table 10-1:
 Planned Total Ore to be Mined from Underground in 2011

Projected concentrate production in 2011 is summarized in Table 10-2 for lead, copper and zinc concentrates.

Table 10-2: Concentrate Production Estimated for 201
--

Variable	Dry Milled Tonnes
Copper Concentrate	10,662
Lead Concentrate	11,188
Zinc Concentrate	60,092
Total Concentrate Produced	81,942

## **Appendix A: Environmental Monitoring Reports**




Part 1 – Site Description	
Date: February 23 <sup>rd</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Access Road Creeks	Location/Co-ordinates: Km 0-km 27
and ends at the YZC Exploration Camp at Wolverine	access road starts at Km 190 on the Robert Campbell Hwy e Lake. The total length of the access road is 32 Km and The key water crossings include; Pitch, Putt, Bunker, Chip
Weather Conditions: Winter/spring weather, tempera	atures ranging from 5°C to -15°C.
Note: Early warm weather changing road conditions	daily.
Part 2 – Site Assessment	
Activity: Maintaining road daily due to snow fall, melting, and Ice removal at KM 7.5. Site Status: Winter/spring road conditions. Ice is building up on the sides of the road at ~ KM 2, Melting is occurring from ~ KM 0-10 due to early war Assessed Risk: Low Photos Attached: Yes (10) Samples Taken: No	5 and 12.
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: None at this time, will need to st the summer period.	team some culverts in spring and install more culverts over
Mitigation Condition: fair	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: During Spring melt.	
Monitoring Frequency: Weekly	
Reporting Requirements: every two weeks	




Date: February 23rd ,2010 Site Name: Access Road Creeks Pitch Creek - down stream Pitch Creek - up stream Putt Creek - up stream Putt Creek - down stream












Part 1 – Site Description			
Date: March 2 <sup>nd</sup> – 15 <sup>th</sup> , 2010	Inspector(s): Jennie Gjertsen		
Site Name: Access Road	Location/Co-ordinates:		
	Wolverine access road - Km 0 to Km 32		
Site Location Description: The Wolverine Mine site access road starts at Km 190 on the Robert Campbell Hwy and ends at the YZC Exploration Camp at Wolverine Lake. The total length of the access road is 32 Km and passes through several different bioclimatic regions. The key water crossings include; Pitch, Putt, Bunker, Chip and Bogey, Hawkowl, Go and Campbell Creeks.			
Weather Conditions: Unusually warm winter conditions10°C to 0°C.	March daily temperature averages to date range from		
Part 2 – Site Assessment			
Activity:			
<ul> <li>Continual clearing of snow and road grading.</li> <li>Maintenance of areas of ice floes</li> </ul>			
Site Status:			
Ice floes are occurring at Kms: 1, 4+500, 7+500 and 12+	500		
Road remains in good repair			
Assessed Risk: Low			
Photos Attached: Yes (4)			
Samples Taken: No			
Additional Information Attached: No			
Part 3 – Mitigation Requirements			
Mitigation Required: None at this time, will need to steam some culverts in spring and install more culverts over the summer period. Ongoing maintenance required.			
Mitigation Condition: good			
Part 4 –Monitoring Requirements			
Follow-up Monitoring: Continue to monitor road drainages, as well as areas of ice and water accumulation. During runoff, monitor for sediment loading in ditches and drainages.			
Monitoring Frequency: Weekly and more frequently once runoff period starts			
Reporting Requirements: Environmental monitoring report every two weeks			








Part 1 – Site Description		
Date: March 16 <sup>th</sup> – 27 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore	
Site Name: Access Road	Location/Co-ordinates:	
	Wolverine access road - Km 0 to Km 32	
Site Location Description: The Wolverine Mine site access road starts at Km 190 on the Robert Campbell Hwy and ends at the YZC Exploration Camp at Wolverine Lake. The total length of the access road is 32 Km and passes through several different bioclimatic regions. The key water crossings include; Pitch, Putt, Bunker, Chip and Bogey, Hawkowl, Go and Campbell Creeks.		
Weather Conditions: Unusually warm winter conditions.		
March daily temperature averages to date range from -1	0°C to 0°C. Periods of melt and then heavy snow fall.	
Part 2 – Site Assessment		
<ul> <li>Activity:</li> <li>Continual clearing of snow and road grading.</li> <li>Maintenance of areas of ice floes</li> <li>Weather cooled down March 23<sup>rd</sup> with some heavy snow fall and freezing road.</li> </ul>		
Site Status: Ice floes are occurring at Kms: 1, 4+500, 7+500 and 12+500 Road remains in good repair Very wet slippery conditions during warmer weather, icy as weather cools. Assessed Risk: Low		
Photos Attached: Yes (6)		
Samples Taken: No		
Additional Information Attached: No		
Part 3 – Mitigation Requirements		
Mitigation Required: None at this time, will need to stean the summer period. Ongoing maintenance required. Mitigation Condition: good	n some culverts in spring and install more culverts over	
Part 4 –Monitoring Requirements		
Follow-up Monitoring: Continue to monitor road drainage runoff, monitor for sediment loading in ditches and draina	es, as well as areas of ice and water accumulation. During ages.	
Monitoring Frequency: Weekly and more frequently once	e runoff period starts	
Reporting Requirements: Environmental monitoring rep	ort every two weeks	



**Date:** March 16<sup>th</sup> – 27<sup>th</sup>, 2010 Site Name: Access Road 10/03/16 Km 1.5 ice build up has been removed to 10/03/16 Km 4.5 ice built up. Ditching put in place to prevent further overflow. divert runoff. 10/03/16 Ditching in place, snow removal and grading to 10/03/16 Km 7.5 ice build up removed to prevent future divert runoff due to snow melt. flooding.








Part 1 – Site Description		
Date: April 3 <sup>rd</sup> , 2010	Inspector(s): Jaymie Skidmore/Jennie Gjertsen	
Site Name: Access Road	Location/Co-ordinates:	
	Wolverine access road - Km 0 to Km 32	
Site Location Description: The Wolverine Mine site access road starts at Km 190 on the Robert Campbell Hwy and ends at the YZC Exploration Camp at Wolverine Lake. The total length of the access road is 32 Km and passes through several different bioclimatic regions. The key water crossings include; Pitch, Putt, Bunker, Chip and Bogey, Hawkowl, Go and Campbell Creeks.		
Weather Conditions: Unusually warm winter conditions.		
April daily temperature averages to date range from -10°	°C to 0°C. Periods of melt and then heavy snow fall.	
Part 2 – Site Assessment		
<ul> <li>Activity:</li> <li>Continual clearing of snow and road grading. (road at this time is clear of snow and mainly mud)</li> <li>Maintenance of areas of ice floes and mud</li> <li>Warm weather causing melt and flooding in areas.</li> </ul>		
Site Status: Ice floes are beginning to melt causing some flooding at Kms: 1, 4+500, 7+500 and 12+500 Road is not in very good condition due to melt Very wet and muddy conditions during warmer weather, icy as weather cools.		
Assessed Risk: Low		
Photos Attached: Yes (9)		
Samples Taken: No		
Additional Information Attached: No		
Part 3 – Mitigation Requirements		
Mitigation Required: None at this time, will need to stear the summer period. Ongoing maintenance required.	n some culverts in spring and install more culverts over	
Mitigation Condition: good		
Part 4 –Monitoring Requirements		
Follow-up Monitoring: Continue to monitor road drainage runoff, monitor for sediment loading in ditches and drainage	es, as well as areas of ice and water accumulation. During ages.	
Monitoring Frequency: Weekly and more frequently once	e runoff period starts	
Reporting Requirements: Environmental monitoring rep	ort every two weeks	











Site Name: Access Road	Date: April 3 <sup>rd</sup> , 2010
10/04/03 km 12+500	




Date: April 14 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Access Road	Location/Co-ordinates:
	Wolverine access road - Km 0 to Km 32
and ends at the YZC Exploration Camp at W	ne site access road starts at Km 190 on the Robert Campbell Hwy olverine Lake. The total length of the access road is 32 Km and regions. The key water crossings include; Pitch, Putt, Bunker, Chip eks.
Weather Conditions: Unusually warm winter of April daily temperature averages to date range snow fall.	conditions. ge from -10°C to 0°C. Extended periods of melt and some heavy
Part 2 – Site Assessment	
Activity:	
<ul> <li>Continual clearing of snow and road g</li> <li>Maintenance of areas of ice floes and</li> </ul>	grading. (road at this time is clear of snow and mainly mud) I mud by grading and clearing
- Steaming all culverts and pipes bega	n on April 14 <sup>th</sup>
Site Status:	
Ice floes continue to melt causing some floor	
Road is not in poor condition due to melt, but	
Very wet and muddy conditions during warm	er weather, icy as weather cools.
Assessed Risk: Low	
Photos Attached: Yes (8)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: Continue to steam culve maintenance required. Continue snow remov	erts and install more culverts over the summer period. Ongoing val to reduce runoff in high traffic areas.
Mitigation Condition: good	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Continue to monitor ro Monitor for sediment loading in ditches and d	ad drainages, as well as areas of ice and water accumulation. Irainages.
Monitoring Frequency: Weekly and more free	quently as required











Part 1 – Site Description		
Date: April 27 <sup>th</sup> – May 10 <sup>th</sup> , 2010	Inspector(s): Jennie Gjertsen and Robin McCall	
Site Name: Access Road	Location/Co-ordinates: Wolverine access road - Km 0 to Km 32	
and ends at the YZC Exploration Camp at Wolveri	e access road starts at Km 190 on the Robert Campbell Hwy ine Lake. The total length of the access road is 32 Km and is. The key water crossings include; Pitch, Putt, Bunker, Chip	
Weather Conditions: Spring weather conditions, da Periods of melting and freezing. Snow and rainfall.	aily temperature averages to date range from 0°C to 10°C.	
Part 2 – Site Assessment		
to prevent ruptures in banks) - K19 – equipment working to sort and source in area Site Status:	enance and repair of fencing, freeing of areas of standing water e material for UG ramp roadbed. Drillers and blasters working	
<ul> <li>Road is drying up significantly (requires watering down)</li> <li>Seeing increased runoff from melting in vegetation</li> </ul>		
Assessed Risk: Low		
Photos Attached: Yes		
Samples Taken: ABA sample taken at K19 on May 10 <sup>th</sup> , 2010		
Additional Information Attached: No		
Part 3 – Mitigation Requirements		
Mitigation Required: Assess as conditions change. need to be hauled into site for proper storage and/	. Barrels at Km 0 of diesel (some of which are waste diesel) or disposal	
Mitigation Condition: good		
Part 4 – Monitoring Requirements		
Follow-up Monitoring: Continue to monitor road dra Monitor for sediment loading in ditches and drainag	ainages, as well as areas of ice and water accumulation. ges.	
Monitoring Frequency: Weekly and more frequent		
Reporting Requirements: Environmental monitorin	ig report every two weeks	
















Part 1 – Site Description	
Date: May 11 <sup>th</sup> – May 24 <sup>th</sup> ,2010	Inspector(s): Jaymie Skidmore and Jennie Gjertsen
Site Name: Access Road	Location/Co-ordinates:
	Wolverine access road - Km 0 to Km 32
and ends at the YZC Exploration Camp at Wol	site access road starts at Km 190 on the Robert Campbell Hwy verine Lake. The total length of the access road is 32 Km and gions. The key water crossings include; Pitch, Putt, Bunker, Chip s.
Weather Conditions: Spring/summer weather c 15°C. Mostly sunny with periods of rainfall.	onditions, daily temperature averages to date range from 5°C to
Part 2 – Site Assessment	
Activity:	
<ul> <li>Sediment and erosion control works (ma to prevent ruptures in banks)</li> </ul>	aintenance and repair of fencing, freeing of areas of standing water
<ul> <li>K27.2 culvert installed for tailings line to</li> </ul>	run through
- Spill kit placed at km 10 bunker bridge	
- Sourcing roadbed material for UG mine	at K 19. Drilling, blasting, crushing
- Road watering sourced from Hawkowl Creek	
Site Status:	
<ul> <li>Road is drying up significantly (requires</li> </ul>	watering down)
- Seeing increased runoff from melting in	vegetation
Assessed Risk: Low	
Photos Attached: Yes	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: Assess as conditions char	nge.
Mitigation Condition: good	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Continue to monitor road sediment loading in ditches and drainages.	drainages, as well as areas and water accumulation. Monitor for
Monitoring Frequency: Weekly and more freque	ently during rain events
Reporting Requirements: Environmental monit	oring report every two weeks








Part 1 – Site Description		
Date: May 24 <sup>th</sup> – June 7 <sup>th</sup> ,2010	Inspector(s): Robin McCall	
Site Name: Access Road	Location/Co-ordinates:	
	Wolverine access road - Km 0 to Km 32	
and ends at the YZC Exploration Camp at Wol	site access road starts at Km 190 on the Robert Campbell Hwy verine Lake. The total length of the access road is 32 Km and gions. The key water crossings include; Pitch, Putt, Bunker, Chip s.	
Weather Conditions: Spring/summer weather control 15°C. Mostly sunny with periods of rainfall.	onditions, daily temperature averages to date range from 0°C to	
Part 2 – Site Assessment		
Activity:		
<ul> <li>Sediment and erosion control works (i.e existing fencing)</li> </ul>	., installation of new fencing and maintenance and repair of	
- Sourcing roadbed material for UG mine	at K 19. Drilling, blasting, crushing	
<ul> <li>Road watering sourced from Hawkowl C</li> </ul>	Creek and Go Creek	
<ul> <li>Small road built over tailings pipeline at KM 26.8 to access water wells down the valley – this road attache to a pre-existing road that leads to the wells.</li> </ul>		
Site Status:		
<ul> <li>Road is drying up significantly (requires watering down)</li> </ul>		
- Seeing increased runoff from melting in	vegetation	
Assessed Risk: Low		
Photos Attached: Yes (8)		
Samples Taken: No		
Additional Information Attached: No		
Part 3 – Mitigation Requirements		
Mitigation Required: Assess as conditions chan	ige.	
Mitigation Condition: good		
Part 4 – Monitoring Requirements		
Follow-up Monitoring: Continue to monitor road for sediment loading in ditches and drainages.	drainages, as well as areas where water is accumulating. Monitor	
Monitoring Frequency: Weekly and more freque	ently during rain events	
Reporting Requirements: Environmental monit	oring report as condition change	












Part 1 – Site Description	
Date: June 23 <sup>rd</sup> – July 4 <sup>th</sup> ,2010	Inspector(s): Robin McCall and Jennie Gjertsen
Site Name: Access Road	Location/Co-ordinates:
	Wolverine access road - Km 0 to Km 32
and ends at the YZC Exploration Camp at Wolve	ite access road starts at Km 190 on the Robert Campbell Hwy erine Lake. The total length of the access road is 32 Km and ons. The key water crossings include; Pitch, Putt, Bunker, Chip
Weather Conditions: Spring/summer weather con 15°C. Mostly sunny with periods of rainfall.	nditions, daily temperature averages to date range from 0°C to
Part 2 – Site Assessment	
Activity:	
<ul> <li>Sediment and erosion control works (i.e., existing fencing)</li> </ul>	installation of new fencing and maintenance and repair of
- Sourcing roadbed material for UG mine a	it K 19. Drilling, blasting, crushing
<ul> <li>Road watering sourced from Hawkowl Cr</li> </ul>	
<ul> <li>Striping of organics and ditching along roadside from KM 19 – 22 to widen road</li> </ul>	
	d silt fencing along road between KM 19 -22
Site Status:	and older of road significant ditables to divert water of verieus
locations is ongoing	ong sides of road significant – ditching to divert water at various
	res (i.e., silt fencing, use of straw bales) and support of existing
Assessed Risk: Low	
Photos Attached: Yes (8)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: Assess as conditions chang	je.
Mitigation Condition: good	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Continue to monitor road or areas of runoff for sediment loading	drainages, as well as areas where water is accumulating. Monitor
Monitoring Frequency: Twice weekly during cons	struction activities
Reporting Requirements: Environmental monito	ring report every two weeks











Part 1 – Site Description	
Date: July 5 <sup>th</sup> to July 19 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Access Road	Location/Co-ordinates: Km 18 - 23 and Km 6 - 4
and ends at the YZC Exploration Camp at Wolver	e access road starts at Km 190 on the Robert Campbell Hwy rine Lake. The total length of the access road is 32 Km and ns. The key water crossings include; Pitch, Putt, Bunker, Chip
Weather Conditions: Summer weather conditions, with periods of sun and rain.	, daily temperatures average from 5°C to 25°C. Mostly cloudy
Part 2 – Site Assessment	
Activity:	
<ul> <li>Sediment and erosion control works (i.e., i existing fencing)</li> </ul>	nstallation of new fencing and maintenance and repair of
<ul> <li>Road watering sourced from Hawkowl Creation</li> </ul>	ek and Go Creek
- Striping of organics and ditching along roa	idside from KM 18 – 23 and km6 - 4 to widen road
<ul> <li>Installation of multiple culverts , rock block</li> </ul>	s and silt fencing along road between KM 18 -23 and km6 - 4
Site Status:	
<ul> <li>Road is receiving rain daily, and runoff alo locations is ongoing</li> </ul>	ng sides of road significant – ditching to divert water at various
<ul> <li>Installation of new erosion control measure measures ongoing, as required</li> </ul>	es (i.e., silt fencing, use of straw bales) and support of existing
Assessed Risk: Low	
Photos Attached: Yes	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: Assess as conditions change	ð.
Mitigation Condition: good	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Continue to monitor road du runoff, monitor for sediment loading in ditches and	rainages, as well as areas where water is accumulating. During d drainages.
Monitoring Frequency: Daily during construction a	and more frequently during rain events.
Reporting Requirements: Environmental monitori	ng report every two weeks










10/07/11 Km 4-6 Stripping organics

10/07/15 Widening road at km6 and extending culvert




Part 1 – Site Description		
Date: July 20 <sup>th</sup> to August 2 <sup>nd</sup> , 2010	Inspector(s): Robin McCall and Jennie Gjertsen	
Site Name: Access Road	Location/Co-ordinates: Km 18 - 23 and Km 6 - 4	
Site Location Description: The Wolverine Mine site access road starts at Km 190 on the Robert Campbell Hwy and ends at the YZC Exploration Camp at Wolverine Lake. The total length of the access road is 32 Km and passes through several different bioclimatic regions. The key water crossings include; Pitch, Putt, Bunker, Chip and Bogey, Hawkowl, Go and Campbell Creeks.		
Weather Conditions: Heavy rains at the beginning of the period, mostly sunny and very dry for the majority, daily temperatures average from 5°C to 25°C.		
Part 2 – Site Assessment		
<ul> <li>Activity:</li> <li>Finishing works from Km 19-22, including seeding from Km 19-21</li> <li>Widening and reducing grade of road sections Km 4 – Km 8</li> <li>Culvert installations between Km 4 – Km 8</li> <li>Coconut matting and seeding at Km 7.5 in area of permafrost</li> <li>Silt fencing in areas of construction</li> </ul> Site Status: <ul> <li>Work ongoing between Km 4 and Km - 6</li> </ul> Assessed Risk: Low Photos Attached: Yes		
Samples Taken: No		
Additional Information Attached: No		
Part 3 –Mitigation Requirements		
Mitigation Required: Steep slopes on areas of recent fill waterways in preparation for next spring	need silt fencing around areas of seasonal runoff and	
Mitigation Condition: good Part 4 –Monitoring Requirements		
- · ·	areas of construction, and look for areas that could require or requests	
Monitoring Frequency: Once or twice weekly as construction continues.		
Reporting Requirements: Environmental monitoring report every two weeks until construction terminates		













Part 1 – Site Description	
Date: August 3 <sup>rd</sup> to August 16 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Access Road	Location/Co-ordinates: Access Road
and ends at the YZC Exploration Camp at Wolverine	cess road starts at Km 190 on the Robert Campbell Hwy Lake. The total length of the access road is 32 Km and The key water crossings include; Pitch, Putt, Bunker, Chip
Weather Conditions: Mostly sunny and very dry for the	e majority, daily temperatures average from 5°C to 25°C.
Part 2 – Site Assessment	
<ul> <li>Activity:</li> <li>Finishing work at Km 7.5 permafrost section to silt fence and rip rap</li> <li>Widening and reducing grade of road sections Silt fencing and rip rap installation in areas of Stripping Material between km 10 – 12.5</li> <li>Reducing the grade of the road to a maximum</li> <li>Grading in various areas between km 0 – 27</li> <li>Straightening the road where there are danger</li> <li>Site Status: <ul> <li>Construction ongoing between Km 4 - Km 7.5</li> <li>Construction started between km 10 – 13</li> <li>Grading/raising the road between 16 – 17</li> </ul> </li> </ul>	construction 10% ous corners
Photos Attached: Yes	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: Steep slopes on areas of recent f waterways in preparation for next spring, seeding alor Mitigation Condition: good	ill need silt fencing around areas of seasonal runoff and ng road side until construction terminates
Part 4 –Monitoring Requirements	
Follow-up Monitoring: Continue to monitor drainages i further mitigation. Provide technical support as contract	n areas of construction, and look for areas that could require ctor requests
Monitoring Frequency: Once or twice weekly as const	
Reporting Requirements: Environmental monitoring re	eport every two weeks until construction terminates




























Part 1 – Site Description		
Date: September 9 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore	
Site Name: Access Road	Location/Co-ordinates: Access Road	
Site Location Description: The Wolverine Mine site access road starts at Km 190 on the Robert Campbell Hwy and ends at the YZC Exploration Camp at Wolverine Lake. The total length of the access road is 32 Km and passes through several different bioclimatic regions. The key water crossings include; Pitch, Putt, Bunker, Chip and Bogey, Hawkowl, Go and Campbell Creeks.		
Weather Conditions: Mostly cloudy and very wet for the	majority, daily temperatures average from 5°C to 15°C.	
Part 2 – Site Assessment		
<ul> <li>Activity:</li> <li>Large amount of material cut from the hill side alor</li> <li>Stripping, grubbing, grading, and ditching ongoin</li> <li>A berm is being installed along the roadside whe</li> </ul>	g between km 14 and 9	
Site Status:       -         Construction ongoing between Km 9.5 - Km 14         Erosion and sediment control ongoing         A seeding/reclamation program is in the works. The access road will be seeded along the sides from 27-0         Borrow pits that are no longer needed will also be reclaimed.         The following areas will need coconut matting to help the seed take due to high amount of rock.         Km 21 – 22.5 borrow pit         Km 19 borrow pit         Km 19 borrow pit         Km 18 borrow pit         Km 14-17 consists of rock walls running along road side not much organic material for seed to take         Assessed Risk: Low         Photos Attached: Yes         Samples Taken: No		
Additional Information Attached: No		
Part 3 –Mitigation RequirementsMitigation Required: Steep slopes on areas of recent fill waterways in preparation for next spring, seeding alongMitigation Condition: goodPart 4 –Monitoring Requirements		
Follow-up Monitoring: Continue to monitor drainages in a	areas of construction, and look for areas that could require	

Follow-up Monitoring: Continue to monitor drainages in areas of construction, and look for areas that could require further mitigation. Provide technical support as contractor requests


Monitoring Frequency: Once or twice weekly as construction continues.

Reporting Requirements: Environmental monitoring report every two weeks until construction terminates












	ital inspection Form
Part 1 – Site Description	
Date: September 21 <sup>th</sup> – October 4 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Access Road	Location/Co-ordinates: Access Road
and ends at the YZC Exploration Camp at Wolverine	ccess road starts at Km 190 on the Robert Campbell Hwy Lake. The total length of the access road is 32 Km and The key water crossings include; Pitch, Putt, Bunker, Chip
Weather Conditions: Fall weather consisting of rain a	nd snow. Average daily temperature 0°C.
Part 2 – Site Assessment	
<ul> <li>Activity:</li> <li>Large amount of material cut from the hill side</li> <li>Road widening and straightening</li> <li>Site Status:</li> <li>Construction ongoing between Km 9 and km 1</li> <li>Erosion and sediment control ongoing</li> <li>The following areas have been seeded</li> <li>9-9.5 deep fill area below road was seeded</li> <li>10.8-11.4 below road</li> <li>11.5-12 below road</li> <li>12.5 below road</li> <li>12.6-12.9 below road</li> </ul>	
Assessed Risk: Low	
Photos Attached: Yes	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: Erosion and sediment control	
Mitigation Condition: good	
Part 4 – Monitoring Requirements	
further mitigation. Provide technical support for contra	
Monitoring Frequency: Once or twice weekly as const	
Reporting Requirements: Environmental monitoring r	eport every two weeks until construction terminates
















Environmental inspection Form	
Part 1 – Site Description	
Date: October 5 <sup>th</sup> – October 19 <sup>th</sup> ,2010	Inspector(s): Robin McCall
Site Name: Access Road	Location/Co-ordinates: Km 9.5 – 11
and ends at the YZC Exploration Camp at Wolver	e access road starts at Km 190 on the Robert Campbell Hwy ine Lake. The total length of the access road is 32 Km and ns. The key water crossings include; Pitch, Putt, Bunker, Chip
Weather Conditions: Fall weather consisting of rai	n and snow. Average daily temperature -2°C.
Part 2 – Site Assessment	
Activity: - Final grading, contouring and berm installa	ation along road side from KM 9.5 - 11
<ul> <li>Site Status:</li> <li>Construction complete between Km 9 and</li> <li>Erosion and sediment control ongoing</li> <li>Borrow pits that are no longer needed are</li> </ul>	
Assessed Risk: Low	
Photos Attached: Yes	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: None	
Mitigation Condition: good	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Continue to monitor drainage further mitigation.	es in areas of construction, and look for areas that could require
Monitoring Frequency: Once a week or as require	d during temporary periods of snow melt during the fall.
Reporting Requirements: None, unless more con	struction is required







Part 1 – Site Description	
Date: January 26 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Arctic Camp	Location/Co-ordinates: Arctic camp Km 25.5
is well drained and within the project's scope o	• •
Part 2 – Site Assessment	
Activity: None	
Site Status: Arctic camp extension is now occu Assessed Risk: Low	pied.
Photos Attached: Yes (4)	
Samples Taken: No	
Additional Information Attached: None.	
Part 3 – Mitigation Requirements	
Mitigation Required: None	
Mitigation Condition: Good	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Monitor entire Arctic can	np routinely for environmental concerns
Monitoring Frequency: Every two weeks	
Reporting Requirements: Change in condition	warranting reporting







Part 1 – Site Description	
Date: Feb. 2 <sup>nd</sup> – 15 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Arctic Camp	Location/Co-ordinates: Arctic camp Km 25.5
Site Location Description:	
road. The camp was initially established in 2008, and located in the Go Creek drainage, and is several hundrinto a septic field and draws water from Hawkowl Cree summer months. Since 2008 additional units have bee deposit waste water into the septic field.	ated at Km 25 of the access road on the west side of the occupied for the construction needs on site. The camp is red metres from the Creek itself. The original camp is tied k in the winter months, and from a well installation in the n added, and draw water from the same source, but do not
Weather Conditions: Typical winter weather. Temperat	ures ranging from +2°C to -20°C.
Part 2 – Site Assessment	
Activity: None	
Site Status: Arctic camp extension continues to be occ use, sewage taken to YZC STP.	upied – water from Hawkowl Creek being trucked there for
Shop area clean and organized. Camp is free of wildlife	e attractants and environmental hazards.
Assessed Risk: Low	
Photos Attached: Yes (4)	
Samples Taken: No	
Additional Information Attached: None.	
Part 3 – Mitigation Requirements	
Mitigation Required: None	
Mitigation Condition: excellent	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Ongoing	
Monitoring Frequency: Twice a month or more frequen	tly
Reporting Requirements: Report if a change in condition	on warrants reporting.









Part 1 – Site Description	
Date: September 30 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Arctic Camp	Location/Co-ordinates: Arctic camp Km 25.5
road. The camp was initially established in 2008, and located in the Go Creek drainage, and is several hundrinto a septic field and draws water from Hawkowl Cree	ated at Km 25 of the access road on the west side of the occupied for the construction needs on site. The camp is red meters from the Creek itself. The original camp is tied k in the winter months, and from a well installation in the n added, and draw water from the same source, but do not
Site Status: -Arctic construction has moved all employees to YZC of -Arctic camp is in the process of being decommissione	•
Assessed Risk: Low	
Photos Attached: Yes Samples Taken: No	
Additional Information Attached: None. Part 3 –Mitigation Requirements	
Mitigation Required: None Mitigation Condition: N/A	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Ongoing	
Monitoring Frequency: As required.	
Reporting Requirements: As the camp is decommissio	ned.











Part 1 – Site Description	
Date: March 1 <sup>st</sup> and March 8 <sup>th</sup> , 2010	Inspector(s): Jennie Gjertsen
Site Name: Access Road Creeks	Location/Co-ordinates: Km 0 - Km 27
Location Description: Key creeks and drainages along	access road.
Weather Conditions: Unusually warm winter conditions10°C to 0°C	March daily temperature averages to date range from
Part 2 – Site Assessment	
Activity:	
None	
Site Status:	
Creeks are still covered in snow and ice, no open areas	near road
Assessed Risk: Low	
Photos Attached: Yes	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: None at this time.	
Mitigation Condition: Excellent	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Monitor Creeks for background in freshet	formation, and for determining mitigation required for
Monitoring Frequency: Weekly, and more frequently whe	en heavy flows commence
Reporting Requirements: Every two weeks	













Part 1 – Site Description	
Date: March 16 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Access Road Creeks	Location/Co-ordinates: Km 0 - Km 27
Location Description: Key creeks and drainage	jes along access road.
Weather Conditions: Unusually warm winter c -10°C to 0°C.	onditions. March daily temperature averages to date range from
Part 2 – Site Assessment	
Activity: Warm weather is causing glaciers to form and	the ice to open up.
Site Status:	
Creeks are still covered in snow and ice, some	e open water observed.
Assessed Risk: none	
Photos Attached: Yes (8)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: None at this time.	
Mitigation Condition: Excellent	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Monitor Creeks for back freshet	ground information, and for determining mitigation required for
Monitoring Frequency: Weekly, and more freq	uently when high flows commence
Reporting Requirements: Every two weeks	












Part 1 – Site Description	
Date: April 3 <sup>rd</sup> , 2010	Inspector(s): Jaymie Skidmore/Jennie Gjertsen
Site Name: Access Road Creeks	Location/Co-ordinates: Km 0 - Km 27
Location Description: Key creeks and drainages along	access road.
Weather Conditions: Unusually warm winter conditions10°C to 0°C.	April daily temperature averages to date range from
Part 2 – Site Assessment	
Activity:	
Warm weather is causing glaciers to form and the ice to	open up.
Site Status:	
Creeks are still covered in snow and ice, some open wa	ter observed.
Assessed Risk: none	
Photos Attached: Yes (9)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: None at this time.	
Mitigation Condition: Excellent	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Monitor Creeks for background in freshet	formation, and for determining mitigation required for
Monitoring Frequency: Weekly, and more frequently whe	en high flows commence
Reporting Requirements: Every two weeks	










Site Name: Access Road Creeks	Date: April 3 <sup>rd</sup> , 2010
Go Creek - Downstream	





Part 1 – Site Description	
Date: April 23 <sup>rd</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Access Road Creeks	Location/Co-ordinates: Km 0 - Km 27
Location Description: Key creeks and drainages	along access road.
Weather Conditions: Unusually warm winter cond to 0°C.	itions. April daily temperature averages to date range from -10°C
Part 2 – Site Assessment	
Activity:	
Warm weather is causing creeks to glaciate and s	some ice to open up.
Site Status:	
Creeks are still covered in snow and ice, some op	en water observed.
Assessed Risk: None	
Photos Attached: Yes (10)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: None at this time.	
Mitigation Condition: Excellent	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Monitor Creeks for backgro freshet	und information, and for determining mitigation required for
Monitoring Frequency: Weekly, and more frequen	tly when heavy flows commence
Reporting Requirements: Every two weeks	














Part 1 – Site Description	
Date: May 8 <sup>th</sup> -10 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Access Road Creeks	Location/Co-ordinates: Km 0 - Km 27
Location Description: Key creeks and drainage	es along access road.
Weather Conditions: Unusually warm winter co -10°C to +10°C.	nditions. April - May daily temperature averages to date range from
Part 2 – Site Assessment	
Activity:	
Much more open water than during last reporting	ng period
Site Status:	
Some creeks are still partly covered in snow ar	nd ice, open water observed at most creeks
Assessed Risk: None	
Photos Attached: Yes (12)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: None at this time.	
Mitigation Condition: Excellent	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Monitor Creeks for back	ground information, and for determining mitigation required for
Monitoring Frequency: Weekly	
Reporting Requirements: Every two weeks	














Part 1 – Site Description	
Date: May 24 <sup>th</sup> , 2010	Inspector(s): Jennie Gjertsen
Site Name: Access Road Creeks	Location/Co-ordinates: Km 0 - Km 27
Location Description: Key creeks and drainages	along access road.
Weather Conditions: Spring/summer weather con 15°C. Mostly sunny with periods of rainfall.	ditions, daily temperature averages to date range from 5°C to
Part 2 – Site Assessment	
Activity:	
None	
Site Status:	
All creeks have open water, flows increasing	
Assessed Risk: None	
Photos Attached: Yes (14)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: None at this time.	
Mitigation Condition: Excellent	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Monitor Creeks for backgro freshet	und information, and for determining mitigation required for
Monitoring Frequency: Weekly	
Reporting Requirements: Every two weeks	




















Part 1 – Site Description		
Date: May 26 <sup>th</sup> - June 7 <sup>th</sup> , 2010	Inspector(s): Robin McCall	
Site Name: Access Road Creeks	Location/Co-ordinates: Km 0 - Km 27	
Location Description: Key creeks and drainages along access road.		
Weather Conditions: Spring/summer weather conditions, daily temperature averages to date range from 0°C to 15°C. Mostly sunny with periods of rainfall.		
Part 2 – Site Assessment		
Activity:		
A small road was built on the south side of the Access road leading to Hawkowl Creek. This was installed so that the Water Truck (Re: for dust control purposes) could access the creek and extract water more safely, as vehicles were having difficulty passing the Water Truck during extraction at its previous access point. Some additional silt fencing was placed along the edges of Hawkowl Creek because of this new development. Also, since water was also being extracted from Go Creek, some silt fencing was installed along Go Creek as well.		
Site Status:		
All creeks have open water, flows increasing		
Assessed Risk: Low		
Photos Attached: Yes (10)		
Samples Taken: No		
Additional Information Attached: No		
Part 3 – Mitigation Requirements		
Mitigation Required: None at this time.		
Mitigation Condition: Excellent		
Part 4 –Monitoring Requirements		
Follow-up Monitoring: Monitor Creeks for background information, and for determining mitigation required during freshet as necessary		
Monitoring Frequency: Weekly		
Reporting Requirements: Every two weeks		


















Part 1 – Site Description		
Date: June 13 <sup>th</sup> ,2010	Inspector(s): Jaymie Skidmore	
Site Name: Access Road Creeks	Location/Co-ordinates: Km 0 - Km 31	
Location Description: Key creeks and drainages along	access road.	
Weather Conditions: Spring/summer weather conditions, daily temperature averages to date range from 5°C to 15°C. Mostly sunny with periods of rainfall with some snow.		
Part 2 – Site Assessment		
Activity: High flows subsiding		
Site Status:		
All creeks have open water, flows reducing.		
Assessed Risk: Low		
Photos Attached: Yes (12)		
Samples Taken: No		
Additional Information Attached: No		
Part 3 – Mitigation Requirements		
Mitigation Required: Improvements to erosion and sediment control is ongoing surrounding drainages		
Mitigation Condition: good		
Part 4 – Monitoring Requirements		
Follow-up Monitoring: Monitor Creeks for determining fu	rther mitigation	
Monitoring Frequency: As changes occur.		
Reporting Requirements: As changes occur.		
















Date: April 13 <sup>th</sup> – April 26 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Ditch 3	Location/Co-ordinates: NW (Ditch 4) and SW (Ditch 3) of Upper and Lower Portal Area

Site Location Description:

Ditches 3 and 4 surround the down slope perimeter of the industrial complex.

Their purpose is to collect all the surface runoff for the Industrial Complex so that the water can be treated at the lower portal treatment sump, or pumped to the tailings upon completion. The longest portions of the ditches run along the valley where the Wolverine Creek watershed begins to form open water. Most of the ditch construction was done using fill from the industrial complex mill excavation, the ditch is lined with enviro liner.

Weather Conditions: Typical spring weather, temperatures ranging from 15C° to 0C° periods of snow, rain and sun.

## Part 2 – Site Assessment

Activity:

-Removal of snow, ice and debris from the ditch to help it flow

Site Description:

-Ditch 3 still has some ice build up

-Has a slow steady flow into sump 2

-Holes in the liner will appear as snow melts and sediment is to be removed

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: None

## Part 3 – Mitigation Requirements

Mitigation Required: holes will need to repaired and sediment removed as the ditch dries

Mitigation Condition: good

## Part 4 – Monitoring Requirements

Follow-up Monitoring: as repairs and construction is done

Monitoring Frequency: Daily during periods of snow melt and heavy rain in spring.

Reporting Requirements: bi-weekly





10/04/15 Snow and ice moved a side water starting to floe freely

# Date: April 13<sup>th</sup> – April 27<sup>th</sup> ,2010



10/04/15 Some sediment built up near the culvert



10/04/16 water is flowing at a steady rate into sump 2



Site Name: Ditch 3	Date: April 13 <sup>th</sup> – April 27 <sup>th</sup> ,2010
Novel 21Ditch is clear of ice and snow and is flowing into sump 2. Sediment will be pumped out as needed.	



Date: June 9 <sup>th</sup> ,2010	Inspector(s): Jaymie Skidmore
Site Name: Ditch 3	Location/Co-ordinates: NW (Ditch 4) and SW (Ditch 3) of Upper and Lower Portal Area

Site Location Description:

Ditches 3 and 4 surround the down slope perimeter of the industrial complex.

Their purpose is to collect all the surface runoff for the Industrial Complex so that the water can be treated at the lower portal treatment sump, or pumped to the tailings upon completion. The longest portions of the ditches run along the valley where the Wolverine Creek watershed begins to form open water. Most of the ditch construction was done using fill from the industrial complex mill excavation, the ditch is lined with enviro liner.

Weather Conditions: Typical spring weather, temperatures ranging from 20C° to 5C° periods of rain and sun.

## Part 2 – Site Assessment

Activity:

-none

Site Description:

-Thick layer of sediment has built up in the ditch and needs to be removed

-Has a slow steady flow into sump 2 during wet weather

-Holes in the liner that have been exposed were marked with blue paint

-The grade of the road has overlapped the ditch

Assessed Risk: Low

Photos Attached: Yes (2)

Samples Taken: No

Additional Information Attached: None

## Part 3 – Mitigation Requirements

Mitigation Required: holes will need to repaired and sediment removed

Mitigation Condition: good

## Part 4 – Monitoring Requirements

Follow-up Monitoring: as repairs and construction is done

Monitoring Frequency: Daily during periods of heavy rain.

Reporting Requirements: during change in condition







Date: April 13 <sup>th</sup> – April 26 <sup>th</sup> ,2010	Inspector(s): Jaymie Skidmore
Site Name: Ditch 4	Location/Co-ordinates: NW (Ditch 4) and SW (Ditch 3) of
	Upper and Lower Portal Area

Site Location Description:

Ditches 3 and 4 surround the down slope perimeter of the industrial complex.

Their purpose is to collect all the surface runoff for the Industrial Complex so that the water can be treated at the lower portal treatment sump, or pumped to the tailings upon completion. The longest portions of the ditches run along the valley where the Wolverine Creek watershed begins to form open water. Most of the ditch construction was done using fill from the industrial complex mill excavation, the ditch is lined with enviro liner.

Weather Conditions: Typical spring weather, temperatures ranging from 15C° to 0C° periods of snow, rain and sun.

## Part 2 – Site Assessment

Activity:

- -Preventing water from flowing over the edge or under the liner
- -Removing debris, snow and sediment from ditch
- -Clearing a path for the water to flow into sump 2
- -Monitoring for leaks from holes and dam ups
- -Filling holes that are allowing water to run under liner
- -Attempting to build up sides where needed
- -Preventing further erosion of the ditch walls

Site Description:

-Water is flowing into ditch 2

-The walls of the ditch are eroding

- -Some water is flowing under the liner through holes and where the edge of the liner has been exposed
- -Some water has flown over the liner into the valley taking some sediment with it
- -Ice and sediment is built up throughout the ditch
- -Clear of most debris (debris has caused multiple holes along liner)
- -Multiple holes in the liner are surfacing as the snow melts away

-A lot of the material holding down the liner on the upper side has eroded and ended up in the ditch (this has allowed water to run under the liner)

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: None

## Part 3 – Mitigation Requirements

Mitigation Required: Debris and ice needs to removed, holes in the liner need to repaired, sides need to built up

Mitigation Condition: good

## Part 4 – Monitoring Requirements

Follow-up Monitoring: monitor daily

Monitoring Frequency: Daily during periods of snow melt and heavy rain in spring.

Reporting Requirements: bi-weekly





10/04/13 Removing snow and debris from ditch to allow flow





10/04/15 The ditch is full of debris, ice and snow.



10/04/15 Ice built up along the ditch blocking flow



**10/04/15** Starting to break up all the ice and snow to all water to flow through



**10/04/15** Guys working on the ditch to get it flowing and stop the over flowing where it is damming up.





sediment to build up in the ditch





10/04/18 The water under the liner has dissipated.



Site Name: Ditch 4

Date: April 13th - April 26th ,2010



**10/04/18** Water is flowing at a steady pace. No more ice and debris damming it up. There is a lot of sediment building up that needs to be removed.



10/04/21 Ditch is clear and is flowing steady. Snow fall and rain have increased the flow significantly.



10/04/22 A sump has been built to collect water pooling above ditch 4. This water is then pumped into ditch 4 or taken via truck to tailings facility



10/04/24 Sump built below north end of ditch 4 to catch runoff from dynamic waste rock pile. This water will then be pumped into ditch 4 or to tailings



Date: May 11 <sup>th</sup> – May 25 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore and Jennie Gjertsen
Site Name: Ditch 4	Location/Co-ordinates: NW (Ditch 4) and SW (Ditch 3) of
	Upper and Lower Portal Area

Site Location Description:

Ditches 3 and 4 surround the down slope perimeter of the industrial complex.

Their purpose is to collect all the surface runoff for the Industrial Complex so that the water can be treated at the lower portal treatment sump, or pumped to the tailings upon completion. The longest portions of the ditches run along the valley where the Wolverine Creek watershed begins to form open water. Most of the ditch construction was done using fill from the industrial complex mill excavation, the ditch is lined with enviro liner.

Weather Conditions: Spring/summer weather conditions, daily temperature averages to date range from 5°C to 15°C. Mostly sunny with periods of rainfall.

## Part 2 – Site Assessment

Activity:

-Holes in the liner have been marked with blue paint. Need to be repaired.

Site Description:

-No runoff water flowing through this period

-Some of the walls of the ditch have collapsed near the south end culvert.

-Multiple holes in the liner

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: None

## Part 3 – Mitigation Requirements

Mitigation Required: Debris and sediment needs to removed, holes in the liner need to repaired, sides need to built up

Mitigation Condition: fair

## Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor for bank stability, blockages and liner damage

Monitoring Frequency: Daily during periods heavy rain.

Reporting Requirements: As conditions change






10/05/13 Sediment build up (south end)



10/05/13 Debris in ditch (North end)





10/05/13 There is no water flowing (looking north)



10/05/13 Holes marked with blue paint (Various sizes)



Date: April 11 <sup>th</sup> – April 17 <sup>th</sup> , 2010	Inspector(s): Robin McCall and Jaymie Skidmore
Site Name: Dynamic Ore Stockpile	Location/Co-ordinates: KM 28.6 / 0439554E;6811058N

Site Location Description:

A dynamic stockpile of ore (i.e., rock that has a high concentration of metals) from the underground was established on a prepared (i.e., compacted and bermed) pad near the northern most end of Ditch 4 (south of the vent raise) within the Industrial complex. The pad sits between the toe of a high sloping hill and Wolverine creek. A lined ditch (Ditch 4) is located between the ore stockpile and the creek, but only extends half way along the ore pile (See attached diagram). The ore from this Dynamic Ore pile will be used to commission the Crusher and Mill, and therefore, will not be in its present location for long.

Weather Conditions: Spring conditions (temperature ranging between -15°C and 5°C) - snow melt in effect.

### Part 2 – Site Assessment

Activity:

- A temporary sump has been established to collect any runoff from the Dynamic Ore Pad. Water from the temporary sump is being pumped into Ditch 4 on a daily basis.
- Debris, snow and sediment are being removed from Ditch 4 to allow water (sourced from the temporary sump as well as some runoff water from the Industrial complex) to flow into Surface Sump #2, and then pumped to the Tailings Facility.
- Temporary berms were established to divert runoff water into Ditch 4, or the temporary sump.

#### Site Status:

Temporary sump catching runoff from Dynamic Ore Pad.

Ditch 4 is being kept clear to divert water into Surface Sump #2.

Assessed Risk: medium

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: Diagram outlining area of concern

### Part 3 – Mitigation Requirements

Mitigation Required: A portion (~10%) of the NW side of the Dynamic Ore Pile is to be removed and placed on the SE side of the pile. Suitable material (i.e., fine sands) will then need to be transported to the same NW corner of the pile and used to elevate and berm the base of the pad to divert any runoff water from snow/rain events toward Ditch 4, as required.

Mitigation Condition: Good


### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor soil conditions (i.e., thawing process) to determine when suitable material can be used. Monitor runoff into temporary sump and pump into Ditch 4 as required. Monitor Ditch 4 and ensure a clear channel is maintained to allow constant flow to Surface Sump #2. Monitor water level within Surface Sump #2 and pump to Tailings Facility as required.

Monitoring Frequency: Daily

Reporting Requirements: As changes occur















Date: April 17 <sup>st</sup> – 24 <sup>th</sup> , 2010	Inspector(s): Robin McCall and Jennie Gjertsen	
Site Name: Dynamic Ore Stockpile	Location/Co-ordinates: KM 28.6 / 0439554E;6811058N	

Site Location Description:

A dynamic ore stockpile was established on a prepared (i.e., compacted and bermed) pad near the northern most end of Ditch 4 (south of the vent raise) within the Industrial Complex area. The stockpile will be used for mill commissioning and consumed during the first year of operations, and therefore is temporary. The stockpile area sits at the base of a high sloping hill and is elevated above Wolverine creek, setback approximately 50m. A lined ditch (Ditch 4) is located between the ore stockpile and the creek, but does not extend the entire distance along the stockpile location.

Weather Conditions: Spring conditions (temperature ranging between -10 and +5°C) - snow melt in effect.

### Part 2 – Site Assessment

Activity:

- A portion (~10%) of the NW side of the Dynamic Ore pile was removed and placed on the SE side of the pile. Suitable fine material (i.e., sand and clay) was then transported to the same NW corner of the pile and used to elevate and berm the base of the pad so that runoff water from snow/rain events would be directed toward Ditch 4 (see Photos below).
- Additional measures were installed as site conditions dictated, including:
  - 1. a lined sump was installed on the south side of the road and
  - 2. small swales were excavated to divert runoff from the stockpile, or roads

Site Status:

The newly installed sump is monitored daily and water collected in it is pumped to Ditch 4 as required.

Assessed Risk: low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: None

### Part 3 – Mitigation Requirements

Mitigation Required: As a precautionary measure, installation of silt fencing to filter runoff downslope of the sump is required.

Mitigation Condition: Good

### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor runoff into sump and pump into Ditch 4 as required. Monitor Ditch 4 and ensure a clear channel is maintained to allow constant flow to Surface Sump #2. Monitor water level within Surface Sump #2 and pump to Tailings Facility as required. Monitor general area for sediment-laden runoff, particularly during rain events.

Monitoring Frequency: Daily

Reporting Requirements: As changes occur















Date: May 5 <sup>th</sup> – 9 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Dynamic Ore Stockpile	Location/Co-ordinates: KM 28.6 / 0439554E;6811058N

Site Location Description:

A dynamic ore stockpile was established on a prepared pad near the northern most end of Ditch 4 (south of the vent raise) within the Industrial Complex area. The stockpile will be used for mill commissioning and consumed during the first year of operations, and therefore is temporary. The stockpile area sits at the base of a high sloping hill and is elevated above Wolverine creek, setback approximately 50m. A lined ditch (Ditch 4) is located between the ore stockpile and the creek, and sumps have been installed to prevent sediment-laden runoff from migrating downslope. In addition, a silt fence runs along the toe of the Industrial Complex embankment along the entire creek length.

Weather Conditions: Spring conditions (temperature ranging between -5 and +15°C) - snow melt in effect.

## Part 2 – Site Assessment

Activity:

- Minor modifications were made to the newly installed sumps. Another berm was constructed to divert any runoff from the disturbed area directly west of the lined sump into the sump. Silt fencing (with straw at base) was installed just below the sump as a precautionary measure to filter runoff from the area around and downslope of the sump.

Site Status:

The newly installed sump is monitored daily and water collected in it is pumped to Ditch 4 as required.

Assessed Risk: low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: None

## Part 3 – Mitigation Requirements

Mitigation Required: None

Mitigation Condition: Good


### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor runoff into sump and pump into Ditch 4 as required. Monitor Ditch 4 and ensure a clear channel is maintained to allow constant flow to Surface Sump #2. Monitor water level within Surface Sump #2 and pump to Tailings Facility as required. Monitor general area for erosion, particularly during rain events.

Monitoring Frequency: Daily

Reporting Requirements: As changes occur







Date: June 25 <sup>th</sup> – July 16 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Dynamic Ore Stockpile	Location/Co-ordinates: KM 28.6 / 0439554E;6811058N

Site Location Description:

A dynamic ore stockpile was established on a prepared pad near the northern most end of Ditch 4 (south of the vent raise) within the Industrial Complex area. The stockpile will be used for mill commissioning and consumed during the first year of operations, and therefore is temporary. The stockpile area sits at the base of a high sloping hill and is elevated above Wolverine creek, setback approximately 50m. A lined ditch (Ditch 4) is located between the ore stockpile and the creek, and sumps have been installed to prevent sediment-laden runoff from migrating downslope. In addition, a silt fence runs along the toe of the Industrial Complex embankment along the entire creek length.

Weather Conditions: Spring conditions (temperature ranging between 5 and +20°C).

### Part 2 – Site Assessment

Activity:

- A temporary sump that was installed in May for sedimentation control was removed (Photo 1) and the area surrounding the SW corner of the temporary ore pile has been built up to divert any runoff water directly into Ditch 4 (Photos 2-4, 6-7).
- A culvert was installed to divert runoff water from the organic stockpile area (located NW of the temporary ore stockpile) to Wolverine creek. Riprap was installed at the inlet and outlet of the culvert, as well as along the ditch leading to the culvert to dissipate energy and sediment load (Photos 5 & 8). Silt fencing and straw bales were also installed at the outlet of the culvert to assist with energy dissipation and filtration of incoming water (Photo 8).

Site Status:

- Final grade complete. Water running off ore pile is diverted directly into Ditch 4. Water running from the organic stockpile area is diverted to Wolverine creek via a ditch and culvert that contains riprap, straw bales and silt fence.

Assessed Risk: low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: None

### Part 3 – Mitigation Requirements

Mitigation Required: With the implemented mitigation in place, regular inspections will be conducted as required.

Mitigation Condition: Acceptable

### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor runoff into Ditch 4 as required. Monitor Ditch 4 and ensure a clear channel is maintained to allow constant flow to Surface Sump #2. Monitor water level within Surface Sump #2 and pump to Tailings Facility as required. Monitor general area for erosion, particularly during rain events.


Monitoring Frequency: As required, with increased frequency during spring thaw and heavy rain events

Reporting Requirements: As changes occur











#### Part 1 – Site Description

Date: January 19 <sup>th</sup> – 27 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

#### Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 where it will be tested and treated if required. IC Ditch #1 will act to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. Infrastructure preparation complete and construction underway.

Weather Conditions: Typical winter weather, temperatures ranging from -10°C to -25°C with periods of snow.

#### Part 2 – Site Assessment

#### Activity:

#### - 2 gen-sets have arrived on site.

Site Status:

- Mill, CLO, and Crusher under construction.
- Ditch 2 not yet excavated.
- Ditch 1 not yet lined.
- Gen-set pad in final stages.
- Fuel storage pad in final stages.

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: None

#### Part 3 – Mitigation Requirements

Mitigation Required: Monitor Fuel farms and generators.

Mitigation Condition: Good


#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor entire job site.


Monitoring Frequency: Several times weekly, with thorough inspection of work sites once a week

Reporting Requirements: Every two weeks
















Part 1 – Site Description

Date: February 2 <sup>nd</sup> – 15 <sup>th</sup>	Inspector(s): Robin McCall
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #3 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Spring-like conditions (temperature ranging between -15 and +5) snow melt in effect.

#### Part 2 – Site Assessment

Activity:

- Welding, steel installation

Site Status:

- Mill, CLO, and Crusher under construction.
- Ditch 2 not yet excavated.
- Ditch 1 not yet lined.

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: None

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching as construction is completed


Mitigation Condition: Good

#### Part 4 – Monitoring Requirements


Follow-up Monitoring: Monitor Fuel farms and generators for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage handles. Ensure the waste program is being followed.

Monitoring Frequency: Every other day











## Part 1 – Site Description

Date: February 15 <sup>th</sup> – March 1 <sup>st</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

#### Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #3 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Typical winter/Spring weather, temperatures ranging from 5°C to -15°C with periods of snow.

#### Part 2 – Site Assessment

Activity:

- Welding and steel installation is ongoing in the Mill, CLO and Crusher buildings.
- Gen-set installation is ongoing

Site Status:

- Mill, CLO, and Crusher under construction.
- Ditch 2 not yet excavated.
- Ditch 1 not yet lined.
- Offices and construction material in the area.

Assessed Risk: Low

Photos Attached: Yes (8)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching as construction is completed


Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor Fuel farms and generators for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage handles. Ensure the waste program is being followed.

Monitoring Frequency: Every other day











### Part 1 – Site Description

Date: March 3 <sup>rd</sup> - March 15 <sup>th</sup> , 2010	Inspector(s): Jennie Gjertsen and Robin McCall
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

### Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Spring-like temperature conditions, periods of snowfall and some heavy winds. Average daily temperatures ranging from -10°C to 0°C

#### Part 2 – Site Assessment

Activity:

- Welding and steel installation is ongoing in the Mill, CLO and Crusher buildings.
- Gen-set installation is ongoing
- A 550L spill occurred March 11<sup>th</sup> on the genset pad. The contaminated material was excavated, removed, and the hole was filled in.
- Conveyors are being lifted into place

Site Status:

- Mill, CLO, and Crusher under construction.
- Ditch 2 not yet excavated
- Hauling from ablution tanks to YZC camp STP on a daily basis

Assessed Risk: Low

Photos Attached: Yes (8)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching as construction is completed


Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor Fuel farms and generators for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage handles. Ensure the waste program is being followed.

Monitoring Frequency: Thorough inspection at least once a week






10/03/07 Genset installation (facing SE)

10/02/18 Glycol stored in 1000L totes







#### Part 1 – Site Description

Date: March 16 <sup>th</sup> - March 29 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 then pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Spring-like temperature conditions, periods of snowfall and some heavy winds. Average daily temperatures ranging from -10°C to 0°C.

#### Part 2 – Site Assessment

Activity:

- Welding and steel installation is ongoing in the Mill, CLO and Crusher buildings.
- Gen-set installation is ongoing
- Conveyors are being lifted into place
- Hydro testing started Tuesday March 23<sup>rd</sup> in the Crusher building. Water is being taken from Hawkowl creek in low volumes for this procedure.

Site Status:

- Mill, CLO, Crusher, and Conveyer under construction.
- Ditch 2 not yet excavated
- Hauling from ablution tanks to YZC camp STP continues

Assessed Risk: Low

Photos Attached: Yes (14)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching as construction is completed


Mitigation Condition: Good

#### Part 4 – Monitoring Requirements


Follow-up Monitoring: Monitor Fuel farms and generators for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage handles. Ensure the waste program is being followed.

Monitoring Frequency: Thorough inspection at least once a week














# **Wolverine Project**

# **Environmental Inspection Form – Photos**





#### Part 1 – Site Description

Date: March 30 <sup>th</sup> – April 12 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Spring-like temperature conditions, periods of snowfall and some heavy winds. Average daily temperatures ranging from -5°C to 10°C.

#### Part 2 – Site Assessment

Activity:

- Welding and steel installation is ongoing in the Mill, CLO and Crusher buildings.
- Gen-set installation is ongoing
- Installation of transfer tower with conveyors connecting it to the Mill and Crusher is ongoing

Site Status:

- Mill, CLO, Crusher, transfer tower and Conveyer under construction.
- Ditch 2 not yet excavated
- Hauling from ablution tanks to YZC camp STP continues on a daily basis
- Runoff from snowmelt evident and erosion on south bank of mill pad starting in localized areas
- 'Winter garbage' surfacing after snowmelt evident

Assessed Risk: low (erosion of south bank a concern)

Photos Attached: Yes (8)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Water control/diversion as necessary, completion of drainage ditching as construction is completed

Mitigation Condition: Good


#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Once all snow has melted, commence general clean-up of IC. Monitor erosion along south bank of Mill Pad. Monitor Fuel farms and generators for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage handles. Ensure the waste program is being followed.


Monitoring Frequency: Thorough inspection at least once a week



# **Wolverine Project**









#### Part 1 – Site Description

Date: April 13 <sup>th</sup> – April 26 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Spring-like temperature conditions, periods of snowfall and some heavy winds. Average daily temperatures ranging from 10°C to 0°C.

#### Part 2 – Site Assessment

Activity:

- Welding and steel installation is ongoing in the Mill, CLO and Crusher buildings.
- Gen-set installation is ongoing

Site Status:

- Mill, CLO, Crusher, and Conveyer under construction.
- Ditch 2 not yet excavated
- Hauling from ablution tanks to YZC camp STP daily

Assessed Risk: Low

Photos Attached: Yes (13)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching as construction is completed, some silt fencing as ground conditions allow

Mitigation Condition: Good


#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor Fuel farms and generators for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage handles. Ensure the waste program is being followed.

Monitoring Frequency: Thorough inspection at least once a week



# **Wolverine Project**













#### 10/04/23

Sump installed at the end of ditch 4 to capture any runoff from the dynamic ore pile and industrial complex. This water will then be pumped into ditch 4.



#### Part 1 – Site Description

Date: April 27 <sup>th</sup> – May 11 <sup>th</sup> , 2010	Inspector(s): Jennie Gjertsen and Robin McCall
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

#### Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Spring conditions, periods of snowfall and some rain. Average daily temperatures ranging from 0°C to 10°C.

#### Part 2 – Site Assessment

Activity:

- Welding and steel installation is ongoing in the Mill, CLO and Crusher buildings.
- Gen-set installation is ongoing
- Diesel tank #2 drained and removed from Procon shop to cap mag road
- Water management control and mitigation
- Conveyors commissioning
- Hydro-testing in crusher

#### Site Status:

- Mill, CLO, Crusher, and Conveyer under construction.
- Ditch 2 not yet excavated
- Hauling from ablution tanks to YZC camp STP on a daily basis
- Installation of new Genset at Procon yard where Diesel Tank #2 was removed

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: Yes, several water samples of drainages around IC

Additional Information Attached: Yes, Mill drainage sketch of sample sites and names

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching as construction is completed.

Mitigation Condition: Good

### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor Fuel farms and generators for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage handles. Ensure the waste program is being followed.

Monitoring Frequency: Thorough inspection at least once a week


















#### Part 1 – Site Description

Date: May 25 <sup>th</sup> - June 7 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Spring/summer weather conditions, daily temperature averages to date range from 0°C to 15°C. Mostly sunny with periods of rainfall.

#### Part 2 – Site Assessment

Activity:

- Welding and steel installation is ongoing in the Mill, CLO and Crusher buildings.
- Ball Mill commissioning
- Re surfacing the mill pad with crush material (contractor offices being placed in front of mill building)
- Commissioning of new sections of tailings line and reclaim line
- Hydrotesting in mill ongoing

Site Status:

- Mill, CLO, Crusher, and Conveyer under construction, nearing completion
- Ditch 2 not yet excavated
- Hauling from ablution tanks to YZC camp STP on a daily basis

#### Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Sediment load in ditches 3 and 4 needs removed. Completion of drainage ditching as construction is completed.

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor Fuel farms and generators for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage handles. Ensure the waste program is being followed.

Monitoring Frequency: Thorough inspection at least once a week







#### Part 1 – Site Description

Date: June 8 <sup>th</sup> to June 21 <sup>st</sup> ,2010	Inspector(s): Jaymie Skidmore
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

### Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Spring/summer weather conditions, daily temperature averages to date range from 5°C to 20°C. Mostly sunny with periods of rainfall.

#### Part 2 – Site Assessment

Activity:

- Applying the finishes to the Mill, CLO, and Crusher.
- Excavation has started for the installation of dust bins along the north side of CLO.
- A rock wall has being built to extend the road to accommodate the size of the ore trucks turning into the CLO.

Site Status:

- Mill, CLO, and Crusher have been completed, concentrate has been produced as a demo
- Gen-set installation complete and energized
- Ditch 2 not yet excavated
- Hauling from office ablution tanks to YZC camp STP on a daily basis

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching as construction is completed.

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor fuel farm and gen-sets for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage handles. Ensure the waste disposal/storage program is being followed for all waste produced by the gen-sets. Monitor IC ditches following completion of construction

Monitoring Frequency: Thorough inspection at least once a week













the CLO.

Form: EM07-01



#### Part 1 – Site Description

Date: June 22 <sup>nd</sup> - July 5 <sup>th</sup> ,2010	Inspector(s): Robin McCall
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

#### Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Spring/summer weather conditions, daily temperature averages to date range from 5°C to 20°C. Mostly overcast and raining.

#### Part 2 – Site Assessment

Activity:

- Applying the finishes to the Mill, CLO, and Crusher.
- Excavation efforts continue on North side of Mill and CLO to accommodate 'entrance platforms', and a foundation for installation of a stair tower.
- Overall grading of Mill pad to favour runoff flow toward Ditch 5, located on West side of CLO
- Removal of outhouse at Portal and backfilling/capping of hole
- Grading and drainage ditching of crusher pad to divert runoff water into sump 2
- Construction of ditch to divert water sourced from the Mill/CLO (via Ditch 5 and down through a culvert) to sump 2

#### Site Status:

- Mill, CLO, and Crusher have been completed, concentrate has been produced
- Gen-set installation complete and energized
- Ditch 2 not yet excavated
- Hauling from office ablution tanks to YZC camp STP on a daily basis

#### Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching on Mill Pad and Crusher Pad.

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor fuel farm and gen-sets for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage handles. Ensure the waste disposal/storage program is being followed for all waste produced by the gen-sets. Monitor IC ditches following completion of construction

Monitoring Frequency: Thorough inspection at least once a week

Reporting Requirements: Every two weeks as operations continue.















Part 1 – Site Description

Date: July 6 <sup>th</sup> - July 19 <sup>th</sup> ,2010	Inspector(s): Jaymie Skidmore
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

#### Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Summer weather conditions, daily temperature averages to date range from 5°C to 20°C. Mostly overcast with some sun and rain.

#### Part 2 – Site Assessment

Activity:

- Applying the finishes to the Mill, CLO, and Crusher. Installation of dust bins outside north side of CLO
- Excavation efforts continue on North side of Mill and CLO to accommodate 'entrance platforms', and a foundation for installation of a stair tower.
- Construction of ditch to divert water sourced from the Mill/CLO (via Ditch 5 and down through a culvert) to sump 2
- Fire Water lines being installed
- Ditching around temp ore pile
- Ditch 5 excavation started

#### Site Status:

- Mill, CLO, and Crusher buildings have been 90 % completed
- Gen-set installation complete and energized
- Ditch 2 not yet excavated
- Hauling from office ablution tanks to YZC camp STP on a daily basis
- Ditch 5 excavated.

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching on Mill Pad and Crusher Pad.

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor fuel farm and gen-sets for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage containers. Ensure the waste disposal/storage program is being followed for all waste produced by the gen-sets. Monitor IC ditches following completion of construction

Monitoring Frequency: Thorough inspection at least once a week. Daily during construction.

Reporting Requirements: Every two weeks as operations continue.















#### Part 1 – Site Description

Date: July 20 <sup>th</sup> to August 2 <sup>nd</sup> , 2010	Inspector(s): Robin McCall and Jennie Gjertsen
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

#### Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Heavy rains at the beginning of the period, mostly sunny and very dry for the majority, daily temperatures average from 5°C to 25°C.

#### Part 2 – Site Assessment

#### Activity:

- Excavation for aprons around CLO and Mill
- Installation of glycol lines from gensets down to crusher
- Mill and crusher test runs
- Excavation for concrete sump at fueling station
- Installation of fire line to proposed assay lab on mill pad
- Decommissioning and removal of construction offices and trailers

Site Status:

- Construction almost complete around Mill, CLO, crusher

#### Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching on Mill Pad

Mitigation Condition: Good


#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor fuel farm and gen-sets for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage containers. Ensure the waste disposal/storage program is being followed for all waste produced by the gen-sets. Monitor IC ditches following completion of construction

Monitoring Frequency: Thorough inspection at least once a week. Daily during construction.

Reporting Requirements: Every two weeks as construction and commissioning continues.











#### Part 1 – Site Description

Date: August 3 <sup>rd</sup> to August 16 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

#### Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Mostly sunny and very dry for the majority, daily temperatures average from 5°C to 25°C.

#### Part 2 – Site Assessment

#### Activity:

- Excavation for aprons around CLO and Mill
- Installation of glycol lines from gen-sets down to crusher
- Mill and crusher test runs
- Concrete poured for sump at fueling station
- Excavation for fire line to proposed assay lab on mill pad complete installation to follow
- Decommissioning and removal of construction offices and trailers is ongoing
- Excavation of Ditch 5

Site Status:

- Construction almost complete around Mill, CLO, crusher

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Completion of drainage ditching on Mill Pad, slope control

Mitigation Condition: Good


#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor fuel farm and gen-sets for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage containers. Ensure the waste disposal/storage program is being followed for all waste produced by the gen-sets. Monitor IC ditches following completion of construction

Monitoring Frequency: Thorough inspection at least once a week. Daily during construction.

Reporting Requirements: Every two weeks as construction and commissioning continues.











#### Part 1 – Site Description

Date: September 26 <sup>th</sup> – September 30 <sup>th</sup> ,2010	Inspector(s): Jaymie Skidmore
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Fall weather consisting of rain and snow. Average daily temperature 0°C.

#### Part 2 – Site Assessment

#### Activity:

- Assay lab excavation and footings ongoing
- Final hook ups and charging the fire water lines
- Glycol lines have been flushed and filled
- The crushing and milling of the temporary ore pile is ongoing
- Excavating a pad at the fuel storage for 5 additional gen-sets (Procon)
- Mill and CLO trimmings
- Cyanide sea-can has been placed on a pad and bermed on the north side of the mill

#### Site Status:

- Final construction and testing of equipment is ongoing
- Cyanide sea-can has been placed at North side of Mill.

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Ditching and drainage will continue to be improved upon in the following year.

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor fuel farm and gen-sets for leaks/spills. Ensure that site services are regularly emptying the fuel nozzle storage containers. Ensure the waste disposal/storage program is being followed for all waste produced by the gen-sets. Monitor IC ditches as weather changes.


Monitoring Frequency: Thorough inspection at least once a week.

Reporting Requirements: As conditions require.















#### Part 1 – Site Description

Date: October 5 <sup>th</sup> to 19 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Industrial Complex (IC)	Location/Co-ordinates: Industrial complex

#### Site Location Description:

The industrial complex at the Wolverine site is situated between Km 27.5 and Km 29 on the access road. The area primarily falls within the Wolverine watershed. Collection ditches are built around the entire complex to contain any surface water runoff that comes in contact with material that could contaminate the water, and directs it to the water treatment sump #2 or pumped directly to tailings where it will be tested and treated if required. IC Ditch #1 is used to collect and divert a source of the headwaters of Wolverine creek and divert it around the IC and deposit it into its natural path. The IC is situated in a mostly pre disturbed area; tree removal, grubbing, organic and overburden removal was completed to prepare site for infrastructure.

Weather Conditions: Late fall conditions, snow fall.

#### Part 2 – Site Assessment

Activity:

- Tree removal, stripping and excavation of material in preparation of a pad for the Truck Shop on top of the hill directly NE of Sump 3. Organics and excavated material being transported to the overburden pile located just NW of Vent raise.
- Installation of rebar with flagging to help guide grader during snow removal over the winter period and avoid cutting into lined IC Ditches 3 and 4
- Reduction of Temporary Ore Stockpile at NE end of the IC as the ore used to commission the Mill

Site Status:

- Excavation of Truck Shop pad underway
- Installation of rebar complete
- Use of ore from Temporary Ore Stockpile continues

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: None

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor excavation and grading of pad and provide guidance where necessary.

Monitoring Frequency: Thorough inspection at least once a week.

Reporting Requirements: As required.








## Part 1 – Site Description

Date: January 12 <sup>th</sup> – 19 <sup>th</sup> , 2010	Inspector(s): Billie Maje	
Site Name: Landfill	Location/Co-ordinates: km 26.2	
Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.		
Weather Conditions:		
Typical winter weather conditions, temperature ranging from -10°C to -30°C with snow.		
Part 2 – Site Assessment		
Activity: Ongoing waste management program.		
Site Status: - Awaiting burn permit to open burn construction waste. - Landfill cell has a few household garbage bags in it, no food was noticed.		
Assessed Risk: Low		
Photos Attached: Yes (2)		
Samples Taken: No		
Additional Information Attached: No		
Part 3 –Mitigation Requirements		
Mitigation Required: None.		
Mitigation Condition: Good.		
Part 4 – Monitoring Requirements		
Follow-up Monitoring: ongoing		
Monitoring Frequency: Daily.		
Reporting Requirements: Every two weeks.		







Part 1 – Site Description		
Date: January 20 <sup>th</sup> – 27 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore	
Site Name: Landfill	Location/Co-ordinates: Km 26.2	
Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south. Weather Conditions: Typical winter weather conditions, temperature ranging from -10°C to -30°C with snow.		
Part 2 – Site Assessment		
Activity: <ul> <li>Ongoing waste management program</li> <li>Construction waste was open-burned</li> <li>Area cleared out for storage beside wash bay</li> <li>Electrical shack being built near the incinerator</li> </ul>		

- Fire extinguisher training set up by incinerator -
- Snow clearing

#### Site Status:

Burn permit was received, and construction waste pile has been burned. Oil filters to be burned. -

Assessed Risk: Low

Photos Attached: Yes (16)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: None

Mitigation Condition: N/A

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Ongoing


Monitoring Frequency: Daily

Reporting Requirements: Every two weeks












Site Name: Landfill	Date: January 19 <sup>th</sup> – 27 <sup>th</sup>
10/01/26 Burn pile #2.	10/01/26 Burn pile #2 after burning all day.
10/01/27 Burn pile #2 after burning over night.	











#### Part 1 – Site Description

Date: February 2 <sup>nd</sup> - 15 <sup>th</sup> , 2010	Inspector(s): Melissa Kirby and Robin McCall
Site Name: Landfill	Location/Co-ordinates: km 26.2
Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area	

comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.

Weather Conditions:

Typical winter weather conditions, temperature ranging from -2°C to -20°C with snow.

#### Part 2 – Site Assessment

Activity: Ongoing waste management program.

Site Status:

- Incinerator area looks well maintained
- Sign for wood/metal areas fallen down, needs to be repaired and stabilized
- Wooden crate (painted "Garbage") left in wood storage area, mixed garbage (plastics, drink bottles and boxes, metals, aerosols, etc.) at least 15-20 ravens rummaging around

Assessed Risk: Med

Photos Attached: Yes (4)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Wood/Metal sign to be repaired, garbage crate to be cleaned up, contractors to be notified of proper waste management protocols.

Mitigation Condition: Site services notified about sign and conditions, "Garbage crate" removed, Robin preparing one page overview of waste management for contractors.


Part 4 – Monitoring Requirements

Follow-up Monitoring: See if conditions improve

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks







Site Name: Landfill	Date: February 2 <sup>nd</sup> – 15 <sup>th</sup>
10/02/12 Wood/Metal location sign stabilized.	10/02/12 Wood only brought up to burn pit. No Raven in sight.
10/02/13 Incinerator area tidy	





### Part 1 – Site Description Date: February 16<sup>th</sup> – March 1<sup>st</sup>, 2010 Inspector(s): Jaymie Skidmore Site Name: Landfill Location/Co-ordinates: km 26.2 Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south. Weather Conditions: Winter/spring weather conditions, temperature ranging from 5°C to -20°C with light snow. Note: The warm weather conditions this winter may cause animals to become active earlier than usual. Part 2 – Site Assessment Activity: - Ongoing waste management program by incineration, open pit burning, and storage. - A new burn permit has been approved for unlimited burning of wood and plastic waste. Site Status: Incinerator area looks well maintained. Burn pit area has excess scrap metal and ashes. - ~ 7 Ravens are hanging around in the area. Assessed Risk: Low Photos Attached: Yes (8) Samples Taken: No Additional Information Attached: No Part 3 – Mitigation Requirements Mitigation Required: Ashes in burn pit need to be put in cell. Steel left in burn pile need to be put in steel pile. Mitigation Condition: Excellent Part 4 – Monitoring Requirements Follow-up Monitoring: ongoing, monitor for non-compliance with permits Monitoring Frequency: Daily Reporting Requirements: Every two weeks.













Date: March 2 <sup>nd</sup> – March 15 <sup>th</sup> , 2010	Inspector(s): Jennie Gjertsen and Robin McCall
Site Name: Landfill	Location/Co-ordinates: km 26.2
Cite Leasting Description Leastill area is an analyzing take 200m by 200m. The laws has dill area	

Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.

Weather Conditions:

Spring-like temperature conditions, periods of snowfall and some heavy winds. Average daily temperatures ranging from -10°C to 0°C

#### Part 2 – Site Assessment

Activity:

- Ongoing waste management program including; incineration, open pit burning, and storage
- Continue work on electrical in sea-can for eventual power line hook-up
- Fewer ravens seen in the area this period
- Incinerator went down March 15<sup>th</sup>, looking for parts to re-commission

Site Status:

- Incinerator area clean and free of animal attractants
- Burn pit area has excess scrap metal and ashes
- 6 waste containers full of antifreeze contaminated material have been moved to the incinerator area from the March 11<sup>th</sup> antifreeze spill. Contents to be incinerated. No sampling required.

Assessed Risk: Low

Photos Attached: Yes (8)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps. Bin of 12V batteries need to be covered with a tarp or plywood

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: ongoing, monitor for non-compliance with permits

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks.











Date: March 16 <sup>th</sup> – March 29 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Landfill	Location/Co-ordinates: km 26.2

Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.

Weather Conditions:

Spring-like temperature conditions, periods of snowfall and some heavy winds. Average daily temperatures ranging from -10°C to 0°C

#### Part 2 – Site Assessment

Activity:

- Ongoing waste management program including; incineration, open pit burning, and storage
- Continue work on electrical in sea-can for eventual power line hook-up
- 7 Ravens seen in the area this period
- Incinerator repaired March 18<sup>th</sup>. Catching up on incinerating trash.

Site Status:

- Incinerator area clean and free of animal attractants
- Burn pit area has excess scrap metal and ashes
- 6 waste containers full of antifreeze contaminated material have been moved to the incinerator area from the March 11<sup>th</sup> antifreeze spill.

Assessed Risk: Low

Photos Attached: Yes (12)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps.

Mitigation Condition: Good


#### Part 4 – Monitoring Requirements

Follow-up Monitoring: ongoing, monitor for non-compliance with permits

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks.















Date: March 30 <sup>th</sup> – April 12 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Landfill	Location/Co-ordinates: km 26.2

Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.

Weather Conditions:

Spring temperature conditions, periods of snowfall and some heavy winds. Average daily temperatures ranging from -5°C to 10°C

#### Part 2 – Site Assessment

Activity:

- Ongoing waste management program including; incineration, open pit burning, and storage

Site Status:

- Incinerator area clean and free of animal attractants
- Landfill cell 2/3 full
- Burn pit area being used daily

#### Assessed Risk: Low

Photos Attached: Yes (4)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps.

Mitigation Condition: Good


#### Part 4 – Monitoring Requirements

Follow-up Monitoring: ongoing, monitor for non-compliance with permits

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks.







Wolverine Project         YukonZinc         Environmental Inspection Form		
Part 1 – Site Description		
Date: April 13 <sup>th</sup> – April 26 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore	
Site Name: Landfill	Location/Co-ordinates: km 26.2	
Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.		
Weather Conditions:		
Spring-like temperature conditions, periods of snowfall and some heavy winds. Average daily temperatures ranging from 0°C to 10°C		
Part 2 – Site Assessment		
<ul> <li>Activity: <ul> <li>Ongoing waste management program including;</li> <li>Spring cleaning in affect around incinerator.</li> <li>Spill kits to be painted and moved to a more visit</li> <li>Debris in and around burn pit to be cleaned up a</li> </ul> </li> <li>Site Status: <ul> <li>Incinerator area clean and free of animal attracta</li> <li>Landfill 1/2 full</li> <li>Burn pit area being used daily</li> <li>Steel storage is increasing significantly</li> </ul> </li> </ul>	ble place. Is snow melts	
Assessed Risk: Low		
Photos Attached: Yes (10)		
Samples Taken: No		
Additional Information Attached: No		
Part 3 – Mitigation Requirements		
Mitigation Required: Continue efforts to inform contract garbage until no domestic waste can be seen in constr Mitigation Condition: Good Part 4 –Monitoring Requirements	tors of waste management information, workers to sort ruction waste dumps.	
	iance with permits	
Follow-up Monitoring: ongoing, monitor for non-compli		
Follow-up Monitoring: ongoing, monitor for non-compli Monitoring Frequency: Daily		
















Date: April 27 <sup>th</sup> – May 10 <sup>th</sup> , 2010	Inspector(s): Jennie Gjertsen and Robin McCall
Site Name: Landfill	Location/Co-ordinates: km 26.2

Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.

Weather Conditions:

Spring conditions, periods of snowfall and rainfall. Average daily temperatures ranging from 0°C to 10°C

#### Part 2 – Site Assessment

Activity:

- Ongoing waste management program including; incineration, open pit burning, and storage
- Incineration not in operation from April 27<sup>th</sup> May 8, required replacement part
- Open burning of domestic wastes so that long term storage does not become an animal attractant
- Commissioning of electric bear fence, with some ongoing maintenance
- Aerosol can puncturing device on order to reduce storage
- Wood waste pile increasing requires open burn when weather becomes more 'wet'
- Signage damaged from weather needs replaced

#### Site Status:

- Incinerator area clean and free of animal attractants
- Landfill 1/2 full
- Burn pit area being used daily

#### Assessed Risk: Low

Photos Attached: Yes (2)

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps. Open burn to be kept in culvert as much as possible as drier conditions progress.

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: ongoing, monitor for non-compliance with permits

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks. Daily incinerator reports







YukonZinc       Wolverine Project         Environmental Inspection Form		
Part 1 – Site Description		
Date: May 11 <sup>th</sup> - May 24 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore	
Site Name: Landfill	Location/Co-ordinates: km 26.2	
Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.		
Weather Conditions:		
Spring/summer weather conditions, daily temperature averages to date range from 5°C to 15°C. Mostly sunny with periods of rainfall.		
Part 2 – Site Assessment		
- Incinerator is up and running		
- Lanofili 1/2 full		

Open pit burning ongoing until construction is complete -

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps. Open burn to be monitored closely in dry conditions

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: ongoing, monitor for non-compliance with permits

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks. Daily incinerator reports











YukonZinc CORP Wolverine Project Environmental Inspection Form		
Part 1 – Site Description		
Date: May 25 <sup>th</sup> - June 7 <sup>th</sup> , 2010	Inspector(s): Robin McCall	
Site Name: Landfill	Location/Co-ordinates: km 26.2	
Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south. Weather Conditions: Spring/summer weather conditions, daily temperature averages to date range from 0°C to 15°C. Mostly sunny with periods of rainfall.		
Part 2 – Site Assessment		
<ul> <li>Activity: <ul> <li>Ongoing waste management program including;</li> <li>Incinerator broke down on June 1<sup>st</sup>, and therefore period since. A replacement part is expected to</li> <li>. Household garbage was found at back of wood clean-up this garbage and burn to avoid potenti</li> </ul> </li> <li>Site Status: <ul> <li>Incinerator area clean and free of animal attractant</li> <li>I andfill 1/2 full</li> </ul> </li> </ul>	e, all domestic waste was open burned since during the arrive within next 2 weeks. stockpile – workers were informed immediately to ial animal attraction.	

- Landfill 1/2 full
- Open pit burning ongoing until incinerator part is received

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps Open burn to be monitored closely in dry conditions

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: ongoing, monitor for non-compliance with permits

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks. Daily incinerator reports







Date: June 8 <sup>th</sup> to June 21 <sup>st</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Landfill	Location/Co-ordinates: km 26.2

Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.

Weather Conditions:

Summer weather conditions, daily temperatures range from 5°C to 20°C. Mostly sunny with periods of rainfall.

#### Part 2 – Site Assessment

Activity:

- Ongoing waste management program including; incineration, open pit burning, and storage
- Large open burns have been continued only under safe conditions
- Incinerator is down and awaiting parts (Approx. 30-40 bags of household waste being burned in the pit daily) Up and running as of June 18<sup>th</sup>
- Sample taken of the anti-freeze contaminated soil located at the incinerator
- Construction debris being burned during safe conditions
- Battery box is full needs to be placed at special waste pad (SWP) and new one placed at landfill
- Ash from the burn piles dumped into cell 1.
- Cell 1 will have an earth cover placed over waste

Site Status:

- Incinerator area clean and free of animal attractants. Bear fence in place
- Cell 1 almost full and partially to be buried
- Steel pile growing daily
- Construction waste is open burned daily

#### Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps. Open burn to be monitored closely in dry conditions

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: ongoing, monitor for non-compliance with permits

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks. Daily incinerator reports












# **Wolverine Project**





•	
Date: June 22 <sup>nd</sup> to July 5 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Landfill	Location/Co-ordinates: km 26.2
Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill	

area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.

Weather Conditions:

Summer weather conditions, daily temperatures range from 5°C to 20°C. Mostly overcast with periods of heavy rainfall.

#### Part 2 – Site Assessment

Activity:

- Ongoing waste management program including; incineration, open pit burning, and storage
- Large open burns have been continued only under safe conditions
- Sample taken of the anti-freeze contaminated soil located at the incinerator
- Construction debris being burned during safe conditions
- Ash from the burn piles dumped into cell 1.
- A section of Cell 1 have been backfilled with earth/soil

#### Site Status:

- Incinerator area clean and free of animal attractants. Bear fence in place
- Cell 1 to be buried partially
- Steel pile growing daily
- Construction waste is open burned daily

Assessed Risk: Low

Photos Attached: Yes

#### Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps. Open burn to be monitored closely in dry conditions

Mitigation Condition: Good


#### Part 4 – Monitoring Requirements

Follow-up Monitoring: ongoing, monitor for non-compliance with permits

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks. Daily incinerator reports







Date: July 6 <sup>th</sup> to July 19 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Landfill	Location/Co-ordinates: km 26.2

Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.

Weather Conditions: Summer weather conditions, daily temperatures range from 5°C to 20°C. Mostly overcast with periods of sunshine and light rainfall.

#### Part 2 – Site Assessment

Activity:

- Ongoing waste management program including; incineration, open pit burning, and storage
- Construction debris being burned during safe conditions
- Site organisation and cleanup ongoing daily

Site Status:

- Incinerator area clean and free of animal attractants. Bear fence in place
- Cell 1 partially buried
- Steel pile growing daily
- Construction waste is open burned daily

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps. Open burn to be monitored closely

Mitigation Condition: Good


#### Part 4 – Monitoring Requirements

Follow-up Monitoring: ongoing, monitor for non-compliance with permits

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks. Daily incinerator reports







Site Name: Landfill	Date: July 6 <sup>th</sup> to July 19 <sup>th</sup> , 2010
10/07/16 Storage shack placed at incinerator.	



Date: July 20 <sup>th</sup> to August 2 <sup>nd</sup> , 2010	Inspector(s): Robin McCall and Jennie Gjertsen
Site Name: Landfill	Location/Co-ordinates: km 26.2

Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.

Weather Conditions: Heavy rains at the beginning of the period, mostly sunny and very dry for the majority, daily temperatures average from 5°C to 25°C.

#### Part 2 – Site Assessment

Activity:

- Ongoing waste management program including; incineration, open pit burning, and storage
- Construction debris being burned during safe conditions
- Site organisation and cleanup ongoing daily

Site Status:

- Incinerator area clean and free of animal attractants. Bear fence has been repaired.
- Steel pile needs to be sorted as time and equipment permits
- Construction waste is open burned daily

Assessed Risk: Low

Photos Attached: Yes

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps. Open burn to be monitored closely as conditions are very dry. Need to develop long term plan for area

Mitigation Condition: Good

Part 4 – Monitoring Requirements

Follow-up Monitoring: ongoing, monitor for non-compliance with permits

Monitoring Frequency: Daily

Reporting Requirements: Every two weeks. Daily incinerator reports to be filled out by operators







Date: September 28 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Landfill	Location/Co-ordinates: km 26.2

Site Location Description: Lower landfill area is approximately 200m by 200m. The lower landfill area comprises the incinerator and the landfill cells, and is surrounded by an electric bear fence. The upper landfill area is contains the recyclable material stockpiles, as well as an area for open burning of construction material. Moss, lichen and willows are the most common vegetation with some small spruce trees. A seasonal spring is located at the entrance to the landfill (to the west), Go creek is located 100m south.

Weather Conditions: Fall weather consisting of rain and snow. Average daily temperature 0°C.

#### Part 2 – Site Assessment

Activity:

- Ongoing waste management program including; incineration, open pit burning, and storage
- Construction debris being burned during safe conditions only
- Site organisation and cleanup ongoing daily
- Metal and ashes removed from burn pit, metal placed in metal pile ashes in landfill

#### Site Status:

- Incinerator area clean and free of animal attractants.
- Steel pile needs to be sorted as time and equipment permits
- Construction waste is open burned daily
- Burn pit area clean of all debris

Assessed Risk: Low

Photos Attached: No

Samples Taken: No

Additional Information Attached: No

#### Part 3 – Mitigation Requirements

Mitigation Required: Continue efforts to inform contractors of waste management information, workers to sort garbage until no domestic waste can be seen in construction waste dumps. Open burn to be monitored closely as conditions are very dry. Need to develop long term plan for area. Double walled gas tank to be installed.

Mitigation Condition: Good

#### Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor for non-compliance with permits daily


Monitoring Frequency: Daily

Reporting Requirements: A separate daily monitoring checklist has been produced and future environmental monitoring reports will be done as conditions require.




Part 1 – Site Description Date: February 25<sup>th</sup> – March 2<sup>nd</sup> ,2010 Inspector(s): Jaymie Skidmore Site Name: Power line Location/Co-ordinates: Mill Gen-set pad to Tailings Facility. Site Location Description: The area cleared is approximately 4km long and 5 meters wide. It consists of spruce trees, willows and light organic material. The power line will cross over Go creek at km 26. A large portion on the route has previously been disturbed. The purpose of the power line is to supply power from the Gen-sets located in the industrial area to the tailings treatment facility. Weather Conditions: Winter/Spring weather, temperatures ranging from 5°C to -20°C with periods of snow. Part 2 – Site Assessment Status: -Route is cleared from mill site gen-set pad through the trees above YZC camp to km 27 onto old road where it continues down until 26.2 where it crosses new access road and starts to run along south side of road then along airstrip below arctic camp then crossing over at 25.2 until it reaches the Tailings pond. Clearing 100% completed. Power poles are 100% erect from gen set pad along to tailings facility. Activity: -The power lines are approx. 70% installed. -Arctic Power has returned to site to complete the installation of the power line. - A few trees have been cleared at ~ KM 26.3 for safer access to poles. Assessed Risk: Low Photos Attached: Yes (8) Samples Taken: No Additional Information Attached: No Part 3 – Mitigation Requirements Mitigation Required: Mitigation Condition: Part 4 – Monitoring Requirements Follow-up Monitoring: Ongoing during construction. Monitoring Frequency: Daily Reporting Requirements: As built












Part 1 – Site Description	
Date: March 2 <sup>nd</sup> – March 15 <sup>th</sup> , 2010	Inspector(s): Jennie Gjertsen
Site Name: Power line	Location/Co-ordinates: Mill Gen-set pad to Tailings Facility.
Site Location Description: The area cleared is approximately 4km long and 5 meters wide. It consists of spruce trees, willows and light organic material. The power line will cross over Go creek at km 26. A large portion on the route has previously been disturbed. The purpose of the power line is to supply power from the Gen-sets located in the industrial area to the tailings treatment facility, and to other facilities along that route.	
Weather Conditions:	
Spring like weather conditions, average daily temperatu	res range form 0°C to -10°C
Part 2 – Site Assessment	
Activity:	
- Power line stringing is ongoing	
Status:	
Work is ongoing	
Assessed Risk: Low	
Photos Attached: Yes (4)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 –Mitigation Requirements	
Mitigation Required: some trees have been felled into the removed before freshet	e old Go Creek channel at Km 26 and need to be
Mitigation Condition: good	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Ongoing during construction.	
Monitoring Frequency: weekly	
Reporting Requirements: Every two weeks	








Part 1 – Site Description		
Date: March 16 <sup>th</sup> – March 27 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore	
Site Name: Power line	Location/Co-ordinates: Mill Gen-set pad to Tailings Facility.	
Site Location Description: The area cleared is approximately 4km long and 5 meters wide. It consists of spruce trees, willows and light organic material. The power line will cross over Go creek at km 26. A large portion on the route has previously been disturbed. The purpose of the power line is to supply power from the Gen-sets located in the industrial area to the tailings treatment facility, and to other facilities along that route.		
Weather Conditions:		
Spring like weather conditions, average daily temperatu	res range form 0°C to -10°C	
Part 2 – Site Assessment		
Activity: - Power line stringing is ongoing - Installed poles at tailings area. Excavation permit approved for pre disturbed area.		
Status:		
Work is ongoing		
Assessed Risk: Low		
Photos Attached: Yes (4)		
Samples Taken: No		
Additional Information Attached: No		
Part 3 –Mitigation Requirements		
Mitigation Required: some trees have been felled into the old Go Creek channel at Km 26 and need to be removed before freshet-Passed on to site services to clean up when possible.		
Mitigation Condition: good		
Part 4 – Monitoring Requirements		
Follow-up Monitoring: Ongoing during construction.		
Monitoring Frequency: weekly		

Reporting Requirements: Every two weeks







Part 1 – Site Description	
Date: April 13 <sup>th</sup> – April 27 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Power line	Location/Co-ordinates: Mill Gen-set pad to Tailings Facility.
Site Location Description: Area cleared through the trees	s up into YZC gen-set pad down behind the medic trail,
above the waste rock pad entering the old road at km 27	running along it then crossing the new access road at km
26.2. Will run along south side of road ending at the Tail	ings pond.
Weather Conditions: Typical spring weather, temperatur	es ranging from 0°C to 10°C with periods of snow.
Part 2 – Site Assessment	
Activity:	
<ul> <li>Communication lines being installed</li> </ul>	
Status:	
- Power poles are 100% erect from gen set pad along to	tailings facility.
-The power lines are approx. 100% installed	
Assessed Risk: Low	
Photos Attached: Yes (6)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 – Mitigation Requirements	
Mitigation Required: None	
Mitigation Condition: Excellent	
Part 4 –Monitoring Requirements	
Follow-up Monitoring: None required	
Monitoring Frequency: N/A	
Reporting Requirements: N/A	







Part 1 – Site Description	
Date: June 9 <sup>th</sup> and 11 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Tailings Pipeline	Location Km 24.2 (tailings) to Km 27.4 (mill pad)
Site Location Description: The tailings discharge pipeline and reclaim pipeline conveys waste water and tails from the camp and industrial processes to and from the tailings facility. The pipeline design is a large insulated double walled HDPE pipe, with welding between sections. The pipeline extends from the mill area to the tailings over a distance of 2.5km. The area disturbed for pipeline access consisted of some small spruce trees, but mainly small willows and a vegetative bed of moss and lichen. The pipeline starts within the wolverine creek drainage (large distance from Creek itself >300m) and travels into the Go Creek drainage, crossing Go Creek at Km 26 on the access road.	
Weather Conditions: Spring conditions with temperature	ranging from 5°C to 15°C with periods of rain and sun.
Part 2 – Site Assessment	
Activity: -The installation of the discharge and reclaim pipelines from the mill building to the tailings pond have been completed. -Daily water testing is ongoing. -The reclaim pipeline barge has been installed and is operational.	
Site Status:	
- Water is continuously being pumped to tailings from w	ater treatment ponds.
- Treated effluent water is being pumped from the Sewag	ge Treatment Plant (STP) to the tailings facility.
- Water is being reclaimed and pumped back to the mill I	building from the tailings pond.
- Slury is being pumped from the mill to the tailings pond	
Assessed Risk: low	
Photos Attached: Yes (5)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 –Mitigation Requirements	
Mitigation Required: none	
Mitigation Condition: Excellent	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: none	
Monitoring Frequency: Daily at end of pipe and length of pipeline periodically	
Reporting Requirements: When conditions change	



Wolverine Project Environmental Inspection Form – Photos






Environmental Inspection Form – Photos

Project Name: Pipeline	<b>Date:</b> June 9 <sup>th</sup> – 11 <sup>th</sup> , 2010
<b>10/06/11</b> Discharge into the tailings pond.	



Part 1 – Site Description	
Date: April 13 <sup>th</sup> – April 26 <sup>th</sup> , 2010	Inspector(s): Jaymie Skidmore
Site Name: Tailings Pipeline	Location Km 24.2 (tailings) to Km 27.4 (mill pad)
Site Location Description: The tailings discharge pipeline and reclaim pipeline conveys waste water and tails from the camp and industrial processes to and from the tailings facility. The pipeline design is a large insulated double walled HDPE pipe, with welding between sections. The pipeline extends from the mill area to the tailings over a distance of 2.5km. The area disturbed for pipeline access consisted of some small spruce trees, but mainly small willows and a vegetative bed of moss and lichen. The pipeline starts within the wolverine creek drainage (large distance from Creek itself >300m) and travels into the Go Creek drainage, crossing Go Creek at Km 26 on the access road.	
Weather Conditions: Spring conditions with temperature	e ranging from 0 to 10°C.
Part 2 – Site Assessment	
Activity: -The discharge line and reclaim line are being installed. -Pump house and pump being installed at tailings. -Pipeline being installed in mill building. -Pipeline from sump 3 to mill being installed to supply mill with water as needed	
Site Status: - Underground water is continuously being pumped to tailings from water treatment ponds. - Treated effluent water is being pumped from the Sewage Treatment Plant (STP) to the tailings facility. - As the temperature has gone up the pipeline has expanded and started to snake Assessed Risk: low	
Photos Attached: Yes (10)	
Samples Taken: No	
Additional Information Attached: No	
Part 3 –Mitigation Requirements	
Mitigation Required: none	
Mitigation Condition: excellent	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Ongoing during construction. Mo	nitor discharge end daily to ensure there is no ice build up
Monitoring Frequency: Daily at end of pipe	
Reporting Requirements: When conditions change	







Project Name: Pipeline


**Date:** April 13<sup>th</sup> – April 26<sup>th</sup>, 2010





Project Name: Pipeline

Date: April 13<sup>th</sup> – April 26<sup>th</sup>, 2010







Part 1 – Site Description	
Date: July 20 <sup>th</sup> to August 2 <sup>nd</sup> , 2010	Inspector(s): Jennie Gjertsen
Site Name: Tailings Facility	Location/Co-ordinates: Km 24.2 on the access road
Site Location Description: The tailings facility consists of a lined basin, the main dam, a seepage dam, a spillway, seepage collection and diversion ditches, reclaim pump barge and pipelines. The reclaim and tailings pipelines extend from the tailings facility to the industrial complex and are aligned along the access road between the two areas. The tailings facility receives all of the waste water and tails effluent from the Wolverine Project. Water will be sent back to the mill for process water, or treated and discharged. The facility is located in the Go Creek drainage, and treated effluent will be discharged to creek once discharge parameters have been met.	
Weather Conditions: Summer weather conditions. average from 10°C to 25°C.	Mostly sunny and very dry, daily temperatures
Part 2 – Site Assessment	
<ul> <li>Activity: <ul> <li>Repair of holes in tailings liner</li> <li>Construction of seepage dam, and installation of underdrain piping</li> <li>Construction of emergency spillway swale across access road</li> <li>Daily monitoring for wildlife in and around facility</li> </ul> </li> <li>Site Status: <ul> <li>Water and tails are being discharged from the underground mine as well as from mill processes. Tailings are from waste being processed to commission the mill.</li> <li>Seepage dam construction complete</li> <li>Pump barge is installed and reclaim line is operational</li> </ul> </li> </ul>	
Culverts for emergency spillway need to be installed Assessed Risk: None	
Photos Attached: Yes	
Samples Taken: No	
Additional Information Attached: None	
Part 3 –Mitigation Requirements	
Mitigation Required: Should look at drainage into seepage dam basin to minimize runoff that requires pumping back to tailings. Planned erosion control and seeding to ditches and slopes this summer/fall Mitigation Condition: Good	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Wildlife monitoring, and for completion of emergency spillway	
Monitoring Frequency: Daily wildlife monitoring	
Depending Depuisements WDD equipements licensection reports	

Reporting Requirements: WPP, environmental inspection reports





















# Part 1 – Site Description

Part 1 – Site Description	Part 1 – Site Description	
Date: April 24th ,2010	Inspector(s): Jaymie Skidmore	
Site Name: Waste Rock Pad – Waste Rock Sump	Location/Co-ordinates: Waste Rock Pad and Sump ~ Km 27.2	
Site Location Description: The waste rock pad is located in an area which is lined and bermed with a large earthen/clay dyke to contain water drainage from the waste rock stored in this area. The waste rock sump is approximately 221m3 and is also lined. This sump is designed to collect contaminated water runoff from the waste rock pile.		
Weather Conditions: Typical spring weather with temperatures ranging from 0 to 15C with periods of snow, rain and sun. Spring melt is in effect.		
Part 2 – Site Assessment		
Activity:		
-Pumped waste rock sump-6 water truck loads pumped and discharged into the tailings facility		
-Ditching the area around the ore pile ramp to divert runoff back into the lined area		
Site Description: Waste rock sump is now empty; the waste rock pile is increasing daily. Ditching and seepage prevention is ongoing.		
Assessed Risk: Low		
Photos Attached: Yes (2)		
Samples Taken: No none needed		
Additional Information Attached: none		
Part 3 –Mitigation Requirements		
Mitigation Required: Pump out waste rock sump and ditch around waste rock pile.		
Mitigation Condition: good		
Part 4 –Monitoring Requirements		
Follow-up Monitoring: Monitor ditches to insure efficiency during melt and rain		
Monitoring Frequency: Daily, during rain events or when mitigation applied		
Reporting Requirements: As conditions change		



Site Name: Waste Rock Pad April 24<sup>th</sup> , 2010





Site Name: Waste Rock Pad April 23th , 2010 10/04/23 Ditching around ore pad ramp to divert runoff back into lined area.



#### Part 1 – Site Description

Date: April 27 <sup>th</sup> – May 11 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Waste Rock Pad – Waste Rock Sump	Location/Co-ordinates: Waste Rock Pad and Sump ~ Km 27.2

Site Location Description: The waste rock pad is located in an area which is lined and bermed with a large earthen/clay dyke to contain water drainage from the waste rock stored in this area. The waste rock sump is approximately 221m3 and is also lined. This sump is designed to collect contaminated water runoff from the waste rock pile.

Weather Conditions: Typical spring weather with temperatures ranging from -5C to 15C with periods of snow, rain and sun. Spring melt is in effect.

#### Part 2 – Site Assessment

Activity:

-Waste rock sump was fully emptied twice and discharged into the tailings facility

- -Ditching the area around the ore pile ramp to divert runoff back into the lined area
- -Removal of Ore from Waste Rock pad

Site Description: Waste rock sump is now empty; the waste rock pile was increasing daily during first week, but has since been discontinued due stoppage of the Underground Mining operations. Ditching and seepage prevention is ongoing.

Assessed Risk: Low

Photos Attached: Yes (5)

Samples Taken: No none needed

Additional Information Attached: none

#### Part 3 – Mitigation Requirements

Mitigation Required: Pump out waste rock sump as required

Mitigation Condition: good

Part 4 – Monitoring Requirements

Follow-up Monitoring: Monitor ditches and any potential seepage from the facility


Monitoring Frequency: Daily, during rain events or when mitigation applied

Reporting Requirements: As conditions change











Part 1 – Site Description	
Date: May 26 <sup>th</sup> – June 7 <sup>th</sup> , 2010	Inspector(s): Robin McCall
Site Name: Waste Rock Pad – Waste Rock Sump	Location/Co-ordinates: Waste Rock Pad and Sump ~ Km 27.2
Site Location Description: The waste rock pad is located in an area which is lined and bermed with a large earthen/clay dyke to contain water drainage from the waste rock stored in this area. The waste rock sump is approximately 221m3 and is also lined. This sump is designed to collect contaminated water runoff from the waste rock pile.	
Weather Conditions: Spring weather with temperatures ranging from 0C to 15C with periods of rain and sun.	
Part 2 – Site Assessment	
Activity:	
-Waste rock sump was emptied and discharged into the	tailings facility
-Remaining Ore removed from Waste Rock Pad	
Site Description: No ore remains on the pad, sump level does not pose risk of runoff	
Assessed Risk: Low	
Photos Attached: Yes (2)	
Samples Taken: No	
Additional Information Attached: none	
Part 3 – Mitigation Requirements	
Mitigation Required: Pump out waste rock sump as required	
Mitigation Condition: good	
Part 4 – Monitoring Requirements	
Follow-up Monitoring: Monitor ditches and any potential seepage from the facility	
Monitoring Frequency: Daily, during rain events or when mitigation applied	
Reporting Requirements: As conditions change	



