



Figure 3-1: Water Quality in Vangorda Creek, near the Town of Faro
at Site V8 (2003 to 2010)




a) Sulphate



c) Copper



b) Zinc (Total)



d) TSS

