



Figure 3-1: Water Quality in Vangorda Creek, near the Town of Faro
at Site V8 (2003 to 2010)




a) Sulphate



c) Copper



b) Zinc (Total)



d) TSS




Figure 3-2: Sulphate in Vangorda Creek
(V19, V27, V8, VG Main + V2BSP) (1998-2010)




Figure 3-6: Zinc (Total) in Vangorda Creek (V19, V27, V8, VG Main + V2BSP) (1998-2010)




Figure 3-3: Sulphate in Shrimp Creek (V4) and Upstream Inflow (V20)
(1998-2010)




Figure 3-5: Sulphate in the West Fork of Vangorda Creek
at V17A and V5 (1998-2010)

