

**Mount Nansen Geotechnical inspections
Video Log**

Video Clip	Description	Date
MOV 001	Tailings Dam	July 15, 2008
MOV 002	Tailings Dam Emergency Spillway	July 15, 2008
MOV 003	Emergency Spillway	July 15, 2008
MOV 004	Tailings Pond Water Intake Structure	July 15, 2008
MOV 005	Water Intake Structure	July 15, 2008
MOV 006	Diversion Channel	July 15, 2008
MOV 007	Tailings Pond	July 15, 2008
MOV 008	Tailings pile: NE Corner of Tailings Pond	July 15, 2008
MOV 009	Tailings Pond	July 15, 2008
MOV 00A	Erosion Gully and Discharge Structure in Tailings Pond	July 15, 2008
MOV 00B	Borehole #3	July 15, 2008
MOV 00C	Tailings Dam Crest at Borehole #2	July 15, 2008
MOV 00D	South Abutment of tailings Dam	July 15, 2008
MOV 00E	Tailings Dam Stabilizing Berm	July 15, 2008
MOV 00F	Surface Mon. Point 4173, Stabilizing Berm	July 15, 2008
MOV 010	Surface Mon. Point 4173, Stabilizing Berm	July 15, 2008
MOV 011	Centerline of Stabilizing Berm @ Borehole #6	July 15, 2008
MOV 012	Bend in Road to Seepage Road	July 15, 2008
MOV 013	Borrow Hole #30, Near Seepage Pond	July 15, 2008
MOV 014	Access Road from Tailings Dam to Seepage Dyke	July 15, 2008
MOV 015	South Abutment Drainage Ditch Filled In	July 15, 2008
MOV 016	50 m Downstream of Seepage Dyke	July 15, 2008
MOV 017	Borehole 0103, Downstream Toe of Seepage Dyke	July 15, 2008
MOV 018	Discharge Line Crossing Seepage Dyke	July 15, 2008
MOV 019	Borehole 0106, Seepage at Toe	July 15, 2008
MOV 01A	Centerline of Seepage Dyke Looking at Seepage Pond	July 15, 2008
MOV 01B	North Edge of Seepage Pond	July 15, 2008
MOV 01C	Downstream Toe at Waste Rock of Seepage Pond	July 15, 2008
MOV 01D	Centerline Emergency Spillway	July 15, 2008
MOV 01E	Confluence Emergency Spillway and Diversion Channel	July 15, 2008
MOV 01F	Rock Weirs in Diversion Channel	July 15, 2008
MOV 020	2 nd Rock Weir, in Diversion Channel	July 15, 2008
MOV 021	Waypoint 55, 4 th and 5 th Weir, in Diversion Channel	July 15, 2008
MOV 022	Waypoint 58, Rock Drop Structure in Diversion Channel	July 15, 2008
MOV 023	Waypoint 60, Rock Drop Structure in Diversion Channel	July 15, 2008
MOV 024	Downstream End of Diversion Channel	July 15, 2008
MOV 025	Access Road that follows Diversion Channel	July 15, 2008
MOV 026	Access Road that follows Diversion Channel	July 15, 2008
MOV 027	Erosion Gully along Access Road at Bridge	July 15, 2008
MOV 029	Discharge Pipe Crossing Diversion Channel	July 15, 2008
MOV 02A	In Diversion Channel @ Waypoint #68	July 15, 2008
MOV 02C	In Diversion Channel @ Waypoint #69	July 15, 2008
MOV 02D	Diversion Channel, Discharge Pipes, Tailings	July 15, 2008
MOV 02E	Diversion Channel, Waypoint #70 Confluence of Diversion Channel and Creek	July 15, 2008
MOV 02F	Diversion Channel, Waypoint #71	July 15, 2008
MOV 030	Channel West of Interceptor Ditch	July 15, 2008
MOV 031	Channel West of Interceptor Ditch, Waypoint #74	July 15, 2008
MOV 033	Centerline of Interceptor Ditch, Waypoint #75	July 15, 2008
MOV 034	Centerline of Interceptor Ditch, Waypoint #76	July 15, 2008
MOV 035	Tailing Side of Road, Waypoint #78	July 15, 2008
MOV 036	Interceptor Ditch, Waypoint #80	July 15, 2008

**Mount Nansen Geotechnical inspections
Video Log**

Video Clip	Description	Date
MOV 037	Tailings along Road, along Side of Interceptor Ditch	July 15, 2008
MOV 038	Pile of West Rock Near Entrance to Pit, Bird's Eye View	July 16, 2008
MOV 039	Top of Waste Rock Pile, Waypoint #83	July 16, 2008
MOV 03A	Halfway Down Open Pit, Waypoint #88	July 16, 2008
MOV 03B	Main Road and Old Pit Road Intersection	July 16, 2008
MOV 03C	GWGLL 0703 Well on Pit Road	July 16, 2008
MOV 03D	Steep Section of Pit Road	July 16, 2008
MOV 03E	End of Pit Road @ Pond	July 16, 2008
MOV 03F	Old Pit Road, Waypoint #92	July 16, 2008
MOV 040	Junction of Lower Road, Waypoint #94, Underhill Survey Log 1977	July 16, 2008
MOV 041	Waste Rock Pile, Bird's Eye View of Mill	July 16, 2008
MOV 042	Edge of Pit (North End)	July 16, 2008
MOV 043	North End of Open Pit	July 16, 2008

Notes: Names of structures in Video may differ from those in the Inspection report as follows:

Video Log	Report
Dam 1, Main Dam	Tailings Dam
Dam 2	Seepage Dyke
Reclaim Pond	Seepage Pond