



Photograph 2 Panoramic View of Tailings Impoundment - from south abutment of Tailings Dam.



Photograph 3 Panoramic View of Tailings Impoundment - from north end of Tailings Dam crest.



Photograph 4 Tailings Dam Downstream Slope and Seepage Recovery Pond.



Photograph 5 Downstream Slope of Buttress Berm - looking upward towards south abutment.



Photograph 6 Downstream Slope of Buttress Berm - looking downward towards Seepage Recovery Pond.



Photograph 7 Close-up of local depressions on buttress berm slope.



Photograph 8 Seepage Recovery Pond and Seepage Control Dam - looking northeast.



Photograph 9 Seepage Control Dam downstream slope - looking northeast (observable seepages exiting from the toe).



Photograph 10 Emergency Spillway Channel - lower segment (used also for conveying water from North Diversion Ditch).



Photograph 11 Emergency Spillway Channel - upper segment (used also for conveying water from North Diversion Ditch).



Photograph 12 Bridge construction in progress - across North Diversion Ditch.



Photograph 13 North Diversion Ditch - looking west (pipelines crossings in background).



Photograph 14 North and West Diversion Ditches - looking north and northwest.