

MOUNT NANSEN GEOTECHNICAL INSPECTIONS - PHOTO LOG		
Photo #	Date	Description
612	15-Jul-08	Brown-McDade Pit - View S From Entrance
613	15-Jul-08	View S at Brown-McDade Pit Lake
614	15-Jul-08	Bench Mark on Brown-McDade Pit Wall
615	15-Jul-08	View of TMA from Waste Rock Pile
616	15-Jul-08	View S at U/S Side of Tailings Pond Dam
617	15-Jul-08	View SE Over Tailings Pond
618	15-Jul-08	Spillway Channel Constriction
619	15-Jul-08	Tailings Pond Discharge Lines
620	15-Jul-08	Emergency Spillway Channel Entrance
621	15-Jul-08	Valve Box
622	15-Jul-08	Tailings Pond Reclaim Lines
623	15-Jul-08	Tailings Pond Pump House
624	15-Jul-08	Beached Tailings Pond Intake Structure
625	15-Jul-08	View SW at Tailings Pond From Pump House
626	15-Jul-08	View SE at Tailings Pond From Pump House
627	15-Jul-08	View U/S Along Diversion Channel From Bridge
628	15-Jul-08	View D/S Along Diversion Channel From Bridge
629	15-Jul-08	View D/S Along Diversion Channel From Bridge
630	15-Jul-08	View S at E Edge of Tailings Pond
631	15-Jul-08	View of Emergency Spillway Channel From Top of Tailings Pile
632	15-Jul-08	View of N Tailings Dam Abutment From Top of Tailings Pile
633	15-Jul-08	View of N Tailings Dam Abutment From Top of Tailings Pile
634	15-Jul-08	View Tailings Dam From Top of Tailings Pile
635	15-Jul-08	View S at Tailings Dam From Top of Tailings Pile
636	15-Jul-08	View SW Across Tailings Pond From Top of Tailings Pile
637	15-Jul-08	View SW Across Tailings Pond From Top of Tailings Pile
638	15-Jul-08	View W at Tailings Pond Pump House From Top of Tailings Pile
639	15-Jul-08	Tension Cracks on Top of tailings Pile (From WP 14)
640	15-Jul-08	View N at Tailings Pile at N Abutment (From WP 14)
641	15-Jul-08	View S at Tailings Pile at S Abutment (from WP 14)
642	15-Jul-08	Tailings Pond Intake Structure
643	15-Jul-08	Erosion Gully Across Tailings From Seepage Pond Discharge Structure
644	15-Jul-08	View S at Along Tailings Pond Dam From BH3
645	15-Jul-08	View E at Seepage Pond From BH3
646	15-Jul-08	View N at Along Tailings Pond Dam From BH3
647	15-Jul-08	Small Depression in Tailings Pond Crest 8 m S of BH2
648	15-Jul-08	View NW at Tailings Pile at S Abutment
649	15-Jul-08	View N Along Tailings Pond Dam From WP 21 at S Abutment
650	15-Jul-08	View NE at Seepage Pond From WP 21 at S Abutment
651	15-Jul-08	Fill Movement Evident at WP 22 Along Stabilizing Berm D/S Side of Tailings Pond Dam
652	15-Jul-08	View S Along Stabilizing Berm From WP 22
653	15-Jul-08	View N Along Stabilizing Berm From WP 22
654	15-Jul-08	View S Along Stabilizing Berm From Mon Pt 4173 at WP 24
655	15-Jul-08	View N Along Stabilizing Berm From Mon Pt 4173 at WP 24
656	15-Jul-08	View NE at Seepage Pond From Mon Pt 4173 at WP 24
657	15-Jul-08	View S Along Stabilizing Berm From BH 6 at WP 26
658	15-Jul-08	View NE at Seepage Pond From BH 6 at WP 26
659	15-Jul-08	View N Along Stabilizing Berm From BH 6 at WP 26
660	15-Jul-08	View W Along Seepage Pond Discharge Lines from BH6 at WP 26
661	15-Jul-08	View E at Seepage Pond From WP 27
662	15-Jul-08	View S at Stabilizing Berm From WP 27
663	15-Jul-08	View SW at Tailings Dam From WP 27
664	15-Jul-08	View of Seepage Pond From Mon Pt 4184 at WP 28
665	15-Jul-08	View of Seepage Pond From Mon Pt 4184 at WP 28
666	15-Jul-08	Iron Staining on Rock Fill at Edge of Seepage Pond at BH8 (WP 30)
667	15-Jul-08	Iron Staining on Rock Fill at Edge of Seepage Pond at BH8 (WP 30)
668	15-Jul-08	View NW From BH8 (WP 30)
669	15-Jul-08	View at Seepage Pond From BH8 (WP 30)
670	15-Jul-08	View W From BH8 (WP 30)
671	15-Jul-08	View W at Rock Fill at WP 31
672	15-Jul-08	View E at Rock Fill at WP 31
673	15-Jul-08	View W From South Abutment of Seepage Pond Dyke at WP 33

Photo #	Date	Description
674	15-Jul-08	View NE From South Abutment of Seepage Pond Dyke at WP 33
675	15-Jul-08	View N Along Seepage Pond Dyke From WP 33
676	15-Jul-08	View NE at D/S Toe of Seepage Pond Dyke From WP 33
677	15-Jul-08	View E From WP 33
678	15-Jul-08	Old Silt Curtain D/S of Seepage Pond at WP 34
679	15-Jul-08	Distressed Vegetation D/S of Seepage Pond at WP 34
680	15-Jul-08	Distressed Vegetation D/S of Seepage Pond at WP 34
681	15-Jul-08	Distressed Vegetation D/S of Seepage Pond at WP 34
682	15-Jul-08	Seepage Pond Discharge Lined From BH01-03 at WP 38
683	15-Jul-08	Seepage Pond Discharge Sump of D/S Side of Dyke
684	15-Jul-08	Lush vegetation D/S of Seepage Pond Discharge Sump (view E)
685	15-Jul-08	Seepage on D/S Side of Seepage Pond Dyke at WP 39
686	15-Jul-08	View S Along Seepage Pond Dyke Crest From WP 40
687	15-Jul-08	View W Across Seepage Pond From WP 40
688	15-Jul-08	View N Along Seepage Pond Dyke Crest From WP 40
689	15-Jul-08	View NE at Seepage Pond Discharge Sump From WP 40
690	15-Jul-08	Seep into Seepage Pond at WP 41
691	15-Jul-08	View of Seepage Pond Pump House From Wp 41
692	15-Jul-08	Seep into Seepage Pond at WP 42
693	15-Jul-08	Seep into Seepage Pond at WP 42
694	15-Jul-08	View S Along Tailings pond Dam Crest from N Abutment at WP 47
695	15-Jul-08	View D/S Along Emergency Spillway Channel From Road Crossing at WP 48
696	15-Jul-08	View U/S Along Emergency Spillway Channel From Road Crossing at WP 48
697	15-Jul-08	View U/S Along Emergency Spillway Channel From Confluence With Diversion Channel at WP 48
698	15-Jul-08	View D/S Along Emergency Spillway Channel From Confluence With Diversion Channel at WP 48
699	15-Jul-08	Diversion Channel Drop Structure 1 at WP 51
700	15-Jul-08	View D/S Along Diversion Channel From Drop Structure 1 at WP 51
701	15-Jul-08	View U/S Along Diversion Channel From Drop Structure 2 at WP 53
702	15-Jul-08	Diversion Channel Drop Structure 2
703	15-Jul-08	Diversion Channel Drop Structure 3 at WP 54
704	15-Jul-08	View U/S Along Diversion Channel From Drop Structure 4 at WP 55
705	15-Jul-08	View D/S Along Diversion Channel From Drop Structure 4 at WP 55
706	15-Jul-08	Diversion Channel Drop Structure 5 at WP 56
707	15-Jul-08	View U/S Along Diversion Channel From Drop Structure 5
708	15-Jul-08	View S of Tailings Pond Dam From Access Road
709	15-Jul-08	Diversion Channel Drop Structure 6 at WP 57
710	15-Jul-08	Exposed Geotextile on N Bank at Drop Structure 6
711	15-Jul-08	View D/S Along Diversion Channel From Drop Structure 7 at WP 58
712	15-Jul-08	View D/S Along Diversion Channel From Drop Structure 8 at WP 59
713	15-Jul-08	View U/S Along Diversion Channel From Drop Structure 8
714	15-Jul-08	View of N Bank of Diversion Channel at Drop Structure 8
715	15-Jul-08	View D/S Along Diversion Channel From Drop Structure 9 at WP 60
716	15-Jul-08	View U/S Along Diversion Channel From Drop Structure 9 at WP 60
717	15-Jul-08	View U/S Along Diversion Channel From Drop Structure 10 at WP 61
718	15-Jul-08	View D/S Along Diversion Channel From Drop Structure 10 at WP 61
719	15-Jul-08	View U/S Along Diversion Channel From Drop Structure 11 at WP 62
720	15-Jul-08	View D/S Along Diversion Channel From Drop Structure 11 at WP 62
721	15-Jul-08	View of N Bank of Diversion Channel at Drop Structure 11
722	15-Jul-08	View of N Bank of Diversion Channel at Drop Structure 11
723	15-Jul-08	View U/S Along Diversion Channel From Drop Structure 12 at WP 63
724	15-Jul-08	View D/S Along Diversion Channel From Drop Structure 12 at WP 63
725	15-Jul-08	View U/S Along Diversion Channel From Drop Structure 13 at WP 64
726	15-Jul-08	View D/S Along Diversion Channel From Drop Structure 13 at WP 64
727	15-Jul-08	Diversion Channel Drop Structure 13
728	15-Jul-08	Confluence of Diversion Channel and Dome Creek
729	15-Jul-08	View W at Seepage Pond
730	15-Jul-08	View W at Seepage Pond
731	15-Jul-08	End of Tailings Pond Discharge Lines on N Bank D/S of Seepage Pond
732	15-Jul-08	Erosion Gully at End of Tailings Pond Discharge Lines on N Bank D/S of Seepage Pond (WP 65)
733	15-Jul-08	Rip Rap Stockpile at WP 66
734	15-Jul-08	Rip Rap Stockpile at WP 66
735	15-Jul-08	Erosion Gully on N Diversion Channel Bank at Access Road Bridge
736	15-Jul-08	View D/S Along Diversion Channel From Tailings Pond Reclaim Line Crossing

Photo #	Date	Description
737	15-Jul-08	N Bank of Diversion Channel at Tailings Pond Reclaim Line Crossing
738	15-Jul-08	View U/S Along Diversion Channel From Tailings Pond Reclaim Line Crossing
739	15-Jul-08	N Bank of Diversion Channel at Tailings Pond Reclaim Line Crossing (view U/S)
740	15-Jul-08	View U/S Along Diversion Channel From WP 68 (Sta 0+510)
741	15-Jul-08	View D/S Along Diversion Channel From WP 68 (Sta 0+510)
742	15-Jul-08	Sloughing of S Bank at Diversion Channel at WP 68 (Sta 0+510)
743	15-Jul-08	View SE at tailings From WP 69 (Sta 0+380)
744	15-Jul-08	Tailings Slurry Pipeline in Tialings Pond at Diversion Channel Sta 0+380
745	15-Jul-08	Dredge Spoils Along S Shoulder of Road Along Diversion Channel at Sta 0+380
746	15-Jul-08	Tailings Slurry Pipeline Crossing Diversion Channel Sta 0+380
747	15-Jul-08	Slumping of S Bank of diversion Channel at Sta 0+380
748	15-Jul-08	View U/S Along Diversion Channel from Sta 0+380
749	15-Jul-08	View D/S Along Diversion Channel from Sta 0+380
750	15-Jul-08	View U/S Along Diversion Channel from Confluence of Dome Cr at Sta 0+320 (WP 70)
751	15-Jul-08	View U/S Along Dome Cr at Diversion Channel Sta 0+320
752	15-Jul-08	View D/S Along Diversion Channel from Confluence of Dome Cr at Sta 0+320 (WP 70)
753	15-Jul-08	View U/S Along Split in Interceptor Ditch at Sta 0+290 (WP 71)
754	15-Jul-08	View D/S Along Interceptor Ditch From Sta 0+290 (WP 71)
755	15-Jul-08	View U/S Along Secondary interceptor Ditch at Sta 0+290
756	15-Jul-08	View U/S Along Interceptor Ditch From Sta 0+250 (WP 72)
757	15-Jul-08	View D/S Along Interceptor Ditch From Sta 0+250 (WP 72)
758	15-Jul-08	View U/S Along Secondary Interceptor Ditch From Sta 0+250 (WP 72)
759	15-Jul-08	View D/S Along Secondary Interceptor Ditch From Sta 0+250 (WP 72)
760	15-Jul-08	S End of Secondary Interceptor Ditch
761	15-Jul-08	View D/S From S End of Secondary Interceptor Ditch
762	15-Jul-08	View U/S Along Interceptor Ditch From Sta 0+210 (WP 75)
763	15-Jul-08	View D/S Along Interceptor Ditch From Sta 0+210 (WP 75)
764	15-Jul-08	View U/S Along Interceptor Ditch From Sta 0+110 (WP 76)
765	15-Jul-08	View E at Dry Channel Entering interceptoir Ditch at Sta 0+110
766	15-Jul-08	View D/S Along Interceptor Ditch From Sta 0+110 (WP 76)
767	15-Jul-08	View U/S Along Interceptor Ditch From Sta 0+030 (WP 77)
768	15-Jul-08	View D/S Along Interceptor Ditch From Sta 0+030 (WP 77)
769	15-Jul-08	Interceptor Ditch Bottom at Sta 0+030 (WP 77)
770	15-Jul-08	Lush Vegetation at East Edge of Tailings Pond at WP 78
771	15-Jul-08	View W Across Tailings From WP 78
772	15-Jul-08	Seepage Into Tailings Pond at WP 78
773	15-Jul-08	View U/S Along Interceptor Ditch From Sta 0+015 (WP 79)
774	15-Jul-08	View D/S Along Interceptor Ditch From Sta 0+015 (WP 79)
775	15-Jul-08	View U/S Along Interceptor Ditch From Sta 0+000 (WP 80)
776	15-Jul-08	View D/S Along Interceptor Ditch From Sta 0+000 (WP 80)
777	15-Jul-08	Creek Flow into Interceptor Ditch at Sta 0+000
778	15-Jul-08	U/S End of Interceptor Ditch at Sta 0-025 (WP 81)
779	15-Jul-08	View D/S From End of Interceptor Ditch at Sta 0-025
780	15-Jul-08	View of Valley Slope W of U/S End of Interceptor Ditch at WP 81
781	15-Jul-08	View of Tailings From U/S End of Interceptor Ditch at WP 81
782	16-Jul-08	View SW at TMA from Waste Rock Pile
783	16-Jul-08	View of Interceptor Ditch From Waste Rock Pile
784	16-Jul-08	View SW at TMA from Waste Rock Pile
785	16-Jul-08	View S Along Pit Access Road (WP 84)
786	16-Jul-08	View S into Pit From GLL07-03 (WP 87)
787	16-Jul-08	View N Along Pit Access Road From GLL07-03
788	16-Jul-08	Brown-McDade Pit Lake From BM 1981
789	16-Jul-08	View N Along Pit Access Road from BM 1981
790	16-Jul-08	Adit in Pit Wall
791	16-Jul-08	View N Across Open Pit Lake
792	16-Jul-08	View N at Junction of Old Pit Road (WP 91)
793	16-Jul-08	View S at Junction of Old Pit Road (WP 91)
794	16-Jul-08	View N at Junction of Old Pit Road (WP 92)
795	16-Jul-08	View S at Junction of Old Pit Road (WP 92)
796	16-Jul-08	Sign at Junction of Main Access Road and Old Pit Road (view N at WP 94)
797	16-Jul-08	Sign at Junction of Main Access Road and Old Pit Road (view N at WP 94)
798	16-Jul-08	Sign at Junction of Main Access Road and Old Pit Road (view N at WP 94)
799	16-Jul-08	View SW at Mill Complex From Waste Rock Pile at WP 95

Mount Nansen - Photo Log

Photo #	Date	Description
800	16-Jul-08	Waste Rock Pile at WP 95
801	16-Jul-08	Warning sign at Open Pit
802	16-Jul-08	View NW From Edge of Open Pit at WP 97
803	16-Jul-08	View SW From Edge of Open Pit at WP 97
804	16-Jul-08	View NW From Edge of Open Pit at WP 98 With Infilling at N End of Pit
805	16-Jul-08	View S Across Open Pit From N End of Pit (WP 99)
806	16-Jul-08	View W Across Open Pit From N End of Pit (WP 99)
807	16-Jul-08	View S Across Open Pit From N End of Pit (WP 99)
P1040692	16-Jul-08	View SW at TMA from Waste Rock Pile
P1040693	16-Jul-08	View of Interceptor Ditch From Waste Rock Pile
P1040694	16-Jul-08	View of Interceptor Ditch From Waste Rock Pile
P1040695	16-Jul-08	View of Interceptor Ditch From Waste Rock Pile
P1040696	16-Jul-08	View SW at TMA from Waste Rock Pile
P1040697	16-Jul-08	View SW at TMA from Waste Rock Pile
P1040698	16-Jul-08	View SW at TMA from Waste Rock Pile
P1040698	16-Jul-08	View of Mill Complex From Waste Rock Pile
P1040700	16-Jul-08	View S Across Open Pit Lake
P1040701	16-Jul-08	View S at Adit on South Pit Wall
P1040702	16-Jul-08	View S Across Open Pit Lake
P1040703	16-Jul-08	View N Across Open Pit From North Wall
P1040704	16-Jul-08	View N Across Open Pit From North Wall
P1040705	16-Jul-08	View N Across Open Pit From North Wall