Yukon Government

YUKON GEOLOGY PROGRAM

Canada

NATIONAL TOPOGRAPHIC SERIES NTDB (1995)

D.I.A.N.D. N.A.P. LAND RESOURCES

CANADA SHEET 115J & K



NOTE: THIS MAP HAS BEEN PRODUCED BY THE COMPILATION OF DATA FROM VARIOUS SOURCES. IT IS NOT TO BE USED TO DEFINE LEGAL BOUNDARIES.

THIS MAP IS ISSUED AS A PRELIMINARY GUIDE FOR WHICH THE YUKON GEOLOGY PROGRAM AND THE GEOLOGICAL SURVEY OF CANADA WILL ACCEPT NO RESPONSIBILITY FOR ANY ERRORS, INACCURACIES OR OMISSIONS WHATSOEVER.

EDITION: 2 PRINT DATE: JULY 27, 1999

SNAG

YUKON TERRITORY

115 J & 115 K (E1/2)

Scale

10 5 0 5 10 20 30 km

5 0 5 10 15 miles

CONTOUR INTERVAL 500 FEET Elevations in Feet above Mean Sea Level
North American Datum 1983 Transverse Mercator Projection
Universal Transvers Mercator Grid ZONE 7



Magnetic Declination 1999 varies from 28° 19' easterly at the centre of the west edge to 26° 32' easterly at the centre of the east edge.

GEOPROCESS FILE SUMMARY REPORT

SNAG MAP AREA - NTS 115J and 115K (E1/2)

INTRODUCTION

The GEOPROCESS File is a compilation of information and knowledge on geological processes and terrain hazards, including mass movement processes, permafrost, flooding risks, faults, seismic activity and recent volcanism, etc. Please refer to the GEOPROCESS File User Guide for more in-depth information on how the maps were developed, which other GEOPROCESS File maps are available, how to utilize this inventory and how to interpret the legend. Special interest should be taken in the detailed description of the terrain hazard map units. Appendices in the User Guide include summary papers on the geological framework, permafrost distribution, and Quaternary geology in Yukon and a list of comprehensive GEOPROCESS File references.

This report includes a brief discussion of the scope and limitations of the GEOPROCESS File compilation maps followed by summaries of the bedrock geology, surficial geology and terrain hazards for this NTS map area, and a list of references.

Geological Processes and Terrain Hazard Compilation Maps

The GEOPROCESS File map units were drafted on the 1:250 000 topographic base maps through interpretation from bedrock geology maps, surficial geology maps and in some cases terrain hazard maps at various scales. The compilation maps have a confidence level reflecting the original source material. All materials used to produce the maps are listed in the references on each map. A file containing the documentation used to construct these maps is available at the Indian and Northern Affairs Library in Whitehorse, Yukon. Areas for which no surficial geology or terrain hazard information is published were left blank. Summary reports on surficial geology and terrain hazards for these map sheets were written by extrapolating the data from adjacent map sheets or smaller scale maps. Information from small scale (e.g., 1:1 000 000) maps was used for the summary reports, but not redrafted onto the 1:250 000 GEOPROCESS File maps.

The GEOPROCESS File compilation maps are intended as a first cut planning tool; the legend on the maps describes the general aspects of terrain hazards (also see below) and associated geological processes. **These maps should never replace individual site investigations for planning of site specific features, such as buildings, roads, pits, etc.**

Bedrock Geology Summaries

Each 1:250 000 NTS map area is described according to morphogeological belts and terranes defined by Gabrielse et al. (1991) and Wheeler et al. (1991). Bedrock geology (including structure) and mineral occurrences are briefly described and taken largely from the referenced, most recent 1:250 000 geological map with additional contributions from Wheeler and McFeely (1991), and Yukon MINFILE (1993). A summary paper ("A Geological Framework for Yukon") in Appendix A of the User Guide provides a framework and context for each of the bedrock summaries.

The level of knowledge and understanding of Yukon geology is constantly evolving with more detailed mapping and development of geological models. Names, ages and terrane affinities of rock units on the most recent 1:250 000 geological maps may, in some cases, now be considered incorrect. Thus information contained within some of the bedrock geology summaries may be out of date. Although much of the information reflects the knowledge at the time that the source map was published, additional information has been inserted whenever possible to assist the user in merging the information with current geological maps, concepts and understanding. The age ranges for similar packages of rocks may also vary between map areas since the actual rocks, or at least the constraints on their age, may vary between map areas.

BEDROCK GEOLOGY (Tempelman-Kluit, 1974)

Snag map area is mainly within the Omineca Belt except for a small portion southwest of the Denali Fault (Shakwak Valley) which is in the Insular Belt. The region is dominated by fairly subdued topography, wide river valleys (Yukon, Donjek, White) and the Wellesley Lake basin.

The Omineca Belt is dominated by crystalline rocks of the Yukon-Tanana Terrane. They include pre-400 million year old Nisling Assemblage muscovite-biotite-quartz schist and micaceous quartzite; 400-320 million year old Nasina Assemblage graphitic quartzite, micaceous quartzite, quartz-mica schist, muscovite-biotite-quartz schist, phyllite, amphibolite and marble; 350 million year old Pelly Gneiss muscovite-chlorite biotite granodiorite gneiss; and 200-180 million year old hornblende granodiorite and quartz monzonite of the Klotassin Suite in the northern part of the map area. In the western area, this crystalline package is structurally overlain by a 400-150 million year old oceanic assemblage of sheared and massive greenstone, gabbro, dunite and peridotite (and serpentinized equivalents), argillaceous chert, hornfels, limestone and marble attributed to the Windy-McKinley Terrane.

The eastern half of map area is dominated by plutons of the 110 million year old Coffee Creek/Nisling Range/Dawson Batholith biotite-hornblende granodiorite, diorite, biotite granite and quartz monzonite. The southern half of the area contains areally extensive flows of 70 million year old Carmacks Group (and Donjek volcanics) amygdaloidal augite olivine basalt, flow breccia and tuff, and local accumulations of 55 million year old Skukum Group (Casino and Mount Nansen volcanics, Tempelman-Kluit, 1984) acid tuff, ignimbrite and tuff-breccia. In the southeastern area, 55-million year old Nisling Range alaskite plutons are associated with vast swarms of north-trending quartz-feldspar porphyry dykes. The alaskite is commonly well jointed and forms castellated outcrops.

Southwest of the Denali Fault, rocks of the Wrangellia Terrane include 260-220 million year old basalt, tuff, argillite, siltstone, greywacke conglomerate and limestone and serpentinized peridotite.

Mineral deposits and occurrences

Yukon MINFILE lists more than 100 mineral prospects for the Snag map area, however many of them are geochemical anomalies, leaving only 30 with mineralization. Most of the occurrences are copper-molybdenum porphyry showings associated with 100-55 million year old plutons in the Dawson Range. The largest of these is the Casino deposit with more than 550 million tonnes of 0.25% copper, 0.025% molybdenum and 0.31 grams per tonne gold. This is one of the largest copper porphyry deposits in Canada. Other deposits in the area include silver-lead-gold veins of which the Bomber veins produced 372 tonnes of 3689 grams per tonne silver, 17.1 grams per tonne gold, 48% lead, with minor zinc, copper and bismuth.

SURFICIAL GEOLOGY

The main source of information in this area consists of two surficial geology and geomorphology maps at the 1:100 000 scale (Rampton, 1980a,b). The legend on these maps includes comments on the following for each major geological unit: the nature of the material, distribution and stratigraphy, geomorphology, permafrost and other related terrain characteristics.

Southwest Yukon was affected by two glaciations during the Pleistocene. In both cases, the ice flowed northwest along the Shakwak Trench and then spread out over the Wellesley Basin in a spatulate manner. High terrain remained exposed as islands, or nunataks, above the ice.

Mirror Creek, the most extensive glaciation, is most likely early Wisconsinan. Moraine deposits and ice limits are believed to have reached 1280 m elevation. This glaciation extended southwest of the Shakwak Trench. Mirror Creek glaciers dammed the drainage of several creeks or streams and the ponded water formed lakes in minor valleys. Scottie Creek was part of such a lake system and strand lines are visible at elevations between 580 and 610 m. The Macauley glaciation was not as extensive and is estimated to date from the late Wisconsinan.

During deglaciation, broad outwash plains were deposited, and in one known case, drainage was diverted (the White River and Sanpete Creek were diverted along Dry Creek). Large amounts of silt were redeposited as loess blankets; at higher elevation this loess cover has been reworked by slope wash and solifluction processes. Following deglaciation, streams began to incise through the glacial, colluvial and glaciofluvial deposits, which resulted in the formation of large alluvial fans at the mouth of most high gradient valleys.

Unglaciated uplands are covered by silty to loamy coarse gravel which is composed of colluvial and residual bedrock material.

TERRAIN HAZARDS

Active geological processes that present the most immediate hazard to human activity are related to shifting channels and flooding risk of the White River.

Seismicity

There are 22 recorded seismic events within the Snag map area. Eight of the 22 events are of magnitude >3.0 to <4.0. Thes rest are less than magnitude 3.0. Most of the events are in the southern part of the map area.

Mass Movement Processes

The colluvium covered slopes of most of the map area are susceptible to gullying and solifluction. In areas underlain by permafrost, disturbance of the surface may result in the detachment of the active layer and failure. The risk of rock avalanches and large landslides on steep, bedrock slopes is restricted to small areas in the higher Nutzotin Mountains (southeast corner of NTS 115K).

Permafrost

The map area lies within the zone of widespread permafrost. Permafrost as thick as 30 m is common throughout the area, except under large lakes and stream channels, for instance, White River and Beaver Creek. Large ice bodies are usually found more often in fine-grained sediments such as fine sandy silt to clays, and under thick peat deposits. A high ice content can be inferred by the presence of ice wedges, ice lenses and ice veins. These ice bodies are not restricted to well-sorted fine-grained deposits but are also found in poorly sorted deposits such as colluvial and moralnal deposits with sufficient silty matrix. Thermokarst is associated with several shallow lakes, particularly in flat bottom valleys of the Klondike Plateau such as the Scottie Creek fine-grained alluvial deposits and associated organic material (Rampton, 1980). Pingos are most likely ice-cored. Permafrost-related and periglacial processes are widespread in this map area. At high elevation, altiplenation terraces and tors can be found in the unglaciated ridges. Patterned ground, solifluction lobes, sorted stripes and polygons are common in the alpine and subalpine zones. Rock glaciers are found southwest of the Denali Fault, in the Nutzotin Mountains.

Flooding and Other Risks

The rivers in the area are subject to seasonal flooding most years due to snowmelt runoff, rainstorm events, and ice jams. In addition to these expected seasonal flow variations, the White River floodplain is characterized by shifting channels and fluctuating flow. Perilodic flooding is a common occurrence along this river.

References: Snag Map Area, NTS 115J and 115K (E1/2)

Note: To be thorough, check the references for adjacent NTS map sheets and the General Reference List.

Most of the following references should be available for viewing in the DIAND library on the third floor of the Elijah Smith building in Whitehorse. The library and call number of some internal government reports are listed.

Calmes, D.D., 1915. Upper White River district, Yukon. GSC, Memoir 50, 191 p. (report and maps 122A, 123A, 113A).

*Canadian Earthquake Epicentre File; Maintained by the Geological Survey of Canada, Geophysics Division.

Casino Trail Project Advisory Committee, 1985. Casino Trail project advisory committee summary report - December, 1985. Whitehorse, Yukon, (NTS 115I, 115J/K)

Clague, J.J., 1979. The Denali fault system in the southwest Yukon territory: A Geological Hazard? In: Current Research, Part A, GSC, Paper 79-1A.

Department of Community and Transportation Services - Highway Engineering Staff, 1986. Proposed Casino Trail Route Location and Terrain Analysis Study, Department of Community and Transportation Services, Government of Yukon, 9 p. (including maps), (NTS 115I, 115J/K)

* Gabrielse, H., Tempelman-Kluit, D.J., Blusson, S.L. and Campbell, R.B. (comps.), 1980. MacMillan River, Yukon - District of MacKenzie-Alaska (Sheet 105, 115) GSC, Map 1398A), (NTS 105, 115)

Gabrielse, H. and Yorath, C.J. (eds.), 1992. Geology of the Cordilleran Orogen in Canada. GSC, Geology of Canada, No. 4, 844 p. (Contains summary of Yukon geology)

GSC, 1987. Regional stream sediment and water geochemical reconnaissance data, Yukon Territory, Open File 1363.

Geo-Physi-Con Co. Ltd., 1980. Depth to Bedrock Investigation by Seismic Refraction - Summer, 1980 Program. Geo-Physi-Con Co. Ltd. (Whitehorse Public Library Call Number: 551.8 Geo Y.Rm)

Godwin, C.I., 1975. Geology of Casino Porphyry Copper-Molybdenum Deposit, Dawson Range, Yukon Territory. Unpublished Ph.D. thesis, The University of British Columbia, Vancouver, British Columbia.

Godwin, C.I., 1976. Casino. In: Porphyry Deposits of the Canadian Cordillera, Brown, Sutherland, A. (ed.), Canadian Institute of Mining and Metallurgy, Special Volume 15, p. 344-358.

* Heginbottom, J.A., and Radburn, L.K. (comps.), 1992. Permafrost and ground ice conditions of northwestern Canada. GSC Map 1691A, 1:1 000 000 scale

Horner, R., 1988. Seismicity in the Glacier Bay Region of Southeast Alaska and adjacent areas of British Columbia. In: Proceedings of the Second Glacier Bay Science Symposium, Millner, A.M. and Wood, J.D., Jr., (eds.), United States Department of the Interior, National Park Service, Anchorage, Alaska, p. 6-11.

Johnston, S.T., 1995. Geological compilation with interpretation from geophysical surveys of the northern Dawson Range, central Yukon (115J/9 & 10, 115I/12). Exploration and Geological Services Division, Yukon Region, DIAND Canada, Canada/Yukon Economic Development Agreement, Geoscience Open file 1995-2(G), (1:100 000-scale map).

Johnston, S.T. and Shives, R.B.K., 1995. Interpretation of an airborne multiparameter geophysical survey of the northern Dawson Range, central Yukon: A progress report. In: Yukon Exploration and Geology, 1994, Exploration and Geological Services Division, Yukon Region, DIAND Canada, p. 105-111.

Lynch, G.V. and Pride, C., 1983. Evolution of a high-level, high-silica magma chamber: the Pattison pluton, Nisling Range alaskites, Yukon. Canadian Journal of Earth Sciences, Vol. 21, No. 4, p. 407-414.

Lynch, G.V. Pride, C. and Watson, P., 1983. Petrology and geochemistry of the Pattison Alaskite pluton. In: Yukon Exploration and Geology 1982, Exploration and Geological Services, Yukon Region, DIAND Canada, p. 38-49.

Milne, W.G., Horner, R.B., McMechan, C.A., 1976. Canadian Earthquakes, 1971, Earth Physics Branch, Seismological Series 74. (NTS 115J/K)

* Payne, J.G., Gonzales, R.A., Akhurst, K. and Sisson, W.G., 1987. Geology of Colorado Creek (115 J/10), Selwyn River (115 J/9) and Prospector Mountain (115I/5) map areas, western Dawson Range, west central Yukon. Exploration and Geological Services Division, Yukon Region, DIAND Canada, Geoscience Open File 1987-3, (three 1:30 000-scale maps with legend and text, 141 p.).

Rampton, V.N., 1967. Pleistocene geology, Snag-Kluane Lake, southwestern Yukon; GSC, Paper 67-1.

* Rampton, V.N., 1968, Pleistocene geology, Snag-Kluane Lake, southwestern Yukon; GSC, Paper 68-1.

Rampton, V.,N., 1969. Pleistocene geology of the Snag-Klutlan area, southwestern Yukon, Canada. Unpublished Ph.D. thesis, University of Minnesota, Minneapolis, Minnesota.

Rampton, V.,N., 1971. Late Pleistocene glaciations of the Snag-Klutlan area, Yukon Territory. Arctic, Vol. 24, No. 4, p. 277-300.

Rampton, V.N., 1971. Late Quaternary vegetational and climatic history of the Snag-Klutlan area, southwestern Yukon Territory, Canada. Geological Sodety of America Bulletin, Vol. 82, No. 4, p. 959-978.

* Rampton, V.N., 1979a. Surficial geology and geomorphology, Koidern Mountain, Yukon Territory; GSC, Preliminary Map 5-1978, scale 1:100 000. (NTS 115K SE)

* Rampton, V.N., 1979b. Surficial geology and geomorphology, Mirror Creek, Yukon Territory, GSC, Preliminary Map 4-1978. (NTS 115K NE)

Sinclair, W.D., Cathro, R.J. and Jensen, E.M., 1981. The Cash porphyry copper-molybdenum deposit, Canadian Institute of Mining and Metallurgy Bulletin, Vol. 74, Sept. No. 9, p. 67-76.

Spencer Environment Management Services Ltd., 1885, Socio-economic/environmental overview for proposed Casino Trail (prepared for DIAND Canada). DIAND Canada, Whitehorse, Yukon, (NTS 115I, 115J/K, DIAND library Call Number: TN27 Y94 S63)

Tempelman-Kluit, D.J., 1972. Operation Snag-Yukon (115H, J (East Half), K (East Half), N (East Half). GSC, Report of Activities, Part A., April to October 1971, No. 72-1, p. 36-39.

Tempelman-Kluit, D.J., 1973, Reconnaissance geology of Aishihik Lake, Snag and part of Stewart River map-areas, west central Yukon; GSC, Open File 161,

Tempelman-Kluit, D.J., 1973. Operation Snag-Yukon 115H, 115J, 115K (E 1/2), 115N (E 1/2), GSC, Report of Activities, Part A, April to October 1972, No. 73-1, p. 48-49.

* Tempelman-Kluit, D.J., 1974. Reconnaissance geology of Aishihik Lake, Snag and part of Stewart River map-areas, west-central Yukon (115H, 115K-J and 115N-O), GSC, Paper 73-41, 97 p. (Includes Maps 16-1973, 17-1973, 18-1973).

Tempelman-Kluit, D.J. and Currie, R., 1978. Reconnaissance rock geochemistry of Aishihik Lake, Snag and Stewart River map-areas in the Yukon crystalline terrane. GSC, Paper 77-8, 72 p.

Van Everdingen, R.O., 1968, Perennial discharge of subpermafrost groundwater in two small drainage basins, Yukon, Canada. In: Permafrost: fifth International conference, Sennesset, K, (ed.), Trondheim, Norway, International Conference on Permafrost, Proceedings (III), Vol. 5, (Vol. 1), p. 639-643.

Wang, Xiu-Chang, 1989. Post-glacial vegetation history of the Alshihik basin and its vicinity, southwestern Yukon Territory, Canada; a palynological perspective. Unpublished Ph.D. thesis, University of Ottawa, Ottawa, Ontario, 544 p.

Wheeler, J.O., Brookfield, A.J., Gabrielse, H., Monger, J.W.H., Tipper, H.W, and Woodsworth, G.J., 1991. Terrane map of the Canadian Cordillera. GSC, Map 1713.

* Wheeler, J.O. and McFeely, P., 1991. Tectonic Assemblage map of the Canadian Cordillera and adjacent parts of the United States of America. GSC, Map 1712A.

Yukon MINFILE, 1994. NTS 115J & 115K (E1/2) - Snag. Exploration and Geological Services Division, Yukon Region, Indian and Northern Affairs Canada.

* References used in compiling this map

NOTE: A new digital compilation of Yukon Geology is now available by Steve Gordley and Andrew Makepeace (GSC Open File D3826 and/or DIAND Open File 1999-1(D)), and more recent MINFILE updates should also be verified (Yukon MINFILE, 2001).

LEGEND

LEGEND TERRAIN HAZARDS

MAP SYMBOL	TERRAIN HAZARDS	ASSOCIATED RISK LEVELS, COMMENTS
	Mass Movement Processes	
A	Snow Avalanched.	high
F	Extremely slow to moderate rates of failure in soil and bedrock, including soil creep, rock creep, earthflow, soil or rock slump, debris or rock slide.	low to intermediate
R	Moderate to extremely rapid rates of failure in soil and bedrock (1.5 m/d to >3 m/s), including rock slump, debris slide, rock slide, debris flow, debris torrent, debris avalanche, rockfall, rock avalanche.	high
	Arctic, Alpine and Periglacial Processes	
X	Permafrost present.	low
K	Thermokarst present.	low
S	Soliflucted.	low to intermediate
Z	Grouped, cryoturbated, soliflucted, nivated.	low to intermediate
	Fluvial Processes	
B	Braided, unstable channels, risk of flooding.	intermediate to high
E	Fluvial erosion, deposition and low risk of flooding.	low to intermediate
J	Anastomosing.	intermediate to high
U	Flooded regularly.	intermediate to high
	Miscellaneous Erosion Processes	
Y	Karst.	intermediate
P	Piping.	intermediate to high
V	Gullied.	low to intermediate
	On Site Symbols	Risk Level
	Unit boundary (defined, approximate).	
	Erosional escarpment.	high
	Landslide escarpment.	high
	Landslide (includes source and runout areas).	high
	Pingo.	high
	Rock glacier.	high
	Spring or saline seep.	low
	Observation of frozen soil or ground ice.	low
	Rapid mass movements (debris torrent) with known point source. Limits of runout not implied by symbol.	high
	Slow mass movement (earth flow) with landslide, escarpment source. Limits of landslide runout not implied by symbol.	intermediate to high

LEGEND GEOLOGICAL PROCESSES

MAP SYMBOL	DESCRIPTION	INFERRED HAZARDS
cf	Talus fan or apron, moderate to steep slope, coarse angular bedrock fragments, sources are often areas of rapidly dilaintegrating bedrock.	Rock fall and debris flows common on active fans, steep slopes generally unstable to traffic.
cl	Landslide, moderate slope, varies from large blocks of bedrock to finer material.	Landslides generally are recurrent in susceptible areas and may be become active if disturbed.
cs	Colluvium covered slope, gentle to moderate slope, underlain by unsorted rubble, solifluction and other periglacial features common.	Areas of fine textured materials and gentle slopes at high elevations, where there is ground ice will be susceptible to high solifluction rates and thermokarst if disturbed.
fa	Alluvial fan, active.	Subject to shifts in channel and bar positions, occasionally subject to flooding.
fp	Floodplain.	Subject to shift in channel and bar positions, occasionally subject to flooding.
gla	Glacier ice.	Crevasses.
im	Mountain ice caps.	Avalanches, ice and rock falls, and crevasses.
is	Cliff glacier.	Avalanches, ice and rock falls.
l	Lacustrine or glaciolacustrine sediments.	Silt and clay, usually susceptible to frost heaving and, if permafrost present, to thermokarsting when disturbed.
ms	Rock glacier, debris covered glacier.	Ice at depth make surface susceptible to thermokarst, unstable slopes.
o	Organic.	Thick organic matter is often underlain by permafrost. Disturbance of permafrost may cause poor drainage and thermokarsting.

LEGEND FAULTS

Fault defined, approximate, assumed, extrapolated beneath overburden

Fault Solid circle indicates downthrown side Arrows indicate relative movement

Thrust Fault (teeth indicate upthrust side)

Alrphoto Lineament

LEGEND SEISMIC EVENTS

SYMBOL	MAGNITUDE REPRESENTED	SYMBOL	MAGNITUDE REPRESENTED
⊡	<2.0	⊡	4.0 to 4.999
⊡	2.0 to 2.999	⊡	5.0 to 5.999
⊡	3.0 to 3.999	⊡	>6.0

LEGEND QUATERNARY VOLCANISM

No known recent volcanism in map area 115J & K

OTHER FEATURES

Roads, Streams, Lakes, Marsh

NOTE: Where areas have more than one identified process or hazard, the colour of the encompassing polygon is assigned based on a hierarchical scheme relating to the severity of the hazard. The relative order of severity is: Terrain Hazards (Mass Movement Processes then Fluvial Processes then Arctic, Alpine and Periglacial Processess) followed by Geological Processes.



After: Gordley, S.P. and Makepeace, A.J. (compilers), 1999, Yukon Digital Geology Geological Survey of Canada Open File D3826. Exploration and Geological Services Division Yukon, Indian and Northern Affairs, Open File 1999-1 (D)



After: Hughes, O.L. in Morrison, S.R. and Smith, C.A.S. (editors) , 1987, XII th INQUA Congress Field Excursions A20, p12'to 16 - Research in Yukon, National Research Council of Canada, Ottawa, Canada, 110p



After: Morteon, S.R. and Smith, C.A.S. (editors), 1987, XII th INQUA Congress Field Excursions A20a and A20b - Research in Yukon, National Research Council of Canada, Ottawa, Canada, 110p



After: Brown, R.J.E., 1978, Permafrost: Plate 32, Hydrological Atlas of Canada, Fisheries and Environment, Canada. 34 plates



Exploration and Geological Services Division
Yukon Region
Indian and Northern Affairs Canada

GEOPROCESS FILE

GEOLOGICAL PROCESSES and TERRAIN HAZARDS of Snag 115J & 115K (E1/2)

by

Mougeot, C.M. and Walton, L.A.

Copies of this map
may be obtained from Geoscience and Information Sales
c/o Whitehorse Mining Recorder, Indian and Northern Affairs Canada,
Room 102, 300 Main Street, Whitehorse, Yukon Y1A 2B5
(867) 667-3266; FAX; (867) 667-3267

Recommended citation: Mougeot, C.M. and Walton, L.A., 1995. Yukon GEOPROCESS File (2002), Geological Processes and Terrain Hazards of Snag, 115J & 115K (E1/2) Exploration and Geological Services Division, Yukon Region, Indian and Northern Affairs Canada, 1:250 000 scale.