

18, 4
1957 JUN 21 PM 1 00

KU023KPA078

MM RUKPSM

DE RUKFNY 2

M 072206Z

FM KREITLOW AND MARTIN NOHEAO1))--(-

TO DISTRICT ENGINEERS ALASKA DISTRICT CORPS OF ENGINEERS US ARMY

ANCHORAGE ALASKA

DA GRNC

BT

REPORTING SELECTED RAMDUM SAMPLINGS OF ICE CRYSTAL AND DIRT FINDINGS
FROM STATION 2A LOGS. BLANKETS NOT USED ON MOORLANES HERE.
PART 2 FROM OCT 24 LOG. BOTH MOORLANES OPERATED WITH SCREENS. TOTAL
OF 33 STRAINER CHANGES WERE MADE BETWEEN 0715 HRS AND 0630 HRS FOLLOWING
MORNING. ELAPSED TOTAL TIME OF 23 HRS 15 MINUTES. ICE CRYSTALS WERE
CONTINUOUSLY REMOVED FROM JP-4 TENDER NUMBER 43-3H. TOTAL OF 49
BARRELS FUEL DRAINED TO BURN PIT AND WASTED INCIDENTAL TO MAKING
CHANGES. PART 2 ON OCT 25 SCREENS AND BASKETS REMOVED FROM BOTH
MOORLANES. FUEL STREAM ALLOWED TO FLOW THROUGH STA WITH OUT CLEANING.
ICE CRYSTAL VOLUME TOO MUCH TO BE HANDLED BY STA PERSONNEL. PART 3

18.4
a. del

1957 JAN 7 AM 11 55

N

NNNKU018KPA132

MM RUKPSM

DE RUKFNY 4

M 072123Z

FM KREITLOW AND MARTIN DISTRICT ENGINEERS NORTHWAY ALASKA
TO DISTRICT ENGINEER ALASKA DISTRICT CORPTS OF ENGINEERS US ARMY
ANCHORAGE ALASKA

DA GRNC

BT

REPORTING ICE CRYSTAL FINDINGS OF FACT FOR DONJEK STA 2B. PART 1
LOG SHEET FOR NOV 13 56 RECORDS 50 MOORLANE CHANGES WERE MADE
BETWEEN 0645 HRS ON 13 THROUGH 0215 HRS ON 15. MOSTLY WHITE ICE
CRYSTAL WITH SPRINKLING OF PIPE SCALE. TOTAL DRAINAGE WASTED TO
BURN PIT FROM JP-4 TENDER NR 43-3H WAS 71 BBLs 18 GAL. FUEL
LINE TEMP PLUS 16 DEGREES. AIR RANGED BETWEEN PLUS 4 MINUS 10
DEGREES FAHN. PART 2 SOMEWHAT LESSER LOADS OF ICE CRYSTAL
REMOVED ON OTHER DAYS DURING THIS PERIOD APPLS WAS ON STREAM.
TOWARD END OF PERIOD OPERATOR COULDN'T KEEP UP WITH ICE SO
ALLOWED EXCESS TO PASS.

BT

CFN DONJEK 2B 1 13 56 50 0645 13 0215 15 JP-4 43-3H 71 18 16 4 10

2

07/2135Z

0097