

ARCL-M

Contract DAFA03-69-C-0079, Right-of-Way Brush Control,  
Haines-Fairbanks Pipeline

Purchasing & Contracting Ofc  
Bldg 977  
ATTN: Mr. Williams  
Mrs. Davenport

Chief, Maint Div  
PDO

5 Sept 69  
Johnston/cdh/862-5118

1. During delivery of the herbicide for the subject contract, fifteen, 30 gallon barrels were damaged (container seams opened, tops and bottoms split) with considerable loss of the liquid herbicide. These damaged barrels were stored at Beaver Creek Pump Station, outside, subjected to all weather conditions and contamination.
2. It is my understanding at this time that the spraying contractor salvaged some of the herbicide from the damaged barrels which he plans to use on his spray job.
3. The Contractor, Okanagan Copter Sprays Ltd. should be notified through the Canadian Cooperation that the fifteen damaged barrels containing the herbicide (Tordon 101) are rejected in accordance to TS-06C, Technical Provision of the contract and that the damaged or contaminated material replaced.

*NOJ*  
 NOBLE O. JOHNSTON  
 Contracting Officer's Representative  
 PDO

PREPARED BY *NOJ* DATE *5 Sept 69*  
 COORDINATION *WFB* DATE *5 SEPT 69*  
 CONCURRENCE *A Mayo* DATE *5 Sept 69*

1503-04 PR 20-69

*Lib  
CDH*