

APPENDIX I  
PHOTOGRAPHS



Photo 1: Forty Mile River showing confluence with Yukon River in background. Clinton Creek enters Forty Mile River just upstream of bridge. June 1985.



Photo 2: Clinton Creek waste dump, showing Hudgeon Lake at bottom of photo and channel of Clinton Creek over waste dump on left. June 1985.





Photo 3: Clinton Creek waste dump, looking upstream toward Hudgeon Lake. Open pit is at left, crusher in foreground, and concentrator site on plateau at upper right. July 1986.



Photo 4: Rock lined section at upper end of Clinton Creek channel over waste dump. Access road culverts at upper left. July 1986.





Photo 5: Access road culverts at upper end of waste dump channel. June 1985.



Photo 6: Waste dump channel looking downstream. Note left bank is protected by bedrock and stream bottom is armoured by large boulders from waste dump. June 1985.





Photo 7: Wolverine Creek tailings piles looking upstream (north).  
July 1986.



Photo 8: Wolverine Creek tailings piles looking northwest. July 1986.





Photo 9: Toe of north tailings lobe. July 1986.



Photo 10: Toe of south tailings lobe. July 1986.