

Table A-11: Summary of 2010 Faro Creek Drainage Geotechnical Monitoring - Faro Pit Slope Stability


			January	February	March	April	May	June	July	August	September	October	November	December
Faro Pit Crest Regression														
Ref. Bar #15351	Tape Measurement	Recommended					S				F			
		Actual in 2010						24	20	20	23			
Ref. Bar #15352	Tape Measurement	Recommended					S				F			
		Actual in 2010						24	20	20	23			
Ref. Bar #15353	Tape Measurement	Recommended					S				F			
		Actual in 2010						24	20	20	23			
Ref. Bar #15354	Tape Measurement	Recommended					S				F			
		Actual in 2010						24	20	20	23			
Ref. Bar #15355	Tape Measurement	Recommended					S				F			
		Actual in 2010						24	20	20	23			
Ref. Bar #15356	Tape Measurement	Recommended					S				F			
		Actual in 2010						24	20	20	23			
Prism Movement														
Prism #13872	Prism Survey	Recommended					S				F			
		Actual in 2010									16 & 17			
Prism #13873	Prism Survey	Recommended					S				F			
		Actual in 2010									16 & 17			
Prism #13874	Prism Survey	Recommended					S				F			
		Actual in 2010									16 & 17			
Prism #13875	Prism Survey	Recommended					S				F			
		Actual in 2010									16 & 17			
Prism #13876	Prism Survey	Recommended					S				F			
		Actual in 2010									16 & 17			
Prism #13877	Prism Survey	Recommended					S				F			
		Actual in 2010									16 & 17			
Prism #13878	Prism Survey	Recommended					S				F			
		Actual in 2010									16 & 17			
Prism #13879	Prism Survey	Recommended					S				F			
		Actual in 2010									16 & 17			
Prism #13880	Prism Survey	Recommended					S				F			
		Actual in 2010									16 & 17			

S: spring; F: fall