



**Table A-13: Summary of 2010 Vangorda Creek Drainage Geotechnical Monitoring -  
Flow Rates**

			January	February	March	April	May	June	July	August	September	October	November	December
<b>Cross Valley Dam - Downgradient Seeps</b>														
Drain #3 (V30)	V-Notch Weir	Recommended					2 x / M	2 x / M	2 x / M	2 x / M	2 x / M	2 x / M		
		Actual in 2010					M	M	2 x / M	2 x / M	2 x / M	2 x / M	M	
Drain #4 (V31)	Channel	Recommended					2 x / M	2 x / M	2 x / M	2 x / M	2 x / M	2 x / M		
		Actual in 2010					M	M	2 x / M	2 x / M	2 x / M	2 x / M	M	
Drain #5 (V32)	V-Notch Weir	Recommended					2 x / M	2 x / M	2 x / M	2 x / M	2 x / M	2 x / M		
		Actual in 2010					M	M	2 x / M	2 x / M	2 x / M	2 x / M	M	
Drain #6 (V33)	V-Notch Weir	Recommended					2 x / M	2 x / M	2 x / M	2 x / M	2 x / M	2 x / M		
		Actual in 2010					M	M	2 x / M	2 x / M	2 x / M	2 x / M	M	