









**Figures 4-2 and 4-3: Water Quality in Rose Creek  
 Downstream of FMC Activities (X5, X10, X13 + X14)(2003 to 2010)**



## Figure 4-4: Water Quality in Rose Creek Downstream of FMC Activities at Station X14 - Winter (2003 to 2010)

