



	Project	Mount Nansen TA5 2013		
	Test	Government of Yukon - AAM		
	Location	N/A		
	Job No.	VM00605E.B001	Sample No.	GS5
	Hole No.	TP-T-13-04	Depth	3.0-3.1 m
ONE-DIMENSIONAL CONSOLIDATION TEST (ASTM D2435-90)	Reported by	CR/SH	Date Started	04-Feb-14



	Project			Mount Nansen TA5 2013				
	Test			Government of Yukon - AAM				
	Location			N/A				
	Job No.		VM00605E.B001	Sample No.		GS5		
	Hole No.		TP-T-13-04	Depth		3.0-3.1 m		
ONE-DIMENSIONAL CONSOLIDATION TEST (ASTM D2435-90)			Reported by		CR/SH	Date Started		04-Feb-14



	Project	Mount Nansen TA5 2013		
	Test	Government of Yukon - AAM		
	Location	N/A		
	Job No.	VM00605E.B001	Sample No.	GS5
ONE-DIMENSIONAL CONSOLIDATION TEST (ASTM D2435-90)	Hole No.	TP-T-13-04	Depth	3.0-3.1 m
	Reported by	CR/SH	Date Started	04-Feb-14

